

Investigation Report

Case

SPFD220517020882	Johnson, Randall	Closed	22-085-751	
Case Number	Lead Investigator	Status	Name	
Confidential	Accidental		Battery Related	
Confidentiality	Disposition		Fire Cause	
05/17/2022	22:52			
Start Date	Start Time	End Date	End Time	
Saint Paul Fire Department			Saint Paul Police Department	
Primary Fire Department	Canada::: ":		Law Enforcement	
rimary rife Department	Secondary Fire	Department	Law Enforcement	
se Narrative The fire department was cal	led to the report of a fire in a losed overhead garage door.	garage. Firefighte	rs arrived and found heavy smoke and guished the fire and conducted overhaul.	
se Narrative The fire department was cal some fire coming from the c	led to the report of a fire in a losed overhead garage door.	garage. Firefighte	rs arrived and found heavy smoke and	
se Narrative The fire department was cal some fire coming from the command was terminated a	led to the report of a fire in a losed overhead garage door.	garage. Firefighte	rs arrived and found heavy smoke and	

Fiге

	Vehicle storage area; garage, carport		
		Equipment Power Source	Equipment Portability
Area of Origin Comments			
Electrical arcing		Plastic	
Heat Source		Material Ignited	
Equipment Involved In Ignition	Equipment Make	Equipment Model	Equipment Serial Number
re and Smoke Spread Inf			
Fire Spread Material		Fire Spread Avenue	
Smoke Spread Material		Smoke Spread Avenue	
Fire Comments			
eather eather			From SSE
eather		9	
eather	Relative Humidity (%)		Wind Direction
	Relative Humidity (%)		
Visibility	1.1	Wind Speed (Mph)	

Property Details (1 of 1)

roperty			
Detached Garage			
Name			
1610 Blair Avenue			
Address		Apt/Suite/Roo	m
Saint Paul	Ramsey County	Minnesota	55104
City	County	State	Postal Code
\$50,000.00	\$25,000.00	\$50,000.00	
Pre Fire Value	Content Loss Value	Structure Los	ss Value
Property Description			
rea			
Structure	Urban		
Area Type	Area Description	Area Quality	

Parking garage, (detached	residential garage)	Unoccupied		
Property Use		Structure Occup	pancy	
	No			
Alarm Type	Smoke Detector P	Present	Smoke Detect	or Performance
None				
Sprinkler Standpipes		Sprinkler Stand	pipes Performance	e
22	20			
Structure Length (Ft) Str	ructure Height (Ft) Structure	Width (Ft) Nun	nber Of Stories	Number Of Units
Wood Frame	Type V		StructureMate	erial_Wood
Construction Type	Structure Type		Structure Mate	erial
Slab	Other	Pitched	Asp	halt
Foundation	Exterior Covering d near front of the right side (gai	Roof Type	Roof	Material
Foundation Heaviest fire damage note was located just below the Right side of garage contain miscellaneous pieces of eq	Exterior Covering d near front of the right side (gain heaviest fire damage. ined a very heavy fire load includ	Roof Type	Roof	Material hat was being charged
Foundation Heaviest fire damage note was located just below the Right side of garage contai	Exterior Covering d near front of the right side (gaing the heaviest fire damage. ined a very heavy fire load including the heaviest.	Roof Type	Roof	Material hat was being charged
Foundation Heaviest fire damage note was located just below the Right side of garage contai miscellaneous pieces of equation of the contains	Exterior Covering d near front of the right side (gaing the heaviest fire damage. ined a very heavy fire load including the heaviest.	Roof Type	Roof	Material hat was being charged
Foundation Heaviest fire damage note was located just below the Right side of garage contai miscellaneous pieces of equation Exam Garage had all doors locked	Exterior Covering d near front of the right side (gaile heaviest fire damage. ined a very heavy fire load includ juipment. d on arrival.	Roof Type	Roof	Material hat was being charged
Foundation Heaviest fire damage note was located just below the Right side of garage contain miscellaneous pieces of equation of the contain the contains th	Exterior Covering d near front of the right side (gaile heaviest fire damage. ined a very heavy fire load includ juipment. d on arrival.	Roof Type	Roof	Material hat was being charged
Heaviest fire damage note was located just below the Right side of garage contain miscellaneous pieces of equation of the contain the cont	Exterior Covering d near front of the right side (gaing the heaviest fire damage. ined a very heavy fire load including the properties of the properties o	Roof Type rage has a dividing ing multiple gas ca	Roof	Material hat was being charged and many
Heaviest fire damage note was located just below the Right side of garage contain miscellaneous pieces of equation of the contain the cont	Exterior Covering d near front of the right side (gainst heaviest fire damage. ined a very heavy fire load including purpose the service of the side (gainst heaviest fire damage.) d on arrival.	Roof Type rage has a dividing ing multiple gas ca	Roof wall). The battery t	Material hat was being charged and many

Motor Vehicle (1 of 1)

	1 10001 10	inete (1 of 1)
Vehicle Description		
1992	Honda	Red
Year	Make	Model Color
27-798	Minnesota	
License Plate Number	License Plate State	Vin
0		
Owner		11
Rick Fowler		
Owner Name		Owner Phone
Owner Street 1		Owner Street 2
	11	
Owner City	Owner State	Owner Postal Code
Operator		
Operator I		
Operator Name		Operator Phone
Operator Street 1		Operator Street 2
Operator City	Operator State	Operator Postal Code
Exterior		
ĺ	Yes	
Exterior Prior Damage		Tires / Wheels Parts Missing
_	_	

Fuel System			
			Gasoline
Fuel System Type	Fuel System Prior Damage	Fuel System Fire Damage	Fuel Type
Condition Of Tank	Filler Cap Condition	on Fuel Lin	e Condition
Facility Constraint			
Engine Compartment	,		,
		No	
Engine Prior Damage		Engine Fire Damage	
Fluid Level Oil	Fluid Level Transmission	Fluid Level Radiator	Fluid Level Other
Interior			
interior	1	ı	
	No		
Interior Prior Damage	Interior Fire Damage	Ignition System	Key In Ignition
Personal Contents Missing	Accessories Missing	Odometer Reading	Service Sticker Information
Security			
	H	11	I
Alarm Present	Doors / Trunk Locl	ked Window	/ Position
Origin / Ignition Sequence			
Area of Origin	Heat Source	Materia	l Ignited
Ignition Factor			

Motor Vehicle Comments

Examination of the exterior of the vehicle found that the fire and heat damage was most significant on the passenger/engine/cargo area of the vehicle. Examination of the interior of the vehicle found that the fire and heat damage was most significant on the passenger/engine/cargo area of the vehicle.

Witness Statement (1 of 2)

Fowler	Rick	
Last Name	First Name	Middle Name
Occupant		
Туре	Emp	oloyer
Interviewed Date	Interviewed By	Interviewed By Other
1610 Blair Ave		
Street 1	Stre	et 2
Saint Paul	Minnesota	55104
City	State	PostalCode
		I L
Race	Date of Birth	Driver's Liscense Number
- I was home at the time of and a half prior to the fire. - I was charging a battery or - I was alerted to the fire wh	n the back of the 4 wheeler.	I had been working in the garage an hour to an hour

Witness Statement (2 of 2)

Goertz	Michael	
ast Name	First Name	Middle Name
Owner		
уре	Employ	yer
nterviewed Date	Interviewed By	Interviewed By Other
Unknown		
treet 1	Street	2
Saint Paul	Minnesota	
ity	State	PostalCode
		l L
Race	Date of Birth	Driver's Liscense Number

Conclusion

Case Conclusion

After examination of the fire scene, observation of fire patterns of both movement and intensity and interviews conducted, it is my opinion the fire began in the garage. The area of origin was the automotive battery being charged while placed on the rear rack of a 4 wheeler. The first fuel/material ignited was most likely plastic. The ignition source was most likely electrical arcing. The oxidant was normal atmospheric air. The action that brought these items together was failure of the charging system. The classification of fire cause is accidental. This concludes my investigation and report.

Signature			
Johnson, Randall			
Lead Investigator	Signature	Date Submitted	

Document Attachment List

Photo Log