

Investigation Report

Case

SPFD220406014461	Smith, Michael	Closed	N/A
Case Number	Lead Investigator	Status	Name
Confidential	Accidental		Electrical System
Confidentiality	Disposition		Fire Cause
04/06/2022	22:26		
Start Date	Start Time	End Date	End Time
Saint Paul Fire Departmen	t		Saint Paul Police Department
Primary Fire Department Secondary Fire Department Law Enforcement			
Primary Fire Department se Narrative	Secondary Fir	e Department	Law Enforcement
Se Narrative The fire department was common such a wince fire and conducted overhal Ladder 18 arrived and four was open but nobody was	alled to the report of a fire i dow and door on the rear No ul. Command was terminate nd smoke coming from the d home. Resident downstairs	n a duplex residential rth side. Firefighters d and the scene was r oor and window from reports that the resid	home. Firefighters arrived and found evacuated the structure, extinguished the released. an upper unit. The door into the apartmenter the structure and her friends
se Narrative The fire department was common smoke coming from a wince fire and conducted overhat Ladder 18 arrived and four was open but nobody was reported the smoke from the smoke fro	alled to the report of a fire i dow and door on the rear No ul. Command was terminate nd smoke coming from the d	n a duplex residential rth side. Firefighters d and the scene was r oor and window from reports that the resid	home. Firefighters arrived and found evacuated the structure, extinguished the released. an upper unit. The door into the apartmenter the structure and her friends
Se Narrative The fire department was common such a wince fire and conducted overhal Ladder 18 arrived and four was open but nobody was	alled to the report of a fire i dow and door on the rear No ul. Command was terminate nd smoke coming from the d home. Resident downstairs	n a duplex residential rth side. Firefighters d and the scene was r oor and window from reports that the resid	home. Firefighters arrived and found evacuated the structure, extinguished the released. an upper unit. The door into the apartmenter the structure and her friends
se Narrative The fire department was common smoke coming from a wince fire and conducted overhat Ladder 18 arrived and four was open but nobody was reported the smoke from the smoke fro	alled to the report of a fire i dow and door on the rear No ul. Command was terminate nd smoke coming from the d home. Resident downstairs	n a duplex residential rth side. Firefighters d and the scene was r oor and window from reports that the resid	home. Firefighters arrived and found evacuated the structure, extinguished the released. an upper unit. The door into the apartmenter the structure and her friends

Fire

Electrical System	Cooking area, kitchen		
Fire Cause Ar	ea of Origin	Equipment Power Source	Equipment Portability
Area of Origin Comments			
Heat from powered equipm	ent, other	Multiple types of mater	ial
Heat Source		Material Ignited	
	l		
Equipment Involved In Ignition	Equipment Make	Equipment Model	Equipment Serial Number
re and Smoke Spread Info			
Fire Spread Material		Fire Spread Avenue	
1		· 	
Smoke Spread Material		Smoke Spread Avenue	
Fire Comments			
/eather			
		18	west
Visibility	Relative Humidity (%) Wind Speed (Mph)	Wind Direction
34.0	0.2	No	
Temperature (Fahrenheit)	Precipitation	Lightning	Information Obtained From Weather

Property Details (1 of 1)

roperty			
N/A			
Name			
733 Thomas Avenue North			
Address		Apt/Suite/Roo	m
Saint Paul	Ramsey County	Minnesota	55104
City	County	State	Postal Code
\$175,000.00	\$25,000.00	\$175,000.00	
Pre Fire Value	Content Loss Value	Structure Los	ss Value
Property Description			
геа			
Structure	Urban		
Агеа Туре	Area Description	Area Quality	

Structure 1 or 2 family dwelling Occupied Property Use Structure Occupancy Unknown Not Operating Alarm Type **Smoke Detector Present** Smoke Detector Performance Unknown None Sprinkler Standpipes Sprinkler Standpipes Performance 60 35 2 Structure Length (Ft) Structure Height (Ft) Structure Width (Ft) Number Of Stories Number Of Units Type V Wood Frame StructureMaterial_Wood Structure Type Construction Type Structure Material Brick/Stone Basement Pitched **Asphalt** Foundation Exterior Covering Roof Type Roof Material Investigation of the second floor found heavy smoke, fire and heat damage. Fire patterns on the exterior of the door to

Investigation of the second floor found heavy smoke, fire and heat damage. Fire patterns on the exterior of the door to the second-floor unit #2 indicate the door had been closed at the time of the fire. The fire started in the kitchen area adjacent the stove. Fire patterns indicate the fire extended upwards and outwards from the floor area adjacent the stove where the refrigerator had been. Rollover had occurred, smoke banked down to the midpoint of the walls and fire, heat and smoke damage extended to all adjacent rooms. Fire patterns on the refrigerator indicate the fire started at the base behind the refrigerator and extended upwards behind the refrigerator. The mechanical assembly and the interior of the refrigerator had been completely destroyed by fire.

Inspection of the attic space found light smoke throughout the attic. No extension of fire was visible.

Observation of the first floor found light smoke throughout. No fire damage was visible.

Examination of the basement found light smoke throughout. There were separate electrical panels for each floor. Fuses ten and five had burned out, the panel did not indicate the location they served. Sub panel #2 had two breakers tripped, 2nd floor kitchen and 2nd floor receptacles. All appliances in the basement appeared to be in working condition and were uninvolved with the fire.

Interior Exam

The structure is a large two story house with brick exterior. The address side of the property faces south. There is a detached garage on the north side of the property with access to the alley.

Observation of the south side of the structure found light smoke coming from an open window for the attic space. There was soot and smoke staining on the interior of the second floor windows.

Examination of the west side of the structure found light smoke staining on the inside of the second floor windows and light smoke coming form the eves. The electrical service for the structure was located on the west side of the structure near the north corner. There are two electrical meters for the structure. Both meters looked to be in good working order and were not involved with the fire.

Inspection of the north side of the structure found smoke and soot staining on the inside of the windows of the second floor.

Investigation of the east side of the structure was difficult because of bushes, an exposure, and a fence. The gas meters for the structure were on the east side near the south corner. Both meters appeared to be in good working order and were not involved with the fire.

Witness Statement (1 of 2)

Brown	Karl	
Last Name	First Name	Middle Name
Occupant		
Туре	Emp	loyer
Interviewed Date	Interviewed By	Interviewed By Other
733 Thomas (lower)		
Street 1	Stree	et 2
Saint Paul	Minnesota	55104
City	State	PostalCode
ĺ		11
Race	Date of Birth	Driver's Liscense Number
- I was home at the time of th - Upstairs residents friends kr - I do not know when the upsi - I think her name is Emma To	nocked on our door and reported sm cairs resident left.	Upstairs resident was not home. oke from the door. called 9-1-1.

Witness Statement (2 of 2)

Chang	Inho	
Last Name	First Name	Middle Name
Owner		
Гуре	Emplo	yer
nterviewed Date	Interviewed By	Interviewed By Other
733 Thomas		
Street 1	Street	:2
Saint Paul	Minnesota	55104
City	State	PostalCode
		<u> </u>
Race	Date of Birth	Driver's Liscense Number
- Owner of the duplex		

Conclusion

Case Conclusion

After examination of the fire scene, observation of fire patterns of both movement and intensity and interviews conducted, it is my opinion the fire began in the kitchen area. The area of origin was the refrigerator. The first fuel/material ignited was most likely electrical wiring or plastic from refrigerator. The ignition source was most likely heat from a mechanical or electrical failure. The oxidant was normal atmospheric air. The action that brought these items together was a malfunction within the appliance. The classification of fire cause is accidental. This concludes my investigation and report.

Si	gnature			
	Smith, Michael			
	Lead Investigator	Signature	Date Submitted	

Document Attachment List

Photo Log