51

53

58

59

60

63 65

ΝŅ

Row of stores

Enclosed mail

Office use


Industrial use

Military use

Fam use

Not mixed use

Business and residential use



Diesel fuel/fuel oil - vehicle fuel tank/portable

Household/office solvent or chemical spill

Paint - spills less than 55 gailons

N None

Motor oil - from engine or portable container

H<sub>2</sub> Detector

Unknown

2

Required for confined fires. Detector alerted occupants

Detector did not alert occupants

HazMat-7

X Apparatus-9

X Personnel-10

Arson-11

WildLand Fire-8

Α	02210	SPFD170125003038 0 0 Cident Number Exposure	NFIRS-2 Fire
В	Property Details C Or or	n-Site Materials  None  Complete If there were any significant amoun industrial, energy, or agricultural products or property, whether or not they became lavolve.	materials on the
B1 B2	1 1 Not Residential  Estimate number of residential living units in building of origin whether or not all units became involved  On-site r	up to three codes. Check one box for each code entered.	On-Site Materials Storage Use 1 Bulk storage or wareheusing 2 Processing or manufacturing 3 Packaged goods for sale 4 Repair or service N None U Undetermined
Вз	None  Acres burned (outside fires)  None  Less than one acre	material (2)	1 Bulk storage or warehousing 2 Processing or manufacturing 3 Packaged goods for sale 4 Repair or service
	On-site s	malerlai (3)	N None U Undetermined  1 Bulk storage or warehousing 2 Processing or manufacturing 3 Packaged goods for sale 4 Repair or service N None U Undetermined
D <sub>1</sub>	Bedroom - < 5 persons; included are jail or prison  Area of fire origin  UU  Undetermined  UU  Undetermined  Check box if fee spread was confined to object of origin.	E1 Cause of Ignition  Check Bills box If this is an exposure report  Cause, other (System generated code only, not used for data entry)  Internitional  Vinintentional  Failure of equipment or heat source  Act of nature  Cause under investigation  Cause undetermined after investigation  Factor southbuting to Ignition  70 Fire spread or control, other  Factor southbuting to Ignition (2)	E3 Human Factors Contributing to Ignition  Check ell applicable boxes  None  1 Asleep 2 Possibly impaired by alcohol or drugs 3 Unattended or unsupervised person 4 Possibly mentally disabled 5 Physically disabled 6 Multiple persons involved 7 Age was a factor N X None Estimated age of person involved 1 Male 2 Fernale
Se Me	H equipment was not involved, skip to Section G  Guipment Involved arand  H equipment was not involved, skip to Equipment Power Source  F3 Equipment Portab  1 Portable  2 Stationary	Eater up to three codes,	ion Factors
L	Not involved in ignition, but burned Involved in ignition, but did not itself burn Idabite property type	Local Use Pre-Fire Plan Available Some of the Information presented in this report in Arson report attached Police report attached Coroner report attached Other reports attached	ray ba based upon reports from other agendes:

A 62210 MN 01 25 2017  FDID State Incident Date	08   SPFD170125003038   0     Station   Incident Number   Exposure	NFIRS-3 Structure Fire
the was in an enclosed building or a portisted method is selected by the complete the selected by the complete the selected bits form.  O Structure type, other  1 X Enclosed building 2 Fixed portable or mobile structure 3 Idle, n 3 Open structure 4 Air-supported structure 5 Vacan 5 Tent 6 Open platform 7 Being	ing Status  ng status, other  construction mal use ing troutinely used major renovation it and secured demolished lermined    3	4 Main Floor Size
J1 Fire Origin  2 Below Grade Story of fire origin  J2 Fire Spread If the spread was confined to bleed of erigin, do not between years (Black 03, Fire Models). Confined to object of origin Confined to room of origin Confined to floor of origin Confined to floor of origin Confined to building of origin Beyond building of origin	Number of Stories Damaged by Flame  Count the roof as part of the highest story.  Humber of slades winning damage (1 lo 24% flame damage)  Number of slades wisignificant damag (25 lo 49% flame damage)  Number of slodes witesyr damag (50 to 74% flame damage)  Humber of slodes witesyr damag (50 to 74% flame damage)  Humber of slodes witesyr damag (75 to 190% flame damage)	K Type of Material Contributing Most to Flame Spread  Check in e fame spread OR if same as Natelial First logical (Block D4, Fire Module) OR if unable to addismone.  K1
L1 Presence of Detectors	L3 Detector Power Supply  0 Detector power supply, other  1 Battery only 2 Hardwire only 3 Plug-in 4 Hardwire with battery backup 5 Plug-in with battery backup 6 Mechanical 7 Multiple detectors and power supplies U Undetermined  L4 Detector Operation 1 Fire too small to activate detector 2 Detector operated 3 Detector failed to operate U Undetermined	L5 Detector Effectiveness Required if delector operated Detector alerted occupants, occupants responded Detector alerted occupants, occupants failed to respond There were no occupants Detector failed to alert occupants Undetermined L6 Detector Failure Reason Required if detector failed to operate Detector faillure reason, other Power failure, hardwired det, shut off, disconnect Improper installation or placement of detector Defective detector Lack of maintenance, includes not cleaning Battery missing or disconnected Battery discharged or dead Undetermined
M1 Presence of Automatic Extinguishing System  1 Present 2 Partial System Present N X None Present U Undetermined  M2 Type of Automatic Extinguishing System Registed if the was within designed range of AES 0 Special hazard system, other 1 Wet-pipe sprinkler system 2 Dry-pipe sprinkler system 3 Other sprinkler system 4 Dry chemical system 5 Foam system 6 Halogen-type system 7 Carbon dioxide system Undetermined	M3 Operation of Automatic Extinguishing System Required if the way with designed range Operation of AES, other 1 System operated and was effective 2 System operated and was not effective 3 Fire too small to activate system 4 System did not operate U Undetermined  M3 Number of Sprinkler Heads Operating Required it system operated Humber of sprinkler heads operating	M5 Reason for Automatic Extinguishing System Failure Required Faystem failed or not effective, other Reason System not effective, other System shut off Not enough agent discharged to control the fire Agent discharged, but did not reach the fire Inappropriate system for the type of fire Fire not in area protected by the system System components damaged Lack of maintenance, including corrosion or heads painted Manual intervention defeated the system Undetermined

J Property Use Structures  419 × 1 or 2 family dwelling  311 24-hour care Nursing homes, 4 or more persons  241 Adult advaellon center, college classroom  162 Bar or nightclub  464 Barracks, dormitory  439 Boarding/rooming house, residential hotels  599 Business office	Otinic, clinic-type infirmery  Doctor, dentist or oral surgeon office  Electric-generating plant  Elementary school, including kindergarten  Food and beverage seles, grocery store  High school/funior high school/middle school  Hospital - medical or psychilatric  Hotel/motel, commercial  Household goods, salas, repairs	629 Laboratory or science laboratory 819 Livestock, poultry storage 700 Manufacturing, processing 579 Motor vehicle or boat sales, services, repair 429 Multifamily dwelling 882 Parking garage, general vehicle 459 Residential board and care 161 Restaurant or cafeteria 571 Service station, gas station					
Outside 981 Construction site 655 Crops or orchard	1981 Jail, prison (not juvenile) 1984 Industrial plant yard - area 1946 Lake, river, stream 1940 Open land or field 1950 Outside material storage area	891 Warehouse 960 Street, other 936 Vacant lot					
919 Dump, sanitary tandfill 669 Forest, limberland, woodland 938 Graded and cared-for plots of land 961 Highway or divided highway	124 Playground 951 Railroad right-of-way 962 Residential street, road or residential driveway	Lock up and enter a Property Use Code and description any it you have NOT chetked a Property Use Box.  Property Use Description  Property Use Description					
K1 Person/Entity Involved  Local Option Check this box if same address as Incident Location (Section B). Then sky the tives duplicate address pines.	Business Hame (if Applicable)  I.V., Ms., Mrs. First Name Mi  Number Prefix Street or Highway  Post Diffee Box Api / Sutte/Reem City  State Zip Code	Area Code Phone Number  Last Hame Suffix  Sircel Type Suffix					
Same as patron involved? Then check this box and step the rest of this block, Check this box it same address as incident Location (Section B), Then skip the time dup@cate address pines.	Business Name (if Applicable)    CHAI	651   - 216   - 1172     VANG   Phone Number     Last Name   ST   Street Type Suifix					
Authorization							
L Remarks Local Copion  FIRE AND RESCUE CREWS RESPONDED TO THE REPORT OF A STRUCTURE FIRE WITH FLAMES SEEN BURNING THROUGH THE ROOF, THE INITIAL ARRIVING							

FIRE AND RESCUE CREWS RESPONDED TO THE REPORT OF A STRUCTURE FIRE WITH FLAMES SEEN BURNING THROUGH THE ROOF, THE INITIAL ARRIVING FIRE UNITS RECOGNIZED THIS AS DEFENSIVE FIRE CONDITIONS AND IMMEDIATELY STARTED EXTINGUISHMENT EFFORTS FROM THE OUTSIDE. THE FIRE HAD BURNED THROUGH THE ROOF PRIOR TO THE ARRIVAL OF THE FIRE DEPARTMENT. IT WAS REPORTED THAT THERE WERE NO VICTIMS IN THE DWELLING AND IT WAS A VACANT STRUCTURE. WATER SUPPLIES WERE ESTABLISHED AND MASTER STREAM OPERATIONS BEGAN.

THE MAIN BODY OF FIRE WAS ON THE SECOND FLOOR WITH EXTENSION TO THE FIRST FLOOR. AFTER THE FIRE WAS EXTINGUISHED, A SMALL CREW WAS SENT IN TO CONFIRM THAT THERE WERE NO VICTIMS AND FOR FINAL EXTINGUISHMENT OF ANY HOT SPOTS.

XCEL POWER AND ELECTRIC ARRIVED ON SCENE AND DISCONNECTED BOTH GAS AND POWER. BOARD-UP ARRIVED AND SECURED THE DWELLING, FIRE INVESTIGATOR ASPNES HAS DETERMINED THAT THE CAUSE IS "UNDER INVESTIGATION."

## Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	17-03038	DATE OF INCIDENT: 01/25/2017		
TIME OF INCIDENT:	0150 hours	POLICE CASE #: 17-017-481		
INVESTIGATOR(s):	M. Aspnes and B. Ricketson			
INCIDENT ADDRESS:	970 Woodbridge Street, Saint Paul, MN 55117			
OCCUPANT NAME:	Unknown PHONE: Unknown			
OWNER NAME:	Chai Vang & Xia Lee	Lee PHONE: 651-216-1172		
ADDRESS OF OWNER:	970 Woodbridge Street, Saint Paul, MN 55117			
PROPERTY DAMAGED:	Single family dwelling AREA OF ORIGIN: Second floor living space			
DAMAGE ESTIMATE:	Building \$60,700	Vehicle \$	Other (Describe) \$	
VALUE:	Building \$60,700	Vehicle \$	Other (Describe) \$	
Damage Estimate CONTENTS ONLY:	\$5,000			
INJURY/DEATH (if yes, explain)	No ☐ Yes			
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present:  Yes  No Unknown  Detector Functioning:  Yes  No Unknown  Sprinkler System Present:  Yes  No Unknown  Sprinkler Heads activated:  Yes # No Unknown  C.O Detector Present:  Yes  No Unknown			
FIRE CAUSE CLASSIFICATION:	RE CAUSE Accidental Juvenile/Incendiary			
SYNOPSIS:	The fire department was dispatched for a reported dwelling fire with flames seen. Firefighters arrived to find a single-family dwelling with heavy fire on the second floor, as well as the stairwell to the second floor. Firefighters extinguished the fire and performed overhaul. A 9-1-1 caller reports that the previous residents moved out of the building approximately 1 week prior to this fire. Very few belongings remained in the building and it appeared vacant. It is unknown if power was still present in the building. Heavy fire damage mainly to the second floor with some minor extension to the first floor via the stairway. Conditions on the second floor reached flashover and also involved some structural collapse. Due to extensive water applied during suppression and the severity of fire damage, no clear point of origin could be determined. The ignition source is unknown. The first fuel ignited is unknown. The classification of fire cause at this time is "under investigation".			
DISPOSITION:	E-mail only DO NOT DEMOLISH until Analysis of Evidence	approved 🔯 Sce	d Scene until approved ene Released port to Follow	

## FIRE INVESTIGATION REPORT

INCIDENT NO: 17-03038

DATE: 01/25/2017

TIME: 0150 HOURS

ADDRESS: 970 WOODBRIDGE STREET

INSURANCE CO: UNKNOWN

DAMAGE ESTIMATE: \$65,700

CN#: 17-017-481

SYNOPSIS: On Wednesday, January 25, 2017, at approximately 0150 hours, the Saint Paul Fire Department was called to a report of a residential structure fire. The location of the incident was 970 Woodbridge Street. Upon the fire department's arrival, Ladder #22's crew found what appeared to be a one and a half story dwelling with a fully involved second floor with fire venting through the roof. Crews extinguished the fire and performed overhaul. Investigation revealed the fire appeared to have started somewhere on the second floor. Witnesses on scene stated that the home is vacant. The ignition source was probably an open flamed device. The first material ignited was possibly vapors from a flammable liquid or ordinary combustibles present in the building. The act that brought them together was probably an intentional human act. The classification of fire cause is undetermined.

**PEOPLE:** Property Owner/Occupant, CHAI VANG, 970 Woodbridge Street, Saint Paul, MN 55117, 651-216-1172, DOB unknown.

Other person/9-1-1 caller,

BACKGROUND: I received notification of the fire via the Communications Center at approximately 0150 hours. I responded to the incident scene and arrived at approximately 0202 hours. Fire extinguishment was in progress upon my arrival. The building was reported to be vacant and no occupants were found in the structure. Weather conditions were cloudy skies with light snow and north winds at approximately 7 mph. The air temperature was approximately 31° Fahrenheit.

Ladder #22's crew arrived to find a fully involved second floor with fire venting through the roof at the peak. Ladder #22's crew forced entry into the building at both the front and rear doors. The front door was locked, but the rear door was not tried prior to being forced, so it is unknown if there was any forced entry prior to fire department arrival. Due to heavy fire, Ladder #22's crew decided to switch to defensive operations, and deployed a high volume master stream into the second floor. Several other hose streams were used to flow water into the second floor. Eventually, entry was made into the dwelling after allowing the second floor to partially drain.

**PROPERTY DESCRIPTION:** The structure is a one and a half story, single family dwelling of wood framed construction with exterior vinyl siding. The building measured approximately 30 feet wide by 50 feet deep. The address side faced west and the building ran east to west. Smoke detectors were not present.

Fire Investigation Report 970 Woodbridge Street Page Two

**EXTERIOR EXAMINATION:** Visual inspection of the west side revealed the main front entrance present in the center of the first floor, with intact windows on either side. Water was flowing from under the front door. Fire was visible venting from the second floor window, with significant heat and smoke damage to the siding starting from below the window sill and extending up to the eaves.

Visual inspection of the north side revealed five windows of various sizes on the first floor. Some of the windows were broken. The roof line extended down to the top of the first floor. No heat or fire damage was visible to the north side.

Examination of the east side revealed an entry door in the middle of the first floor with windows on either side. One broken window was present on the second floor. Heavy heat and smoke damage was present from the level of the first floor ceiling extending up to the peak of the roof. The power drop was present on the east side of the building just to the north of the rear entry door. The electric meter had been removed and a clear cover was in its place. The electric meter socket was under a secured blue tarp upon the fire department's arrival, indicating that the meter had probably been removed prior to the time of the fire and that the building was not energized at the time of the fire. It is unknown where the gas meter was located, but gas appliances were present inside the dwelling.

Inspection of the south side revealed six windows of various sizes, as well as three basement windows. A few of the first floor windows were broken. The roof line extended to the first floor ceiling level. No smoke or heat damage was observed on the first floor siding.

The roof covering was asphalt shingles and the roof had significant mass loss and a partial collapse at the peak, next to the chimney. The collapsed portion of the roof is about half way between the west and east ends of the building.

INTERIOR EXAMINATION: Visual inspection of the basement interior revealed large amounts of suppression water leaking from the floor above and standing water approximately two to three feet deep. No heat or smoke damage was observed. The fuse panel on the east wall appeared to have no blown fuses. The furnace and water heater appeared to be undamaged by the fire. The washer and dryer in the basement also appeared undamaged by the fire. The basement had almost no contents other than appliances.

Examination of the first floor revealed smoke and heat damage at the ceiling level only. Significant suppression water was draining from the second floor above. The kitchen appliances appeared undamaged by fire. Minimal contents were present and the home appeared vacant. Only a small amount of time was spent on the first floor due to the large loading of the floor above by water as indicated by some sagging ceiling members.

Fire Investigation Report 970 Woodbridge Street Page Three

The door located at the base of the stairs leading to the second floor showed significant heat and smoke damage, as well as mass loss to the top half indicating that a flashover condition was present in the area of the stairs. The lack of significant damage to the first floor indicated that the door was likely closed at the time of the fire.

The second floor ceiling/roof revealed a partial collapse in the center of the roof at the peak, adjacent to the chimney. There was a substantial amount of brick missing from the chimney presenting a collapse hazard. The entirety of the second floor exhibited significant mass loss to structural members throughout. Due to the large amount of damage, copious amounts of suppression water flowed into the second floor, and standing water at a depth of approximately six inches precluded determination of an exact area of origin. Inspection of electrical junction boxes and wires present on the second floor revealed no signs of arcing, indicating that the electricity was off at the time of the fire. This corresponds with the lack of an electrical meter as stated above.

**INTERVIEWS:** One neighbor on scene who left prior to providing any personal information stated that the home is vacant and that the occupants moved out approximately one week prior to the day of the fire. It is unknown if this person is the 911 caller (described below). No other persons were on scene to be interviewed. The phone number for the owner listed on the City of Saint Paul's STAMP website was called, but the voicemail message stated that the phone belonged to someone other than the listed owner, a SETH FRANKLIN.

The CAD notes stated that the 9-1-1 caller is a believes the occupants moved out a week ago.

. CAD notes stated that the caller

PHOTOGRAPHS/SKETCH: Digital photographs were taken.

**EVIDENCE:** No evidence was collected. All possible evidence was left on scene for examination by an insurance company representative.

**CONCLUSION:** After examination of the fire scene and the interview conducted, and fire patterns of both movement and intensity observed it is my opinion the fire began somewhere on the second floor or at the stairwell leading to the second floor. The greatest area of mass loss was present at the roof peak near the chimney, however this was also the highest point of the roof and may have suffered more severe damage due to its location. The fact that the stairwell was also significantly heat damaged down to floor level indicated this area was a possible site for the origin, however significant radiant heat from above may have also produced this damage.

Fire Investigation Report 970 Woodbridge Street Page Four

The ignition source was probably an open flamed device, as the electricity appears to have been shut off at the time of the fire, no arcing was observed on electrical wires on the second floor, and there appeared to be no involvement of any of the appliances. However, the lack of witnesses on scene, the fact that the home appears vacant, and the significant amount of damage precludes the exclusion of other ignition sources. The first fuel/material ignited was possibly vapors from a flammable liquid or ordinary combustibles present inside the residence. The action that brought these items together was probably an intentional human act. The classification of fire cause is undetermined. This report will be submitted to the Saint Paul Police Department. This concludes my investigation and report.

M. Aspnes, Fire Investigator, C Shift, 02/19/2017

MA/su