MM DD	YYYY Delete
62210 MN 01 31	2014 107 114-0003208 000
FDID A State Incident Date	Station Incident Number * Exposure * No Activity
	diane that the address for this incident is mostified on the Wildland Nive
	"Alternative Location Specification". Use only for Wildland fires. Census Tract 0315 - 00
X Street address	
	JESSIE ST
Intersection Number/Milepost Prefi	
Rear of SA	INT PAUL MN 55130 -
Apt./Suite/Room Cit	State Zip Code
Directions Cross street or directions	ections, as applicable
	Midnight is 0000
C Incident Type *	E1 Date & Times E2 Shirt & Ararms
111 Building fire	Check boxes if Month Day Year Hr Min Sec Local Option
Incident Type	same as Alarm ALARM always required D3
D Aid Given or Received*	Date. Alarm * 01 31 2014 05:24:47 Shift or Alarms District Platoon
1 Mutual aid received	ARRIVAL required, unless canceled or did not arrive
2 Automatic aid recv. Their FDID Their	X Arrival * 01 31 2014 05:28:03 E3
3 Mutual aid given	CONTROLLED Optional, Except for wildland fires Special Studies
4 Automatic aid given	Controlled Local Option
5 Other aid given Their	LAST UNIT CLEARED, required except for wildland fires
N X None	Last Unit
	Creared
F Actions Taken *	G1 Resources * G2 Estimated Dollar Losses & Values
	Check this box and skip this LOSSES: Required for all fires if known. Optional
	Personnel form is used. for non fires. None
Primary Action Taken (1)	Apparatus Personnel Property \$, 050, 000
, , , , , , , , , , , , , , , , , , , ,	
Additional Action Taken (2)	EMS PRE-INCIDENT VALUE: Optional
	Other Property \$, 000 , 000
Additional Action Taken (3)	Check box if resource counts
	include aid received resources. Contents \$, 000, 000
Completed Modules H1*Casualties	None H3 Hazardous Materials Release I Mixed Use Property
X Fire-2 Deaths Inj	uries N None NN L Not Mixed
XStructure-3	10 Assembly use
Civil Fire Cas4 Service	2 Propane gas: <21 lb. tank (as in home BBO grill) 20 Medical use
Fire Serv. Cas5 Civilian	Gasoline; vehicle fuel tank or portable container 40 Residential use
EMS-6	51 Row of stores
H2 Detector Required for Confined	E Diogol fuel/fuel oil.
Wildland Fire-8	6 Develored golventary
X Apparatus-9	7 Motor oil: from angine or portable doubtiner 60 Industrial use
Personnel-10 2 Detector did not al	
Arson-11 U unknown	Of Other: Special HazMat actions required or spill > 55gal., OO Other mixed use
T Property Hack Characterist	Please complete the HazMat form 341 Clinic, clinic type infirmary 539 Household goods, sales, repairs
J Property Use* Structures	342 Doctor/dentist office 579 Motor vehicle/boat sales/repair
131 Church, place of worship	361 Prison or jail, not juvenile 571 Gas or service station
161 Restaurant or cafeteria	419 X 1-or 2-family dwelling 599 Business office
162 Bar/Tavern or nightclub	429 Multi-family dwelling 615 Electric generating plant
213 Elementary school or kindergarten	439 Rooming/boarding house 629 Laboratory/science lab
215 High school or junior high	449 Commercial hotel or motel 700 Manufacturing plant
241 College, adult education	459 Residential, board and care 819 Livestock/poultry storage(barn)
311 Care facility for the aged	464 Dormitory/barracks 882 Non-residential parking garage
331 Hospital	519 Food and beverage sales 891 Warehouse
Outside	936 Vacant lot 981 Construction site
124 Playground or park	938 Graded/care for plot of land 984 Industrial plant yard
655 Crops or orchard	946 Lake, river, stream
669 Forest (timberland)	951 Railroad right of way Lookup and enter a Property Use code only if you have NOT checked a Property Use box:
807 Outdoor storage area	960 Other street Property Use 419
919 Dump or sanitary landfill	961 Highway/divided highway 1 or 2 family dwelling
931 Open land or field	962 Residential street/driveway NFIRS-1 Revision 03/11/99

A MM DD YYY	YY 1014	07 Station	Incident Numb		00 Exposur	— ⊦	Delete Change No Activity	NFIRS -2 Fire
B Property Details	***************************************	C On-Site or Produce	cts		mounts d gricultu	of commer ural prod	were any signif- cial,industrial, lucts or material; or not they beca	energy or on the
B1 0002 Not Residential Estimated Number of residential living units building of origin whether or not all units became involved		or more boxes for each code entered. NNN None On-site material (1)			Bulk storage or warehousing Processing or manufacturing Packaged goods for sale Repair or service Bulk storage or warehousing			
B2 001 Buildings not involve	đ	On-site material	(2)		2 P 3 P 4 P	rocess ackage lepair	ing or manufa d goods for a or service	acturing sale
B3 X None Acres burned (outside fires) Less than one acre	WISHAMISANIA AMPIRANJANIA PRABINA	On-site material	(3)		2 P 3 P 4 P	rocess ackage lepair	orage or ware ing or manufa d goods for a or service	cturing
D Ignition 1	E1	Cause of I	:his is an exp	osure report		Cont	an Factors tributing To all applicable	_
D1 24 Cooking area, kitchen Area of fire origin *	2	Intentional Unintentional X Failure of eq	uipment or h	eat source		2 🗍	Asleep Possibly impai	ga
D2 13 Electrical arcing Heat source *	5 U		nvestigation mined after	investigat		4 5	Unattended per Possibly menta Physically Dis Multiple perso	l disabled abled
D3 81 Electrical wire, cable Item first ignited * 1 Check Box if fire spread was confined to object of origin	<u>62</u> [3	3 Short	-circuit	arc	None	Estim	Age was a fact	or
Type of material Required only if item first first ignited ignited code is 00 or <70	Fa	actor Contributing	To Ignition (2	2)		1 []	n envolved	? Female
None If Equipment was not involved, Skip to Section G	11 Equipme	Equipment Po	al	En	ter up		ssion Factoree codes.	ors None
Brand Model		Portable X Stationary		Fire s	uppressi	on factor	c (2)	
Serial #	oved by e use i	e equipment normary one person, is n multiple local no tools to in	designed to	Fire s	uppressi	on factor	c (3)	
None Not involved in ignition, but burned Involved in ignition, but did not burn Involved in ignition and burned	obile		ype & Ma	ke	t f f DPC	ome of the his report of the r	E Fire Plan Av ne information pr nt may be based u r Agencies eport attache report attach report attach eports attach	esented in pon reports d ed ched
License Plate Number State VIN	Number					NFIR:	S-2 Revision	01/19/99

I1 Structure Type * If Fire was In enclosed building or a	I ₂ Buildin	g Status *			I4 Main Floor Size*	NFIRS-3	
portable/mobile structure complete				ight		Structure Fire	
the rest of this form 1 X Enclosed Building	1 Under cons	struction	of the high	ROOF as part nest story			
2 Portable/mobile structure	2 X Occupied 8	operating					
3 Open structure		routinely used	00	_		00	
4 Air supported structure	4 Under major			mber of stories ove grade	Total square feet		
5 Tent	6 Vacant and			1	OR		
6 Open platform (e.g. piers) 7 Underground structure(work areas)	7 Being demo	lished	Total nu	mber of stories			
8 Connective structure (e.g. fences	O Other		below gra	ade	060 BY	030	
0 Other type of structure	U Undetermin	ıed			Lenght in feet Wid	th in feet	
J1 Fire Origin +	J3 Numb	er of Stori	es	77 Mat	erial Contributing M	logt.	
Ul Fire Origin *	, ,	ged By Flam		1	Flame Spread	OBC	
002 Below Grade	Count the ROOF as			,	=	ip To	
Story of fire origin	Number of a	tories w/ minor de	amage		ume as material first ignited Se able to determine	ction L	
To	(1 to 24% f	lame damage)		72°-1	1.1	ı	
J ₂ Fire Spread *		stories w/ signifi	cant damage	K1 L	contributing most to flame spread		
Confined to object of origin	─────────────────────────────────────	flame damage)					
Confined to room of origin X Confined to floor of origin		tories w/ heavy da flame damage)	mage	K2			
4 Confined to building of origin	Wumban of g	- 	4		f flame spread contri	ed only if item buting	
5 Beyond building of origin		tories w/ extreme flame damage)	danage	***************************************	code i	s 00 or<70	
L1 Presence of Detectors *	T.3 Detec	tor Power	Supply	r.s Det	ector Effectiveness		
(In area of the fire)		101101	Dobbal .		uired if detector operate	đ	
N None Present Skip t			1	_	ed Occupants, occupants re		
section 1 [X] Present	M 2 Hardw	ire only	1		ants failed to respond	esponded	
		vire with batt	ery	= -	were no occupants		
U Undetermined	5 Plug	in with batte	ry	므	d to alert occupants		
L2 Detector Type	6 Mecha			U Undete	ermined		
	, -	le detectors supplies	& :	L6 Det	ector Failure Reason	i	
1 Moke	0 Other		İ	Required	d if detector failed to op	perate	
2 Heat	1	ermined					
3 X Combination smoke - heat	T.4 Dete	ctor Operat	tion		failure, shutoff or disc		
	1 1	ire too small		2 Improper installation or placement 3 Defective			
4 Sprinkler, water flow detecti	O11 3	o activate		- =	of maintenance, includes	cleaning	
5 More than 1 type present		perated		5 Batter	ry missing or disconnecte	ď	
O Other		Complete Section ailed to Opera		_ =	ry discharged or dead		
U Undetermined		Complete Section		U ☐Undete			
	_ n □ n	ndetermined		0 Dougece	simineu		
M ₁ Presence of Automatic Extinguis	hment System *	M3 Automati	c Extingu	ıishment	M5 Automatic Extingu	ishment	
N X None Present		-	peration		System Failure Rea	ason	
	plete rest	Required if fire		-	wedning it sharew rain	ed	
	Section M	1 0perated 2 0perated					
M ₂ Type of Automatic Extinguishme Required if fire was within design	- "	3 Fire too			2 Not enough agent d		
1 Wet pipe sprinkler	ed lange of ABS	4 Failed to	operate	(Go to M5) 3 Agent discharged by not reach fire	it did	
2 Dry pipe sprinkler		0 Other	فسسا		4 Wrong type of system	em	
3 Other sprinkler system		U Undetermi	ruea		5 Fire not in area p		
4 Dry chemical system 5 Foam system			of Sprinkl	ler	6 System components of		
6 Halogen type system		Heads Op	_		7 Lack of maintenance 8 Manual Intervention		
7 Carbon dioxide (CO ₂) system	ι	Required if	system ope	rated	0 Other		
0 Other special hazard system	ı	Number - 5	minbla b-		U Undetermined		
U Undetermined		Number of sp	rinkier ue	aus operatir	NFIRS-3 Revision 0	1/19/99	

K1	Person/Entit	Ty Involved Business name (if applicable) Business name (if applicable) Business name (if applicable) Area Code Phone Number
؛ لــا : :	Check This Box if same address as incident location. Then skip the three duplicate address lines.	CLAIRE Mr.,Ms., Mrs. First Name MI Last Name Suffix 750 Vumber Prefix Street or Highway Street Type Suffix Apt./Suite/Room City
Г	More people inv	Post Office Box Apt./Suite/Room City MN 55130 -
	Then che	person involved? k this box and skip of this section. Business name (if Applicable) [612] - 354 - 0807 Area Code Phone Number
i — i	Check this box if same address as incident location. Then skip the three duplicate address lines.	RICKY Mr.,Ms., Mrs. First Name MI Last Name Suffix 750 Number Prefix Street or Highway Last Name Suffix ST Street Type Suffix Post Office Box Apt./Suite/Room City
		MN 55130 - Zip Code - Zip Code
REE NO'COI ANI US. AS. SQU OF ENU LA. TH. ST. ME. AS. CH. HO'CO	TICED HER LIGHMING FROM INSI D FLAMES EMITT GINE #4 ARRIVE ED A HOSE LINE SUMED COMMAND UAD #1 PARKED THE SECOND FI GINE #4 AND US DDER #7 RAISED E LADDER TO TH AND BY SAFETY DIC #22. DIST SISTED COMMAND ECKS WERE COME URS.	DE THE KITCHEN WALL, SO SHE STRUCK THE WALL. THAT IS WHEN SHE NOTICED SMOKE ING FROM THE WALL AND CEILING. D ON SCENE, COMPLETED A WALK AROUND, AND DIRECTED IN COMING COMPANIES. THEY TO ATTACK THE FIRE IN THE KITCHEN AND ON THE SECOND FLOOR IN THE REAR. I FROM ENGINE #4 AND REQUESTED XCEL GAS AND ELECTRIC. IN THE REAR, USED A HOSE LINE TO BACK UP ENGINE #4, AND COMPLETED THE SEARCH OOR BUT DID NOT FIND ANY VICTIMS. ENGINE #17 CONNECTED A WATER SUPPLY TO ED A SECOND HOSE LINE TO PUT THE FIRE OUT IN THE ATTIC ABOVE THE KITCHEN. GROUND LADDERS AND PROVIDED LIGHTS AND FANS FOR SMOKE. THEY ALSO RAISED E ROOF TO CUT SMOKE VENTILATION HOLES IN THE ROOF. CREWS WERE DISTRICT CHIEF #2, ENGINE #8, LADDER #8, SQUAD #3, MEDIC #8, AND RICT CHIEF #2 WAS ASSIGNED DIVISION C IN THE REAR. MEDIC #22'S CREW
SA	LVAGE AND OVER	HAUL OPERATIONS WERE COMPLETED. A FIRE REVIEW WILL BE HELD LATER. R BLANK ON SCENE FOR FURTHER INVESTIGATION.
L	Authorization	
	1892 Officer in charg	JADWINSKI, STANLEY J 150 C3 02 01 2014 e ID Signature Position or rank Assignment Month Day Year
came	if X 1892	JADWINSKI, STANLEY J 150 C3 02 01 2014
as O	fficer Member making re harge.	port ID Signature Position or rank Assignment Month Day Year

Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	14-03208	DATE OF INCIDEN	IT: 01-31-2014			
TIME OF INCIDENT:	0524 Hours	POLICE CASE #: N/A				
INVESTIGATOR (s):	Blank, J					
INCIDENT ADDRESS:	750 Jessie Street, Apart	ment #2, 55130				
OCCUPANT NAME:	Claire E Coenen PHONE: 612-810-1318					
OWNER NAME:	Ricky L Baker PHONE:612-354-0807					
ADDRESS OF OWNER:	750 Jessie Street, Apartment #1,55130					
PROPERTY DAMAGED:	Up/Down Duplex AREA OF ORIGIN: East Kitchen Wall					
DAMAGE ESTIMATE:	Building \$50,000	Vehicle \$n/a	Other (Describe) \$n/a			
VALUE:	Building \$151,000 Vehicle \$n/a Other(Describe) \$n/					
Damage Estimate CONTENTS ONLY:	\$10,000					
INJURY/DEATH (if yes, explain)	No Yes					
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: Yes No Unknown Detector Functioning: Yes No Unknown Sprinkler System Present: Yes No Unknown Sprinkler Heads activated: Yes No Unknown C.O Detector Present: Yes No Unknown					
FIRE CAUSE CLASSIFICATION:	Accidental Juvenile/Incendiary Incendiary Child (under 10 years old) Natural Undetermined Under Investigation					
SYNOPSIS:	The Fire Department was called to a report of a kitchen fire. Upon arrival the fire was venting out of the second floor door on the south side of the house. Crews stretched hoselines and extinguished the fire. The occupant in the upstairs Unit #2 reports waking up when she noticed her TV was off as well as the lights in the kitchen. She then noticed sounds coming from inside the kitchen wall. After banging on the wall, smoke and then fire emitted from the wall at the ceiling level. The occupant denies any electrical problems or burning candles. Examination revealed a mostly destroyed electrical outlet attached to the wiring in the kitchen wall (area of origin). No other ignition sources in the area were present. The ignition source is a high resistance electrical connection. The first fuel ignited is the insulation on the wiring. The action that brought these items together was a loose wire connection. The classification of cause is accidental.					
DISPOSITION:	E-mail only DO NOT DEMOLISH until Analysis of Evidence I	approved Sce	d Scene until approved ne Released ort to Follow			

FIRE INVESTIGATION REPORT

INCIDENT NO: 14-03208

DATE: 01/31/2014

TIME: 0524 HOURS

ADDRESS: 750 JESSIE STREET

INSURANCE CO: AMERICAN FAMILY

DAMAGE ESTIMATE: \$60,000

SYNOPSIS: On Friday, January 31, 2014, at approximately 0524 hours, the Saint Paul Fire Department responded to a report of a kitchen fire. The location of the incident was 750 Jessie Street, Apartment #2. Upon the fire department's arrival, fire suppression personnel stretched hose lines and quickly extinguished a fire in the kitchen of the upstairs unit. The source of ignition was a high resistance electrical connection. The first fuel ignited was the insulation on the wiring. The action that brought these items together was a loose wire connection. The classification of fire cause is accidental.

PEOPLE: Property Owner/Occupant RICKY L BAKER, 750 Jessie Street, Apartment #1, 55130, 612-354-0807, DOB 09/11/1959.

Occupant, CLAIRE A COENEN, 750 Jessie Street, Apartment #2, 55130, 612-810-1318, DOB 07/14/1958.

<u>BACKGROUND</u>: I received notification of the fire via the Communications Center at approximately 0524 hours. I responded to the incident scene and arrived at approximately 0541 hours. Engine #4 was the first arriving fire department vehicle. At the time of my arrival, fire extinguishment and checking for extension were underway. At the time of the fire, the visibility outside was clear, the temperature was approximately -17 degrees Fahrenheit, and the winds were calm.

PROPERTY DESCRIPTION: The fire-damaged structure is a two and a half-story up and down duplex. The foundation is made of fieldstone. The exterior walls are covered with vinyl siding. The structure has a pitched roof with asphalt shingles. The interior walls are covered with wood paneling. The structure measures approximately 30 feet wide by 60 feet deep. The front of the structure faces west and the structure runs west to east.

EXTERIOR EXAMINATION: Visual inspection of the building's west side revealed the front door. Examination of the west and north sides of the structure found there were no signs of smoke or fire damage.

The east side of the building showed signs of soot staining that ran down the vinyl siding from the side closest to the south wall. There was no fire damage visible. The roof over the southeast corner of the structure showed signs of freshly melted snow.

Fire Investigation Report 750 Jessie Street Page Two

The electric meters were located on the east side of the building and did not appear to have suffered any damage due to the fire. The electric weatherhead and service drop appeared in good condition with no visible damage sustained.

The south side of the structure showed signs of soot damage that ran down from the outside porch stairs that led to the upstairs unit. The roof that covered the exterior staircase on the south side of the structure suffered heavy fire and smoke damage to its underside with a small amount of fire damage to the vinyl siding to the west of the porch roof. The window to the west of the second floor south side entry was broken by fire suppression personnel during suppression efforts. Two gas meters were located on the south side of the structure and were turned off by firefighters.

INTERIOR EXAMINATION: Observation of the first floor revealed no signs of smoke or fire damage. There was a small amount of water damage in the area of the kitchen as a result of firefighting operations. Both the front door on the west side of the unit and the side door on the south side of the structure did not appear damaged.

Inspection of the stairs leading to the basement showed no signs of smoke or fire damage. Examination of the water heater, washer, dryer, and furnace appeared in good condition and indicated no signs of smoke or fire damage. Examination of the fuse box for the lower unit revealed no burnt fuses. The fuse box for the upstairs unit showed a 20 AMP and 30 AMP burnt fuses. There was no labeling for the fuse panel for the upper unit. Both fuse boxes had their main fuse pulled by firefighters during suppression efforts. Neither fuse box showed signs of smoke or fire damage.

Observation of the stairs leading to the attic space showed light smoke damage and no signs of fire damage. There was a smoke detector visible lying on the staircase leading to the attic that had not sounded during the fire. The attic space showed signs of smoke and fire damage in the southeast corner. Fire suppression personnel performed overhaul in this area to remove charred blown-in insulation. The fire damage in this area appeared to come from below due to charring on the underside of the blown-in insulation and no damage to the topside of the blown-in insulation. The interior of the attic roof suffered charring in the southeast corner.

Examination of the front interior stairs leading to the second floor unit revealed no smoke or fire damage. The locks on the door at the top of the staircase appeared intact and undamaged. Investigation of the second floor front bedroom located on the west side of the unit had the door shut during the fire. There was a smoke detector located in the front bedroom that did not sound during the fire. The room suffered no smoke or fire damage. The bedroom on the north side of the unit suffered light smoke damage and no fire damage.

Fire Investigation Report 750 Jessie Street Page Three

In the living room area, which was located to the west of the kitchen, there was moderate smoke damage and no fire damage. On the east side of the second floor unit there was a bathroom that contained a large whirlpool tub. Inspection of this room revealed moderate smoke damage and no fire damage.

Investigation of the kitchen showed the most smoke and fire damage in the building. Along the north wall of the kitchen there was moderate smoke damage down to approximately the four-foot level. The gas stove appeared in good condition with no fire damage. The west wall of the kitchen revealed heavy smoke damage down to approximately the four-foot level. The refrigerator appeared in good condition with no fire damage. The south wall of the kitchen revealed heavy charring on the exit door leading to the exterior staircase from the top of the doorframe to approximately the four-foot level. The window located to the west of the south kitchen door also suffered heavy charring from the ceiling level down to approximately the four-foot level above the floor.

Examination of the east wall of the kitchen showed the heaviest fire damage in the kitchen. The kitchen wall cabinets located along the east wall had lighter fire charring to the north and increasing fire charring moving from north to the south. Located behind the kitchen cabinets, along the east wall, there was charring in a stud channel that went from the ceiling level and extended all the way to approximately six inches above the floor level. Vector patterns to the right and left of this stud channel showed that the fire originated within this wall cavity. This stud channel suffered the heaviest charring compared to the stud channels on either side.

Inspection of the stud channel revealed complete burn through towards the bottom of the stud channel. Visible through the complete burn area was PVC piping that showed burning on the side closest to the stud channel and no burning on the side away from the stud channel. Examination of the space behind the stud channel showed no fire damage to the rest of the interior space located behind the whirlpool tub space.

Investigation within the heavily charred stud space revealed metal covered Romex wiring and knob and tube wiring. Investigation to locate the plug that should have been located at approximately the two-foot level showed that the electrical outlet was missing from the stud channel. Examination of the wiring located in the stud channel revealed that a very small part of the electrical outlet box was still attached to the Romex wiring, but the rest of the electrical box was missing. Inspection of the Romex wiring showed that metal had spattered on the parts of the remaining outlet and Romex wiring.

INTERVIEWS: Property Owner/Occupant, RICKY L BAKER, stated in person on 01/31/2014:

I haven't had any electrical problems with the house.

Fire Investigation Report 750 Jessie Street Page Four

- I've owned the house for a long time.
- We had a history of a raccoon in the wall on the west side of the house last year.
- I have American Family Insurance.

Occupant, CLAIRE A COENEN, stated in person on 01/31/2014:

- My granddaughter and I were sleeping in the living room.
- I woke up when I noticed the TV wasn't on anymore.
- I noticed that the lights in the kitchen were off also.
- There was no smoke or fire visible at this time.
- I heard what I thought was a scratching noise coming from inside the east kitchen wall around the area of the countertop.
- I pounded on the wall because I thought it might be a mouse.
- Smoke came out of the wall where it meets the ceiling after I pounded on the wall.
- Then a small amount of fire came out where the smoke had been.
- I filled a pan with water and put the fire out.
- The smoke increased and then more fire came out at the ceiling level.
- I told my granddaughter to go downstairs to the neighbors to call 9-1-1 because my cell phone was out of minutes.
- I then exited the house.
- The smoke alarm in the front bedroom on the west side of the house never sounded.
- I had my front bedroom door shut to conserve heat and that's the only smoke detector up here.
- I don't have any renter's insurance.

Fire Investigation Report 750 Jessie Street Page Five

- I'm the only one who regularly lives here.
- My granddaughter stays here sometimes while she goes to college.
- The shelving that is located between the kitchen cabinets and the south door of the house had a coffee pot and cell phone sitting on it.
- The coffee pot and cell phone weren't plugged in.

PHOTOGRAPHS/SKETCH: Digital photographs were taken.

EVIDENCE: No evidence was collected.

<u>CONCLUSION</u>: After examination of the fire scene and investigation of fire patterns of both movement and intensity, it is my opinion this fire originated in the east wall of the kitchen in the upstairs unit. All other competent ignition sources have been eliminated. The source of ignition was a high resistance electrical connection. The first fuel ignited was insulation on the wiring. The action that brought these items together was a loose wire connection. The classification of cause is accidental. This investigation is considered closed.

J. Blank Fire Investigator, A Shift, 2-3-2014

JB/su