



February 24, 2025

OIG HOLDINGS LLC  
8931 FARNSWORTH AVE N  
BROOKLYN PARK MN 55443 USA

## **FIRE INSPECTION CORRECTION NOTICE**

RE: 383 TORONTO ST  
Ref. #127320

Dear Property Representative:

Your building was inspected on February 21, 2025, for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date. A re-inspection will be made **after administrative hearing on February 25, 2025.**

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

### DEFICIENCY LIST

1. Exterior - Rear entry door - SPLC 34.09 (4)(i), 34.33 (3) - Repair and maintain the door frame. **-Repair and provide the missing door frame trim.**
2. Interior - Basement - MSFC 604.5 - Discontinue use of extension cords used in lieu of permanent wiring. **-Remove the extension cords in the basement. (2)**
3. Interior - SPLC 310.02 - Post the DSI-Licensing issued license in an approved location. **-Post CO certificate. (Once approved)**

4. Interior - Basement - SPLC 34.10 (7), 34.17 (5) - Repair and maintain the walls in an approved manner. **-Repair the unfinished walls in the basement.**
5. Interior - Basement - SPLC 34.11 (6), 34.35 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Existing Fuel Burning Equipment Safety Test Report to this office. **-Remove the duct tape on the furnace flexible joints. Remove the duct tape on the vents and replace with approved materials.**
6. Interior - Basement - MSFC 604.1 - Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-8989. **-Repair or remove the wiring in the basement. South wall string.**
7. Interior - Rear stairs - SPLC 34.10 (3), 34.34(2) - Provide an approved handrail. Every required handrail and guard shall be firmly fastened and capable of supporting imposed loads and shall be maintained in a professional state of maintenance and repair and in accordance with the building code in effect at the time of construction or as altered/modified under an approved building permit. **-Provide the rear entry handrail.**
8. Interior - Throughout - MSFC 604.6 - Provide electrical cover plates to all outlets, switches and junction boxes were missing. **-Provide the missing outlet, junction box covers.**
9. Interior - Throughout - MSFC 604.6 - Provide all openings in junction boxes to be sealed. **-Any open junction boxes missing covers.**

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: [Torrance.Harriel@ci.stpaul.mn.us](mailto:Torrance.Harriel@ci.stpaul.mn.us) or call me at 651-266-8941 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,  
Torrance Harriel  
Fire Safety Inspector  
Reference Number 127320