

## **Investigation Report**

### Case

SPFD210724031281	Johnson, Randall	Closed	N/A
Case Number	Lead Investigator	Status	Name
Confidential	Undetermined		Electrical System
Confidentiality	Disposition		Fire Cause
07/24/2021	21:35		
Start Date	Start Time	End Date	End Time
Saint Paul Fire Department			Saint Paul Police Department
Primary Fire Department	Secondary Fire	Department	Law Enforcement
se Narrative  The fire department was cal smoke showing from multip overhaul. Command was ter  Case Background	le sides. Firefighters evacua	ited the structure, e	ng. Firefighters arrived and found light extinguished the fire and conducted

# Fire

Electrical System	Closet				
Fire Cause	Area of Origin	Equipment Power Source	Equipment Portability		
Area of Origin Commen	ts				
Electrical arcing		Sawn wood, including a	Sawn wood, including all finished lumber		
Heat Source		Material Ignited	Material Ignited		
Equipment Involved In Ignition	Equipment Make	Equipment Model	Equipment Serial Number		
e and Smoke Spread	Information				
Confined to building of o	origin				
Fire Spread Material		Fire Spread Avenue			
Smoke Spread Material		Smoke Spread Avenue			
Fire Comments					
eather					
	П	H	П		
		5	W		
Visibility	Relative Humidity (%)	) Wind Speed (Mph)	Wind Direction		
78.0	0	No			
Temperature (Fahrenhe	it) Precipitation	Lightning	Information Obtained From Weather		
•	es.				

Property Details (1 of 1)

Property			
N/A			
Name			
1079 Arkwright Street			
Address		Apt/Suite/Roon	n
Saint Paul	Ramsey County	Minnesota	55130
City	County	State	Postal Code
\$194,400.00	\$20,000.00	\$50,000.00	
Pre Fire Value	Content Loss Value	Structure Loss	s Value
Property Description			
Area			
Structure	Urban		
Area Type	Area Description	Area Quality	

Multifamily dwelling		Occupied	
operty Use St		Structure Occupancy	
	Yes		Operating Properly
Alarm Type	Smoke Detector Pr	esent	Smoke Detector Performance
None			
Sprinkler Standpipes		Sprinkler Standpi	pes Performance
72	31	3	
Structure Length (Ft) Stru	cture Height (Ft) Structure W	Vidth (Ft) Numb	er Of Stories Number Of Un
Wood Frame	Type III		
Construction Type	Structure Type		Structure Material
Basement	Brick/Stone	Flat	Other
The heaviest damage appea room. A "V" pattern was visi extending up from the close Breakers were found to be t	red to be located on the lowest ( ble along side the closet with uni et allowed heat/smoke/ fire to tra cripped in multiple areas, includin	iform heavy char or avel to second and t ag the determined a	area of origin. No accelerants were
room. A "V" pattern was visi extending up from the close Breakers were found to be t found with the aid of monito issue.  nterior Exam	red to be located on the lowest ( ble along side the closet with uni et allowed heat/smoke/ fire to tra ripped in multiple areas, includin	(garden) level in a u iform heavy char or avel to second and t ng the determined a f other causes in tha	tility closet adjacent to the laundr n all sides of the closet. A pipe cha third floors. area of origin. No accelerants were at area leads to probable electrica
The heaviest damage appea room. A "V" pattern was visi extending up from the close Breakers were found to be to found with the aid of monitorissue.  nterior Exam  Brick exterior. Crews reporte	red to be located on the lowest (ble along side the closet with uniet allowed heat/smoke/ fire to traction from the process of elimination of ed smoke coming from rear door	(garden) level in a u iform heavy char or avel to second and t ng the determined a f other causes in tha	tility closet adjacent to the laundr n all sides of the closet. A pipe cha third floors. area of origin. No accelerants were at area leads to probable electrica
The heaviest damage appea room. A "V" pattern was visi extending up from the close Breakers were found to be t found with the aid of monitorissue.  Interior Exam  Brick exterior. Crews reporte	red to be located on the lowest (ble along side the closet with uniet allowed heat/smoke/ fire to traction from the process of elimination of ed smoke coming from rear door	(garden) level in a u iform heavy char or avel to second and t ng the determined a f other causes in tha	tility closet adjacent to the laundr n all sides of the closet. A pipe cha third floors. area of origin. No accelerants were at area leads to probable electrica
The heaviest damage appearoom. A "V" pattern was visi extending up from the close Breakers were found to be to found with the aid of monitorissue.  Interior Exam  Brick exterior. Crews reported Exterior Exam  Exterior Exam  Arm and Security Service None	red to be located on the lowest (ble along side the closet with unit allowed heat/smoke/ fire to tractification of the process of elimination of the smoke coming from rear doors.  Yes	(garden) level in a u iform heavy char or avel to second and t ng the determined a f other causes in tha	tility closet adjacent to the laundr n all sides of the closet. A pipe cha chird floors. area of origin. No accelerants were at area leads to probable electrica arlie Side).
The heaviest damage appearoom. A "V" pattern was visi extending up from the close Breakers were found to be to found with the aid of monitorissue.  Interior Exam  Brick exterior. Crews reported Exterior Exam	red to be located on the lowest (ble along side the closet with unit allowed heat/smoke/ fire to tractification of the process of elimination of the smoke coming from rear doors.  Yes	(garden) level in a u iform heavy char or avel to second and t ing the determined a f other causes in tha	tility closet adjacent to the laundr n all sides of the closet. A pipe cha chird floors. area of origin. No accelerants were at area leads to probable electrica arlie Side).

#### **Conclusion**

_	_		
Case	( On	clu	SION

After examination of the fire scene, observation of fire patterns of both movement and intensity and interviews conducted, it is my opinion the fire began in an unfinished utility closet located in the lower level. The first fuel/material ignited was most likely wood. The ignition source was most likely electrical. The oxidant was normal atmospheric air. The action that brought these items together was undetermined. The classification of fire cause is accidental. This concludes my investigation and report.

Note: No excessive amount of volatile organic compounds (accelerants) were found.

Signature			
Johnson, Randall			
Lead Investigator	Signature	Date Submitted	

#### **Document Attachment List**

Photo Log