



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-9124
Web: www.stpaul.gov/dsi

Code Compliance Report

January 13, 2011

PREMIERE ASSET SERVICES C/O ANGELA LARSON
3585 LEXINGTON AVE N
ARDEN HILLS MN 55117

Re: 1028 Loeb St
File#: 08 057075 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on January 06, 2011.

Please be advised that this report is accurate and correct as of the date January 13, 2011. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from January 13, 2011. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING **Inspector: Jim Seeger** **Phone: 651-266-9046**

- Insure basement cellar floor is even, is cleanable, and all holes are filled.
- Install plinth blocks as needed under posts in basement & ensure adequate footing for load imposed.
- Tuck Point interior/exterior of foundation as necessary.
- Permanently secure top and bottom of support posts in an approved manner.
- Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Strap or support top of stair stringers for structural stability.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Install floor covering in bathroom and kitchen that is impervious to water.

Re: 1028 Loeb St
January 13, 2011
Page 2

BUILDING **Inspector: Jim Seeger** **Phone: 651-266-9046**

- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Any framing members that required repair or do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner.
- Re-level structure as much as is practical.
- Provide fire block construction as necessary and seal chases in basement ceiling.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Install flashing in an approved manner at the intersection of the roof with walls, chimneys, and other conjoined surfaces.
- Provide general rehabilitation of garage.
- Install address numbers visible from street and on the alley side of garage.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Openings in stair risers must be less than 4 inches.
- Front porch ceiling not framed diagonally to support load imposed and foundation has sagged in center, correct framing and foundation to meet code.
- Properly support all loads imposed in basement and install floor joist where cut off or missing. Also install post and beams where needed to meet code.
- Repair all foundation walls and repair basement wall covering.
- Install proper joist hanger nails in joist hanger.
- Insulate vent second floor ceiling to meet code. All framing and insulation to be inspected before covering.
- Install tempered glass in window in south stair wall.
- Install framing for ceiling on second floor sized to meet code.
- Install new ledger board to carry floor joist at center wall on first floor to carry floor joist by chimney.
- Rebuild rear deck to meet code and install joist hanger nails as needed.
- Bolt deck ledger board to house.
- Rebuild chimney to meet code or remove.
- Remove lean to from west side of garage or insure lean to be built to code and has clearance from tree.
- A building permit is required to correct the above deficiencies.

Re: 1028 Loeb St
January 13, 2011
Page 3

ELECTRICAL **Inspector: Dan Moynihan** **Phone: 651-266-9036**

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits no panel cover
- Verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Verify that fuse/circuit breaker amperage matches wire size
- Close openings in service panel/junction box with knock out seals, breaker blanks and/or junction boxes
- Properly strap cables and conduits in basement
- Provide one (1) light for each 200 square feet in unfinished basement. One light must be switched on from the top of the stairs
- Remove all cord wiring
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Install hard-wired, battery backup smoke detector per bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Install exterior lights at front entry doors
- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage no access.
- All walls on first and second floor are open except exterior walls in kitchen behind cabinets, and front second floor wall.
- Raise service mast so service conductors are at least 10 feet above deck.
- Purchase permit for service and all circuits in panel.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the 2008 NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING **Inspector: Denny Watters** **Phone: 651-266-9051**

- Basement - Water Heater and Water Meter are missing
- Basement - Water Heater - T and P relief discharge piping incorrect (MPC 2210 Subp. 4)
- Basement - Water Heater - T and P valve Required (MPC 2210 Subp. 2)
- Basement - Water Heater - Vent must be in chimney liner (IFGC 501.12)

Re: 1028 Loeb St
January 13, 2011
Page 4

PLUMBING **Inspector: Denny Watters** **Phone: 651-266-9051**

- Basement - Water Heater - Water piping incorrect (MPC 1730 Subp. 1)
- Basement - Water Heater - not fired or in service (MPC 2180)
- Basement - Water Meter - meter is removed or not in service (MPC 4715.1700)
- Basement - Water Meter - service valves not functional or correct (MPC 1800 Subp 3,4)
- Basement - Water Meter - support meter properly (MPC 2280)
- Basement - Water Piping - add appropriate hangers (MPC 1430 Subp. 4)
- Basement - Water Piping - pipe sizing incorrect (MPC 4715.1730)
- Basement - Water Piping - provide water piping to all fixtures and appliances (MPC 1700)
- Basement - Water Piping - repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement - Water Piping - run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement - Gas Piping - add appropriate metal hangers (IFGC 407.2)
- Basement - Gas Piping - bond the CSST to code (IFGC 310.1)
- Basement - Soil and Waste Piping - add appropriate hangers (MPC 1430 Subp. 4)
- Basement - Soil and Waste Piping - improper connections, transitions, fittings or pipe usage (MPC 2420)
- Basement - Soil and Waste Piping - no front sewer clean out (MPC 1000)
- Basement - Soil and Waste Piping - unplugged or open piping; back pitched piping (MPC 1000)
- First Floor - Lavatory - faucet is missing (MPC 0200.P.)
- First Floor - Lavatory - fixture is missing (MPC 0200 0.)
- First Floor - Lavatory - unvented (MPC 0200. E)
- First Floor - Lavatory - waste incorrect (MPC 2300)
- First Floor - Sink - unvented (MPC 0200. E)
- First Floor - Sink - waste incorrect (MPC 2300)
- First Floor - Toilet Facilities - unvented (MPC 0200. E)
- First Floor - Toilet Facilities - waste incorrect (MPC 2300)
- First Floor - Tub and Shower - provide anti-scald valve (MPC 1380. Subp. 5)
- First Floor - Tub and Shower - replace waste and overflow (MPC 1240)
- First Floor - Tub and Shower - unvented (MPC 0200. E)
- First Floor - Tub and Shower - waste incorrect (MPC 2300)
- Second Floor - Lavatory - faucet is missing (MPC 0200.P.)
- Second Floor - Lavatory - fixture is missing (MPC 0200 0.)
- Second Floor - Toilet Facilities - fixture is missing (MPC 0200 0.)
- Second Floor - Toilet Facilities - incorrectly vented (MPC 2500)
- Second Floor - Toilet Facilities - waste incorrect (MPC 2300)
- Second Floor - Toilet Facilities - water piping incorrect (MPC 0200 P.)
- Second Floor - Tub and Shower - faucet is missing (MPC 0200. P.)
- Second Floor - Tub and Shower - fixture is missing (MPC 0200 0.)

Re: 1028 Loeb St
January 13, 2011
Page 5

PLUMBING **Inspector: Denny Watters** **Phone: 651-266-9051**

- Second Floor - Tub and Shower - provide anti-scald valve (MPC 1380. Subp. 5)
- Second Floor - Tub and Shower - unvented (MPC 0200. E)
- Second Floor - Tub and Shower - waste incorrect (MPC 2300)
- Second Floor - Tub and Shower - water piping incorrect (MPC 0200 P.)
- Exterior - Lawn Hydrants - Requires backflow assembly or device (MPC 2000)
- Obtain plumbing permits prior to commencement of work.

HEATING **Inspector: Kevin Chapdelaine** **Phone: 651-266-9042**

1. Install heating and all mechanical systems to code.
2. Appropriate mechanical permits are required for the above work.

ZONING

1. This property is in a (n) R4 zoning district.
2. This property was inspected as a Single Family Dwelling.

Notes:

- See attachment for permit requirements and appeals procedure.
- Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.
- There was considerable storage/clutter within property at the time of the inspection. Property is to meet appropriate Codes when complete.
- Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.) If you have any questions regarding this inspection report, please contact Joe Ehrlich between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger, Code Compliance Officer
Phone: 651-266-9046 Email: james.seeger@ci.stpaul.mn.us

JLS:ml

Attachments