

PRE BRIDGE	Flinis dylezerioti i aktor zeo ezo
B2210 MN 10 09 2016 0	Dasic
B Location Type  X Street address Intersection In front of Rear of Adjacent to Directions US National Grid  Check this box to indicate that the address for this in Modifie in Section B, "Atternative Location Specifics  Modified in Section B, "Atternative Location B, "Atternative Location B, "Atternative Location B, "Atternative	
C Incident Type    111	Arrival Arrival Last Unit Cleared  Last Unit Cleared    Factor   F
F Actions Taken    11   Extinguishment by fire service personnel   Primary Action Taken (1)   12   Salvage & overhaul   Accidenal Action Taken (2)   51   Ventillate   Accidenal Action Taken (3)	G1 Resources  X Check this box and test this block and test this b
Completed Modules  X Fire-2  X Structure Fire-3 Civilian Fire Cas4 Fire Service Cas5 EMS-6 HazMai-7 Widtland Fire-8  X Apparatus-9 X Personnel-10 Arson-11  H1 Casualties  Death Injury Fire 0 0 0 Civilian 0 1 0 Fire Service Civilian 0 1 0  Received for confreed fires. 1 Defector 2 Detector did not alert occupant unknown	None H3 Hazardous Materiats Release   Mixed Use Property  0 Special HazMat actions required ur spill >= 55 gal.   00 Mixed use, other  1 Natural gas: slow leak, no evac, or HazMat actions   10 Assembly use   2 Propane gas - Less then a 21 lb. tank   20 Educational use   3 Gasoline - vehicle fuel tank or portable container   33 Medical use   4 Kerosene - fuel-burning equipment/portable storage   40 Residential use   5 Diasol fuel/fuel oil - vehicle fuel tank/portable   51 Row of stores   6 Household/office solvent or chemical spill   53 Enclosed mail   7 Motor oil - from engine or portable conteiner   58 Business and residential use   8 Paint - spills less than 55 gallions   69 Office use   10 Industrial use   60 Industrial use   11 Mixed Use Property   60 Industrial use   60 Industrial use   12 Mixed Use   61 Farm use   62 Farm use   63 Not mixed use   64 Industrial use   65 Farm use   65 Farm use   65 Farm use   66 Industrial use   66 Industrial use   66 Industrial use   66 Industrial use   67 Industrial use   66 Industrial use   67 Industrial use   67 Industrial use   68 Industrial use   69 Industrial use

	82210 MN 10 09 2018 07  FDIO Slate Incident Gate Station	SPFD161	161009034770 0 F	RS-2 ire
В	Property Details C	On-Site Ma or Products	icts property, whether or not they became involved	
B1 B2	1 Not Residential  Estimate number of residential ifring units in  subdang of origin whether or not all units  became involved  On	nter up to three c	ee codes, Check one box for each code entered.  On-Site Materials Storage Use 1 Butk storage or warehousing 2 Processing or manufacturing 3 Packaged goods for safe 4 Repair or service N None U Undetermined	
Вз	Less than one acre	o-são material (2)	3 Packaged goods for sale 4 Repair or service N None U Undetermined	
	Or and a second	m-site material (3)	1 Bulk storage or warehousing 2 Processing or manufacturing 3 Packaged goods for sale 4 Repair or service N None U Undetermined	
D	Ignition    03     Interior stairway or ramp	F	E1 Cause of Ignition  Check this box if this is an exposure report  Check this box if this is an exposure report  Check this box if this is an exposure report  Check this box if this is an exposure report	
D <sub>2</sub>	Area of file origin    60	1	Cause, other (System generated code only, not used for data entry)  1	ıř
D4	20   Flammable or combustible   liquid, other		Factor contributing to ignition (2) 1 Male 2 Female	
L	Equipment Involved in Ignition  If equipment was not involved, skip to Section G  Interpret Involved In Ignition  If equipment was not involved, skip to Section G  Equipment Power Source  1 Portable 1 Portable 2 Station Portable equipment not be used in multiplet.	ote nary	G Fire Suppression Factors  None  Enfer up to three codes.  Fire suppression factor (1)  Fire suppression factor (2)  Fire suppression factor (3)	
L	Mobile Property Involved  Not involved in ignition, but burned Involved in ignition, but did not itself burn Involved in ignition and burned  Mobile property make  Mobile property make	Property Tyl	Type and Make    Local Use   Pre-Fire Plan Available   Some of the Information presented in this report may be based upon reports from other agendes: Arson report attached   Police report attached   Coroner report attached   Other reports attache	

•

<u> </u>	07 SPFD161009034770 0	NFIRS-3 Structure Fire
It structure Type If fre was han enclosed beliefing or a portablemble structure, complete the rest of this form.  Structure Type, other  1 X Enclosed building 2 Fixed portable or mobile structure 3 Open structure 4 Alr-supported structure 5 Tent 6 Open platform 7 Underground structure work area 70 Testing 8 Connective structure  J1 Structure  J3 Building State 0 Building status 1 Under construction to normal use 1 Under construction to normal use 2 the normal use 3 tide, not routing 4 Under major of the vacant and use 6 Vacant and use 7 Underground structure work area 7 Underground structure  J3 Number	s, other colion  I Total number of stories at or above grade onovation accured  Total number of stories at or above grade one or accurate of stories at or above grade one or accurate of stories below grade on account of stories account on account of stories at or above grade on account of stories account of stories account on account of stories account on account of stories account of stories account on acc	4 Main Floor Size
J2 Fire Spread  If the spread was confined to object of origin, do not theck a box (pet. Block 12), five Module).  Confined to object of origin  Confined to floor of origin  Confined to floor of origin  Confined to building of origin  Beyond building of origin	Number of Mories wisiguificant damag (25 to 49% flams damage)  Number of doties wisheavy damag (50 to 74% flams damage)  Number of doties westerned damage (75 to 1001% flams damage)	K1
L1 Presence of Detectors  1 X Present N None present U Undetermined L2 Detector Type Detector type, other Smoke Heat Combination smoke and heat in a single unit Sprinkler, water flow detection More then one type present U X Undetermined	L3 Detector Power Supply  0 Detector power supply, other  1 Battery only  2 Herdwire only  3 Plug-in  4 Hardwire with battery backup  5 Plug-in with battery backup  6 Mechanical  7 Multiple detectors and power supplies  U X Undetermined  L4 Detector Operation  1 Fire too small to activate detector  2 Detector failed to operate  U Undetermined  Undetermined	L6 Detector Effectiveness Required idelector operation Detector alerted occupants, occupants responded Detector alerted occupants, occupants failed to respond There were no occupants Detector failed to alert occupants Undetermined L6 Detector Failure Reason Required if director failed to perate Detector failure reason, other Power failure, hardwired det. shut off, disconnect Improper instellation or placement of detector Defective detector Lack of meintenance, includes not cleaning Battery missing or disconnected Battery discharged or dead U X Undetermined
M1 Presence of Automatic Extinguishing System  1 Present 2 Partial System Present N X None Present U Undetermined  M2 Type of Automatic Extinguishing System Required if fer year with designed range of AES Spacial hazard system, other 1 Wet-pipe sprinkler system 2 Dry-pipe sprinkler system 3 Other sprinkler system 4 Dry chemical system 5 Foam system 6 Halogen-type system 7 Carbon dioxide system U Undetermined	M3 Operation of Automatic Extinguishing System Required five was wished designed range Operation of AES, other  1 System operated and was effective System operated and was not effective System operated and was not effective Undetermined  M3 Number of Sprinkler Heads Operating Required if system operated    M3 Number of sprinkler heads operating	M5 Reason for Automatic Extinguishing System Failure Reason system not effective, other  Reason system not effective, other  System shut off  Not enough agent discharged to control the fire  Agent discharged, but did not reach the fire  Inappropriete system for the type of fire  Fire not in area protected by the system  System components damaged  Lack of maintenance, including corrosion or heads painted  Manual intervention defeated the system  Undetermined

...

J Property Use Structures  419 × 1 or 2 family dwelling 311 24-hour care Nursing homes, 4 or more persons  241 Adult education center, college classroom  182 Barror nightclub  184 Barracks, dormitory  189 Boarding/rooming house, residential hotefs  189 Business office  131 Church, mosque, synagogue, temple, chapel	341 Clinic, dinic-type infirmary 342 Doctor, dentilist or otal surgeon office 615 Electric-generating plant 213 Elementary school, Including kindergarten 519 Food and beverage seles, grocery store 215 High school/junior high school/middle school 331 Hospital - medical or psychiatric 449 Hotel/motel, commercial 539 Household goods, sales, repairs 361 Jall, prison (not juvenile)	Laboratory or science laboratory Livestock, poultry storage Manufacturing, processing Meter vehicle or boat sales, services, repair Multifamily diveiling Parking garage, general vehicle Residential board and care Restaurant or cafeteria Service station, gas station Warehouse
Outside 981 Construction site 655 Crops or orchard 919 Dump, sanitary landfill 669 Forest, timberland, woodland 938 Graded and cared-for plots of land 961 Highway or divided highway	984 Industrial plant yard - area 948 Lake, river, stream 931 Open land or field 807 Outside material storage area 124 Playground 951 Railroad right-of-way 962 Residential street, road or resklantial driveway	950 Street, other 936 Vacant tot  Look up and enter a Property Use 419 Code than the code and the code and the code than the code that the code than the code that the code that the code that the code that the cod
K1 Person/Entity Involved  Local Option  Check this box if same address as incident in the control of the contr	Business Hame (if Applicable)  Mr., Ms., Ms., Ms., First Name  Number Prefix Street or Highway  Post Office Box Apt / Sute/Room City  State Zip Gods	Area Code Phone Number  Last Name  Suffix  Sizet Type  Suffix
K2 Owner  Same as preson involved? Then check this box and skip the rest of this block, to-cal Option Check this box if same andress as incident Location (Section I). The check this box if same andress as incident Location (Section I). The check this box if same andress as incident Location (Section I). The check this box and skip the rest of this block, the check this box and skip the rest of this block, the check this box and skip the rest of this block, the check this box and skip the rest of this block, the check this box and skip the rest of this block, the check this box and skip the rest of this block, the check this box and skip the rest of this block, the check this box and skip the rest of this block, the check this box and skip the rest of this block, the check this box if same and the check this box and skip the rest of this block, the check this box if same and the check this box and skip the rest of this block, the check this box if same and the check this box is the check this block this box is the check this bo	Business Name (if AppRoable)    MARJORIE   E	Area Code Phone Number  KISCH Lest Horne  Lest Horne  Area Code Phone Number  Phone Number  Phone Number  Suffix  NW  Street Type Swiffx
M Authorization    7225	DC	2016   Year 2016   Year
L Remarks	•	

ENGINE #17'S CREW WAS INITIALLY SENT ALONE FOR SMOKE IN THE AREA, ENGINE #17'S CREW FOUND A DWELLING FIRE AT 812 WELLS AND CALLED FOR A FULL ASSIGNMENT OF FIRE COMPANIES TO RESPOND.

ENGINE #17'S CREW PULLED A PRE-CONNECTTED HOSE LINE. SQUAD #1'S CREW PULLED A BACK-UP HOSE LINE. ENGINE #4'S CREW SECURED A WATER SUPPLY. LADDER #7'S CREW WAS ASSIGNED PRIMARY SEARCH RESPONSIBILITIES, ENGINE #7'S CREW WAS INITALLY RI.T. I ASSUMED COMMAND AND DISTRICT CHIEF #1 ASSUMED SAFETY COMMAND. LADDER #22'S CREW TOOK OVER FOR ENGINE #7'S CREW AS R.I.T. BECAUSE ENGINE #7'S CREW WAS REASSIGNED, SQUAD #2'S CREW WAS TASKED TO SECOND FLOOR EXTENSION. MEDIC #22'S CREW AND ENGINE #9'S CREW REMAINED STAGED FOR THE

THE MAIN BODY OF THE FIRE WAS QUICKLY EXTINGUISHED WITH EXTENSIVE OVERHAUL NEEDED TO FULLY EXTINGUISH THE FIRE. PRIMARY AND SECONDARY SEARCHES WERE DONE ON ALL FLOORS WITH AN ALL CLEAR FOUND, UTILITIES SECURED AND BOARD-UP CALLED. THIS WAS A VACANT HOME. NO INJURIES REPORTED. FIRE INVESTIGATOR BLANK ON SCENE FOR ORIGIN AND CAUSE INVESTIGATION.

## Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	16-34770	DATE OF INCIDEN	T: 10-09-2016		
TIME OF INCIDENT:	0038 Hours	POLICE CASE #:	16-207-131		
INVESTIGATOR(s):	J. Blank				
INCIDENT ADDRESS:	612 Wells Street, Saint Paul, MN 55130				
OCCUPANT NAME:	Unoccupied	PHONE:n/a			
OWNER NAME:	Marjorie E. Kisch	PHONE: 763-755-1542			
ADDRESS OF OWNER:	510 115th Ave Northwest, Coon Rapids, MN 55448				
PROPERTY DAMAGED:	Single Family Dwelling	AREA OF ORIGIN:	Basement Staircase		
DAMAGE ESTIMATE:	Building \$68,800	Vehicle \$	Other (Describe) \$		
VALUE:	Building \$68,800	Vehicle \$	Other (Describe) \$		
Damage Estimate CONTENTS ONLY:	\$0				
INJURY/DEATH (if yes, explain)	No Yes				
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present:				
FIRE CAUSE CLASSIFICATION:	Accidental Juvenile/Incendiary Incendiary Child (under 10 years old) Natural Undetermined Under Investigation				
SYMOPSIS:	The Fire Department was called to a report of a smoke odor and smoke in the area. Firefighters discovered smoke coming from the roof of a vacant dwelling and balanced the assignment. Firefighters found fire on the first floor, basement stairs, and the stairs leading to the second floor burned out. The basement door was found unlocked. The were no witnesses to interview. The ignition source was probably an open flamed device. The first fuel ignited was possibly an ignitible liquid. The action that brought these items together was an intentional human act. The classification of fire cause is incendiary.				
DISPOSITION:	E-mail only DO NOT DEMOLISH until Analysis of Evidence	. approved 🔯 Sc	ld Scene until approved ene Released port to Follow		

## FIRE INVESTIGATION REPORT

INCIDENT NO: 16-34770 DATE: 10/09/2016 TIME: 0038 HOURS

ADDRESS: 612 WELLS STREET INSURANCE CO: UNKNOWN

DAMAGE ESTIMATE: \$68,800 CN#: 16-207-131

SYNOPSIS: On Sunday, October 9, 2016, at approximately 0038 hours, the Saint Paul Fire Department responded to a report of smoke in the area. Firefighters arrived and found smoke coming from the eaves of a dwelling and called for additional resources for a dwelling fire. The location of the incident was 612 Wells Street. Upon the arrival of the fire department, firefighters stretched hand-lines and extinguished the fire. Upon my arrival, fire extinguishment and search and rescue were underway. The origin the fire appeared to be on the basement staircase leading to the first floor kitchen. The classification of fire cause is incendiary.

PEOPLE: Property Owner, MARJORIE E. KISCH, 510 115th Avenue Northwest, Coon Rapids, MN 55448, 763-755-1542.

Witness/9-1-1 Caller,

BACKGROUND: I received notification of the fire via the Communications Center at approximately 0048 hours. I responded to the incident scene and arrived at approximately 0053 hours. Engine #17 was the first arriving fire department vehicle. At the time of my arrival, fire extinguishment and search and rescue were underway. At the time of the fire, the visibility was clear, the temperature was approximately 39° F, and the winds were calm.

**PROPERTY DESCRIPTION:** The fire damaged structure is a 1 1/2 story single-family dwelling. The foundation is sand stone. The exterior walls are covered with asbestos siding. The structure has a pitched roof covered with asphalt shingles. The interior walls were covered with plaster and lath. The structure measures approximately 20 feet wide by 50 feet deep. The structure faces north and the structure runs north to south.

**EXTERIOR EXAMINATION:** Visual examination of the north side of structure revealed heavy smoke venting from the front door which was determined to be opened by firefighters.

Observations of the east side of the structure revealed smoke venting from the roofline from the second floor extending all the way to the rear the structure. The gas meter was on the east side of the structure and was found in the open position and turned off by firefighters. The gas meter appeared in good condition and showed no signs of smoke or fire damage.

Inspection of the south side of structure showed heavy smoke venting from a first floor and a second floor window. The electric meter was located on the south side of the structure and appeared in good condition with no signs of smoke or fire damage. The conduit that ran from the

Fire Investigation Report 612 Wells Street Page Two

electric meter upwards towards the weather-head appeared in good condition with no signs of smoke or fire damage. There was a wooden Bilco type door built over a descending staircase that led to the basement door. The basement door knob appeared to have damage to it before I witnessed a firefighter kick in the door without first checking to see if the door was locked.

Examination of the west side of the structure revealed heavy smoke venting from the rear porch door. This door was forced open by firefighters during fire suppression efforts. Fire was visible on the west side of the structure along the lower roofline towards the rear. Later in the fire event there was fire visible along the roofline where the second floor wall met the lower roofline peak. Observations of the upper roofline revealed heavy smoke pushing from the eaves.

**INTERIOR EXAMINATION:** I made my initial entry into the structure through the front door which was located on the north side of the structure. Inspection of the door lock revealed that the door was found in the locked position and it was determined through questioning that firefighters had kicked in the door to gain access. Located to the south, beyond the front foyer, was a room that led towards the kitchen at the back of the house. Fire damage was visible on the south wall of this room indicating the fire had vented from the kitchen into this room. There was no furniture in this room however there were signs of some remodeling work being done.

A front room located to the east of the front door was empty with the exception of beer cans strewn about on the floor. Also located on the floor were paint rollers and other items indicative of some remodel work. There was no furniture in this room. This room suffered no fire damage but did suffer extensive smoke damage from the ceiling level down to the floor level.

Inspection of the kitchen which was located on the first floor in the southwest corner of the structure revealed heavy fire damage. The door along the west wall of the kitchen was found in the closed and locked position by first responding firefighters. The door was forced open by firefighters to gain access to the kitchen fire. Observations of the ceiling beams revealed heavier fire damage located on the north end of the room as compared to the south end of the room.

Examining the lower portions of the kitchen cabinets located on the west side of the room revealed minor heat damage and the lower portions of the walls on the east side of the room showed heavy fire damage. Inspection of the stove indicated that although it suffered fire damage to the very upper portion of the stove that was in line with a heat layer, the lower portion of the stove and the burners all suffered uniform damage that was inconsistent with the origin of the fire. All of the knobs on the stove were found in the off position and the plastic knobs were still intact.

Observations of the refrigerator, which was located closer to the north end of the room, found that it had suffered heavy fire damage on its north side as compared to its south.

Fire Investigation Report 612 Wells Street Page Three

A staircase that went to the second floor was located on the east side of the kitchen. The staircase suffered heavy fire damage consistent with a layer of hot gas and flame impinging upon the open staircase opening. At the level of the hot gas layer, the stairs were burned out leading towards the second floor.

A doorway which was located along the east wall, closest to the north, led to a staircase which accessed the basement. This basement staircase ran from north to south along the east wall of the structure. The area in and around the doorway, leading to the staircase, suffered heavy fire damage. There was an area of inconsistent fire damage that was well below the floor level at the top of the staircase where hot gases and flames would have exited the kitchen door and risen up towards the second floor. This area of inconsistent fire damage extended down the staircase to approximately the third step above the basement floor below. There were also irregular burn patterns on the risers between the stair treads that was localized in the middle of the riser. Located towards the area where the stairs have a turn and start to head towards the west there was a metal can that was collected as evidence. In the area of the irregular fire damage on the stair risers there was no fire damage to the walls or other areas of the stair risers.

Access to the second floor was gained through an exterior ground ladder located on the west side of the structure due to the staircase being burned out from the fire. Inspection of the second floor revealed no fire damage but extensive smoke damage from the ceiling level all the way to the floor. The second floor was void of any furniture. The staircase that led to the second floor was located along the east wall of the structure, closest to the south end, and was burned out approximately two steps down from the second floor landing. Firefighters performed extensive overhaul in the ceiling and void space on the second floor to check for hidden fire that had traveled within the walls from the floor below.

Observations of the basement were made through the rear access Bilco door. Inspection of the door leading to the interior of the basement showed signs of forced entry on its exterior that appeared to be in addition to the door being kicked in by a firefighter. Examination of the door handle lock appeared to show that the door was in the unlocked position when it was kicked in. The door handle turned freely and the thumb lock button was in the unlocked position and when the thumb lock button was turned the handle would not rotate.

The stairs that led from the basement level towards the first floor level along the east wall of the basement closest to the south wall of the structure contained a large amount of fire debris. Smoke damage was visible along the basement wall extending from the floor above down to approximately six feet above the basement floor. Inspection of the basement stairs showed signs of fire damage along the handrail and wall that extended approximately two feet below the ceiling level of the basement.

Fire Investigation Report 612 Wells Street Page Four

After removing debris from the staircase there were signs of fire damage that continued down the stair treads approximately six feet below the ceiling with no corresponding damage to the wall or railing. Located in this area of fire damage was a container similar in shape to a metal bottle of charcoal lighter fluid. A photoionization detector determined that the container had contained a possible ignitable liquid and this container was gathered as evidence for testing at a lab.

Inspection of the rest of the basement showed no signs of fire damage and light to moderate smoke damage throughout. Observations of the water heater and furnace showed no signs of smoke or fire damage. Inspection of the clothes washer and dryer showed no signs of smoke or fire damage and appeared in good condition. Inspection of the electric panel showed no signs of smoke or fire damage on the exterior or interior of the panel. Observations of the wires leading to the electric panel from above showed no signs of smoke or fire damage or arcing. Numerous circuit breakers showed signs that they had tripped. The following circuit breakers had tripped: One, three, five, six, seven, nine, 10, 11, and 14. The main panel breaker switch was turned off by firefighters during fire suppression efforts. Not all of the breakers located in the panel were labeled on the door, but most of them referred to kitchen lighting and first floor outlets and second floor lighting.

**INTERVIEWS:** No interviews were conducted due the fact there was no one on scene to interview.

PHOTOGRAPHS/SKETCH: Digital photographs were taken.

**EVIDENCE:** The following piece of evidence was collected and packaged at the scene. This item was then transported back to the Saint Paul Fire Department headquarters building and placed inside the Fire Investigation's locked evidence locker. Saint Paul Police Sergeant CANDICE JONES was then notified of the evidence collected.

Item #1 - Square shaped and burned metal can recovered from the basement stairs

**CONCLUSION:** After examination of the fire scene and fire patterns of both movement and intensity observed my conclusion is this fire originated on the basement stairs. The ignition source was probably an open flamed device. The first fuel ignited was probably an ignitable liquid. The action that brought these items together was due to an intentional human act. The classification of fire cause is incendiary. This report will be forwarded to the Saint Paul Police Department. This concludes my investigation and report.

J. Blank, Fire Investigator, A Shift, 10/24/2016

JB/su