

### **NFIRS-1 Basic**

			• '	II IK3- I	Dusic		
A 62210 FDID	MN State	01 Month	11 Day	2025 Year	Station #8 (08) Station	SPFD250111001 Number	0 Exposure
B Location Type  Street Address Intersection							Census tract: 0305.00
In Front Of Rear Of Adjacent To Directions US National Grid	80 Number	Prefix	COTTA Street o	GE or Highway		AVE-A	Type Suffix
	Apt./Suite/		Saint Pa City	ul		State	Zip Code
C Incident Type  111-Building fire  D				Alarm Arrival Controlled Last Unit	01 11 2025		E2 Shifts and Alarms  C 1 D2  Shift Alarms District or Platoon
Aid Given Or Received  1 Mutual Aid Received 2 Auto. Aid Received 3 Mutual Aid Given 4 Auto. Aid Given 5 Other Aid Giver None	eived ved en	FDID Incident Num	Their State	Cleared		J	E3 Special Studies  9244 3 - No, COVID 19 was not a factor  ID# Value

F Actions Taken  11-Extinguishment by fire services Primary Action Taken	service personnel	Suppression EMS Other	ersonnel Module is used.  Apparatus Personnel  13 0  2 0  1 0  s include aid received	Losses: Recknon nor Property: \$  Contents: \$  Pre-Incident \	Values: Optional None
Completed Modules  2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson		ths Injuries	H3 Hazardous Ma 1 - Natural Gas 2 - Propane Gas 3 - Gasoline 4 - Kerosene 5 - Diesel Fuel / 6 - Household S 7 - Motor Oil 8 - Paint 0 - Other None	'Fuel Oil	Mixed Use Property Not Mixed 10 - Assembly Use 20 - Education Use 33 - Medical Use 40 - Residential Use 51 - Row Of Stores 53 - Enclosed Mall 58 - Business and Residential 59 - Office Use 60 - Industrial Use 63 - Military Use 65 - Farm Use 00 - Other Mixed Use
J Property Use Non Structures 131 Church, Place of 161 Restaurant or Ca 162 Bar/Tavern or Ni 213 Elementary School, June 241 College, Adult Ed 311 Nursing Home 331 Hospital	Worship afeteria ghtclub ool, Kindegarten iior High ducation	342 Doctor/Den 361 Prison or Ja 419 1- or 2-Fami 429 MultiFamily 439 Rooming/Bo 449 Commerical 459 Residential, 464 Dormitory/B	il, Not Juvenile ly Dwelling Dwelling parding House Hotel or Motel Board and Care	571 Gas or Ser 579 Motor Veh 599 Business C 615 Electric-Ge 629 Laborator 700 Manufactu 819 Livestock/	enerating Plant y/Science Laboratory uring Plant Poultry Storage (Barn) ential Parking Garage
Outside  124 Playground or Pa 655 Crops or Orchard 669 Forest (Timberla 807 Outdoor Storage 919 Dump or Sanitar 931 Open Land or Fie	ark d and) e Area y Landfill eld	946 Lake, River, 951 Railroad Rig 960 Other Stree 961 Highway/Di	ht-of-Way t vided Highway Street/Driveway n Site		a Property Use code and you have NOT checked a

Person/Entity Involved			Skd Enterpr	ises LLC	6513633923	
Local Option	Person/Entity Typ	pe	Business Na	me (if applicable)	Phone Number	
	<u> </u>					
Mr., Ms., Mrs.	First Name	MI		Last Name	Suffix	
80		COTTAGE		AVE-Avenue	W-West	
Number	Prefix	Street or Hig	hway	Street Type	Suffix	
				St Paul		
Post Office Box	Apt./	Suite/Room		City		
MN			55117			
State			Zip Code			

Owner				
Local Option	Person/Entit	y Type Busines	ss Name (if applicable)	Phone Number
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
Number	Prefix	Street or Highway	Street Type	Suffix
Post Office Box	,	Apt./Suite/Room	City	
State		Zip Cod	e	

#### L Remarks:

Saint Paul Fire Department crews responded to a report of a structure fire at a commercial property. Engine 22 and Ladder 22 arrived at a one-story automotive repair business with flames visible from the roof. Engine 22 declared a defensive strategy and assumed command, deploying a 2 1/2" hose line for the defensive fire attack. Ladder 22 was instructed to raise their aerial and prepare for defensive operations. Engine 17 arrived and established a water supply to both Engine 22 and Ladder 22.

District Chief 2 arrived and assumed command, having already balanced the assignment for additional fire crews while en route. Command reaffirmed the defensive strategy and identified an exposure building on the Charlie side of the fire structure (see exposure report).

Ladder 18 approached from Arlington Avenue and positioned on the Bravo side, raising their aerial. Engine 18 was directed to forward lay from Arlington Avenue and Park to establish a water supply to Ladder 18, while Engine 8 positioned at Arlington and Park to pump Engine 18's 4" supply hose line. Police were called for traffic control on Arlington Avenue to protect the supply lines.

Squad 1 was tasked with forcible entry to the Charlie exposure and an assessment of additional needs. Squad 3 was assigned as the rapid intervention team (RIT) and to perform additional 360-degree assessments while softening the building.

Engine 8 and Engine 17 established their water supplies and deployed additional handlines for defensiv...

Full primary narrative can be found in NFIRS 1S - Supplemental

6686	Jeseritz, Paul	DC	C2	01/11/2025
fficer In Charge ID	Signature	Position or Rank	Assignment	Date
6686	Jeseritz, Paul	DC	C2	01/11/2025

#### NFIRS-2 Fire

					MLIK2-	z riie				
А										
	62210	MN	01	11	2025	Station #8 (08)	SPFD25011100	)1996	0	
F	DID	State	Month	Day	Year	Station	Number		Exposure	_
В						С				
В	operty Details	1_				On-Site M Or Produc		On-Site Storage	Materials Use	
	Estimated numbe	er of resident		its in the b	uilding of origin			2 - Pro	k Storage or warel	cturin
В	•	1 —	ings Not In	volved		810-Motor other	vehicles and parts,	✓ 4 - Rep	kaged goods for so pair or service	ale
	Number of building	ngs involved				On-site ma	terial (1)	_ U - Un	determined	
В	3	☑ None	Less th	nan 1 acre						
	Acres burned (ou	tside fires)								
D				E1			E3			
Igr	nition			Cau	se of Ignition		Human Fact	ors Contri	ibuting to	
D	storage  Area of Fire Orig  Undetermined  Heat Source		dead	2 3 Sour 4 5 V	- Intentional - Unintentional - Failure of Equip ce - Act of Nature - Cause Under In - Cause Undeter stigation	vestigation	Check all appl None 1 - Asleep 2 - Possibl drugs 3 - Unatte	ly impaired ended pers	d by alcohol or son y Disabled	
	Item First Ignited	I		E2				le Persons		
D					tors Contributii	ng to Ignition	7 - Age Wa		Г	l
	Type of Material	First Ignited			determined or Contributing to	lanition	Person Involv	ved	Female	
F1	uipment Involved	In Ianition		F2 Fauinm	ent Power Sour	re		G Fire S	uppression Fact	ors
1 -	None	g		<b>~</b>					<b></b>	0.5
Equ	uipment Involved			 Equipme	nt Power Source					
	odel	] ]		F3 <b>Equipm</b>	ent Portability					
	erial#	]			ationary	lly can be moved by	one or two			


H1  Mobile Property Involved  1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn 3 - Involved in ignition and burned None	H2  Mobile Property Type and Make  Mobile Property Type  Mobile Property Make	Local Use  Pre-Fire Plan Available Arson Report Attached Police Report Attached Coroner Report Attached Other Reports Attached
Mobile Property Model  State License Plate Number	Year  VIN	

### **NFIRS-3 Structure Fire**

	141 1172 2 201 00001	<u> </u>		W.
l1	12	13		14
Structure Type	Building Status	Building H	leight	Main Floor Size
1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	Number of S At/Above G 0 Number of S Below Grad	Stories rade Stories	Total Square Feet OR  BY Length (ft) X Width (ft)
14	15		V	
Fire Origin  1 Below Grade Story of Fire Origin  J2 Fire Spread	Number of Stories Damaged By Flan  Number of Stories w/Minor Damag  Number of Stories w/Significant Da  Number of Stories w/Heavy Damag  Number of Stories w/Extreme Dam  *Count the roof as part of the highest stories	ge (1-24%) amage (25-49%) ge (50-74%) nage (75-100%)	K1 Llem to Fl K2 Ll	Material Contributing Flame Spread  Contributing Most lame Spread  of Material Contributing t To Flame Spread
L1 Presence of Detectors  N - None Present 1 - Present U - Undetermined	L3  Detector Power Supply  1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors & Power Supplies		Occupants, ( Occupants, ( ere No Occu Alert Occup	
Detector Type  1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	Detector Operation  1 - Fire Too Small To Activate 2 - Operated 3 - Failed To Operate U - Undetermined	2 - Improper 3 - Defective 4 - Lack of M	ilure, Shuto Installation Saintenance Aissing or D Discharged o	isconnected

M1	МЗ	M5
Presence of Automatic Extinguishing System	Operation of Automatic Extinguishing System	Reason for Automatic Extinguishing System Failure
M - None Present 1 - Present 2 - Partial System Present U - Undetermined  M2  Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler 3 - Other Sprinkler System	1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range	1 - System Shut Off 2 - Not Enough Agent Discharged 3 - Agent Discharged But Did Not Reach Fire 4 - Wrong Type of System 5 - Fire Not In Area Protected 6 - System Components Damaged 7 - Lack of Maintenance 8 - Manual Intervention 0 - Other U - Undetermined Required if system failed or not effective
4 - Dry Chemical System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M4  Number of Sprinkler  Heads Operating  Required if system operated	

### **NFIRS-1S Supplemental**



#### **Primary Narrative:**

Saint Paul Fire Department crews responded to a report of a structure fire at a commercial property. Engine 22 and Ladder 22 arrived at a one-story automotive repair business with flames visible from the roof. Engine 22 declared a defensive strategy and assumed command, deploying a 2 1/2" hose line for the defensive fire attack. Ladder 22 was instructed to raise their aerial and prepare for defensive operations. Engine 17 arrived and established a water supply to both Engine 22 and Ladder 22.

District Chief 2 arrived and assumed command, having already balanced the assignment for additional fire crews while en route. Command reaffirmed the defensive strategy and identified an exposure building on the Charlie side of the fire structure (see exposure report).

Ladder 18 approached from Arlington Avenue and positioned on the Bravo side, raising their aerial. Engine 18 was directed to forward lay from Arlington Avenue and Park to establish a water supply to Ladder 18, while Engine 8 positioned at Arlington and Park to pump Engine 18's 4" supply hose line. Police were called for traffic control on Arlington Avenue to protect the supply lines.

Squad 1 was tasked with forcible entry to the Charlie exposure and an assessment of additional needs. Squad 3 was assigned as the rapid intervention team (RIT) and to perform additional 360-degree assessments while softening the building.

Engine 8 and Engine 17 established their water supplies and deployed additional handlines for defensive fire attack on the Bravo and Delta sides, respectively.

District Chief 3 arrived and assumed Safety Officer position, while Car 5-Deputy Chief served as Senior Advisor. Medic 3 and Ambulance 2 established Rehab areas.

Safety Officer informed command that the gas to the structure had been secured and made crews aware of overhead wires at the Alpha-Delta corner. Xcel Energy arrived on scene and secured both the gas meter and power to the building.

Ladders 22 and Ladder 18 used aerial master streams to knock down the bulk of the fire. Once the bulk of the fire was extinguished, exterior handlines and master streams were shut down. Squad 1 cut a hole in the side of the building at the Alpha-Bravo corner to provide better access to the front office, which contained active fire that crews were unable to reach from the exterior. Safety Officer oversaw Squad 1's operations.

Crews continued to extinguish hot spots in both the main fire structure and the Charlie exposure. Command was transferred to the oncoming District Chief 2, and crews were switched out with the next on-coming shift.

At the time of this report, operations were still ongoing under District Chief 2, with Engine 17, Engine 22, Ladder 22, and Car 20-Fire Investigator Tweed on scene.



## **Investigation Report**

### Case

SPFD250111001996	Tweed, Joshua	Closed	25-005-721
Case Number	Lead Investigator	Status	Name
Confidential	Undetermir	ned	Undetermined
Confidentiality	Disposition		Fire Cause
01/11/2025	05:26		
tart Date	Start Time	End Date	End Time
Saint Paul Fire Departmer	nt		Saint Paul Police Department
rimary Fire Department	Secondary F	Fire Department	Law Enforcement
			ito repair shop. Firefighters arrived and
The fire department was of found heavy fire venting foperations were started. It workers on the scene investigate the area and for the started two longer transfers.	rom the roof and front win Firefighters extinguished the stated they were driving ir ound the building fire.  o large vehicle repair areas	dows of a large metal cone fire and conducted over the area when they saw separated by a storage a	mmercial building. Defensive fire
The fire department was of found heavy fire venting foperations were started. It workers on the scene investigate the area and for the storage area and adjacent to the storage area.	From the roof and front win Firefighters extinguished the stated they were driving in ound the building fire.  To large vehicle repair areas cent repair shop with a rook	dows of a large metal cone fire and conducted over the area when they saw separated by a storage af collapse.	mmercial building. Defensive fire erhaul.  I flames in the distance. They went to
The fire department was of found heavy fire venting foperations were started. It is workers on the scene investigate the area and finvestigation revealed two the storage area and adjacture illance cameras from	From the roof and front win Firefighters extinguished the stated they were driving in ound the building fire.  To large vehicle repair areas cent repair shop with a rook	dows of a large metal cone fire and conducted over the area when they saw separated by a storage af collapse.	emmercial building. Defensive fire erhaul.  I flames in the distance. They went to erea. Severe fire damage was observed to
The fire department was of found heavy fire venting foperations were started. It is workers on the scene investigate the area and finvestigation revealed two the storage area and adjact surveillance cameras from fire.	From the roof and front win Firefighters extinguished the stated they were driving in ound the building fire.  To large vehicle repair areas cent repair shop with a rook	dows of a large metal cone fire and conducted over the area when they saw separated by a storage af collapse.	emmercial building. Defensive fire erhaul.  I flames in the distance. They went to erea. Severe fire damage was observed to

### Fire

Undetermined	Storage: supplies or tools; dead storage		
Fire Cause A	Area of Origin	Equipment Power Source	Equipment Portability
Area of Origin Comments			
Undetermined		Undetermined	
Heat Source		Material Ignited	
Equipment Involved In Ignition	[ Equipment Make	Equipment Model	Equipment Serial Number
Beyond building of origin Fire Spread Material		Fire Spread Avenue	
Smoke Spread Material		Smoke Spread Avenue	
Fire Comments			
eather			
		0	Calm
Visibility	Relative Humidity (%)	Wind Speed (Mph)	Wind Direction
	0	No	
17.0		Lightning	Information Obtained
17.0 Temperature (Fahrenheit)	Precipitation	Lighthing	From Weather

Property Details (1 of 4)

N/A			
lame			
80 Cottage Avenue West			
ddress		Apt/Suite/Room	
Saint Paul	Ramsey County	Minnesota 55117	
ity	County	State Postal Code	<u>,</u>
\$175,000.00	\$85,000.00	\$175,000.00	
re Fire Value	Content Loss Value	Structure Loss Value	
roperty Description			
a			
		1 1	
Structure	Urban		
	Urban Area Description	Area Quality	
Structure rea Type		Area Quality	
		Area Quality	
rea Type Jcture	Area Description		
геа Туре	Area Description  Area Description  Greater Description		
rea Type  ucture  Motor vehicle or boat sales	Area Description  Area Description  Greater Description	ied	
rea Type  Jcture  Motor vehicle or boat sales roperty Use	Area Description  Structure	ied	
rea Type  Jcture  Motor vehicle or boat sales roperty Use	Area Description  Structure	ied • Occupancy	
rea Type  Jcture  Motor vehicle or boat sales roperty Use	Area Description  Unoccup Structure Unknown Smoke Detector Present	ied • Occupancy	
rea Type  Jcture  Motor vehicle or boat sales roperty Use  larm Type  None	Area Description  Unoccup Structure Unknown Smoke Detector Present	ied  Occupancy  Smoke Detector Performance	
rea Type  Jcture  Motor vehicle or boat sales roperty Use  larm Type  None prinkler Standpipes	Area Description  Structure  Unoccup  Structure  Unknown  Smoke Detector Present  Sprinkler	ied  Occupancy  Smoke Detector Performance  Standpipes Performance	
rea Type  Jcture  Motor vehicle or boat sales roperty Use  larm Type  None prinkler Standpipes	Area Description  Structure  Unknown  Smoke Detector Present  Sprinkler	ied  Occupancy  Smoke Detector Performance  Standpipes Performance	

The first part of the interior exam began through the open overhead door on the northeast corner of the South building. This door was accessed via a 7' X 10' hole that was cut by fire suppression personnel.

Extensive fire damage was found on the northern 1/3 of the interior space. The north wall showed signs of mass loss beginning at the roof line and continuing down the wall to a height of approximately 8 feet. This mass loss continued from the east wall all the way to the western wall. Fire made its way from the small adjacent structure into this area through the eaves and common roof area. Fire damage was observed to these structural members of the roof framing. The rafters are covered by sheetrock that extends the length of the building. Mass loss of fire drop down can be seen on the first two sections of sheetrock towards the north end of the ceiling wallboard. A line of demarcation is seen throughout the building's exterior walls starting at a level of three feet towards the north end of the building and increasing in height as one walks towards the south end of the structure. Items that were collected on the north wall include a metal cabinet toolbox, another rolling toolbox, and assorted items collected on top along with several plastic 5-gallon buckets.

Drop down from the ceiling and the upper wall can be found on the ground in this area of the north wall. Soot accumulation can be found on all exposed surfaces, with a higher level of soot at the upper ceiling level and decreased levels towards the bottom near the two-foot mark.

The investigation continued onto the north structure.

Access to the interior of this building was limited to a small area on the south and accessible through the small mezzanine area between the two buildings. Due to roof collapse and compromise of the exterior walls, no entry into this space was permitted. From the vented vantage point of the southern wall, it can be assessed that the items collected within the north warehouse contributed to a high fuel load which sustained fire growth, leading to flame and thermal impingement to the structural roof components, leading to failure and collapse. Fire most likely transferred into this compartment through the open door in the middle mezzanine area, which housed canisters of fuel and various liquids used for operations in the business.

An assessment of the collapsed portion of the north building shows structural members of the ceiling and roof sheeting collected on the floor space of the north building with evidence of thermal damage. This area of damage spans the length of the north building up to the office area, which is located on the far northeast corner of the building.

Access to the office area was made through the doorway on the northeast exterior. No signs of forced entry were found on the door or door frame. The small lobby area of the entrance showed evidence of fire damage and calcination of drywall that began at the level of 3 feet and extended to the ceiling height, increasing in severity. Extensive overhaul was completed in this area. This was performed by fire suppression personnel on scene. Evidence of charring to the ceiling joists can be found with a higher level of charring towards the main building, located on the south side of the office. Items within the office such as desks, computers, and office materials show signs of thermal damage, along with soot accumulation on nearly all exposed surfaces to the level of the floor.

The final area examined was the small storage area that was built between the two warehouse-type buildings. This is believed to be the building of origin of the fire. The roof and ceiling components of this area were collapsed in on itself, but was deemed accessible by the investigator for examination purposes. Deep charring to the wooden structural members in this area was extensive and severe, and continued to the floor level. All products located within this area, which contained combustible materials, were consumed by the intense heat. Only items that were steel or metal-based remained intact. These items were identified as storage receptacles, most likely for liquids that may have been of a flammable nature. Due to the intense flame impingement on collected products and items in this area, no discernible area of origin was observed.

It was discovered that multiple security cameras were located on the exterior of the building and had captured video footage of two individuals walking northbound on the eastern exterior of the building. One of these individuals was carrying what appeared to be a fuel canister. Both men were wearing clothing that obscured their facial features.

#### Interior Exam

The structure is a large one-story metal-frame warehouse building facing East and running South to North. The exterior investigation began upon arrival on the scene and was conducted clockwise, noting areas of fire-related damage. The structure is surrounded by a chain-link fence approximately 6 feet high. At the south end of this fence is a gate with double doors on the eastern end. A gap of approximately 2 feet is visible where access was made into the property. According to the owner, the gap in the fence was present prior to the fire. Vehicles are found parked in spaces that surround both the North and South buildings. Three of these vehicles were affected by the structure fire and sustained fire-related damage. All three of these automobiles were located on the eastern side and the examination of said vehicles is found in the Motor Vehicles Tab in this report.

Upon observing the north exterior, a small office area is connected to a larger warehouse. Two small windows, approximately 2 feet in diameter, are seen on the side. Brown smoke is venting from the upper eaves with a higher velocity of smoke movement towards the peak.

Moving to the east-facing elevation, gray smoke can be seen venting out the entire length of the eaves. Smoke staining is observed at the soffit level and continuing down the metal face to approximately 2 feet. Four large overhead doors are present on the north warehouse building. The second overhead door from the north appears compromised and folded onto itself towards the interior of the building.

Fire suppression activities were underway at the time of the investigation, with multiple hose lines stretched into the eastern parking lot. Two aerial master streams were in place, flowing water from the north onto the roof of the north building. Flames can be seen venting out the southeast corner of the north building.

At the time of the investigation, the roof of the northern building had collapsed inward, with fire venting through the void space left by the collapsed metal roof.

Between the north and south buildings, located on the eastern side, is a small 22 x 34' structure connecting both warehouses. This building's roof section was compromised and had collapsed inward, with evidence of high heat and fire damage to the metal roofing material. The door opening to this area was open, and one window was missing at the time of the investigation. At the time of the investigation, it was unknown whether this door was forced open or was found in the open position. Radial heat patterns above the doorway indicate fire venting through the open doorway and possibly through the compromised window to the south of this doorway. Radial patterns of heat damage on either side of these entry points also indicate high heat within the small structure, ranging from approximately 1 foot off the ground to the ceiling height.

The south building's roof section remained intact, with radial heat patterns and smoke staining on the northernmost section of the roofline. The severity of staining decreased approximately 30 feet south of the most northern point of the building. Staining along the entire length of the top peak was observed.

The eastern exterior of the south building contained four large overhead doors. All doors were intact and in the closed position, with foot staining on the upper two panels of all doors. The northernmost door was compromised by fire suppression personnel, who cut a  $6 \frac{1}{2} \times 8 \frac{1}{2}$  inch hole through the center of the overhead door for entry.

Multiple security cameras were observed fixed to the exterior of the south and the north buildings on all sides.

The south-facing exterior wall of the southernmost building shows smoke venting from the upper eaves and peak, with light smoke damage at the eve level extending 3/4 up the roof line. Two straight ladders were resting against the south wall, noted as not having been placed by fire suppression personnel.

On the west elevation, access was made through a hole in the chain-link fence, compromised by fire suppression personnel. The western elevation of the south building shows foot staining on the upper walls near the eaves and soffits, running the length of the building.

The small center section between the two buildings displays radial patterns and thermal damage to the metal exterior walls, continuing to the south wall of the northernmost building. Radial patterns extend down the length of the west exterior of the northernmost building, with paint blistering at approximately 2-foot diameter points at the 8, 15, and 18-foot marks moving north from the southern wall. Flames can be seen venting from the roof line on the western wall at the area where the roof collapses.

Exterior Exam

None	Unknown	
Sprinkler Standpipes	Smoke Detectors Present	Smoke Detector Locations Fire Suppression
Closed And Locked	Closed And Locked	d
Doors	Windows	Other Entrances

Electrical Status	_	Electrical Entrance	
	Natural	Xcel Energy	
Fuel Status	Fuel Type	Fuel Company	
		City of Saint Paul Municipal Water	
Water Status		Water Company	
 Telephone Status 			
Utility Comments			

# Property Details (2 of 4)

Name		
80 Cottage Avenue West (Exp	oosure -2005 Volvo XC90)	
Address		Apt/Suite/Room
Saint Paul	Ramsey County	Minnesota 55117
City	County	State Postal Code
\$3,520.00	0	\$2,400.00
Pre Fire Value	Content Loss Value	Structure Loss Value
Property Description		
rea		
1	11	H
Vehicle	Urban	
Агеа Туре	Area Description	Area Quality
ructure	1.1	
Property Use	Struct	cure Occupancy
Alarm Type	Smoke Detector Present	Smoke Detector Performance
Sprinkler Standpipes		kler Standpipes Performance
	ture Height (Ft) Structure Width (	Ft) Number Of Stories Number Of Units
Structure Length (Ft) Struc		1.1
Structure Length (Ft) Struc	Other (Add more in Comr	ments)
Structure Length (Ft) Struct  Construction Type	Other (Add more in Comr	Structure Material

Exterior Exam			
arm and Security Servi	ces		
Sprinkler Standpipes	Smoke Detectors Present	Smoke Detector Locations Fire Suppression	
Doors	Windows	Other Entrances	
Alarm Protection/Securi	ty Comments		
ilities			
L			
ilities       Electrical Status		L Electrical Entrance	
L	Natural	Electrical Entrance	
L	Natural Fuel Type	1.1	
Electrical Status		Xcel Energy	
Electrical Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	
Electrical Status Fuel Status		Xcel Energy Fuel Company	
Electrical Status Fuel Status Water Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	
Electrical Status Fuel Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	

# Property Details (3 of 4)

2017 Mitsubishi Outland	der (exposure)			
Name	der (exposure)			
80 Cottage Avenue Wes	st - (Exposure -2017 Mitsubi	shi Outlander)		
Address	<u> </u>		Apt/Suite/Rooi	m
Saint Paul	Ramsey Co	untv	Minnesota	55117
City	County	uncy	State	Postal Code
\$6,895.00	0		\$2,500.00	
Pre Fire Value	Content L	oss Value	Structure Los	es Value
	Content L	O33 Valu <del>c</del>	Structure LOS	55 Value
Property Description				
Vehicle Area Type	Urban Area Desc	ription	Area Quality	
tructure				
tructure				
tructure L Property Use		   Structure (	Occupancy	
Property Use				
	_   Smoke De	Structure ( tector Present		tor Performance
Property Use  L Alarm Type	L Smoke De	tector Present	Smoke Detec	
Property Use	L Smoke De	tector Present		
Property Use  Alarm Type  Sprinkler Standpipes	Smoke De	tector Present 	Smoke Detec	
Property Use  Alarm Type  Sprinkler Standpipes  Structure Length (Ft)	L L Structure Height (Ft) Str	tector Present    L Sprinkler S	Smoke Detection Smoke Detectio	ce       Number Of Units
Property Use  Alarm Type  Sprinkler Standpipes		tector Present    L Sprinkler S	Smoke Detection tandpipes Performan  Number Of Stories	ce       Number Of Units

Exterior Exam			
arm and Security Servi	ces		
Sprinkler Standpipes	Smoke Detectors Present	Smoke Detector Locations Fire Suppression	
Doors	Windows	Other Entrances	
Alarm Protection/Securi	ty Comments		
ilities			
L			
ilities       Electrical Status		L Electrical Entrance	
L	Natural	Electrical Entrance	
L	Natural Fuel Type	1.1	
Electrical Status		Xcel Energy	
Electrical Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	
Electrical Status Fuel Status		Xcel Energy Fuel Company	
Electrical Status Fuel Status Water Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	
Electrical Status Fuel Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	

# Property Details (4 of 4)

1998 Honda Civic (exposu	ire)		
Name	16)		
I	(Fuzzania 1000 Handa Civia)	11	
Address	(Exposure -1998 Honda Civic)	Apt/Suite/Doom	
1	П	Apt/Suite/Room	1.1
Saint Paul	Ramsey County	Minnesota	55117
City	County	State	Postal Code
\$2,567.00	0	\$2,100.00	
Pre Fire Value	Content Loss Value	Structure Loss	Value
Property Description			
леа			
I	11	11	
Vehicle	Urban		
Area Type	Area Description	Area Quality	
tructure			
	[1		
Property Use	Structure	Occupancy	
Alarm Type	Smoke Detector Present	Smoke Detecto	or Performance
Sprinkler Standpipes	Sprinkler S	Standpipes Performance	2
Chaushuse I as abb (Fb) Ch		Number Of Sharing	Number Of Units
structure Length (Ft) Sti	ructure Height (Ft) Structure Width (Ft)	Number Of Stories	Number Of Onics
	Other (Add more in Comment	cs)	
c	Structure Type	Structure Mate	erial
Construction Type		1.1	
Construction Type  [ Foundation			Material

Exterior Exam			
arm and Security Servi	ces		
Sprinkler Standpipes	Smoke Detectors Present	Smoke Detector Locations Fire Suppression	
Doors	Windows	Other Entrances	
Alarm Protection/Securi	ty Comments		
ilities			
L			
ilities       Electrical Status		L Electrical Entrance	
L	Natural	Electrical Entrance	
L	Natural Fuel Type	1.1	
Electrical Status		Xcel Energy	
Electrical Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	
Electrical Status Fuel Status		Xcel Energy Fuel Company	
Electrical Status Fuel Status Water Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	
Electrical Status Fuel Status		Xcel Energy Fuel Company City of Saint Paul Municipal Water	

## Motor Vehicle (1 of 3)

Vehicle Description			
1998	Honda	Civic   Black	
Year	Make	Model Color	
JGE 609	Minnesota	1HGEJ6679WL036465	
License Plate Number	License Plate State	Vin	
Owner			
Ku Shee			
Owner Name		Owner Phone	
1313 Garfield Ave.			
Owner Street 1		Owner Street 2	
Albert Lea	Minnesota	56007	
Owner City	Owner State	Owner Postal Code	_
Operator			
Operator		11	ı
Operator Name		Operator Phone	
L		<u> </u>	
Operator Street 1		Operator Street 2	
Operator City	Operator State	Operator Postal Code	
Operator City	Operator State	Operator Postal Code	
Exterior			
	Yes		
Exterior Prior Damage	Exterior Fire Damage	Tires / Wheels Parts Missing	
Fuel System			
		Gasoline	
Fuel System Type	Fuel System Prior Damage	Fuel System Fire Damage Fuel Type	<b>—</b>

	Present		
Condition Of Tank	Filler Cap Condit	ion	Fuel Line Condition
Engine Compartment			
		No	
Engine Prior Damage		Engine Fire Dama	age
Fluid Level Oil	Fluid Level Transmission	Fluid Level Radia	tor Fluid Level Other
Interior			
	No		
Interior Prior Damage	Interior Fire Damage	lgnition System	Key In Ignition
1	II	11	
Personal Contents Missing	Accessories Missing	Odometer Readi	ng Service Sticker Information
C			
Security	1.1		
	Yes		Closed
Alarm Present	Doors / Trunk Lo	cked	Window Position
Osigin / Ignition Sequence			
Origin / Ignition Sequence	1.1		
Exterior, exposed surface	Conducted heat	from another fire	Plastic
Area of Origin	Heat Source		Material Ignited
Exposure fire			
Ignition Factor			

#### **Motor Vehicle Comments**

Examination of the exterior of the vehicle found that the fire and heat damage was most significant on the passenger/engine/cargo area of the vehicle. Examination of the interior of the vehicle found that the fire and heat damage was most significant on the passenger/engine/cargo area of the vehicle.

# Motor Vehicle (2 of 3)

Vehicle Description			
2017	Mitsubishi	Outlander Brown	
Year	Make	Model Color	
AUL 021	Minnesota	JA4AR3AU8HZ070067	
License Plate Number	License Plate State	Vin	
Owner			
Eh Mu Paw			
Owner Name		Owner Phone	_
1511 Hazelwood St.			
Owner Street 1		Owner Street 2	
St Paul	Minnesota	55106	
Owner City	Owner State	Owner Postal Code	<u> </u>
Operator			
Operator Name		Operator Phone	
		Operator Street 2	
Operator Street 1	11	Operator Street 2	ı
Operator City	Operator State	Operator Postal Code	
Exterior	1 1	11	ı
	Yes		
Exterior Prior Damage	Exterior Fire Damage	Tires / Wheels Parts Missing	
Fuel System			
		Gasoline	
Fuel System Type	Fuel System Prior Damage	Fuel System Fire Damage Fuel Type	<b>—</b>

	Present			
Condition Of Tank	Filler Cap Condit	ion	Fuel Line Condition	-
Engine Compartment				
		No		
Engine Prior Damage		Engine Fire Dam	age	_
		J [		_
Fluid Level Oil	Fluid Level Transmission	Fluid Level Radia	ator Fluid Level Other	
Interior				
	No		П	ĺ
Interior Prior Damage	Interior Fire Damage	」 Ignition System	Key In Ignition	_
L	] [			
Personal Contents Missing	Accessories Missing	Odometer Readi	Service Sticker Information	1
Security				
	11.,			ĺ
	Yes		Closed	
Alarm Present	Doors / Trunk Lo	cked	Window Position	
Origin / Ignition Sequence				
Vehicle storage area; garage	e. carport     Conducted heat	from another fire	Plastic	
Area of Origin	Heat Source		□ L  Material Ignited	_
Exposure fire			-	1
Ignition Factor				]
igilicion Faccoi				

#### **Motor Vehicle Comments**

Examination of the exterior of the vehicle found that the fire and heat damage was most significant on the passenger/engine/cargo area of the vehicle. Examination of the interior of the vehicle found that the fire and heat damage was most significant on the passenger/engine/cargo area of the vehicle.

# Motor Vehicle (3 of 3)

Vehicle Description			
2005	Volvo	XC90 Gold	
Year	Make	Model Color	_
RPY 243	Minnesota	YV1CZ592451155425	
License Plate Number	License Plate State	Vin	
Owner			
Joan Leslie Johnson			
Owner Name		Owner Phone	-
1121 Heard Ave.			
Owner Street 1		Owner Street 2	_
Champlin	Minnesota	55316	
Owner City	Owner State	Owner Postal Code	_
Operator			
			1
Operator Name		Operator Phone	_
			J
Operator Street 1		Operator Street 2	
Operator City	Operator State	Operator Postal Code	
	•	'	
Exterior			
	Yes		
Exterior Prior Damage	Exterior Fire Damage	Tires / Wheels Parts Missing	
Fuel System			
		Gasoline	
Fuel System Type	Fuel System Prior Damage	Fuel System Fire Damage Fuel Type	1

		Present				
Condition Of Tank	-	Filler Cap Condit	on Fuel Line Condition		ne Condition	
Engine Compartment						
			No			
Engine Prior Damage			Engine Fire Dama	age		
			J			
Fluid Level Oil	Fluid Lev	el Transmission	Fluid Level Radia	tor	Fluid Level Other	
Interior						
	No					
Interior Prior Damage	Interior I	Fire Damage	Ignition System		Key In Ignition	
No						
Personal Contents Missing	Accessor	ies Missing	Odometer Readi	ng	Service Sticker Information	
Security						
	I	Yes		Closed	1	
Alarm Present			Doors / Trunk Locked		Window Position	
Addini Present		DOOIS/ HUIK LO	cked	vviiidov	V POSICIOII	
Origin / Ignition Sequence						
Vehicle storage area; garage, carport Radiated heat fr		om another fire	Plastic			
Area of Origin Heat Source		Heat Source	Materi		al Ignited	
Exposure fire						
Ignition Factor						

#### **Motor Vehicle Comments**

Examination of the exterior of the vehicle found that the fire and heat damage was most significant on the passenger/engine/cargo area of the vehicle. Examination of the interior of the vehicle found that the fire and heat damage was most significant on the passenger/engine/cargo area of the vehicle.

### Witness Statement (1 of 4)

Vitness Statement			
Bundy	Derrick		Daniel
Last Name	First Name		Middle Name
Discover of Fire			
Туре		Employer	
Interviewed By		Interviewed By Ot	her
3660 160th Street East			
Street 1		Street 2	
Rosemount	Minnesota		55068
City	State		PostalCode
White	03/23/1980		
Race	Date of Birth		Driver's Liscense Number
Q: Can you tell me how you discovered A: We work for the city, we were comin We tried to get closer and see where it to let them know that we had a fully-in walked around the back side, there was	ng down Arlington ar was coming from. A volved structure. We	as soon as we knew, w e couldn't get into it b	ve came down here and called dispatch because the gate was locked shut. We
Q: Did you notice anyone around at the A: No. Nobody was around.	e time?		
Q: Where was the location of the fire, a A: It was in the walkway in between the street looking South.			ır and a little bit of two. From the

Witness Statement Comments

### Witness Statement (2 of 4)

ast Name	First Name	Middle Name
911 Caller		
Гуре	Er	nployer
Interviewed By	In	terviewed By Other
Street 1	St	reet 2
Saint Paul	Minnesota	
City	State	PostalCode
Race	Date of Birth	Driver's Liscense Number
SPPW EMPLOYEE		

## Witness Statement (3 of 4)

Doh	Soe	Kapaw
ast Name	First Name	Middle Name
Owner		
уре	Emp	loyer
nterviewed By	l	viewed By Other
-		viewed by Other
2778 Southlawn Dr. Street 1	Stre	nt 2
	H	TT.
Maplewood	Minnesota	55109
City	State	PostalCode
Asian	11/02/1983	
Race	Date of Birth	Driver's Liscense Number
Q: Can you tell me how you	were alerted of the fire today?  ext door, called me. Pah from Dale In	port. He said "Your building burned down."
<ul><li>Q: Can you tell me how you</li><li>A: Pah, the neighbor right n</li><li>Q: What time was that?</li></ul>		port. He said "Your building burned down."
<ul><li>Q: Can you tell me how you</li><li>A: Pah, the neighbor right n</li><li>Q: What time was that?</li><li>A: 0720</li></ul>	ext door, called me. Pah from Dale In	port. He said "Your building burned down."
<ul><li>Q: Can you tell me how you</li><li>A: Pah, the neighbor right n</li><li>Q: What time was that?</li><li>A: 0720</li><li>Q: When were you last here</li></ul>	ext door, called me. Pah from Dale Im on site?	port. He said "Your building burned down."
A: Pah, the neighbor right n Q: What time was that?	ext door, called me. Pah from Dale Im on site? 830 or 1900.	port. He said "Your building burned down."
<ul> <li>Q: Can you tell me how you</li> <li>A: Pah, the neighbor right n</li> <li>Q: What time was that?</li> <li>A: 0720</li> <li>Q: When were you last here</li> <li>A: Last night. Until about 18</li> </ul>	ext door, called me. Pah from Dale Im on site? 830 or 1900.	port. He said "Your building burned down."
<ul> <li>Q: Can you tell me how you</li> <li>A: Pah, the neighbor right n</li> <li>Q: What time was that?</li> <li>A: 0720</li> <li>Q: When were you last here</li> <li>A: Last night. Until about 18</li> <li>Q: Were you the last person</li> </ul>	ext door, called me. Pah from Dale Im on site? 830 or 1900. I here at the time?	port. He said "Your building burned down."
<ul> <li>Q: Can you tell me how you</li> <li>A: Pah, the neighbor right n</li> <li>Q: What time was that?</li> <li>A: 0720</li> <li>Q: When were you last here</li> <li>A: Last night. Until about 18</li> <li>Q: Were you the last person</li> <li>A: Yes.</li> </ul>	ext door, called me. Pah from Dale Im on site? 830 or 1900. I here at the time?	port. He said "Your building burned down."
Q: Can you tell me how you A: Pah, the neighbor right n Q: What time was that? A: 0720 Q: When were you last here A: Last night. Until about 18 Q: Were you the last person A: Yes. Q: Did you close the gate an A: Yes.	ext door, called me. Pah from Dale Im on site? 830 or 1900. here at the time? nd lock it?	port. He said "Your building burned down."

A: Yes, it has been like that.

Q: Is the building heated?

A: Yes. We have natural gas heaters in the garages.

Q: Have you ever had a problem with those in the past?

A: No, no problems.

Q: In the middle area between the two buildings, is there heat in that section?

A: No. No heat. That is where was have our compressor and oil tanks.

Q: Is the compressor connected to electricity?

A: Yes.

Q: Have you had any threats made to you?

A: No, but there is this one guy, who is homeless, I used to have him come and help out. But he is not working out. He is on drugs and he doesn't listen. So I said that he had to go.

Q: Do you have his name?

A: I took down his information just in case. MARK. REEKO

Witness Statement Comments

### Witness Statement (4 of 4)

Krantz	Joeseph		S
ast Name	First Name		Middle Name
Discover of Fire			
Гуре		Employer	
nterviewed By		Interviewed E	By Other
2167 Lake Airs Blvd			
Street 1		Street 2	
White Bear Lake	Minnesota		55110
City	State		PostalCode
	02/10/1989		
Race	Date of Birth		Driver's Liscense Number

### Conclusion

#### Case Conclusion

After examination of the fire scene, observation of fire patterns of both movement and intensity and interviews conducted, it is my opinion the fire began in the storage area. The area of origin was the interior of the storage area. The first fuel/material ignited was unknown. The ignition source was undetermined. The oxidant was normal atmospheric air. The action that brought these items together was undefined. The classification of fire cause is undetermined. This concludes my investigation and report.

Technical Review by J. Blank, IAAI-CFI, 3-15-25

Signature			
Tweed, Joshua			
Lead Investigator	Signature	Date Submitted	

#### **Document Attachment List**

Photo Log

JDIC5363























