
Date: February 07, 2022
File #: 18 - 035791
Folder Name: 16 ACKER ST W
PIN: 302922340070








Date: February 07, 2022

File #: 18 - 035791 Folder Name: 16 ACKER ST W 97 302922340070



 Date:
 February 07, 2022

 File #:
 18 - 035791

 Folder Name:
 16 ACKER ST W

 PIN:
 302922340070








February 07, 2022 18 - 035791 Date:

File #: **Folder Name:** 16 ACKER ST W PIN: 302922340070

	WARNI	NG STARRA	1000	
	AN UNSAFE CONDITION HAS BEEN DETECTED IN YOUR GAS EQUIPMENT			
	CORRECTIONS MUST BE MADE IN ACCORDANCE WITH M	E BY A QUALIFIED PERSON OR AGENCY IANUFACTURER'S INSTRUCTIONS / WITH LOCAL REGULATIONS,	7	
TA	G PLACED ON: RANGE WATER			
4	FURTHER USE OF THE EQUIP DANGEROUS AND THEREFORE	-		
	LEAK OR DEFECT IN GAS PIPE GAS LEAK IN GAS APPLIANCE NO VENT PIPE DEFECTIVE VENT PIPE NOT VENTED PROPERLY VENT OR CHIMNEY STOPPAGE	☐ APPLIANCE NOT INSTALLED TO CODE ☐ CONTROLS DEFECTIVE OR MISSING ☐ NO SAFETY PILOT OR IS DEFECTIVE ☐ FAULTY ELECTRIC WIRING		
	IMPROPER DRAFT DIVERTER IMPROPER VENT SIZE POSSIBLE LEAKAGE OF FLUE PRODUCTS IN WARN AIR CIRCULATION NON-APPROVED APPLIANCE	NO RELIEF VALVE OR IS DEFECTIVE IMPROPER GAS PIPING COMBUSTION PRODUCTS SPILLING AT DIVERTER OTHER CONDITION WHICH IS HAZARDOUS		
	REMARKS High CO DOCKED IN ET NAME VEN ACK	Black Soot HITE B. Common SINTO CHOMEDINEY		
	CONSEQUENCES RESULTIN	RGY, ARE ACCOUNTABLE FOR ANY ADVERSE IN FROM THIS UNSAFE CONDITION NOT ING CORRECTED		
A	UNSAFE CONDITION HAS BE	EMPLOYEE OF XCEL ENERGY THAT AN EEN DETECTED ON MY PREMISES AND LY ARRANGE TO HAVE THE CONDITION PERSON BEFORE THE GAS SUPPLY TO		
	DMER SIGNATURE	DATE 2/7/	7	
	OWNER	☐ TENANT ☐ AGENT		
XCEL ENERGY &				
1	Form 17-2652 (3-01)	SERVICE PERSON #		

Date: February 07, 2022

File #: 18 - 035791 Folder Name: 16 ACKER ST W 97 302922340070



February 07, 2022 18 - 035791 Date:

File #: **Folder Name:** 16 ACKER ST W PIN: 302922340070

