## CITY OF SAINT PAUL HERITAGE PRESERVATION COMMISSION STAFF REPORT

FILE NAME: 451 Selby Avenue

OWNER: Mi2 LLC

AGENCY: Department of Safety and Inspections- Code Enforcement

DATE OF HEARING: June 14, 2012 HPC SITE/DISTRICT: Hill Historic District

CATEGORY: Contributing CLASSIFICATION: Demolition

STAFF INVESTIGATION AND REPORT: Christine Boulware, Hilary Holmes

DATE: June 7, 2012

### A. SITE DESCRIPTION:

The Charles F. F. Abbott house at 451 Selby Avenue is a two and one-half story wood frame Eastlake style dwelling, constructed in 1883. The roof is intersecting gables with asphalt shingles and one central chimney. The exterior is wood lap siding and the foundation is limestone. The front entry porch has a pedimented roof and a transom over the door. A rectangular bay window flanks the side entry porch on the east elevation. Fenestration is two-over-two double-hung windows, with Queen Anne style upper and fixed sash. There is a three-course stone retaining wall at the front and east side of the property. This is one of four ornate, Eastlake style houses on this block of Selby Avenue. The property is classified as contributing to the character of the Hill Historic District.

### **B. PROPOSED CHANGES:**

This property has been vacant since September 5, 2006. Records indicate that the owner is Mi2 LLC and on March 9, 2012 an Order to Abate Nuisance Building was issued. HPC will review a potential demolition permit application by the Department of Safety and Inspections (DSI) or the property owner or owner's representative. The Department of Safety and Inspections (DSI) has issued a Remove or Repair order given the structure's nuisance conditions. Given the building is located within the Hill Historic District, the HPC is required to review and approve or disapprove the issuance of city permits for demolition pursuant to Leg. Code § 73.06(a)(4) generally and Leg. Code § 74.67 specifically.

### C. GUIDELINE CITATIONS:

### Hill Historic District Guidelines

Leg. Code § 74.64. Restoration and Rehabilitation.

A. General Principles:

- (1) All work should be of a character and quality that maintains the distinguishing features of the building and the environment. The removal or alteration of distinctive architectural features should be avoided as should alterations that have no historical basis and which seek to create an earlier appearance. The restoration of altered original features, if documentable, is encouraged.
- (2) Changes which may have taken place in the course of time are evidence of the history and development of a building, structure, or site and its environment. These changes may have acquired significance in their own right, and this significance shall be recognized and respected.
- (3) Deteriorated architectural features should be repaired rather than replaced whenever possible. In the event of replacement, new materials should match the original in composition, design (including consideration of proportion, texture and detail), color and overall appearance.
- (4) New additions or alterations to structures should be constructed in such a manner that if such additions or alterations were to be removed in the future, the form and integrity of the original structure would be unimpaired.
- (5) The impact of alterations or additions on individual buildings as well as on the surrounding streetscape will be considered; major alterations to buildings which occupy a corner lot or are otherwise prominently sited should be avoided.

(6) New construction should be compatible with the historic and architectural character of the district.

(7) The surface cleaning of structures shall be undertaken with the gentlest means possible. Sandblasting and other cleaning methods that will damage the historic building materials shall not be undertaken.

(8) Every reasonable effort shall be made to protect and preserve archaeological resources affected

by, or adjacent to any project.

(9) Contemporary design for alterations and additions to existing properties shall not be discouraged when such alterations and additions do not destroy significant historical, architectural or cultural material, and such design is compatible with the size, scale, color, material, and character of the property, neighborhood, or environment.

(10) Wherever possible, new additions or alterations to structures shall be done in such a manner that if such alterations were to be removed in the future, the essential form and integrity of the structure

would be unimpaired.

(Ord. No. 17815, § 3(II) 4-2-91)

### § 74.67. Demolition

When reviewing proposals for demolition of structures within the district, the Heritage Preservation Commission refers to Section 73.06 (i)(2) of the Saint Paul Legislative Code which states the following:

In the case of the proposed demolition of a building, prior to approval of said demolition, the commission shall make written findings on the following: the architectural and historical merit of the building, the effect of the demolition on surrounding buildings, the effect of any proposed new construction on the remainder of the building (in case of partial demolition) and on surrounding buildings, and the economic value or usefulness of the building as it now exists or if altered or modified in comparison with the value or usefulness of any proposed structures designated to replace the present building or buildings.

(Ord. No. 17815, § 3(V) 4-2-91)

### SECRETARY OF THE INTERIOR'S STANDARDS FOR REHABILITATION

### District/Neighborhood

### Recommended:

-Identifying, retaining, and preserving buildings, and streetscape, and landscape features which are important in defining the overall historic character of the district or neighborhood. Such features can include streets, alleys, paving, walkways, street lights, signs, benches, parks and gardens, and trees.

- -Retaining the historic relationship between buildings, and streetscape and landscape features such as a town square comprised of row houses and stores surrounding a communal park or open space.
- -Protecting and maintaining the historic masonry, wood, and architectural metals which comprise building and streetscape features, through appropriate surface treatments such as cleaning, rust removal, limited paint removal, and reapplication of protective coating systems; and protecting and maintaining landscape features, including plant material.
- -Repairing features of the building, streetscape, or landscape by reinforcing the historic materials. Repair will also generally include the replacement in kind or with a compatible substitute material of those extensively deteriorated or missing parts of features when there are surviving prototypes such as porch balustrades, paving materials, or streetlight standards.

-Replacing in kind an entire feature of the building, streetscape, or landscape that is too deteriorated to repair - when the overall form and detailing are still evident - using the physical evidence to guide the new work. This could include a storefront, a walkway, or a garden. If using the same kind of material is not technically or economically feasible, then a compatible substitute material may be considered.

### Alterations/Additions for the New Use

- -Designing required new parking so that it is as unobtrusive as possible, i.e., on side streets or at the rear of buildings. "Shared" parking should also be planned so that several business' can utilize one parking area as opposed to introducing random, multiple lots.
- -Designing and constructing new additions to historic buildings when required by the new use. New work should be compatible with the historic character of the district or neighborhood in terms of size, scale, design, material, color, and texture.
- -Removing nonsignificant buildings, additions, or streetscape and landscape features which detract from the historic character of the district or the neighborhood.

### Not Recommended:

- -Removing or radically changing those features of the district or neighborhood which are important in defining the overall historic character so that, as a result, the character is diminished.
- -Removing or relocating historic buildings, or features of the streetscape and landscape, thus destroying the historic relationship between buildings, features and open space.
- -Failing to undertake adequate measures to assure the preservation of building, streetscape, and landscape features.
- -Removing a feature of the building, streetscape, or landscape that is unrepairable and not replacing it; or replacing it with a new feature that does not convey the same visual appearance.

### Design for Missing Historic Features

-Introducing a new building, streetscape or landscape feature that is out of scale or otherwise inappropriate to the setting's historic character, e.g., replacing picket fencing with chain link fencing.

### Alterations/Additions for the New Use

- -Placing parking facilities directly adjacent to historic buildings which cause the removal of historic plantings, relocation of paths and walkways, or blocking of alleys.
- -Introducing new construction into historic districts that is visually incompatible or that destroys historic relationships within the district or neighborhood.
- -Removing a historic building, building feature, or landscape or streetscape feature that is important in defining the overall historic character of the district or the neighborhood.
- **E. FINDINGS** The following findings are based upon HPC records, research and HPC staff inspection of the property's exterior:
- 1. Leg. Code § 74.67. The Preservation Program for the Hill Historic District states that *In the* case of the proposed demolition of a building, prior to approval of said demolition, the commission shall make written findings on the following the architectural and historical merit of the building, the effect of the demolition on surrounding buildings, the effect of any proposed new construction on the remainder of the building (in case of partial demolition) and on

surrounding buildings, and the economic value or usefulness of the building as it now exists or if altered or modified in comparison with the value or usefulness of any proposed structures designated to replace the present building or buildings.

- 2. The category of the building. The building is classified as contributing to the Hill Historic District.
- 3. Architectural and historical merit of the building and effect of demolition on surrounding buildings. Although in need of repair, staff considers the building's historic and architectural integrity to be fair to good. The house is an example of Eastlake Patternbook style of architecture and is part of a collection of buildings on the north side of Selby between Arundel and Mackubin. The house was constructed during the period of significance and during building boom of the late 1880's and early 1890's. The Saint Paul Historic Hill Heritage Preservation District Guidelines for Design Review Booklet states the following about late 19<sup>th</sup> century vernacular properties;

The original Ramsey Hill neighborhood expanded north and west from Summit Avenue. Houses north of Summit were of wood frame construction with some brick or stone, contrasting with the more substantial masonry houses along Summit. While these houses are generally not of the same design quality as those found along Summit Avenue, they represent upper-middle class, late nineteenth-century architectural taste.

The Sanborn Insurance map for this site indicates the footprint of the house since 1925 has changed slightly with the removal of a one-story rear addition and a one-story shed near the rear of the house.

Selby Avenue has more commercial uses than residential, and 451 Selby Avenue is one of a row of four houses that still remain on the avenue. The block face on the north side of Selby Avenue has a collection of four houses, including 451 Selby, in a Victorian-era "Painted Lady" Eastlake style, with architectural continuity between the four structures. The south side of the block is faced with a surface parking lot, two story commercial building, the Saint Paul Curling Club, a larger surface parking lot and a corner commercial building.

Staff has not researched other historical associations, such as persons that have contributed in some way to Saint Paul's history and development or an architect or association with an important event, with this property. The original building permit and Saint Paul and Ramsey Historic Sites Inventory form identify the builder and original owner as Charles F.F. Abbott, a carpenter.

- 4. Structural condition of the building. On March 1, 2012 a Building Deficiency Inspection Report was compiled. The list of deficiencies is not necessarily all the deficiencies present at the time and would not substitute for a team inspection and Code Compliance Report. A more comprehensive report would be necessary for staff to review for compliance with the rehabilitation guidelines. Staff is not aware of any other structural evaluations that have been completed. Staff has received a voicemail from the owner, Matt Miller, on May 30<sup>th</sup>, stating his intent to order a code compliance report and post the performance bond.
- 5. The economic viability of the structure. According to DSI Code Enforcement, the rehabilitation costs of the structure exceed \$100,000 and demolition costs are estimated to exceed \$15,000. For 2012, Ramsey County estimates the land value at \$87,100 and the building value at \$59,900. The property is sited on a 40 ft. wide by 117 ft. deep lot (4,680 sq. ft.).

- 6. In general, the Secretary of the Interior's Standards for Rehabilitation recommend against removing buildings that are important in defining the overall historic character and destroying historic relationships between buildings and open space. Given the architectural integrity of 451 Selby Avenue and its contribution to a collection of similar neighboring houses, HPC staff finds that the building reinforces and contributes to the architectural and historic character of the Hill Historic District and its removal would destroy the historic relationship of the built environment along the north side of Selby Avenue.
- 7. HPC staff finds that the proposed demolition of the building at 451 Selby Avenue will have a negative impact on the Hill Historic District. A vacant lot will have a negative impact on the historic district and the loss of historic fabric is irreversible.

### F. STAFF RECOMMENDATION:

Based on the findings, staff recommends denial of a potential demolition permit application.

# Historic Sites Survey Storical Society Saint Paul Heritage Preservation Commission

Ramsey County Historical Society

1. 3	Street Address/451 W. Selby Avenue	
2 1	District/village: 8 3. Common name:	ann±ng
Α .	Historic name: Charles F.F. Abbott House 5. Original use: House	vil
6	Present Use: House 7. Access: Yes X No Limited	village #:
8	Period of construction: 1883 9. Style: Victorian	# C
n	# of bays: 2 11. # of stories: 2 12. Roof style: Intersecting gable	<
.0.	Roof covering: Asphalt shingles; paper. Dormer style & #: 1 gable	∞
.5 -	Chimney style, material, location & #: Interior brick	
	Type of fenestration: 1/2, 1/1 rectangular	1
	Type of foundation: Limestone	Location:
10	Structural system/main exterior wall covering: X Wood frame: X clapboardshingle	tic ess
LO.	aluminum asbestos Brick: stretcher bond American bond header bond	ı. ğ
	Stone:random rubblecoursed rubblerandom ashlarcoursed ashlar	
	Type of stone/brick or other bonding pattern:	45
	Concrete blockCast concreteStuccoTerra cottaCurtain wall	1 W.
	or (mate) Othors	S
	Other significant details: Asymmetrical design. Bargeboards with squared ends with other significant details: Asymmetrical design. Bargeboards with squared ends with incised roundels. Band of rectangular windows on 2nd story of main facade. Fishscale shingled overhang between floors. Pediment over entrance is all that remains of the original front porch. Transom over door. Rectangular bay window flanking entrance.	elby Avenue
20.	Integrity of Design:basically intact & unaltered <u>x</u> altered slightly	
		1
	alterations & additions more apparent than originaloriginal design not apparent	
21.	Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.	
22.	Physical condition of building:ExcellentGood X FairPoorDeteriorated  Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.	Name:
22.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	Name:
22.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	
22.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	
<ul><li>22.</li><li>23.</li><li>24.</li><li>25.</li></ul>	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	Name: Charles F.
22. 23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	"
22. 23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	"
22. 23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	"
22. 23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	"
23. 24. 25. 26.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
23. 24. 25. 26.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
23. 24. 25. 26.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
22. 23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
23. 24. 25.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	: Charles F.F. Abbott
23. 24. 25. 26.	Physical condition of building:ExcellentGood _X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of cross street  Side of street:North acricultural _X residential _X commercialindustrial suburban _X Other: Near Gurling Glub Small stone retaining wall.  Threats to site: Additional comments:	Charles F.F. Abbott
23. 24. 25. 26. 27. 28.	Physical condition of building:ExcellentGood X FairPoorDeteriorated Additions and alterations: Part of porch has been removed. Vertical sheathing in gable ends. New windows. Some ornamentation removed.  If a corner lot, describe:NWNESESW corner of	Charles F.F. Abbott

33.	Architect/engineer:	Charles E	F. Abbott	151 Selby
34.	. Builder/contractor:	Charles F	.F. Abbott	151 Selby
	Present Owner:	,		
	Address:			37. Date source: Building Permit
38.	. Legal Description: Lot 28, B.	lock 2, S	elby, McClu	ng & Van Meter's Addition
	-			
39.	. Building Permit #: 68			
40.	. Location of architect's drawings:			
41.	. On National Register? Yes X	No 42.	National R	egister potential?Yes _XNo
43.	. HPC/local historic site?Yes X	No 44.	Local desi	gnation potential?Yes _x_No
45.	. In historic district? X Yes	No 46.	Historic d	istrict potential? X Yes No
	Which? H.P.C. District		If yes, ex	plain rationale: Possible extension
				onal Register District
47.	. Historical background: This hou	se was bu	ilt in 188:	3 by and for Charles F.F. Abbott, a

- 47. Historical background: This house was built in 1883 by and for Charles F.F. Abbott, a carpenter who lived here.
- 48. Level of significance: \_\_xLocal \_\_State \_\_National
- 49. Statement of significance: This deteriorated house is one of the oldest in the area.
- 50. Sources of information:

1885-86 Polk's St. Paul City Directories.

Photographs



# REPORT OF INSPECTOR.

Work was commenced on the within described building on the 2 2 aday of Cet 2 2 2 188 & and of Cet 2 2 2 aday and has been done in accordance with the plans and specifications except as noted below.

Respectfully submitted,

REMARKS

Detailed Statement of Specifications	NEW BUILDINGS.	No. 6 8 Submitted Oct 22, 188 3	LOCATION	Lot 2 8 Block 2 of My	Malauthan	Owner Architect "	Builder	The same of the same	
MEMORANDA.							•		

# Detailed Statement of Specifications for the Erection of Buildings.

1.	What side of Street or Avenue? Mooth Clare Cellby
	Between Assurable and Muckesbern Streets.
2.	Lot 28 Block 2 of Selly McCling Have Mete
3.	Size of Lot? No. of feet front. # O No. of feet rear # O No. of feet deep . / * C
4.	Size of Building? No. of feet front 12.6
	No. of stories in height. 2 cellar, basement and attic. No. of feet in height, from curb level
	to highest point. 3.0 addition 10×14
5.	What will building cost (exclusive of lot)? \$ 2300
6.	What will be the depth of foundation walls, from curb level or surface of the ground?
7.	Will foundation be laid on earth, rock, timber or piles?
8.	What will be the base—stone or concrete?
9.	What will be the size of piers?
LO	What will be the sizes of the base of piers?
11.	What will be the thickness of foundation walls? 20 and of what materials
	constructed? Morre
12	What will be the thickness of cellar walls? 2inches; basement walls?inches.
13.	What will be the thickness of walls in 1st story?
	story?inches; 4th story?inches; from thence to top?inches;
•	and of what material to be constructed?
14.	Whether independent or party walls? If party walls, give thickness thereofinches.
15.	With what material walls to be coped?
16.	What will be the materials of front?
	thickness of front ashlar and thickness of backing thereof.
17.	Will the roof be flat, peaked or Mansard?
18.	If flat, height of rear and side walls above roof?
19.	Height of division and party walls above roof.
20.	What will be the materials of roofing?
21.	What will be the means of access to the roof?
22.	What will be the materials of cornices?
23.	If there are to be skylights, of what material constructed?

Are skylights provided with proper screens?..... Is the building to be provided with iron shutters or blinds?.... Give size and material of floor joists: 1st tier 2 x / O 2d tier 2 x 3d tier x 4th tier x 5th tier 6th tier ceiling tier 2 x 6 roof tier 2 x 4. State distance from centers on 1st tier 16 inches; 2d tier 6 inches; 3d tier inches; 4th tier inches; 5th tier inches; 6th tier.....inches; ceiling tier.....inches; roof tier.....inches. 27. If floors are to be supported by columns and girders, give the following information: size and material of girders under 1st floor....x....under upper floors...x. size and material of columns under 1st floor.....x. under upper floors .....x. 28. What will be the distance of wooden girders from all flues and steam pipes?..... State if hot air, steam or other furnaces..... 30. If the front, rear or side walls are to be supported, in whole or in part, by girders or lintels, give definite particulars ..... 31. If girders are to be supported by brick piers and columns, state the size of piers and columns..... Will a fire escape and standpipe be provided? For what purpose is building constructed? Any boiler house or room connected with building? If so, distance of any woodwork from boiler, breeching or smoke conductor and dome. Of what material floor constructed? If any hoistways, state how protected... How are the stairways to be constructed, and of what materials? How are the wall partitions to be constructed, and of what materials?.... ...... 40: How are the floors of cellars, basement and other stories to be constructed?..... 41. How are the ceilings to be constructed? Seells O Castlo Will all materials and workmanship be in accordance with the requirements of the law? Architect Address

Address


Address

Builder.

Plumber

BUILDING I	PERMI	T INDEX C	ARD-c	ITY OF ST	. PAUL DEPA W. 1	RTM	ENT C	OF PA	RKS, PLAY	GROUNDS	AND PL	BLIC	BUILD	INGS-	-DIVI	SION C	F BUIL	DING	INSPE	cciio
STREET	el	By !	ave.	10.4	5/ Ex	TYPE STRI	OF JCTU	re <i>L</i>	wig	WARD		.: _LOT₄	28	_BLO	CK_	2	DDITIO	AN	N	
ORIGINA	L-CO	NSTRUC	TION	PER	MITS o	WNI	ERC		F. 19	BBO	77		CENSI _TRAC	us r			CENSU BLOCK		ACT	
TYPE OF PERMIT	DATE ISSUED	PERMIT NUMBER	DATE LAST IN- SPECTION	CONT	RACTOR	ES	TIMA		TYPE OF STRUC- TURE	TYPE OF CON- STRUCTION	1-1	デー	8.3	C.	F,	466	5022	-		
BUILDING	1/8/83	68	10/22/22	C.F.F	a. Borr	2	300		BL 5.	T.C.	NO. OF	STORI	I 9.	TH, FE	ET LEN	STH,FEE	*	7.FEE	T FLOO	RSFA
PLASTER- ING	95/	B all	10/22/	C.F.	<u> </u>	-000			BLS.			ERICR	LATH	EX	TERIO	PLAS	A STATE OF THE PARTY OF THE PAR	-	RICR L	АТН
	1 783	68	183	ABR	3017	<u> </u>	<u> </u>		<u>X</u>	1100	P.L	<u>L.</u>	1_	VDE	OF 14	ODK	DONE			-
											CODE	No.	CODE			NO.	CODE	<del></del>	CODE	E NO
ELECTRICAL	1 1			,												-				
		*.		,					İ	' '		7								
				`.				.		İ	_	1								-
HEATING STEAMFITTING					<del>Kindana kanasana kanas</del>						mentel trittidaelolesse							-	 	
WARMAIR		·		-													4		·	1
	1	,						-		l	CODE	NO.	LO. CO	DE	10.1.0	CODE	NO.L	<b>о.</b> с	ODE N	10. L
	I	<del></del>			***************************************		ļ							- 1				-		
PLUMBING								<i>t</i>				Ť		-		l	-  -	_		- -
						ļ							<u> </u> :	.						_ _
		•																	.	
ELEVATOR		netiFesetthitelettingr <sub>e</sub> ngangen verse osenenggen ee		Consequencia e e e e e e e e e e e e e e e e e e e	-				Enusemble of Control of the Control	-	TY	PE	P	OWER	NO.	OF CAR	S NO. OF	LDGS		-
		•			<u>.</u>															
	· ·	The same of the selection of the selecti	-		Marie Communication Communicat		CONTRACTOR OF THE PARTY OF THE	Device and the last	*******************************	,	***************************************						<u>.</u>			-
AGE OF BUIL JANUARY 1		S OF			STIMATED BUILDIÑG															* * *

		,	-		RECOR	D OF SUB	PE	R	MIT	rs								
	TYPE OF PERMIT	PERMIT NUMBER	DATE ISSUED	DATE LAST IN-		CONTRACTOR	ES.	COST	TED	TYPE STRUC-	T/PE COV-	PURPOSE OF			PE OF			Ť
	Build	30441	71-13	5, 201,0.4	C.J.J. allett	C.T. allto			50	TURE Bとび 20	STR' CT'N	BLD1	BL BL	NO.	CODE	NO.	CODE	NO.
	Build	32440	11-13 8-16 1978 1927		C. J. abbott		<del> </del>		50	30 BLS X	1100	AL2	84		80			-
	PM	6557	1527	_	Red Resty L	Dairy Elder			50	BIS	77.00	INSL	PA	l,-	-			
	Bed.		5/11/35		Q. E Krueger	O.E. Krueger			50	BLS X BLS 13	Te 1100	BLDI	BL	-			<u> </u>	$\Box$
	Steam	18925	0/5/37		Joe France	adamson B.		7	675	BLX	TE 1100	Insl	H5	1	H5 A8	12		7
	Blag	70603	9/26/4		Jac. Frager	O Warmania	lad		135			sel						
940000	Thirth	98616	5/12/42		J. 7 ruger	Cookman	ļ	<u>~</u>	80									
	0.00	121958	730		wind the	a) Shackitan		-	35~		8.00	8 ann	2000	202	22			
	HUXOV.	14(15)	75		of trager	Helson			65						<u> </u>	-		
							<u> </u>	<del></del>									<u></u>	
						***************************************	-											-
								٠.				,		-				-1
		-														$\neg$		_
					·													
	·																	
								-										
						_												
	, k														-			$\dashv$
									_									
Section 1													.					
														_		-		-
																_		



Insurance Maps of St. Paul, Minnesota - Volume 1 Publisher: Sanborn Map Co. 1903 revised through August 1925 Handwritten notations by St. Paul Planning Commission Digital Images Created 2007 by Historical Information Gatherers, Inc.

