






Item 7 - Old likely lead painted base moldings were removed from the entire house when the new floors were installed in kitchen and living room – my son decided that the kitchen did not need a base molding






























"A Tradition of Quality for Over 75 Years"




HEATING • COOLING • ELECTRICAL

1400 Concordia Avenue • St. Paul, MN 55104 • 651-646-7381

8/24/2011

A4 Kevin 77541

Paul Ellringer & Ben Ellringer 613 Bay St Saint Paul, MN 55102 (651) 696-0267 Paul



Equipment Info	armation				
			7		
Dendinet		126321		Sautal Managers	Phase Immedian

Product	Model	Serial Number	Date Installed	Warranty End
Lennox Air Conditioner			-01/04/1983	
Leanox Furnace	G23Q3/4-100-6	5800A56732	01/01/2000	

Bryant Jumace 355 AAV542080FASA Sp 1006 A05549 Bryant A/C 124ANA024000 BAAA Sh 2906E38308

	sched & OK D - Delective C -	Cleaned R = Replaced	CFC HANDLIN	NG REPORT
[] PILOT [[] SENSOR [] IGNITER [] GAS VALVE [] PRIMARY CONTROL [] TRANSFORMER [] RELAY [] MANIFOLD PRES [] GAS INPUT [] WATER PRES [] BLOWER AMP []] BURNERS [] COMB. BLOWER [] ILIMIT CONTROL [] IVENT AND DRAFT [] ITHERMOSTAT [] BLOWER & MOTOR [] I	FILTER COND. FAN MOTOR CONDENSER COIL EVAP. COIL HUMIDIFIER COMPRESSOR 4. 8 EAC 7] SUC LINE PRES] SA TEMP/AC] RA TEMP/AC] COND. FAN AMP	REFRIGERANT RECOLBS SYSTEM EVACUATED LEAK CHECK REFRIGERANT ADDELBS	R22410 D YES NO YES NO YES NO ED YES NO
COMMENTS:		Service Type: Regular PMC FA. Go to 16	ular 40 Scheffer 1st then ove	er to this house.
		PART	PART#	AMOUNT
RECOMMENDATIONS:		PART PMC A ARCMOO	PART# 1/C 4 14 25 4	AMOUNT 149 89