

Other (Fence Variance, Code Compliance, etc.)

APPLICATION FOR APPEAL

Saint Paul City Council - Legislative Hearings

RECEIVED

OCT 10 2017

OCT 02 2017

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

Ve need the following to process your appeal: CITY CLERK CITY CLERK	
\$25 filing fee (non-refundable) (payable to the City of Saint Paul) (if cash: receipt number) Copy of the City-issued orders/letter being appealed Attachments you may wish to include This appeal form completed Walk-In OR Mail-In for abatement orders only: Email OR Fax	HEARING DATE & TIME (provided by Legislative Hearing Office) Tuesday, October 17, 2017 Time 11:30 Location of Hearing: Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 1108 Western Aven City: St. Paul State: MM Zip: 55117	
appellant/Applicant: Lance Holder Email lanceKoholder Egmail.com	
Phone Numbers: Business Residence Cell 612-598-9173	
ignature: 10-2-2017	
Name of Owner (if other than Appellant): José + Rose Felix	
Tailing Address if Not Appellant's: 205 W. 15 St., Minnzapolis, MN 55403	
hone Numbers: Business Residence	Cell <u>6/2-598-9173</u>
What Is Being Appealed and Why? Attachments Are Acceptable	
Vacate Order/Condemnation/ Revocation of Fire C of O I need more	time to fulfill the order.
Summary/Vehicle Abatement I recently came into the job but have	
Fire C of O Deficiency List/Correction Just agriced the time to do so due to Code Enforcement Correction Notice other clients. I do not want this to reflect	
Vacant Building Registration poorly on whe elieut, thank you.	
The street is the Alle.	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

October 9, 2017

JOSE AND ROSE FELIX 2744 TIMBER CT GRAND PRAIRIE TX 75052-4443

Revocation of Fire Certificate of Occupancy and Order to Vacate

RE:

1108 WESTERN AVE N

Ref. # 12886

Dear Property Representative:

Your building was inspected on October 6, 2017, for the renewal of the Certificate of Occupancy. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 40.06 of the Saint Paul Legislative Code.

A re-inspection will be made on November 1, 2017 at 10:00 AM or the property vacated.

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

DEFICIENCY LIST

- 1. All Units CO Alarms MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturers instructions.-Provide carbon monoxide alarms to all units except Unit 3 & 8.
- 2. Exterior Building SPLC 34.09 (1)(2), 34.33 (1) Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-There is a section of the brick wall that has large and running cracks.

One of the black support post at the front of the building is missing. (New)

- 3. Exterior Front Entry Door SPLC 34.33 (3) Repair and maintain the door in good condition.-The frame and trim for the front entry door is cracked, damaged and has chipped pieces. The door does not latch.

 The front entry door has been damaged and has a very large crack on it. The latch is now missing.(New).
- 4. Exterior Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.-The window frame for the mechanical room has been rebuilt and the glass has a hole in the corner.
- 5. Exterior Window Screens SPLC 34.09 (4), 34.33 (3) -Provide or repair and maintain the window screen.-There are windows screens that are ripped, torn and have bent frames.
- 6. Exterior Key Box MSFC 506.2 Install a fire department key-box near the main entry at 7 feet high. Provide the correct type of key box and contact the Fire Department Communication Center at 651-266-7702 to provide the correct keys and lock the box.
- 7. Interior Fire Doors MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:

 One hour. The fire doors in the building do not self-close, do not latch, have broken and bent strike plates and have loose door knobs.

 One hour. The East fire door has a cracked a kick plate.
- 8. Interior Fire Extinguisher MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.-The fire extinguishers are expired.
- 9. Interior First Floor Hallway MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-The smoke alarm is missing.
- 10. Interior Front Stairway SPLC 34.10 (7), 34.17(5) Repair and maintain the floor in an approved manner.-There is a piece of a stair runner that is ripped and is a tripping hazard.
- 11. Interior Guardrails SPLC 34.10 (3), 34.34(2) Repair or replace the damaged guardrail in an approved manner.-The interior guardrails are loose and unsecure.
- 12. Interior Laundry Room Door MSFC 1008.1.9.3 Remove unapproved locks from the exit doors. The door must be open-able from the inside without the use of keys or special knowledge or effort.-There is a doubled-keyed deadbolt on the laundry room door. This is a new lock and was installed recently.
- 13. Interior Laundry Room MMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work requires a permit(s). Call DSI at (651) 266-8989.

 There is one dryer machine that has the wrong type of exhaust duct connected.

 The metal exhaust duct has the wrong type of tape on it.

- 14. Interior Laundry Room MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-The cover for the ceiling fan light fixture is missing. (New).
- 15. Interior Mechanical Room MSFC 703.1, 1106.1 Provide and maintain fire rated floor and/or ceiling construction with approved materials and methods. This work may require a permit(s). Call DSI at (651) 266-8989. The minimum rating must be:-One hour. There is still a large opening in the ceiling in the mechanical room over the equipment.
- 16. Unit 01 Bathroom SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.-There is an unapproved light fixture that is sitting on top of the vanity light fixture. This light fixture is not properly installed. It must be properly installed under permit or remove the light fixture.
- 17. Unit 01 Bathroom SPLC 34.14 (3), MPC 4714.01 (T) Provide and maintain a window or approved ventilation system in all bathrooms.-The bathroom fans makes a rubbing sound.
- 18. Unit 01 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-20 minutes. The entry door does not self-close.
- 19. Unit 01 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-The hard-wired smoke alarm is missing. The hard-wired smoke alarm must be maintain as hard-wired.

 Note: There is a temporary battery--powered smoke alarm in unit.
- 20. Unit 01 Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.-The left window does not open.
- 21. Unit 02 Bathroom SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is black spots and cracks on the bathroom walls.
- 22. Unit 02 Bathroom SPLC 34.14 (3), MPC 4714.01 (T) Provide and maintain a window or approved ventilation system in all bathrooms.-The bathroom fan makes a loud rattling sound.
- 23. Unit 02 Bedroom MSFC 1030.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path..-There are items behind one of the bedroom doors.
- 24. Unit 02 Door SPLC 34.33 (3) Repair and maintain the door in good condition.-The door knob for the bathroom door is loose.
- 25. Unit 02 Living Room MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-The outlet behind the entertainment center is missing.

- 26. Unit 02 Living Room MSFC 605.4 Discontinue use of all multi-plug adapters.-There is a multi-plug adapter behind the entertainment center.
- 27. Unit 03 Bedroom MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-There is broken and damaged outlet in one of the bedrooms.
- 28. Unit 03 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-20 minutes. The trim for the entry door has come off.

 One of the bedroom doors has a broken strike plate.
- 29. Unit 03 Kitchen SPLC 34.10 (7) Repair and maintain the cabinets in an approved manner.-One of the kitchen drawer is missing.
- 30. Unit 03 Left Bedroom MSFC 308.1.2 No person shall throw or place, or cause to be thrown or placed, a lighted match, cigar, cigarette, matches, or other flaming or glowing substance or object on any surface or article where it can cause an unwanted fire.-There is a used cigarette and other tobacco product sitting on the left bedroom window sill.
- 31. Unit 03 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.

 The hard-wired smoke is missing and has a working battery-powered smoke alarm in it place. Provide and maintain the hard-wired smoke alarm.

 In the left bedroom, the battery-powered smoke alarm is missing. Smoke alarms must be maintain inside and outside the bedrooms.
- 32. Unit 03 Throughout MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Throughout the apartment there are light switches and outlets that are missing the covers.
- 33. Unit 04 Bathroom SPLC 34.33 (3) Repair and maintain the door in good condition.— There are doors in this apartment that is cracked, damaged and missing strike plates.
- 34. Unit 04 Bathroom & Kitchen SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition. The bathroom faucet sink is loose and unsecure.
 The cover for the bath tub drain line is missing.
 The kitchen faucet has loose and damaged knobs.
- 35. Unit 04 Door SPLC 34.33 (3) Repair and maintain the door in good condition.-The patio door is hard to open and close and the door does not latch.
- 36. Unit 04 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-20 minutes. The entry door does not self close and is damaged with a large crack on the side.

- 37. Unit 04 Floors SPLC 34.10 (7), 34.17 (5) Repair and maintain the ceiling in an approved manner.-The carpeting in the apartment has dark stains and markings. The carpet also has sections that is ripped, damaged and unsecure.
- 38. Unit 04 Stove SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.-The handle bar for the oven is missing.
- 39. Unit 05 Bathroom SPLC 34.10 (4), 34.34 (3) Provide a bathroom impervious to water.-The tile shower wall is smashed in.
- 40. Unit 05 Bathroom SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is cracked and damages to the bathroom wall.
- 41. Unit 05 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-The hard-wired smoke alarm is expired and is not functioning properly. Replace and maintain the hard-wired smoke alarm.

 Note: There is a battery-powered smoke alarm in the unit.
- 42. Unit 06 Bedroom MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-There is a broken outlet in the right bedroom.
- 43. Unit 06 Bedroom Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.-There is a bedroom window sill and frame that is cracked and damaged.
- 44. Unit 06 Doors SPLC 34.33 (3) Repair and maintain the door in good condition.There are doors in this apartment that are unable to close, have loose and missing strike plates, cracked and damaged frames, loose door knobs and hardware and other damages.
- 45. Unit 06 Entry Door MSFC 1008.1.9.2 Hardware Height. Door handles, pulls, latches, locks and other operating devices shall be installed 34 inches(864 mm) minimum and 48 inches (1219 mm) maximum above the finished floor. Lock used only for security purposes and not used for normal operation are permitted at any height.-The latch on the entry door is too high.
- 46. Unit 06 Floors SPLC 34.10 (7), 34.17(5) Repair and maintain the floor in an approved manner.-There are spots on the carpet and linoleum that is ripped and damaged.
- 47. Unit 06 Light Fixtures MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-There are light fixtures in the apartment that is missing the cover, including over the kitchen sink.
- 48. Unit 06 Wall SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is a hole on the wall behind one of the bedroom doors.

- 49. Unit 07 SPLC 34.19 Provide access to the inspector to all areas of the building.Provide access to this unit and ensure that is has working smoke and carbon monoxide alarms.
- 50. Unit 08 Bathroom SPLC 34.08 (1), 34.34 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.-The is black spots and mildew developing on the shower wall and along the bottom of the bathroom window.
- 51. Unit 08 Bathroom SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.-The bath tub faucet is leaking.

 The toilet is loose.
- 52. Unit 08 Bedroom Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window frame.-The top portion of the bedroom window frame is cracked and damaged and has chipping and peeling paint.
- 53. Unit 08 Door SPLC 34.33 (3) Repair and maintain the door in good condition.-The bathroom door is cracked and damaged and the door knob is loose and unsecure.
- 54. Unit 08 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-20 minutes. The entry door does not self-close, has a loose door knob and the trims around the door is cracked and damaged.
- 55. Unit 08 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-The hard-wired smoke alarm is missing. The hard-wired connection is covered by a non-working battery-powered smoke alarm. All hard-wired smoke alarms must be maintain as a hard-wired smoke alarm.
- 56. Unit 08 Wall SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is a large hole on the living room wall.
- 57. Unit 09 Bathroom SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.-The toilet is loose.
- 58. Unit 09 Walls SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is a hole on the left bedroom wall behind the door.
- 59. SPLC 40.06. Suspension, revocation and denial. (A) Grounds for revocation. The fire code official may, in writing, issue a notice to the owner(s) and known interested parties of the city's suspension or revocation of a fire certificate of occupancy issued under the provisions of this code, or deny an application therefor:

 (3) If it is found upon inspection of the fire code official that the building or
 - (3) If it is found upon inspection of the fire code official that the building or occupancy is in violation of provisions of this or other applicable safety codes, ordinances, rules and regulations;
 - -The Fire Certificate of Occupancy has been revoked due to long-term noncompliance and unable to gain access to apartments. The Legislative Hearing Officer has set a vacate date of November 1, 2017.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 8:00 - 9:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Efrayn Franquiz Fire Inspector

Ref. # 12886



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul. Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

September 19, 2017

JOSE AND ROSE FELIX 2744 TIMBER CT GRAND PRAIRIE TX 75052-4443

RE: RE-INSPECTION FIRE CERTIFICATE OF OCCUPANCY WITH DEFICIENCIES 1108 WESTERN AVE N

Ref. # 12886

Dear Property Representative:

Your building was re-inspected for the Fire Certificate of Occupancy on August 4, 2017. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected immediately.

A re-inspection will be made on October 6, 2017 at 3:15PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

DEFICIENCY LIST

- 1. All Units CO Alarms MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions.-Provide carbon monoxide alarms to all units except Unit 3 * 8
- 2. Exterior Building SPLC 34.09 (1)(2), 34.33 (1) Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.-There is a section of the brick wall that has large and running cracks.
- 3. Exterior Front Entry Door SPLC 34.33 (3) Repair and maintain the door in good condition.-The frame and trim for the front entry door is cracked, damaged and has chipped pieces. The door does not latch.

An Equal Opportunity Employer

- 4. Exterior Parking Surface SPLC 34.08 (7) All parking spaces shall be paved with asphalt, concrete, or durable dustless surfacing. Before any existing spaces may be paved, site plan approval must be obtained as specified in the St. Paul Zoning Code. Contact DSI Zoning at 651-266-8989.-The parking surface has sections that are in disrepair and have large cracks and deteriorated asphalt.
- 5. Exterior Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.-The window frame for the mechanical room has been rebuilt and the glass has a hole in the corner.
- 6. Exterior Window Screens SPLC 34.09 (4), 34.33 (3) -Provide or repair and maintain the window screen.-There are windows screens that are ripped, torn and have bent frames.
- 7. Exterior Key Box MSFC 506.2 Install a fire department keybox near the main entry at 7 feet high. Provide the correct type of key box and contact the Fire Department Communication Center at 651-266-7702 to provide the correct keys and lock the box.
- 8. Interior Fire Doors MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:

 One hour. The fire doors in the building do not self-close, do not latch, and have loose door knobs.

 One hour. The East fire door has cracked a kick plate.
- 9. Interior Fire Extinguisher MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.-The fire extinguishers are expired.
- 10. Interior First Floor Hallway MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-The smoke alarm in the first floor hallway is of the incorrect type. Provide a battery-powered smoke alarm.
- 11. Interior Front Stairway SPLC 34.10 (7), 34.17(5) Repair and maintain the floor in an approved manner.-There is a piece of a stair runner that is ripped and is a tripping hazard.
- 12. Interior Laundry Room MMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work requires a permit(s). Call DSI at (651) 266-8989.

 There is one dryer machine that has the wrong type of exhaust duct connected. The metal exhaust duct has the wrong type of tape on it.
- 13. Interior Mechanical Room MSFC 703.1, 1106.1 Provide and maintain fire rated floor and/or ceiling construction with approved materials and methods. This work may require a permit(s). Call DSI at (651) 266-8989. The minimum rating must be:-One hour. There is still a large opening in the ceiling in the mechanical room over the equipment.

- 14. Unit 01 Bathroom SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.-There is an unapproved light fixture that is sitting on top of the vanity light fixture. This light fixture is not properly installed. It must be properly installed under permit or remove the light fixture.
- 15. Unit 01 Bathroom SPLC 34.14 (3), MPC 4714.01 (T) Provide and maintain a window or approved ventilation system in all bathrooms.-The bathroom fans makes a rubbing sound.
- 16. Unit 01 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-20 minutes. The entry door does not self-close.
- 17. Unit 01 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.

 The hard-wired smoke alarm is missing. The hard-wired smoke alarm must be maintain as hard-wired.

 Note: There is a temporary battery--powered smoke alarm in unit.
- 18. Unit 01 Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.-The left window does not open.
- 19. Unit 02 Bathroom SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is black spots and cracks on the bathroom walls.
- 20. Unit 02 Bathroom SPLC 34.14 (3), MPC 4714.01 (T) Provide and maintain a window or approved ventilation system in all bathrooms.-The bathroom fan makes a loud rattling sound.
- 21. Unit 02 Bedroom MSFC 1030.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit path..-There are items behind one of the bedroom doors.
- 22. Unit 02 Door SPLC 34.33 (3) Repair and maintain the door in good condition.-The door knob for the bathroom door is loose.
- 23. Unit 02 Living Room MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-The outlet behind the entertainment center is missing.
- 24. Unit 02 Living Room MSFC 605.4 Discontinue use of all multi-plug adapters.-There is a multi-plug adapter behind the entertainment center.
- 25. Unit 03 Bedroom MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-There is broken and damaged outlet in one of the bedrooms.

- 26. Unit 03 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:20 minutes. The trim for the entry door has come off.One of the bedroom doors has a broken strike plate.
- 27. Unit 03 Kitchen SPLC 34.10 (7) Repair and maintain the cabinets in an approved manner.-One of the kitchen drawer is missing.
- 28. Unit 03 Left Bedroom MSFC 308.1.2 No person shall throw or place, or cause to be thrown or placed, a lighted match, cigar, cigarette, matches, or other flaming or glowing substance or object on any surface or article where it can cause an unwanted fire.-There is a used cigarette and other tobacco product sitting on the left bedroom window sill.
- 29. Unit 03 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area. The hard-wired smoke is missing and has a working battery-powered smoke alarm in it place. Provide and maintain the hard-wired smoke alarm. In the left bedroom, the battery-powered smoke alarm is missing. Smoke alarms must be maintain inside and outside the bedrooms.
- 30. Unit 03 Throughout MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Throughout the apartment there are light switches and outlets that are missing the covers.
- 31. Unit 04 Bathroom SPLC 34.33 (3) Repair and maintain the door in good condition.

 There are doors in this apartment that is cracked, damaged and missing strike plates.
- 32. Unit 04 Bathroom & Kitchen SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.

The bathroom faucet sink is loose and unsecure.

The cover for the bath tub drain line is missing.

The kitchen faucet has loose and damaged knobs.

- 33. Unit 04 Door SPLC 34.33 (3) Repair and maintain the door in good condition.-The patio door is hard to open and close and the door does not latch.
- 34. Unit 04 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-20 minutes. The entry door does not self close and is damaged with a large crack on the side.
- 35. Unit 04 Floors SPLC 34.10 (7), 34.17 (5) Repair and maintain the ceiling in an approved manner.-The carpeting in the apartment has dark stains and markings. The carpet also has sections that is ripped, damaged and unsecure.

- 36. Unit 04 Stove SPLC 34.12 (2), SPLC 34.36 (1) Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.-The handle bar for the oven is missing.
- 37. Unit 05 Bathroom SPLC 34.10 (4), 34.34 (3) Provide a bathroom impervious to water.-The tile shower wall is smashed in.
- 38. Unit 05 Bathroom SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is cracked and damages to the bathroom wall.
- 39. Unit 05 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area. The hard-wired smoke alarm is expired and is not functioning properly. Replace and maintain the hard-wired smoke alarm.
 Note: There is a battery-powered smoke alarm in the unit.
- 40. Unit 06 Bedroom MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989.-There is a broken outlet in the right bedroom.
- 41. Unit 06 Bedroom Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window in good condition.-There is a bedroom window sill and frame that is cracked and damaged.
- 42. Unit 06 Doors SPLC 34.33 (3) Repair and maintain the door in good condition. There are doors in this apartment that are unable to close, have loose and missing strike plates, cracked and damaged frames, loose door knobs and hardware and other damages.
- 43. Unit 06 Entry Door MSFC 1008.1.9.2 Hardware Height. Door handles, pulls, latches, locks and other operating devices shall be installed 34 inches(864 mm) minimum and 48 inches (1219 mm) maximum above the finished floor. Lock used only for security purposes and not used for normal operation are permitted at any height.-The latch on the entry door is too high.
- 44. Unit 06 Floors SPLC 34.10 (7), 34.17(5) Repair and maintain the floor in an approved manner.-There are spots on the carpet and linoleum that is ripped and damaged.
- 45. Unit 06 Light Fixtures MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-There are light fixtures in the apartment that is missing the cover, including over the kitchen sink.
- 46. Unit 06 Wall SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is a hole on the wall behind one of the bedroom doors.
- 47. Unit 07 SPLC 34.19 Provide access to the inspector to all areas of the building. Provide access to this unit and ensure that is has working smoke and carbon monoxide alarms.

- 48. Unit 08 Bathroom SPLC 34.08 (1), 34.34 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.-The is black spots and mildew developing on the shower wall and along the bottom of the bathroom window.
- 49. Unit 08 Bathroom SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.

The bath tub faucet is leaking.

The toilet is loose.

- 50. Unit 08 Bedroom Window SPLC 34.09 (4), 34.33 (3) Repair and maintain the window frame.

 The top portion of the bedroom window frame is cracked and damaged and has chipping and peeling paint.
- 51. Unit 08 Door SPLC 34.33 (3) Repair and maintain the door in good condition.-The bathroom door is cracked and damaged and the door knob is loose and unsecure.
- 52. Unit 08 Entry Door MSFC 703.1 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-20 minutes. The entry door does not self-close, has a loose door knob and the trims around the door is cracked and damaged.
- 53. Unit 08 Smoke Alarm MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.

 The hard-wired smoke alarm is missing. The hard-wired connection is covered by a non-working battery-powered smoke alarm. All hard-wired smoke alarms must be maintain as a hard-wired smoke alarm.
- 54. Unit 08 Wall SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is a large hole on the living room wall.
- 55. Unit 09 Bathroom SPLC 34.11 (1), MSBC 2902.1, SPLC 34.35 (1), MPC 301.1 Repair or replace and maintain all parts of the plumbing system to an operational condition.-The toilet is loose.
- 56. Unit 09 Walls SPLC 34.10 (7), 34.17 (5) Repair and maintain the walls in an approved manner.-There is a hole on the left bedroom wall behind the door.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 8:00 a.m. - 9:30 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Efrayn Franquiz Fire Inspector Ref. # 12886