

CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 
 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

# **Code Compliance Report**

December 10, 2012

DANIEL RUBINO C/O SCOTT MONTGOMERY 7029 20TH AVE S CENTERVILLE MN 55038 \* \* This Report must be Posted on the Job Site \* \*

Re: 1323 Edmund Ave File#: 12 114105 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on November 19, 2012.

Please be advised that this report is accurate and correct as of the date December 10, 2012. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from December 10, 2012. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING Inspector: Jim Seeger Phone: 651-266-904	BUILDING	Inspector: Jim Seeger	Phone: 651-266-9046
---	----------	-----------------------	---------------------

- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Air-seal and insulate attic/access door.
- Provide major clean-up of premises.

Re: 1323 Edmund Ave December 10, 2012 Page 2

<b>BUILDING</b>	Inspector: Jim Seeger	Phone: 651-266-9046
<ul> <li>Install Small</li> </ul>	a Dataatara/Carbon Manavida Dataa	store par MN Concernation Code and the

- Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Install address numbers visible from street and on the alley side of garage.
- Provide durable, dustless parking surface as specified in the zoning code.
- Remove trees which are against foundation of home and garage.
- Openings in stair risers must be less than 4 inches.
- Install handrail at front steps and at rear deck steps to code.
- Remove ceiling covering above 2nd floor bathtub by sky light and repair insulation and roofing.
- Install sink for bathroom.
- Remove garage or totally rebuild to code.
- A building permit is required to correct the above deficiencies.

# ELECTRICALInspector: Dave BlankPhone: 651-266-9035

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- Verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Close openings in junction boxes with knockout seals, and/or junction box covers
- Properly strap cables and conduits in basement.
- Provide one (1) light for each 200 square feet in unfinished basement.
- Install/replace GFCI receptacle in basement/first/second bathroom adjacent to the sink
- Ground bathroom light in second floor bathroom.
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Install hard-wired, battery backup smoke detector and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Properly wire exterior lights at back door
- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage
- Replace all painted-over receptacles.
- Install box extensions on paneled walls.
- Replace meter socket.
- Install Main Bonding Jumper.
- Based on repair list, purchase permit for at least 8 circuits
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.

Re: 1323 Edmund Ave December 10, 2012 Page 3

### ELECTRICAL Inspector: Dave Blank

• All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

## PLUMBING Inspector: Rick Jacobs Phone: 651-266-9054

- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Piping provide water piping to all fixtures and appliances (MPC 1700)
- Basement Water Piping repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement Water Piping run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement Gas Piping dryer gas shutoff; connector or piping incorrect (MFGC 411)
- Basement Gas Piping replace improper piping or fittings (MFGC 411)
- Basement Gas Piping run dryer vent to code (MFGC 614.1 614.7)
- Basement Soil and Waste Piping add appropriate hangers (MPC 1430 Subp. 4)
- Basement Soil and Waste Piping improper connections, transitions, fittings or pipe usage (MPC 2420)
- Basement Soil and Waste Piping replace the floor drain cover or clean out plug (MPC 1300)
- Basement Soil and Waste Piping unplugged or open piping; back pitched piping (MPC 1000)
- Basement Laundry Tub fixture is broken or parts missing (MPC 0200 0.)
- Basement Laundry Tub provide a vacuum breaker for the spout (MPC 2000 B)
- Basement Laundry Tub unvented (MPC 0200 E)
- Basement Laundry Tub waste incorrect (MPC 2300)
- First Floor Gas Piping range gas shut off; connector or piping incorrect (MFGC 411)
- First Floor Sink incorrectly vented (MPC 2500) and waste incorrect (MPC 2300)
- First Floor Sink First Floor Sink water piping incorrect (MPC 0200 P.)
- Second Floor Lavatory faucet is missing, broken, or parts missing (MPC 0200.P.)
- Second Floor Lavatory fixture is broken or parts missing (MPC 0200 0.)
- Second Floor Lavatory waste incorrect (MPC 2300)
- Second Floor Lavatory water piping incorrect (MPC 0200 P.)
- Second Floor Toilet Facilities reset the toilet on a firm base (MPC 0870)
- Second Floor Tub and Shower Provide access (MPC 0900)
- Second Floor Tub and Shower faucet is missing, broken or parts missing (MPC 0200. P.)
- Second Floor Tub and Shower provide stopper (MPC 1240)
- Exterior The black gas piping must be protected from the elements.
- Exterior Lawn Hydrants Requires backflow assembly or device (MPC 2000)
- All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4715 & Chapter 326, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and the Saint Paul Regional Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul under an approved permit.

Phone: 651-266-9035

Re: 1323 Edmund Ave December 10, 2012 Page 4

## HEATING Inspector: Kevin Chapdelaine Phone: 651-266-9042

- Clean and Orsat test boiler burner. Check all controls for proper operation. Provide documentation from a licensed contractor that the heating unit is safe
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed. Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- Provide heat in every habitable room and bathrooms.
- Repair or replace radiator valves as needed.

## **ZONING**

- 1. This property is in a(n) R4 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

### Notes:

- See attachment for permit requirements and appeals procedure.
- Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.) If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger, Code Compliance Officer Phone: 651-266-9046 Email: james.seeger@ci.stpaul.mn.us

JLS:ml Attachments