

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Inside of entry door
Frame assembly damaged and poor fit
1 hour required assembly compromised
20 minute door compromised

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Continuation of first picture

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



2nd Floor corridor

Owner's repair for hole looking into the bathroom of a first floor unit

Does not meet one-hour separation requirements for materials or application

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Replacement window not finished. Insulation showing at lower sash/sill

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Missing unit number

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Unit entry door frame

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Ceiling fixture had wiring running along the ceiling at previous inspection. Property owner rewired without a permit, running wiring above ceiling.

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Entry door does not fit in frame.

Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015



Date: June 12, 2015
File #: 13 - 252825
Folder Name: 1052 ROSS AVE
PIN: 282922340015

