



Opening at the 3rd floor. No door but evidence of a past plywood door and hasp locking arrangement. No landing on stair side where door opening is.



Freight elevator at 3rd floor



Opening at 3rd floor taken from stair side.



Opening at 2nd floor. No door but a landing on both sides of the opening.



A second open stair that goes from 3rd to 2nd floor.



Opening at 1st floor. No landing or lobby area. Next picture is an enlargement of the bottom right of this picture.



Enlargement of framing adjacent to plaster/terrazzo construction.



1st floor opening from the stair side.



Basement opening



Structural elements of exterior loading dock which also serves as a means of egress from the building.



Enlargement showing the lack of footing.



Structural elements of exterior loading dock which also serves as a means of egress from the building.



Enlargement showing one structural member out of plumb.

Photos taken by Angie Wiese, Supervisor of Commercial Section
1/6/2014