
Date: February 05, 2010 File #: 10 - 019633

Folder Name: 591 MACKUBIN ST PIN: 362923230004





North and west sides, posting



South and east sides, postings



East side, postings



Kitchen floor



Kitchen ceiling



1st floor middle room

Date: February 05, 2010 File #: 10 - 019633

Folder Name: 591 MACKUBIN ST

PIN: 362923230004



Kitchen



Kitchen, ice covered appliance, wall, floor



Improper trap repair, leaking

HP District: Property Name: Survey Info:



Kitchen ceiling




Damaged ceiling 2nd floor bathroom



Stair way to basement, flooding, no hand rail

Date: February 05, 2010 File #: 10 - 019633

Folder Name: 591 MACKUBIN ST PIN: 362923230004



Basement storage



Basement storage



Bubbling, flaking paint

HP District: Property Name: Survey Info:



Improper post installation, improper spill tube, no handle on gas shut off



Basement storage



Front postings

Date: February 05, 2010 File #: 10 - 019633

Folder Name: 591 MACKUBIN ST

PIN: 362923230004



Rear posting

HP District: Property Name: Survey Info: