





More damage exterior west wall. Window pulling away from the brick






















Interior East wall damage with carious cracking. Note the piping.











PIN: 012823310114