

**Date:** February 16, 2010  
**File #:** 10 - 108002  
**Folder Name:** 579 LEXINGTON PKWY S  
**PIN:** 102823410033

**HP District:**  
**Property Name:**  
**Survey Info:**



**East and south side**



**Posting**



**Inside screen porch**



**Open electrical outlet**



**West side house**



**South side house**

Date: February 16, 2010  
File #: 10 - 108002  
Folder Name: 579 LEXINGTON PKWY S  
PIN: 102823410033

HP District:  
Property Name:  
Survey Info:



Unfinished window installation, boarded on interior



North side



Large separating crack



Cracking in masonry



Large separating shifting crack



Rotted eaves house and garage, rotted wall

**Date:** February 16, 2010  
**File #:** 10 - 108002  
**Folder Name:** 579 LEXINGTON PKWY S  
**PIN:** 102823410033

**HP District:**  
**Property Name:**  
**Survey Info:**



**Large separating shifting crack**



**East side house and garage**