

**Date:** February 05, 2010  
**File #:** 10 - 019633  
**Folder Name:** 591 MACKUBIN ST  
**PIN:** 362923230004

**HP District:**  
**Property Name:**  
**Survey Info:**



**North and west sides, posting**



**South and east sides, postings**




**East side, postings**



**Kitchen floor**



**Kitchen ceiling**



**1<sup>st</sup> floor middle room**



**Date:** February 05, 2010  
**File #:** 10 - 019633  
**Folder Name:** 591 MACKUBIN ST  
**PIN:** 362923230004

**HP District:**  
**Property Name:**  
**Survey Info:**



**Kitchen**



**Kitchen ceiling**



**Kitchen, ice covered appliance, wall, floor**



**Damaged ceiling 2<sup>nd</sup> floor bathroom**



**Improper trap repair, leaking**



**Stair way to basement, flooding, no hand rail**



Date: February 05, 2010  
File #: 10 - 019633  
Folder Name: 591 MACKUBIN ST  
PIN: 362923230004

HP District:  
Property Name:  
Survey Info:



Basement storage



Improper post installation, improper spill tube, no handle on gas shut off



Basement storage



Basement storage



Bubbling, flaking paint



Front postings

**Date:** February 05, 2010  
**File #:** 10 - 019633  
**Folder Name:** 591 MACKUBIN ST  
**PIN:** 362923230004

**HP District:**  
**Property Name:**  
**Survey Info:**



**Rear posting**