July 17, 2017

City of St. Paul Department of Safety and Inspections 375 Jackson Street, Suite 220 St. Paul, Minnesota 55101 RECEIVED
JUL 18 2017
CITY CLERK

To Whom It May Concern:

Enclosed is the mold remediation report required to have the inspection for 855 South Lexington Parkway South.

I have enclosed the Performance deposit if after the inspection we decide to remediate the property.

Please send me by return mail a copy of the performance bond payment.

Regards,

Gary M. Johnson

GMJ/sn

CC: Ed Pardee

Mai Vang



Fire / Water Restoration • Mold Remediation • Asbestos Abatement Soda Blasting • Drug Lab Decontamination • HVAC System Cleaning

June 20, 2017

Mr. Gary Johnson Arizona RECEIVED
JUL 18 2017
CITY CLERK

Re: Mold Remediation Status at 855 South Lexington Blvd, St Paul, MN

Please consider this letter to be a project status of the mold remediation at the above referenced address.

DCI has completed the bulk removal of the building materials with visual mold growth. The exposed building materials that remain have been disinfected. The disinfecting also includes the basement block foundation walls.

Due to the severity of the rot on the upper level, backside walls, DCI halted the final remediation process per our discussion. The final process would have included HEPA vacuuming and another disinfecting of the walls, ceilings and floors, and coating the exposed walls cavities with a stain blocker/sealer.

If you have any questions, please call me at (763) 229-7204.

Respectfully Submitted,

Charles Wilcox

Charles Wilcox President