

APPLICATION FOR APPEAL

Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

RECEIVED

SEP 0 7 2010

CIA	Y ÇLERK			
The City Clerk needs the following to process your appeal:		YOUR HEARING Date and Time:		
\$25 filing fee payable to the City of S				
(if cash: receipt number)		Tuesday, Sept- 14		
Copy of the City-issued orders or let	ter which			
are being appealed		Time_\`30 Q.M.		
Attachments you may wish to includ	le	Location of Hearing:		
This appeal form completed		Room 330 City Hall/Courthouse		
Address Being Appealed:				
Number & Street: 1637 Conwan	1 Street City: 5	r. Paul State: MN Zip: 55106		
Appellant/Applicant: Mary Marrin Email Mary emarrin@msn.com				
Phone Numbers: Business <u>(65/1776-1315</u> Residence Cell				
Signature: Date: 9/7/2010				
Name of Owner (if other than Appellant): NAWW NAVELLO				
Address (if not Appellant's): 1700 Liv	ringston Ave	Ste 109 WSP, MWS5118		
Phone Numbers: Business USI-775-13 I Stesidence Cell				
What Is Being appealed and why? Attachments Are Acceptable				
Vacate Order/Condemnation/	See Alfra	diod		
Revocation of Fire C of O	the national			
 Summary/Vehicle Abatement 	# 10 1/0/1mm			
□ Fire C of O Deficiency List	Bedvooms at The time the			
☐ Fire C of O: Only Egress Windows	Fire C of O: Only Egress Windows Way and I Was			
Code Enforcement Correction Notice ACM AND TOLD TO DUT LANGES				
Uscant Building Registration to the Windows for an escape				
KOther route for fire and thus was do				
□ Other	DVIDY to T	hen Moving in Mans		

Revised 8/20/2010

Ransey, 1700 Livingston

□ Other



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

August 27, 2010

MARY E MARRIN 1700 LIVINGSTON AVE SUITE 102 WEST ST PAUL MN 55118

FIRE INSPECTION CORRECTION NOTICE

RE:

1637 CONWAY ST

Ref. #109082

Residential Class: C

Dear Property Representative:

Your building was inspected on August 20, 2010 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on September 27, 2010 at 12:30pm.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

- 1. 2nd Level Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling and walls in an approved manner.
- 2. 2nd Level Bathroom SPLC 34.10 (4), 34.33 (3) Provide a bathroom floor impervious to water.-Caulk around the tub to ensure water tightness.
- 3. 2nd Level Bathroom MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.-Replace the cracked/broken cover plate.

- 4. 2nd Level Bathroom MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.-Replace the covers on the florescent light fixtures.
- 5. 2nd Level Southwest Bedroom MSFC 605.5 Discontinue use of extension cords and multi-plug adapters used in lieu of permanent wiring.
- 6. Basement Bathroom SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Repair/replace the missing/inoperable sink stopper.
- 7. Basement Bathroom SPLC 34.10 (7), 34.33 (6) Repair and maintain the ceiling in an approved manner.
- 8. Basement Bathroom SPLC 34.11(5), 34.34(2), SPC 4715.0200Q Provide adequate hot water between 120 degrees F and 130 degrees F.-Provide hot water to the basement bathroom sink.
- 9. Basement Dryer UMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter. This work will require a permit(s). Call DSI at (651) 266-8989. Replace the crushed flexible exhaust duct. Remove the excessive accumulation of lint from behind and around the dryer.
- 10. Egress Windows 2nd Level Northwest and Southwest Bedrooms MSFC1026.1 Provide and maintain an approved escape window from each sleeping room. The minimum size must be 5 square feet of glazed area with a minimum of 24 inches of openable height and 20 inches of openable width. With a finished sill height not more than 48 inches. This work may require permit(s). Call DSI at (651) 266-9090. Refer to the Escape Windows for Residential Occupancies handout for more information.

2nd Level Northwest Bedrooms (Awning)

15h x 38w - Openable

21h x 36w - Glazed

Sill height is 55 inches from the floor, 32 inches from the top ladder rung. Ladder is affixed to the wall and floor.

2nd Level Southwest Bedroom (Awning)

15h x 47w - Openable

21h x 44w - Glazed

Sill height is 56 inches from the floor, 30 inches from the top ladder rung.

<u>Note:</u> Both windows open to a width of 20 inches but you have to get through the 15 inches to make it to the 20 inch width.

11. Lower Level - Stairway - SPLC 34.10 (3), 34.33(2) - Repair or replace the damaged handrail in an approved manner.-Secure the loose handrail.

- 12. Lower Level West Bedroom SPLC 34.09 (3), 34.32 (3) Repair and maintain the window lock.
- 13. Main Floor Kitchen MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
- 14. Main Floor Rear Entry Door SPLC 34.09 (3), 34.32 (3) Repair and maintain the door frame.-Repair/replace the damaged door frame. Replace all missing door trim. Provide a weather-tight seal around the door.
- 15. Upper Floor Room SPLC 34.09 (3), 34.32 (3) Repair and maintain the door in good condition.-Secure the loose closet door handle.
- 16. Upper Floor Room NEC 440.13 For cord-connected equipment such as room air conditioners, household refrigerators and freezers, drinking water coolers, and beverage dispensers, a separable connector or an attachment plug and receptacle shall be permitted to serve as the disconnecting means. The appliance must plug directly into a permanent outlet.-A/C unit must be plugged directly into a permanent outlet. Remove and discontinue the use of the multi-plug adapter.
- 17. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 18. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: wayne.spiering@ci.stpaul.mn.us or call me at 651-266-8993 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Wayne Spiering Fire Inspector

Reference Number 109082

FOSTER CARE LICENSING FIRE INSPECTION RAMSEY COUNTY HUMAN SERVICES 160 East Kellogg Boulevard, St. Paul, MN 55101

Name	Home Phone	Mark Dham		
·		Work Phone		
IMD-Conway	(651)775-1315			
Address 1637 Conway	Requested by Karen Allen	Date 8/4/05		
		0/4/03		
If Corporate Corp. Name	Contact Person	Phone		
	Mary Warrin	(651) 775-1315		
This person has applied to provide: Adult Foster Care Chid Foster Care				
Reason for Referral: New License Re-license				
Address Change Foster Person already in Home				
# of Adults in Home # of Natural Children in Home: # of Foster Persons				
In accordance with the provisions of MN Rules 9545.0010 and 9555.6105 and 9555.6105 to 9555.6275 and MN Statute 299F.011, MN Uniform Fire Code, inspection of the above premises was completed and the following violations and/or deficiencies were noted requiring corrective action:				
Address must be clearly visible on exterior of the house that are clearly identifiable from the street. Provide a minimum 2A10BC rated fire extinguisher, placed in kitchen area. Must be serviced and tagged annually. Smoke detectors on each level including the basement. If 4 or more unrelated occupants: hard-wired smoke detectors that are inter-connected on each floor are required and smoke detectors are required in each bedroom. Must provide bedroom space for own family and the foster care as follows: For Child Foster Care: Bedroom for 1 child must be 75 sq. ft, bedroom for 2 children must be 100 sq. ft. For Adult Foster Care: Bedroom for 1 resident must be 80 sp. ft. with a 7 ½ ft. ceiling, for 2 residents must be 120 sq. ft. with a 7 ½ ft ceiling. All sleeping rooms must have an escape window, openable area 5.7 sq. ft. The sill height can be no more than 48" from the floor.				
Exit doors and windows are not obstructed and are easily opened from the inside. Handrails for all sets of steps with 3 or more risers. Guardrails and balustrades for decks and exposed stairways. Understairs storage area must have all exposed wood covered with 5/8" type X Gypsum Board, to provide required fire separation or remove all combustible storage from the area. Must have minimum 3 ft. clearance around furnace, water heater and electric panel. Furnace is checked regularly and maintained in good working condition.				
 Wiring appears safe. Extension cords may not be used in place of permanent wiring; approved surge protector allowed on computer/stereo. 				
Double cylinder locks (key required on both sides) on exit doors are prohibited. All interior doors can be unlocked from the inside and the key must be easily accessible to open the door from the outside in case of an emergency. Fireplaces, wood burning stoves and other hot surfaces are protected by guards to prevent burns. Residences with an attached garage must have a self-closing, tight fitting solid wood bonded core door at least 1-3/8 inch tick, or door with a fire protection rating of 20 minutes or greater and a separation wall consisting of 5/8 inch tick gypsum wallboard or its equivalent on the garage side between the residence and the garage. An operable battery flashlight and a battery radio or TV is located in the home. Gas and fueled equipment cannot be stored, operated or repaired within the residence. Propane tanks must be outside.				
Develop emergency fire escape plan; develop emergency storm shelter plan; conduct quarterly fire and storm drills. GFI is recommended in bathrooms with electrical outlets. Additional Requirements/Instructions:				
. 1	The same of the sa	- Albay		
Inspection Results:				
Meets the minimum requirements of MN	nspection Required Ca	Il Fire Inspector aten above deficiencies are corrected		
Signature of Inspector Ala Bill Signature of Applicant/Provider:				
· A				