

# **APPLICATION FOR APPEAL**

# Saint Paul City Council – Legislative Hearings

RECEIVED

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8585

NOV 02 2015

We need the following to process your appeal:	
\$25 filing fee (non-refundable) (payable to the City of Saint Paul) (if cash: receipt number	HEARING DATE & TIME  (provided by Legislative Hearing Office)  Tuesday, November 10 2015  Time 1.30 P. M.  Location of Hearing:  Room 330 City Hall/Courthouse
Address Being Appealed:	
Number & Street: 1818-1816 7th Street E City: St Paul State: MN Zip: 55119	
Appellant/Applicant: <u>LeeAnn Schray, Owner</u> Email <u>lschray@yahoo.com</u>	
Phone Numbers: Business 612-339-4229 Residence 651-485-8407 Cell 651-485-8407  Signature: Date: 10-27-2015  Name of Owner (if other than Appellant): Diane Schray, Co-owner	
Mailing Address if Not Appellant's: _790 Chippewa Ave, St. Paul, MN 55107	
Phone Numbers: Business <u>651-808-1373</u> Residence <u>651-808-1373</u>	08-1373 Cell <u>651-808-1373</u>
What Is Being Appealed and Why? Attachments Are Acceptable  Vacate Order/Condemnation/ Revocation of Fire C of O  Summary/Vehicle Abatement  Fire C of O Deficiency List/Correction Request extension on retaining wall repair and other concerns.  Code Enforcement Correction Notice	
United Teach Variance Code Compliance etc.)	



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

October 23, 2015

DDN FUTURES LLC 790 CHIPPEWA AVE ST PAUL, MN 55107-3554

## FIRE INSPECTION CORRECTION NOTICE

RE:

1818 7TH ST E

Ref. #114237

Residential Class: D

## Dear Property Representative:

Your building was inspected on October 20, 2015 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

#### A re-inspection will be made on December 7, 2015 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional reinspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

#### **DEFICIENCY LIST**

- 1. 1816 Basement MSFC 104.9, 1005.3.2.2 Remove the storage under the stairs or provide and maintain 1 hour fire resistive construction on the storage side of the stairs.
- 2. 1816 Basement SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass. The glass is missing for the last cellar window.
- 3. 1816 Basement SPLC 34.10 (3), 34.33(2) Repair or replace the unsafe stairway in an approved manner.-The stone being used as a step is unsafe and unapproved.

- 4. 1816 Basement SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner.

  The wall at the bottom of the stairs has a piece broken off of it.
- 5. 1816 Basement UMC 1346.703 Provide 30 inches clearance around all mechanical equipment.
- 6. 1816 Side Entry Door MSFC 1003.3.1.8 The maximum number of locks on unit doors is two. Remove all locks in excess of two.

  There are three locks on the side entry door.
- 7. 1816 Sleeping Area MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions. There is no carbon monoxide alarm in the area the tenant is sleeping in.
- 1816 Throughout Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.
  The door knob for the bedroom door is loose.
  The bathroom door does not fit properly within its frame and does not close properly.
  When trying to close the door the top corner hits the frame.
- 1816 Throughout SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved manner.
   In the basement there is a support beam that is cracked and damaged.
   In the bedroom closet, there are two holes on the ceiling.
- 10. 1816 & 1818 Basement MSMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989.-Unit 1816 Unit 1816 The wrong type of tape is being used for the dryer exhaust duct. Unit 1818 The dryer exhaust duct is loose from the machine at the bottom.
- 11. 1818 Basement MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes where missing.The cover for the light switch near the laundry machine is broken.
- 12. 1818 Basement NEC 110-26 Provide and maintain a minimum of 36 inches clearance in front of all electrical panels.
- 13. 1818 Basement MSFC 104.9, 1005.3.2.2 Remove the storage under the stairs or provide and maintain 1 hour fire resistive construction on the storage side of the stairs.

- 14. 1818 Basement UMC 1346.703 Provide 30 inches clearance around all mechanical equipment.
- 15. 1818 Basement SPLC 34.11 (5), 34.34 (2) Contact a licensed contractor to repair or replace the water heater. This work may require a permit(s). Call DSI at (651) 266-9090.
   The water connecting pipes being used are of the incorrect type. They are of the metal flexible type.
- 16. 1818 Bathroom Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.The bathroom door does not fit within its frame and does not close properly.
- 17. 1818 Bathroom SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition.-Repair or replace and maintain an approved private toilet. This work may require a permit(s). Call LIEP at (651) 266-9090.

  The toilet is loose and it is missing the toilet seat cover.
- 18. 1818 Kitchen MSFC 605.4 Discontinue use of all multi-plug adapters.
- 19. 1818 Kitchen SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.-There is an excessive amount of grease on the stove.
- 20. 1818 Near Bedroom MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.-The smoke and carbon monoxide detector (combination) alarm is not working.
- 21. 1818 Near Bedroom MN State Statute 299F.50 Immediately provide and maintain an approved Carbon Monoxide Alarm in a location within ten (10) feet of each sleeping area. Installation shall be in accordance with manufacturer's instructions. The smoke and carbon monoxide (combination) alarm is not working.
- 1818 Throughout SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner.The walls in the basement stairway are damaged with large cracks and holes.There is a hole on the wall behind the bedroom door.
- 23. 1818 Throughout SPLC 34.10 (7), 34.34 (6) Repair and maintain the ceiling in an approved manner.

  The ceiling in the basement stairway is damage with a large hole and cracks.

24. Exterior - Back of House - SPLC 34.08(5), 34.32(3) - All accessory structures including, but not limited to, detached garages, sheds and fences shall be maintained structurally sound and in good repair. Provide and maintain exterior unprotected surfaces painted or protected from the elements.

The wooden retaining wall is damaged and deteriorating.

25. Exterior - Front of House - MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.

The light fixtures at the front of the house are missing the covers.

26. Exterior - Throughout - SPLC 34.09 (1) b,c, 34.33 (1) b, c - Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.

There is an opening on the wall near the side entry door for 1816. There are chipping and peeling paint in various spots of the building.

The water gutter drain spout is disconnected.

27. Unit 1818 - Basement Door - MSFC 1003.3.1.8 - Remove unapproved locks from the unit doors. The door must be openable from the inside without the use of keys or special knowledge or effort.

There is a one-way deadbolt lock on the basement door.

28. Unit 1818 - Door - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.

The screen is torn for the front entry screen door.

The hardware for the front entry door is off.

- 29. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 30. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office. (RECEIVED)

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Efrayn Franquiz Fire Inspector

Reference Number 114237