

Photo #1:

Loose vinyl floor covering and swollen sub-flooring noted at the floor in the bedroom. Bedroom door no longer closes at this location.



Photo #2:

Thermal anomalies noted at the floor in the bedroom. Sub-flooring has bulged at this location.




Photo #3:

Loose vinyl floor covering and/or swollen sub-flooring noted at the hallway adjacent to the hallway bathroom.



Photo #4:

Thermal anomalies noted at the hallway floor adjacent to the bathroom.




Photo #5:

Protruding fasteners (nail/screw) head noted below the vinyl floor covering.



Photo #6:

Potential safety hazard noted at the adjacent units tub/shower access door. This area should be assessed by a fire and safety officer.

