


**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

This is the interior, east side wall during  
the second visit.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114



Interior East side wall, different angle.  
Note the piping. Second inspection.


**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Interior carriage house east side wall on  
second inspection.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Interior carriage house east side wall on second inspection.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Furnace inside the main house that was not working during second inspection.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Kitchen remodel in the main house not  
done under permit.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Kerosene heater in main house bedroom.




Date: January 17, 2019  
File #: 16 - 032685  
Folder Name: 455 GRAND AVE  
PIN: 012823310114

Kerosene heater in main house bedroom.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114


Propane heater inside main house  
bedroom.



Date: January 17, 2019  
File #: 16 - 032685  
Folder Name: 455 GRAND AVE  
PIN: 012823310114



A white door with a large window featuring a grid pattern. A 'CONDEMNED' sign is posted on the window. The door is set in a stone wall.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114