

Date: September 15, 2011
File #: 11 - 276186
Folder Name: 23 ISABEL ST W
PIN: 072822110042

HP District:
Property Name: O.A. Beal House
Survey Info: RA-SPC-1952



Unapproved exterior electrical wiring



Bulge in wall, deteriorated masonry



West side and garage



South side




Unfinished rehab



Front posting

Date: September 15, 2011
File #: 11 - 276186
Folder Name: 23 ISABEL ST W
PIN: 072822110042

HP District:
Property Name: O.A. Beal House
Survey Info: RA-SPC-1952



Posting for owner's agent



Open wall



Water damaged masonry



Unfinished rehab



Missing caulk, open wall



Missing caulk, open wall

Date: September 15, 2011
File #: 11 - 276186
Folder Name: 23 ISABEL ST W
PIN: 072822110042

HP District:
Property Name: O.A. Beal House
Survey Info: RA-SPC-1952



Shed



Electrical conductors coming out of the ground



East side