



APPLICATION FOR APPEAL

Saint Paul City Council – Legislative Hearings

310 City Hall, 15 W. Kellogg Blvd.

Saint Paul, Minnesota 55102

Telephone: (651) 266-8585

Fax: (651) 266-8574

Email: legislativehearings@ci.stpaul.mn.us

RECEIVED

OCT 28 2015

CITY CLERK

We need the following to process your appeal:

- \$25 filing fee payable to the City of Saint Paul (if cash: receipt number check # 6058)
 - Copy of the City-issued orders/letter being appealed
 - Attachments you may wish to include
 - This appeal form completed
 - Walk-In OR Mail-In
- for abatement orders only: Email OR Fax

HEARING DATE & TIME

(provided by Legislative Hearing Office)
Tuesday, November 3 2015

Time 1:30 p.m

Location of Hearing:

Room 330 City Hall/Courthouse

Address Being Appealed:

Number & Street: 1350 Maryland Ave City: St. Paul State: MN Zip: 55106

Appellant/Applicant: Ray Simpson Email Ray.simpson5@hotmail.com

Phone Numbers: Business 651-486-9404 Residence _____ Cell 651-983-9404

Signature: [Signature] Date: 10-28-15

Name of Owner (if other than Appellant): SIA

Mailing Address if Not Appellant's: 3624 Grovner Rd N, Oakdale, MN 55128

Phone Numbers: Business _____ Residence _____ Cell _____


What Is Being Appealed and Why?

Attachments Are Acceptable

- Vacate Order/Condemnation/
- Revocation of Fire C of O
- Summary/Vehicle Abatement
- Fire C of O Deficiency List
- Code Enforcement Correction Notice
- Vacant Building Registration
- Other (Fence Variance, Code Compliance, etc.)

See attachments

RAMAR Rentals



Phalen Apartments

Raymond J Simpson
3624 Grovner Rd N
Oakdale, MN 55128
Office Phone 651-486-9404
Cell Phone 651-983-9404
Fax 651-486-9404
Email raysimpson5@hotmail.com

October 28, 2015

To Whom It May Concern;

I am appealing the following specific items from the fire department correction notice dated October 19, 2015:

- Item 2. I may need more time depending on availability of painting contractors. The painting may not be able to be done until next spring.
- Item 4 which coincides with items 11, 12, and 13. On September 8, 2015 I received a correction notice based on a tenant complaint of mice in the unit. The notice stated the reinspection would be made on October 9th at 11am. I made the necessary repairs and had a professional exterminator out on September 17th. See attachment A. The inspector failed to show up for the Oct 9th 11am inspection at which time I emailed him a copy of the extermination report. Since these items had been addressed previously and the inspector failed to close this case in a timely manner, I do not believe they should be addressed on the fire inspection correction notice.
- Item 5. The closet knob was loose, which I re-tightened during the inspection. The building has 62 closet door knobs. I don't believe they should be called out for simply being loose.
- Item 10. Smoke detector is a combination fire/CO and is located in the living area. Empty bracket was old CO detector and no longer needed.
- Item 14. Maximum number of locks allowed on unit door is two. The door had a deadbolt lock and a hook and eye hardware also, totaling two locks. Doorknob was non-locking style.
- Item 16. Tenant consists of a Cambodian family that lines the cooking area with tin foil and replaces the foil in a timely manner.
- Item 23. Opening under door must be high enough to clear living room carpet so door will open/close freely. See Attachment B.
- Item 30. Carpet is wall to wall carpet. Tenant is a Karen family from Myanmar. Their family eats/socializes on the vinyl pad they installed over the carpet.
- Item 31. Opening on the door must be high enough to clear living room carpet so door will open/close freely. See Attachment C.
- Item 39. Test report was sent to the city dated October 7, 2015. I also hand delivered a copy of the report to the inspector on the day of the inspection. See Attachment D.

Sincerely yours,

Raymond Simpson



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-8951
Web: www.stpaul.gov/dsi

October 19, 2015

RAYMOND SIMPSON
3624 GROVNER RD N
OAKDALE, MN 55128

FIRE INSPECTION CORRECTION NOTICE

RE: 1350 MARYLAND AVE E
Ref. #16811
Residential Class: B

Dear Property Representative:

Your building was inspected on October 14, 2015 for the renewal of your Fire Certificate of Occupancy. Approval for occupancy will be granted upon compliance with the following deficiency list. The items on the list must be corrected prior to the re-inspection date.

A re-inspection will be made on December 1, 2015 at 1:00 PM.

Failure to comply may result in a criminal citation or the revocation of the Fire Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Fire Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

YOU WILL BE RESPONSIBLE FOR NOTIFYING TENANTS IF ANY OF THE FOLLOWING LIST OF DEFICIENCIES ARE THEIR RESPONSIBILITY.

DEFICIENCY LIST

1. Exterior - Front of Building - SPLC 34.09 (2), 34.32(2) - Repair or replace the damaged handrail in an approved manner. This work may require a permit(s). Call DSI at (651) 266-9090.-The left handrail at the front of the building is very loose.

2. Exterior - Throughout - SPLC 34.09 (1) b,c, 34.33 (1) b, c - Provide and maintain all exterior walls free from holes and deterioration. All wood exterior unprotected surfaces must be painted or protected from the elements and maintained in a professional manner free from chipped or peeling paint.
There is chipping and peeling paint on the white pillars.
The soffit at the front of the building has a lot of chipping and peeling paint and large yellow stains on it.
There is a large cement crack running along the edge of the foundation at the front of the building.
3. Interior - Hallway - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the walls in an approved manner.
There is a large crack on the wall near the exit door on the third floor on the South end.
4. Interior - Throughout - SPLC 34.10 (6), 34.33 (5) - Exterminate and control insects, rodents or other pests. Provide documentation of extermination.-Mouse droppings have been discovered in Units 103, 104 and 105.
5. Unit 102 - Throughout - SPLC 34.12 (2), SPLC 34.36 (1) - Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.
The knobs on the closet doors are loose.
6. Unit 102 - Throughout - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the walls in an approved manner.
There are markings and stains on the wall.
7. Unit 102 - Throughout - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the ceiling in an approved manner.-There are markings and stains on the ceiling.
8. Unit 103 - Kitchen & Bathroom - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the walls in an approved manner.
There is an opening in the wall underneath the kitchen & bathroom sink. The opening is large enough to allow insect and rodents to enter.
9. Unit 104 - Kitchen - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the walls in an approved manner.
There is an opening in the wall underneath the kitchen sink. The opening is large enough to allow insects and rodents to enter.
10. Unit 104 - Throughout - MN Stat. 299F.362 - Immediately provide and maintain a smoke detector located outside each sleeping area.-The smoke detector is missing and there is an empty bracket.
11. Unit 105 - Bathroom - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the cabinets in an approved manner.-Repair the opening at the bottom corner of the bathroom cabinet.

12. Unit 105 - NW Bedroom - SPLC 34.12 (2), SPLC 34.36 (1) - Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code. The radiator in the North West bedroom has an opening above it. Seal the opening to prevent insect and rodents from entering.
13. Unit 105 - Throughout - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the walls in an approved manner.
Repair, scrape and paint the wall in the living room closet. In the lower right corner there is hole covered by tape that needs to be fix.
Repair the holes and openings underneath the radiators throughout the apartment.
Cover the opening around the pipes underneath the bathroom sink.
14. Unit 106 - Entry Door – MSFC 1003.3.1.8 - The maximum number of locks on unit doors is two. Remove all locks in excess of two.-There is a hook and eye hardware on the entry door.
15. Unit 106 - Hallway - MSFC 1028.3 - Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit-way.-There is television on a table stand in the middle of the hallway that is obstructing the exit path.
16. Unit 106 - Kitchen - SPLC 34.10 (5), 34.33 (4), 34.16 - Provide and maintain interior in a clean and sanitary condition.-There is aluminum foil on the stove.
17. Unit 106 - Kitchen - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the walls in an approved manner.
There is an opening under the kitchen sink. The opening is large enough to allow insects and rodents to enter.
18. Unit 106 - SW & NW Bedroom - SPLC 34.09 (3), 34.33 (3) -Provide or repair and maintain the window screen.-The window screen in the South West bedroom is torn. The window screen in the North West bedroom is torn.
19. Unit 106 - SW Bedroom - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.-The strike plate for the South West bedroom door is damaged. The South West bedroom door is damaged with the surface of the door splitting away from the core and there is a hole on the door.
20. Unit 201 - Bedroom - SPLC 34.12 (2), SPLC 34.36 (1) - Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.
-The bedroom closet door is off the track.
21. Unit 201 - Bedroom Door - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.-There is unfinished repairs to the bedroom door.

22. Unit 202 - Bathroom - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the ceiling in an approved manner.-There is a large spot on the ceiling that has an unfinished repairs to it and there is chipping and peeling paint.
23. Unit 202 - Entry Door - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.-There is a large opening under the entry door.
24. Unit 202 - NE Bedroom - MSFC 1028.3 - Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit-way.-There are items behind the North East bedroom door.
25. Unit 204 - Patio Door - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.-The strike plate is missing for the patio door.
26. Unit 205 - NW Bedroom - SPLC 34.09 (3), 34.32 (3) - Repair and maintain the window in good condition.-The North West bedroom window does not open all the way.
27. Unit 205 - Throughout - MSFC 1028.3 - Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit-way.-The window in the North West bedroom is obstructed by a dresser and table.
The South West bedroom door has items behind the door.
28. Unit 205 - Throughout - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the ceiling in an approved manner.-There are yellow stain marks on the ceiling.
29. Unit 206 - NW Bedroom - MSFC 1028.3 - Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit-way.-The air conditioner in the North West bedroom is occupying the only egress window.
30. Unit 206 - Throughout - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the floor in an approved manner.-The carpeting in the living room is not installed properly and is a tripping hazard.
31. Unit 302 - Entry Door - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.-There is a large opening at the bottom of the entry door.
32. Unit 303 - Entry Door - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.-The entry door does not close and latch properly. The strike plate for both locks are dented and so is the frame.
33. Unit 305 - Bathroom - SPLC 34.14 (2) c - Provide or replace the duplex convenience outlet with ground fault protection within 3 feet of the basin on an adjacent wall in all bathrooms. This work may require a permit(s). Call DSI at (651) 266-9090.-The GFCI outlet in the bathroom does not trip when tested.

34. Unit 305 - Entry Door - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.-The entry door frame is cracked and it does not close properly.
35. Unit 305 - Throughout - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the walls in an approved manner.
There is excessive markings and stains on the walls. There are also spots on the wall that were repaired, but unfinished and not painted.
36. Unit 306 - Doors - Ext. Door SPLC 34.09 (3), 34.33 (3) - Repair and maintain the door in good condition.
The door knob for the North West bedroom door does not work properly. When turning the knob, the latch does not move.
The strike plate is missing for the patio door and for the South West bedroom door.
The entry door trim on the outside is coming loose from the frame.
37. Unit 306 - Throughout - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the walls in an approved manner.
There is excessive markings and stains on the wall.
There is a crack on the wall in the kitchen area.
38. Unit 306 - Throughout - SPLC 34.10 (7), 34.34 (6) - Repair and maintain the ceiling in an approved manner.-There are markings and stains on the ceiling.
39. SPLC 34.11 (6), 34.34 (3) - Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Efrayn Franquiz
Fire Inspector

Reference Number 16811



CITY OF SAINT PAUL

Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Telephone: 651-266-8989
Saint Paul, MN 55101-1806 Fax: 651-266-8951

September 8, 2015

RAYMOND SIMPSON
3624 GROVNER RD N
OAKDALE MN 55128

A

CORRECTION NOTICE - COMPLAINT INSPECTION

RE: 1350 MARYLAND AVE E
Ref. # 16811

Dear Property Representative:

An inspection was made of your building on September 8, 2015 in response to a referral. You are hereby notified that the following deficiency list must be corrected immediately.

A re-inspection will be made on October 9, 2015 at 11:00 AM.

Failure to comply may result in a criminal citation or revocation of the Certificate of Occupancy. The Saint Paul Legislative Code requires that no building shall be occupied without a Certificate of Occupancy. The code also provides for the assessment of additional re-inspection fees.

DEFICIENCY LIST

1. UNIT 105 - Throughout - SPLC 34.10 (6), 34.33 (5) - Exterminate and control insects, rodents or other pests. Provide documentation of extermination.-
2. Unit 105 - Bathroom - SPLC 34.10 (7), 34.33 (6) - Repair and maintain the cabinets in an approved manner.-Repair the opening at the bottom corner of the bathroom cabinet.
3. Unit 105 - NW Bedroom - SPLC 34.12 (2), SPLC 34.36 (1) - Repair and maintain all required and supplied equipment in an operative and safe condition to properly and safely perform their intended function in accordance with the provisions of the applicable code.
The radiator in the North West bedroom has an opening above it. Seal the opening to prevent insect and rodents from entering.

approved manner.
Repair, scrape and paint the wall in the living room closet. In the lower right corner there is hole covered by tape that needs to be fix.
Repair the holes and openings underneath the radiators throughout the apartment.
Cover the opening around the pipes underneath the bathroom sink.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: <http://www.stpaul.gov/cofo>

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of the original orders.

If you have any questions, email me at: Efrayn.Franquiz@ci.stpaul.mn.us or call me at 651-266-8955 between 7:30 a.m. - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

Efrayn Franquiz
Fire Inspector

Ref. # 16811

Customer's Signature

MINI BEST CONTROL, LLC • P.O. BOX 429 • Cambridge, MN 55008 • 651.307.6368

B

202



302





CITY OF SAINT PAUL
 Department of Safety & Inspection
 Fire Safety Inspection Division

HEATING SYSTEM TEST REPORT

(Use a separate form for each appliance)

375 Jackson Street Suite 220
 Saint Paul, MN 55101-1806
 (P) 651-266-8989 (F) 651-266-8951

Revised 07/2014

D



ADDRESS: 1350 Maryland #2

OWNER:

DATE: 10/7/15

Type of Heat:

Gravity Air Forced Air Gravity Hot Water Forced Hot Water
 Steam Unit Heater Space Heater Other:

Type of Fuel: Gas Oil Other:

Gas Design		Conversion	
Make of Burner: Knight		Make:	
Model: KBN285		Model:	
Serial: D06H10010897		Max BTU Rating:	
Input: 285,000		Make of Furnace:	
Equipment Venting Type:	<input type="checkbox"/> Atmospheric	<input checked="" type="checkbox"/> Induced Fan	<input type="checkbox"/> Other:

Total BTU input of all vented gas appliances per chimney: 285,000

Type of Chimney: Masonry Class B Other: PVC
 Type of Liner: None Metal Clay Tile
 Vent Connector Material: Type-C Type-B
 Combustion Air Supply Required? Yes No Installed? Yes No

Safety & Operating Control Tests:

Pilot/Flame Safeguard Operating Properly
 Limit(s) Operating Properly
 Operator(s) Operating Properly
 Low Water Cut-off Operating Properly
 All Controls Operating Properly

Yes	No
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Fuel Analysis/Flue Gas Analysis:

Vents properly without spillage
 Flame stays inside/Doesn't roll out
 Burner lights smoothly

Yes	No
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Combustion Analysis			Visual Inspection	
Stack Temperature	135.3	°F/Net	Fuel Piping System - Okay?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Oxygen	5.00	%	Vent Systems: Draft hood, Connector, Vent Chimney - Okay?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Carbon Dioxide	8.91	%	Heating Unit - Okay?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Carbon Monoxide	4	PPM		

Look At The Total Heating System Before You Leave: Yes No
 Does the system operate safely and properly? Yes No

COMMENTS:

Name of Licensed Contractor	Ray VinZant Plumbing and Heating DBA Orsat Testing	Address	1101 Snelling Ave N, Suite 200 Saint Paul MN 55104	Phone	651-888-2616
Person Doing the Test (Print):	Carlton Bradley	Signature:	<i>Carlton Bradley</i>		
Certificate of Competency from the City of Saint Paul for Appropriate Fuel:				20060000681	

THIS TEST IS VALID FOR ONE (1) YEAR



CITY OF SAINT PAUL
 Department of Safety & Inspections
 Fire Safety Inspection Division

HEATING SYSTEM TEST REPORT

(Use a separate form for each appliance)

375 Jackson Street Suite 220
 Saint Paul, MN 55101-1806
 (P) 651-266-8989 (F) 651-266-8951

Revised 07/2014

ADDRESS: 1350 Maryland #1

OWNER:

DATE: 10/7/15

Type of Heat:

Gravity Air
 Steam
 Forced Air Unit Heater
 Gravity Hot Water Space Heater
 Forced Hot Water
 Other:

Type of Fuel:	<input checked="" type="checkbox"/> Gas	<input type="checkbox"/> Oil	<input type="checkbox"/> Other:
Gas Design	Conversion		
Make of Burner: Knight	Make:		
Model: KBN210	Model:		
Serial: E06H10011988	Max BTU Rating:		
Input: 210,000	Make of Furnace:		
Equipment Venting Type:	<input type="checkbox"/> Atmospheric	<input checked="" type="checkbox"/> Induced Fan	<input type="checkbox"/> Other:

Total BTU input of all vented gas appliances per chimney: 210,000

Type of Chimney: Masonry Class B Other: PVC
 Type of Liner: None Metal Clay Tile
 Vent Connector Material: Type-C Type-B
 Combustion Air Supply Required? Yes No Installed? Yes No

Safety & Operating Control Tests:

	Yes	No	Fuel Analysis/Flue Gas Analysis:	Yes	No
Pilot/Flame Safeguard Operating Properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Vents properly without spillage	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Limit(s) Operating Properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Flame stays inside/Doesn't roll out	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Operator(s) Operating Properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Burner lights smoothly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Low Water Cut-off Operating Properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
All Controls Operating Properly	<input checked="" type="checkbox"/>	<input type="checkbox"/>			

Combustion Analysis			Visual Inspection	
Stack Temperature	174.4	°F/Net	Fuel Piping System – Okay?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Oxygen	5.10	%	Vent Systems: Draft hood, Connector, Vent Chimney – Okay?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Carbon Dioxide	8.85	%	Heating Unit – Okay?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Carbon Monoxide	84	PPM		

Look At The Total Heating System Before You Leave:

Does the system operate safely and properly?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--	-------------------------------------	--------------------------	--------------------------

COMMENTS:

Name of Licensed Contractor	Ray VinZant Plumbing and Heating DBA Orsat Testing	Address	1101 Snelling Ave N, Suite 200 Saint Paul MN 55104	Phone	651-888-2616
Person Doing the Test (Print):	Carlton Bradley	Signature:	<i>Carlton Bradley</i>		
Certificate of Competency from the City of Saint Paul for Appropriate Fuel:					20060000681

THIS TEST IS VALID FOR ONE (1) YEAR



Account Number _____ Route _____ Telephone Number () _____ Service Day 9-17-15 Service Charge 152.00 Time In 9 am Time Out _____

Service Address Phalen Apts
1350 Maryland
St. Paul

Billing Address 161.45

Darwin Pest Control will provide treatment for the following insects:

- Cockroaches
- Fleas
- Spiders
- Crickets
- Bed Bugs
- Pharo Ants
- Carpenter Ants
- Centipedes
- Ground Beetles
- Earwigs
- Asian Beetles
- Bees
- House Ants
- Silverfish
- Clover Mites
- Millipedes
- Indian Meal Moth
- Mice
- Pavement Ants
- Sow Bugs
- Box Elder Bugs
- Grain Beetles
- Rats

Pesticide Application Sites:

- | | | | | | | |
|---------------------------------------|--------------------------------------|---------------------------------------|--|--|--|--------------------------------------|
| Commercial | <input type="checkbox"/> Kitchen | <input type="checkbox"/> Produce | <input type="checkbox"/> Employee Lounge | <input checked="" type="checkbox"/> Kitchen | <input type="checkbox"/> Water Heater | <input type="checkbox"/> Porch/Patio |
| <input type="checkbox"/> Delicatessen | <input type="checkbox"/> Class Rooms | <input type="checkbox"/> Locker Room | <input type="checkbox"/> Refrigerator | <input checked="" type="checkbox"/> Bed Rooms | <input type="checkbox"/> Attic | <input type="checkbox"/> Garage |
| <input type="checkbox"/> Bakery | <input type="checkbox"/> Office | <input type="checkbox"/> Bar | <input type="checkbox"/> Stove | <input type="checkbox"/> Basement | <input type="checkbox"/> Living Areas | <input type="checkbox"/> Pet Areas |
| <input type="checkbox"/> Warehouse | <input type="checkbox"/> Equipment | <input type="checkbox"/> Dish washing | <input type="checkbox"/> Washer/Dryer | <input checked="" type="checkbox"/> Living Areas | <input checked="" type="checkbox"/> Exterior | <input type="checkbox"/> Wood Pile |
| <input type="checkbox"/> Stored Foods | <input type="checkbox"/> Restrooms | <input type="checkbox"/> Loading Dock | <input checked="" type="checkbox"/> Bathroom | | | |

Special service information and summary of work completed/Please allow 21 days to work

Mice control - Treated unit 103 & 105.
103 spider control - Allow 2 weeks before exclusion

Materials Used	%	Amount	EPA#	Mfg - Name	Method
TRANSPORT (Acetamiprid, Bifenthrin)	0.05		8033-109-279	FMC	
SUSPEND SC (Deltamethrin)	0.5		2001-04-155-0237	BASF	
TEMPRID SC (Cyfluthrin, Cyclopropanecarboxylate)	0.005		432-1483	BAYER	
TERMIDOR (Fipronil)	0.06		2003-04-220-0073	BASF	Exterior Only
PHANTOM (Chlorfenapri)	0.005		241-392	BASF	
GENTROL	0.9		2724-351	ZOECON	
PRECOR IGR (Methoprene)	1.0		2724-352-50809	SANDOZ	
DELTA DUST (Deltamethrin)	0.05		432-772	AGREVO	
MAX FORCE (Fipromil)	0.01		6428-2	MAX FORCE LABORATORIES	
CONTRAC (Bromadiolone) Brigand WB	0.005		12455-36	BELL LABORATORIES	
FINAL WBRODIFACOU	0.005		12455-89	BELL LABORATORIES	
<u>DITRAC (Diphacnone)</u>	0.05	<u>10 Stations</u>	12455-29	BELL LABORATORIES	

Service Guarantee

90 Days 120 Days _____ 180 Days _____

All treatments will conform to the laws of this State

Price Protection Plan \$ _____
Per Treatment After Initial Guarantee

12 Months _____ 24 Months _____ 36 Months _____

From Date OF Initial Treatment

AMOUNT PAID \$ 161.45

All returned checks are subject to a \$30.00 service fee

Dennis Dawson
State Certified Technician

20084987
Lic#

Customer's Signature _____ Date _____