

Date: September 23, 2014
File #: 14 - 331688
Folder Name: 295 SUMMIT AVE UNIT 3
PIN: 012823130294

HP District: HPL-Hill
Property Name:
Survey Info:



Deteriorated mortar joints



Water damage to masonry



Deteriorated mortar joints



Deteriorated mortar joints



Deteriorated mortar joints



Vertical cracking through brick face

Date: September 23, 2014
File #: 14 - 331688
Folder Name: 295 SUMMIT AVE UNIT 3
PIN: 012823130294

HP District: HPL-Hill
Property Name:
Survey Info:



Deteriorated masonry



Deteriorated mortar joints, movement in bricks




West side



South and east sides



North side



Deteriorated mortar joints

Date: September 23, 2014
File #: 14 - 331688
Folder Name: 295 SUMMIT AVE UNIT 3
PIN: 012823130294

HP District: HPL-Hill
Property Name:
Survey Info:



Deteriorated mortar joints



North side