



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

*375 Jackson Street, Suite 220
St Paul, Minnesota 55101-1806*

*Telephone: 651-266-8989
Facsimile: 651-266-9124
Web: www.stpaul.gov/dsi*

August 24, 2017

Re: Site Review
Code Compliance Inspection (Building)

Address: 694 Snelling Ave. No.

Deficiencies

Exterior:

- 1) Properly repair all exterior walls and siding. SPLC Sect. 34.03 (1) c.
- 2) Repair or replace doors and windows. SPLC Sect. 34.33 Sect.(1&3)
- 3) Repair or replace Siding and trim. SPLC Sect. 34.33 (1)

Interior:

- 1) Basement pipe wrap Asbestos to be abated . SPLC Sect. 34.22
- 2) Have Structural Engineer's report done on ceiling joist and joist for 1st. floor. Some appear over spanned and of poor quality. SPLC Sect. 34.34 (1)
- 3) Provide plans and spec's to DSI for building .
- 4) Repair all interior ceiling , walls and floors to code. SPLC Sect. 34.34 (6)

James Seeger
Code Compliance Officer