



## Saint Paul Fire Department FIRE INCIDENT DISPOSITION

INCIDENT NUMBER:	20-29601	DATE OF INCIDENT: 08-06-2020	
TIME OF INCIDENT:	0830 Hours	POLICE CASE #: N/A	
INVESTIGATOR(s):	Roy Mokosso		
INCIDENT ADDRESS:	914 Cook Ave E.		
OCCUPANT NAME:	Roxann Stumbo	PHONE: 651-502-5401	
OWNER NAME:	Stephanie Powers	PHONE: Unknown	
ADDRESS OF OWNER:	19610 Blackfoot St Nw Oak Grove MN 55303-8854		
PROPERTY DAMAGED:	Two Story Home	AREA OF ORIGIN: Entry	
DAMAGE ESTIMATE:	Building \$4,000	Vehicle \$N/A	Other (Describe) \$N/A
VALUE:	Building \$87,100	Vehicle \$N/A	Other (Describe) \$N/A
Damage Estimate CONTENTS ONLY:	\$500		
INJURY/DEATH (if yes, explain)	<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Detector Functioning: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler System Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown Sprinkler Heads activated: <input type="checkbox"/> Yes # <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown C.O Detector Present: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Unknown		
FIRE CAUSE CLASSIFICATION:	<input checked="" type="checkbox"/> Accidental <input type="checkbox"/> Juvenile/Incendiary <input type="checkbox"/> Incendiary <input type="checkbox"/> Child (under 10 years old) <input type="checkbox"/> Natural <input type="checkbox"/> Undetermined <input type="checkbox"/> Under Investigation		
SYNOPSIS:	<p>The Fire Department was called to the report of a fire in a residence. Crews arrived and found an electrical fire confined to an overhead light fixture in the entryway. Crews extinguished the fire and conducted overhaul. The occupant reported seeing flickering before witnessing the fixture "explode shooting sparks everywhere". The electrical panel had an unlabeled tripped breaker. The occupant had recently replaced the lightbulbs in the fixture. There were no working smoke detectors in the home. The point of origin was the light fixture. The ignition source was electrical current. The oxidant was normal atmospheric air. The first fuel ignited was filament. The action that brought these items together was most likely an electrical failure due to the use of higher wattage bulbs or older corroded wiring in the fixture. The classification of fire cause is accidental.</p>		
DISPOSITION:	<input checked="" type="checkbox"/> E-mail only <input type="checkbox"/> Hold Scene until approved <input type="checkbox"/> DO NOT DEMOLISH until approved <input checked="" type="checkbox"/> Scene Released <input type="checkbox"/> Analysis of Evidence Pending <input type="checkbox"/> Report to Follow		

