
Date: June 23, 2010 File #: 10 - 511807 Folder Name: 755 ANDREW ST PIN: 082822410090





South and east sides



West side, posting



East and north sides, garage



Garage, north and west sides



Front posting




South and east sides, posting

Date: May 10, 2011
File #: 10 - 511807
Folder Name: 755 ANDREW ST
PIN: 082822410090



Rot damaged window sash, trim, framing





Rot damaged door trim, threshold, framing



Locked gas meter





Deteriorated eave covering



Missing siding, open wall

Date: May 10, 2011
File #: 10 - 511807
Folder Name: 755 ANDREW ST
PIN: 082822410090



Garage



Electric meter buried in roof installation



Open siding, deteriorated siding, water damaged open eave

HP District: Property Name: Survey Info:



Open siding, water damaged open eave



Unapproved flashing



North and east sides house and garage

Date: May 10, 2011 File #: 10 - 511807 Folder Name: 755 ANDREW ST PIN: 082822410090



South and east sides

HP District: Property Name: Survey Info: