

NFIRS-1 Basic

B Location Type Street Address Intersection In Front Of Rear Of Adjacent To Directions	State 1006 Number	Month Prefix	Day 3RD Street o	Year r Highway	Station #4 (04) Station		-Street	Census 03-	tract: 45.00
US National Grid	Apt./Suite/Roo	om	Saint Pau	ıl		MN		106 Code	
C Incident Type 111-Building fire D Aid Given Or Receiv	ved			Alarm Arrival Controlle Last Unit	02 09 2021 ·	15:17 15:23	С	and Alarms 1 D3 Alarms Dist	3 trict
1 Mutual Aid Recci 2 Auto. Aid Recci 3 Mutual Aid Give 4 Auto. Aid Given 5 Other Aid Giver None	red Their FC	DID cident Num	Their State				E3 Specia 9244 ID#	l Studies	wn
F Actions Taken 87-Investigate fire ou Primary Action Taken			Suppress E Ot	us or Personne: Apparatu	0 0	Property Contents Pre-Incid	Required for known. Opt non-fires. 2 \$ 15,000.00 52 \$ 1,500.00 dent Values: 2 \$ 203,000.00 53 \$ 4,000.00	onal for all	None None

Completed Modules 2 - Fire 3 - Structure Fire 4 - Civilian Fire Cas. 5 - Fire Service Cas. 6 - EMS 7 - HazMat 8 - Wildland Fire 9 - Apparatus 10 - Personnel 11 - Arson	Fire Service 0 Civilian 0 H2 Detector Required for Confi	aths Injuries	1 - Natural 2 - Propano 3 - Gasolino 4 - Keroser 5 - Diesel F	e Gas e ne fuel / Fuel Oil old Solvents	Mixed Use Property Not Mixed 10 - Assembly Use 20 - Education Use 33 - Medical Use 40 - Residential Use 51 - Row Of Stores 53 - Enclosed Mall 58 - Business and Residential 59 - Office Use 60 - Industrial Use 63 - Military Use 65 - Farm Use 00 - Other Mixed Use
J Property Use Non Structures 131 Church, Place of 161 Restaurant or Ca Bar/Tavern or Ni 213 Elementary Scho 215 High School, Jun 241 College, Adult Ed 311 Nursing Home 331 Hospital	Worship Ifeteria ghtclub ol, Kindegarten ior High	341 Clinic, Clinic-Type 342 Doctor/Dentist Ol 361 Prison or Jail, Not 419 1- or 2-Family Dwel 429 MultiFamily Dwell 439 Rooming/Boardin 449 Commerical Hotel 459 Residential, Board 464 Dormitory/Barrac 519 Food and Bevera	fice Juvenile Elling ing g House or Motel d and Care ks	571 Gas or Ser 579 Motor Vel 599 Business 0 615 Electric-Go 629 Laborator 700 Manufacti 819 Livestock/	enerating Plant y/Science Laboratory uring Plant (Poultry Storage (Barn) lential Parking Garage
Outside 124 Playground or Pr 655 Crops or Orchard 669 Forest (Timberla 807 Outdoor Storage 919 Dump or Sanitar, 931 Open Land or Fie 936 Vacant Lot	d nd) e Area y Landfill	938 Graded/Cared for 946 Lake, River, Strear 951 Railroad Right-of 960 Other Street 961 Highway/Divided 962 Residential Street 981 Construction Site 984 Industrial Plant Ya	n Way Highway //Driveway		a Property Use code and you have NOT checked a
K2 Owner	I	П		П	ĺ
Local Option	Person/Enl	L tity Type Bu	siness Name (if app	olicable) Phone	Number
I	П		П	11	ı
Mr., Ms., Mrs.	First Name	MI	Last Na		Suffix
			Street	Turne	L
Number	Drofiv	Stroot or Highway			
L Number	Prefix	Street or Highway	, street	П	Juliix
Number L Post Office Box	Prefix	Street or Highway L Apt./Suite/Room		L City	
Post Office Box	Prefix	Apt./Suite/Room		LI L City	
	Prefix	Apt./Suite/Room		L City	
L Post Office Box L State L Remarks: Squad 1 was dispatch family residence. Saint I on the vacant/condemn Neighbors have been re basement of the buildir previous fire in the base door on bravo side (eas: An extinguished fire wa an ottoman with v-patch heat was generated to it. However the structure anaterials found in mult throughout the dwellin throughout the dwellin.	ed as the Fire Invest Paul Police were not ed list for multiple r porting suspicious a g. Squad 1 arrived a ment and began in t side) appeared for s noticed in the base erns noted on an adj melt blinds and ceiling appeared to be large iple areas of the hou	Apt./Suite/Room L Zip	Paul Police with of Safety and Inspand a young chil olice Officers states broken on side site. In the immenificant smoke state of the immenificant smoke state. The same the same state of the s	reports of a possible sections that the add that were supposed ing that there appeal alpha (north side) of diate area of original ining located on all ergoing renovation and burst causing significances.	e break-in at a single dress of concern has been edly living out of the ars to have been a f the residence and the on what appeared to be I three floors and enough with related construction nificant water damage
Post Office Box L State L Remarks: Squad 1 was dispatch family residence. Saint I on the vacant/condemn Neighbors have been re basement of the buildin previous fire in the base door on bravo side (eas: An extinguished fire wa an ottoman with v-pattheat was generated to I however the structure materials found in mult throughout the dwellin current Full primary narrative ca	ed as the Fire Invest Paul Police were not ed list for multiple r porting suspicious a g. Squad 1 arrived a ment and began in t side) appeared for s noticed in the base erns noted on an adj melt blinds and ceili appeared to be large iple areas of the hou g. A mattress was lo	Apt./Suite/Room Zip igation Unit to assist Saini ified by the Department of the complete of	Paul Police with of Safety and Inspand a young chil olice Officers states broken on side site. In the immenificant smoke state of the immenificant smoke state. The same the same state of the s	reports of a possible sections that the add that were supposed ing that there appeal alpha (north side) of diate area of original ining located on all ergoing renovation and burst causing significances.	e break-in at a single dress of concern has been edly living out of the ars to have been a f the residence and the on what appeared to be I three floors and enough with related construction nificant water damage
Post Office Box L State L Remarks: Squad 1 was dispatch family residence. Saint I on the vacant/condemn Neighbors have been rebasement of the building previous fire in the base door on bravo side (east An extinguished fire wan ottoman with v-patcheat was generated to I However the structure imaterials found in mult throughout the dwellincurrent Full primary narrative ca	ed as the Fire Invest Paul Police were not led list for multiple re porting suspicious a g. Squad 1 arrived a ment and began int is side) appeared for s noticed in the base erns noted on an adj melt blinds and ceiling appeared to be large iple areas of the hou g. A mattress was lo	Apt./Suite/Room Zip igation Unit to assist Saint iffied by the Department of the complete of	Paul Police with If Safety and Insp and a young chil blice Officers stat s broken on side site. ined to the imme nificant smoke st cloor. beared to be und d to have froze a ar the area of original	reports of a possible sections that the add that were supposed ing that there appeal alpha (north side) of diate area of original ining located on all ergoing renovation and burst causing significances.	e break-in at a single dress of concern has been edly living out of the ars to have been a f the residence and the on what appeared to be I three floors and enough with related construction nificant water damage er significant signs of
Post Office Box L State L Remarks: Squad 1 was dispatch family residence. Saint I on the vacant/condemn Neighbors have been rebasement of the buildir previous fire in the base door on bravo side (east An extinguished fire wa an ottoman with v-patcheat was generated to it. However the structure materials found in mult throughout the dwellin current Full primary narrative ca	ed as the Fire Invest Paul Police were not led list for multiple reporting suspicious arg. Squad 1 arrived a sment and began invitation of the passerns noted on an adjuelt blinds and ceiling appeared for led arg. A mattress was lown be found in NFIRS 1:	Apt./Suite/Room Zip igation Unit to assist Saint iffed by the Department of the complete of	Paul Police with if Safety and Inspirant a young chil blice Officers stats is broken on side site. Fined to the imme nificant smoke state of the area of original to have froze a for the area of original to have froze a for the area of original to	reports of a possible sections that the add d that were supposed ing that there appeal pha (north side) of diate area of original aining located on all ergoing renovation and burst causing siggin, however no other	e break-in at a single dress of concern has been edly living out of the ars to have been a f the residence and the on what appeared to be I three floors and enough with related construction nificant water damage er significant signs of
Post Office Box L State L Remarks: Squad 1 was dispatch family residence. Saint I on the vacant/condemn Neighbors have been rebasement of the building previous fire in the base door on bravo side (east An extinguished fire wan ottoman with v-patcheat was generated to I However the structure imaterials found in mult throughout the dwellincurrent Full primary narrative ca	ed as the Fire Invest Paul Police were not led list for multiple re porting suspicious a g. Squad 1 arrived a ment and began int is side) appeared for s noticed in the base erns noted on an adj melt blinds and ceiling appeared to be large iple areas of the hou g. A mattress was lo	Apt./Suite/Room Zip igation Unit to assist Saint iffied by the Department of the complete of	Paul Police with If Safety and Insp and a young chil blice Officers stat s broken on side site. ined to the imme nificant smoke st cloor. beared to be und d to have froze a ar the area of original	reports of a possible sections that the add d that were supposed ing that there appeal pha (north side) of diate area of original aining located on all ergoing renovation and burst causing siggin, however no other	e break-in at a single dress of concern has been edly living out of the ars to have been a f the residence and the on what appeared to be I three floors and enough with related construction nificant water damage er significant signs of

NFIRS-2 Fire

Α	62210	MN	02	09	2021	Station #4	SPFD210209005	5551 0		
	FDID	State	Month	Day	Year	(04) Station	Number	Exposure		
В						С				
	operty Details	1 —		On-Site Materials Or Products			On-Site Materials Storage Use			
E	31 1	J	esidential							
Estimated number of residential living units in t origin whether or not all units became involved					ilding of					
E	32 1	Buildir	ngs Not In	volved						
	Number of building	1								
E	33	☑ None	Less th	nan 1 acre						
	Acres burned (outs	side fires)								
D				E1			E3			
lg	nition			Cause	of Ignition			ors Contributing to		
	1 40-Storage area, o	ther			itentional nintentional		Ignition Check all appl	applicable boxes		
	Area of Fire Origin	1			ailure of Equi	│	·p			
40-Hot or smoldering object, other								ssibly impaired by alcohol or		
	Heat Source		_	U - Cause Undetermined After				ttended person sibly Mentally Disabled sically Disabled tiple Persons Involved		
	21-Upholstered so vehicle seats	fa, chair,								
Item First Ignited D4 99-Multiple types of material Type of Material First Ignited			E2 7-				ge Was A Factor			
			Factors Contributing to Ignition Estima			Estimated Ag	d Age of			
			Male				Female			
				Factor Contributing to Ignition						
F1				F2				G		
E	quipment Involved I None	n Ignition			ent Power So	urce		Fire Suppression Factors		
ı				П						
Equipment Involved			Equipment Power Source							
Е	rand			F3						
Model L			Equipment Portability							
9	erial#			1 - Poi	table tionary					
Y	ear				equipment nor					
				persons.						
Н1				H2				Local Use		
Mobile Property Involved				Mobil	e Property T	ype and Make		Pre-Fire Plan Available		
1 - Not involved in ignition, but burned 2 - Involved in ignition, but did not burn			Mobile	Property Type	e		Arson Report Attached Police Report Attached			
3 - Involved in ignition and burnedNone							Coroner Report Attached Other Reports Attached			
					Property Mak	e		_ Julier Reports Attached		
Mo	bile Property Model			L Ye	ar					
L										
State License Plate Number					N	<u> </u>				

NFIRS-3 Structure Fire

	- 111 1113 5 5 5 11 0 0 0 0		
I1 Structure Type 1 - Enclosed Building 2 - Portable/Mobile Structure 3 - Open Structure 4 - Air-Supported Structure 5 - Tent 6 - Open Platform 7 - Underground Structure 8 - Connective Structure 0 - Other	I2 Building Status 1 - Under Construction 2 - In Normal Use 3 - Idle, Not Routinely Used 4 - Under Major Renovation 5 - Vacant and Secured 6 - Vacant and Unsecured 7 - Being Demolished 0 - Other U - Undetermined	Building H 2 Number of: At/Above Gi 1 Number of: Below Grad	Stories Total Square Feet OR Stories 20 BY 20
J1 Fire Origin 0 Below Grade Story of Fire Origin J2 Fire Spread Confined to Object of Origin 2 - Confined to Room of Origin 3 - Confined to Floor of Origin 4 - Confined to Building of Origin 5 - Beyond Building of Origin	Number of Stories Damaged By Fl Number of Stories w/Minor Dam Number of Stories w/Significant Number of Stories w/Heavy Dam Number of Stories w/Extreme Dam *Count the roof as part of the highest significant	age (1-24%) Damage (25-49%) age (50-74%) amage (75-100%)	K Type of Material Contributing Most to Flame Spread K1
L1 Presence of Detectors N - None Present 1 - Present U - Undetermined L2 Detector Type 1 - Smoke 2 - Heat 3 - Combination of Smoke and Heat 4 - Sprinkler, Water Flow Detection 5 - More Than One Type Present 0 - Other U - Undetermined	L3 Detector Power Supply 1 - Battery Only 2 - Hardwire Only 3 - Plug-In 4 - Hardwire With Battery 5 - Plug-In With Battery 6 - Mechanical 7 - Multiple Detectors 8 Power Supplies 0 - Other U - Undetermined L4 Detector Operation 1 - Fire Too Small To Activate 2 - Operated 3 - Failed To Operate U - Undetermined	2 - Alerted O 3 - There Wei 4 - Failed to A U - Undeterm L6 Detector Failur 1 - Power Fail 2 - Improper 3 - Defective 4 - Lack of Ma 5 - Battery M	ccupants, Occupants Responded ccupants, Occupants Failed to Respond e No Occupants elert Occupants ined e Reason ure, Shutoff, or Disconnect installation or Placement sintenance, Dirty issing or Disconnected scharged or Dead
M1 Presence of Automatic Extinguishing System N - None Present 1 - Present 2 - Partial System Present U - Undetermined M2 Type of Automatic Extinguishing System 1 - Wet-Pipe Sprinkler 2 - Dry-Pipe Sprinkler 3 - Other Sprinkler System 4 - Dry Chemical System 5 - Foam System 5 - Foam System 6 - Halogen-Type System 7 - Carbon Dioxide System 0 - Other U - Undetermined Required if fire was within designed range of AES	M3 Operation of Automatic Extinguishing System 1 - Operated/Effective 2 - Operated/Not Effective 3 - Fire Too Small To Activate 4 - Failed To Operate 0 - Other U - Undetermined Required if fire was within designed range M4 Number of Sprinkler Heads Operating Required if system operated	System I	tem Shut Off t Enough Agent Discharged ent Discharged But Did Not Reach Fire ong Type of System e Not In Area Protected tem Components Damaged k of Maintenance nual Intervention

NFIRS-1S Supplemental

Α								
	62210	MN	02	09	2021	Station #4 (04)	SPFD210209005551	0
	FDID	State	Month	Day	Year	Station	Number	Exposure

Primary Narrative:

Squad 1 was dispatched as the Fire Investigation Unit to assist Saint Paul Police with reports of a possible break-in at a single family residence. Saint Paul Police were notified by the Department of Safety and Inspections that the address of concern has been on the vacant/condemned list for multiple months.

Neighbors have been reporting suspicious activity to include a couple and a young child that were supposedly living out of the basement of the building. Squad 1 arrived and were met by on-site police Officers stating that there appears to have been a previous fire in the basement and began investigations. A window was broken on side alpha (north side) of the residence and the door on bravo side (east side) appeared forced per police officers on site.

An extinguished fire was noticed in the basement. The fire was contained to the immediate area of origin on what appeared to be an ottoman with v-patterns noted on an adjoining wall. There was significant smoke staining located on all three floors and enough heat was generated to melt blinds and ceiling fan blades on the first floor.

However the structure appeared to be largely intact. The building appeared to be undergoing renovation with related construction materials found in multiple areas of the house. Several pipes appeared to have froze and burst causing significant water damage throughout the dwelling. A mattress was located in the basement near the area of origin, however no other significant signs of current occupancy existed.

Xcel gas was called and confirmed that the gas had been previously secured. Xcel electric secured utilities at the pole. A daughter confirmed she was en route to the location but was going to stop at Home Depot and purchase materials to secure the residence and refused fire personnel from contacting a board-up service. Saint Paul Police were called to provide security and Squad 1 and Car 7 returned to service, terminating command.