

## APPLICATION FOR APPEAL

RECEIVED

DEC 0 1 2010

## Saint Paul City Clerk

310 City Hall, 15 W. Kellogg Blvd. Saint Paul, Minnesota 55102 Telephone: (651) 266-8560

s your appeal: YOUR HEARING Date and Time:
Tuesday, <u>Dec. 7</u> Which  Time /// DO am  Location of Hearing: Room 330 City Hall/Courthouse
<b>1:</b>
Ave City: St. Vanl State: MNZip: 55103  Pas Email holand argory colu.
Pao Email holand argory colu.
(1) Residence Cell (651) 553897/
Date: 12/1/10
Residence San Cell San
Residence $S_{\alpha}$ Cell $S_{\alpha}$
and why? Attachments Are Acceptable
Il items and deficiences has been corrected as of 1/24 The condemnation was lifted, bent Cof O was revoked. I have no idea why?  I am include all invoices, resources at which we have invested in the building of except of over \$100K. The building by been varieted. I am regioning an imm

644 Grand Avenue, St. Paul, MN 55105-3498 (651) 228-9200 M (651) 228-9201 F stpaulplumbing.com

## INVOICE

Invoice Number: 203704 Invoice Date: 11/22/10 Order Number: 97843 Order Date: 11/15/10

Page:1

**CALVIN TRAN GERI** PO BOX 49099 BLAINE, MN 55499 Site **CALVIN TRAN** 360 FULLER AVE ST PAUL, MN 55105

Customer ID

74971

Terms

C.O.D.

PO No.

Contact

**Customer Report:** 

Orsat test

Service As Follows: PERFORMED ORSAT TEST ON WEIL MCLAIN BOILER. CLEANED SITE GLASS AND PRESSURE

TROLL LINE. LEFT TEST ON SITE.

Item No.	Description	Unit	Quantity	Unit Price	Total Price
	ORSAT TEST Pipe dope FJim W ADDITIONAL WORK FJim W 11/22/10 LAURA	Each Each Hour Hour	1 1 0.5 1	180.60 1.90 174.00	180.60 1.90 87.00





CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

### Web: www.stpaul.gov/dsi

# SMOKE AND CARBON MONOXIDE DETECTOR INSPECTION AFFIDAVIT

	362 Fulley		<u> </u>	encontractive contractive cont	
St.Pa	al Address	55103	# o:	f Units	C of O#
I affirm t	hat I have give				room in the buil
<ol> <li>Instr</li> <li>The</li> <li>Who</li> </ol>	ructions describitions procedures for to contact whe	eration of each sang the action to lesting the detector a low-battery to abling smoke de	be taken when an ors. one sounds or po	n alarm sounds. ower light fails.	ection.
C:			DIRECTOR AND PROPERTY OF THE CONTROL	Date:	11/23/1
dwelling ı	hat I personally units and guest	rooms in the bu	ilding at the ab		nonoxide detecto s follows and tha
I affirm tl dwelling t	hat I personally inits and guest were in place a Apt. #		ilding at the ab		
I affirm tl dwelling u detectors	hat I personally inits and guest were in place a	rooms in the bu nd good workin	ilding at the ab g order:	ove address as	follows and tha
f affirm the description of the legislation of the	hat I personally inits and guest were in place a Apt. #	rooms in the bu nd good workin	ilding at the ab g order:	ove address as	follows and tha
f affirm the description of the legislation of the	hat I personally inits and guest were in place a Apt. #	rooms in the bu nd good workin	ilding at the ab g order:	ove address as	follows and tha
I affirm tl dwelling u detectors	hat I personally inits and guest were in place a Apt. #	rooms in the bu nd good workin	ilding at the ab g order:	ove address as	follows and tha
I affirm tl dwelling u detectors	hat I personally inits and guest were in place a Apt. #	rooms in the bu nd good workin	ilding at the ab g order:	ove address as	follows and tha

# ELECTRIC, FIRE AND SECURITY INC. • 4921 BABCOCK TRAIL • I.G.H., MN 55077 • (651) 450-0352 SERVICE REPORT

<u>a</u>	3 NUM		CUSTOM	IER AUTH.		SE	ERVICED BY		TE,
10	45	was a superior of the superior		allengathere a statut er ea Julia inn web er hankhankhalkterings i note bund uit do hannaur i nou dibber e source		ANO	y Ang	N 11/1k	1/0
	(	CUSTOMER	NAME AND ADDRESS				PHONE	NUMBER	
36	<u>v/</u>	362 1	VLER AU		AC L		ADVANCE	driverneesiaareдиния описальных принценторующих принценторующих выпольных принценторующих выпольных выпольных	XT.    I
31	<u> </u>	AUL	$\Delta M$	operant never an unumproprietate sur proprietation de l'action de l'établishes défauts de l'action de la réferênce de l'action		YES	ADVANCE NO	DATE PRO	MISED
								/ T AND UNIT NUMBE	/
			ada tani dingga katalan muutaa 444 o kan ada ada da da kata kamin oo kata bir mee da asaa kata ada ada ada kata	one errormen von met mer gerkompt von jaminelijk de die trent met und vir de plante de die kalende de die kalende de		NAN	AE OF CONTAC	I AND UNIT NUMBE	
BILL TO:					☐ CON	TRACT	☐ SERVICE	E 🛛 WARRANTY	OTHER
OFIRE A	LARN	1 DOOR	ENTRY DINSPE	CT. Q PHONE	☐ NURS	E CALL	. O MATV	□ ELECT. □ EM.	LIGHTING
PROBLE	<b>ZECOMORIO</b>							DISPATC	HED
				<				DATE: // //	· //a
Communication and an experience of the control of t	no canigado no escucio policiam dilerciti del	ookkeyneelikohyeyko in qualisaan oo misoo siiii isaan oo saca kee yeen oo addiin aad		unigkann kolong yili su sagan salayun sa sayan ndukko direntek diresa di en moni ekit di ini salah salah salah		ng diang-proving glogophy indicense age-culture on glab descape		TIME: 2:45	AM PM
WORK P	erfo	RMED:				T.		ARRIVED AT	SITE
								DATE: 11 / 16	1/0
gawanesa Apigula dinagan kasali na uun kesakan dinamera Abbahii	adonagyanan iris ontologici (h	is in misse see ministrative in the ministrative of the first section of the sect		derezionici dengli kejn indocessorate professionici ne de travegració de distributo de digitalmente profession	asing side parameters of the control	zirra godininski naktirika kiri naktirani namek	17	TIME: 3:00	AM PM
Danger and the state of the sta	ORDER SERVICES SON OF SERVICES	<u> </u>	UAL 5/4	A commence of the commence of				TRAVEL TO JOB	
Designation of the relationship control and the second second second second second second second second second	water and the second section is						r szczuwi zmałki ki Zduwi inkretne de archieliki ki	SPECIAL TRAVEL	6 6
			en edite below en		diagnos i en applica companien de susingen familie en chille houseau	ethartismi dhimadomo nashindis menandan		BENCH TIME	
								WAIT TIME	ntermonitàre misma reprostatorita posterio i socia de conscione de con
								TIME AT JOB	• ~ ~
and the second s	O MIKON KODINGO NOVINSO	gereg zeme dan szazáján észe heletekének ésenék mégyek és filontól ések és az veszere dadá						SUPPLY TIME	•
garagiones presentares presentares per administrativos de la defenda de la defenda de la defenda de la defenda	acen les landar ca citros conscenden	rm kana terrénai koji kini finala devi din kini dinevi din kini dina dina dina dina dina dina dina d	od and kanala an anala an	an apazan apopulu gilimay geh fisio di vasta da esas eres visto 400 400 fisio di distributi di se		ertiesten habbeitelligeleen bevolgen of en entdeutien o	ng agus ann dhe sausgeainn agus ann à the faire ann ain de fheir an cuaidh mach ann ann an ann ann ann ann ann	RETURN TRAVEL HOURS	describe consist and all and all constraints are consistent and an experience of the constraints are consistent as a constraint and a constrai
COMME	NTS:							OVERTIME	en allerenis in conservation and an analysis of the conservation and an
	minimiserve engalisise kamalandari keri	perphilippes sergifikum verdelichten oppdatuden Aren viller Geschlichten Aren ville Geschlichten Aren viller Geschlichten					makan panda Ambasan yang dapat dan pertambah sama dan dapat dan dapat dan sama dan dapat dapat dan dapat dan d	TOTAL HOURS	1:25
								Mell delfast hlad klad klad klad klad klad klad skap klad skap klad skap klad klad klad klad klad klad klad klad	
P.O. STK.			DESCRIPTION	PRICE	P.O. STK.	#	DES	CRIPTION	PRICE
	1/4	<u> </u>	<u> Shake</u>				wenterbolum terminischen Angel of desprüner und Ansanger ung kenstelle der dam kleiste kon.		
	44	<u> </u>	AIR					nunner contracte de la manual su de la contracte de la contrac	
			ndeng Granus ag har san naphanaka san araban na karaban bahar bahar bahar karaban na karaban naga napan pagan,					ntiglorinopriikin nyyggisaa jaajaja pakidelehine gyra attaadespehiniyi sannenninnid gyra attaili riidin attabo	
									Ž
						and the second s		TOTAL	
U JOB (	COM	PLETED	☐ ADDITIONAL	WORK NEED	ED (	CONTI	NUED ON I	NVOICE NO	
	WOR	K COMPLE	TED BY	DATE	CUST	OMER	SIGNATURE		DATE
R)	1 1	w/A	Noy III	1/6 / /0	X				/

#### Fax (651) 450-9740 email: efsservice@efsmn.com Phone (651) 450-0352 Web Site: www.efsmn.com ALARM SYSTEM TEST REPORT Name Of Property Address City Zip 360/36 Phone Number Type of Inspection Job No. **Annual** 0453 Monitoring Company Acct# Control Panel Brand Model Amp. Hours **Test Voltage** Silent knowlyt 2224 25.4 Communicator Panel Brand Model **Amp Hours** Test Voltage Remote Power Supply Model Test Voltage Amp. Hours Do the control Switches Work Correctly? 回Yes Did the Control Panel transfer to Battery backup? Yes No Do the Trouble Light and Sounder work Properly? ☑ Yes ☐ No. Does the Supervision work Properly? ☑Yes ☐ No N/A Is the AC Power Disconnect Location Labeled? ☑Yes ☐No **System Initiating Devices** Qty. Type of Device Brand Model **Proper Operation Smoke Detectors** Yes 15 fray 500501 □ No □ N/A **Pull Stations Vyes** Fron 1stre $\square$ No □ N/A L **Heat Detectors** ☑ Yes $\square$ N/A ☐ Yes □ No □ N/A Yes Пио $\square$ N/A ☐ Yes ΠNo $\square$ N/A System Audible / Visual Devices Qty. Type of Device **Brand** Model Proper Operation Horns DYes. □No LI N/A ☐ Yes □ No □ N/A Yes □No $\square$ N/A □ Yes □ No □ N/A Yes $\square$ N/A Does Remote Annunciator work correctly? **WNA** ☐ Yes ☐ No Brand Model Are the Alarm Zones properly labeled and identified? Пио Пиа U Yes Does The Initiating Device report to the Proper Zones? Pryes I No Did the Door Holder Release on Alarm? Yes No NA Did the Elevator recall work Properly? Yes □ No PANIA Were the Proper Signals sent to Central Station? ☐ Yes ☐ No List Deficiencies That must be Corrected to Certify System: Inspection Agents Signature: Site Agents Signature: Repair Job # **Todays Date** Your Next Inspection Due: Yellow Copy-E.F.S. CC: White Copy-City Inspector Pink Copy- Property

ELECTRIC FIRE AND SECURITY INC. • 4921 BABCOCK TRAIL • I.G.H., MN 55077



### Laughlin's Pest Control Company 1908 University Ave. St. Paul, Minnesota 55104 (651) 646-6131

					E 112
DATE   - 6 - 10	TIME INOUT	ACCOUNT NO		ROUT	E NO.
NAME Hyang Dag		ACCOUNT TY	R I	RESIDENTIAL	
360 2362 1	Mer Ave	1-TIME		<b>2</b> COMMERCIAI	LJUIDUUR
PHONE PHONE	55103	☐ ANNUAL		6 MONTHS	☐ 3 MONTHS ☐ WEEKLY
651-35	3-897	☐ MONTH	LY I	☐ BI-MONTHLY	CT WEEVEL
☐ INSPECTION	☐ TREATMENT ☐	]	and the second		
TARGET PEST(S)	SITE TREATED	APPLICATION N	METHOD	APPLIC	CATION RATE
Poaches	中了-363-362				
-Mile	#3-360, #5-362				and the same new same many man have been same have been same
100 AM AT THE SECOND SE	#2-360, 42-32				
LOCAL STATE OF THE PROPERTY OF	CALS USED	AMOUNT	%	EP/	NUMBER
And Power	A STATE OF THE PROPERTY OF THE	2	.154	1	· · · · · · · · · · · · · · · · · · ·
and the state of the section and an are and are are an are and		6095	205		
- CONTRC !	Novise Bait	1-10-	<u> 20</u> 2		_0У
any days don't that good dops have about about pure about pasts don't have more		<b></b>	l		
	advaganta manganinan dalama la dana dum mini dum mangadan produm admanda da da sant antima da hara sant manga		<u></u>		ooyyay (Aria 6-9) (kaasalkakaasastii iiraa moon oo koonaa ay ka saa iiraa ahaa ka k
segriposaministra parimentalis con los presentes de los presentes de la constitución de l	TION/REMARKS		Ayuqua a de la ferencia del la ferencia de la feren	An experience of the control of the	
	e listed unity.	······································	na en estado de la contractica del la contractica de la contractica del la contractica de la contracti	nestigative en franch solet en en institutivis in en institutivis	 
tol mice -	- Concluds		COLOR DE LA CO	ustuvasionis analysis taken heranaranainsi ini ini ahii erinna (tile tarini	
-Minimal-6	utivity in			and defended in the second section of the	ganis insuperante and angular and an insuperante and angular and angular and an angular and an angular and and
Doth un	15		usantio en los es		
			IDADAAA HAMAAA IAAA KAA	SUB-TOTAL	
COC hate soon who wink DOC after 60th type were noted dear and the sound of the contract of th			reconstruction of the control of the	TAX	41
you and you had by the the hard the set you and the man you.			nin drawnikasila vestera	TOTAL	177116W
માન્ય તરફ તરફ પશ્ચે પત્તે હોંદ્રો કોંદ્રોટ કહેશ દેશને દેશને દેશને હતાન લાગ લાગ લાગ લાગ લાગ લાગ છે.		AC	COUI	VT BALANCE	
SERVACED BY A	CLUKS. LICENSE NO.	□ CASH □ CHECK		MOUNT PAID	E E E E E E E E E E E E E E E E E E E
RUSTOMER SIGNATURE		gaganga <del>ra matata</del>	ALANCE DUE		
CEDVICE	ORDER/INVO	ice Ice	Ng	825	<u> C</u>
OCUAIPE (	OHDEN/HVVU	<b>TUL</b>	1 W es	. 060	VV



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

November 18, 2010

Hoang Dao 1445 Shryer Ave W Roseville MN 55113-5831

### NOTICE OF CONDEMNATION UNFIT FOR HUMAN HABITATION ORDER TO VACATE

RE: 360 FULLER AVE

Dear Property Representative:

Your building was inspected November 24, 2010.

The building was found to be unsafe, unfit for human habitation, a public nuisance, a hazard to the public welfare or otherwise dangerous to human life. A Condemnation Placard has been posted on the building.

The following deficiency list must be completed or the building vacated by the re-inspection date.

#### CONDEMNATION OF THE BUILDING REVOKES THE CERTIFICATE OF OCCUPANCY.

Failure to complete the corrections may result in a criminal citation. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy.

#### **DEFICIENCY LIST**

- 1. 362-1 and throughout MSFC 703 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-Repair and maintain the door closer.
- 2. 362-1, 2 and 360-3 MSFC 1003.3.1.8 Remove unapproved locks from the unit doors. The door must be openable from the inside without the use of keys or special knowledge or effort.
- 3. 362-1-4, 360-3 SPLC 34.13 (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the sleeping rooms to: 2 occupants.-Building 362-1, 2, 3, and 4

Building 360-3 No access to unit 1

- 4. 362-1-4, 360-3 SPLC 34.13 (2), (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the unit.
- 5. 362-2,4 MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.
- 6. Basement MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.
- 7. Basement and throughout SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.-Remove all mattresses, couches, furniture, tires, personal items from the basement and vacant units off the property.
- 8. Exterior SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screen. Replace all torn or missing screens.
- 9. Exterior-Throughout SPLC 34.09 (3), 34.32 (3) Repair and maintain the window glass.
- 10. Exterior-Throughout SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screen.-Replace all missing and torn screens.
- 11. Interior SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.-This building is condemned based on multiple deficiencies and the majority of all units over-occupied. This property is not maintained or managed and should have an administrator appointed.
- 12. Interior SPLC 34.19 Provide access to the inspector to all areas of the building.-Provide access to all units including unit 1, and the basement.
- 13. Interior-Basement MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.-Remove all furniture and mattresses from the basement.
- 14. Interior-Basement and Hallways MSFC 315.2.5 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.
- 15. Interior-Hallways MSFC 308.2.1 No person shall throw or place, or cause to be thrown or placed, a lighted match, cigar, cigarette, matches, or other flaming or glowing substance or object on any surface or article where it can cause an unwanted fire.
- 16. Interior-Throughout SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Repair or replace all broken and missing door handles throughout.

- 17. Interior-Throughout SPLC 34.11 (6) Provide and maintain a minimum of 68 degrees F in all habitable rooms at all times.-Building 360 radiators are cold and unit 360-2 using space heater.
- 18. Interior-Throughout MSFC 907.20 as amended Provide required annual maintenance of the fire alarm system by a qualified person and provide written documentation to this office as proof of compliance.-Immediately have the annual maintenance of the fire alarm system and provide written verification.
- 19. Throughout All Units SPLC 34.09 (3), 34.32 (3) Repair and maintain the window sash.-All openable windows must be able to remain in the open position when opened.
- 20. Throughout All Units and Hallways SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Paint and patch the walls throughout as necessary.
- 21. Unit 3 SPLC 34.10 (6), 34.33 (5) Exterminate and control insects, rodents or other pests. Provide documentation of extermination.-Report of mice. Hire a licensed exterminator to treat the unit for mice and roaches.
- 22. Unit 360-2 MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
- 23. Unit 360-2 MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Immediatly discontinue use of lamps hung upside down hanging on extension cords-Fire hazard.
- 24. Unit 362-2 MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.-Fire extinguisher expired in 2008. Immediately service all expired fire extinguishers.
- 25. Unit 362-2 SPLC 34.10 (7), 34.33 (6) Repair or replace and maintain the woodwork in an approved manner.-Hire a licensed contractor to replace the entry door to unit.
- 26. Unit 362-2 SPLC 34.09 (3) i Repair and maintain an approved one-inch throw single cylinder deadbolt lock.-Hire a licensed contractor to repair the deadbolt that was not installed properly.
- 27. Unit 362-2 SPLC 71.01 Provide address numbers on unit 362-2
- 28. Unit 362-2 SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 Repair or replace and maintain the plumbing fixture to an operational condition.-Hire a licensed plumber to repair the toilet that is running in unit 362-2.
- 29. Unit 362-2 and 360-4 SPLC 34.10 (7), 34.33 (6) Repair and maintain the floor in an approved manner.-Hire a licensed contractor to install new pad and carpet in the living

room of unit 360-4 and repair or replace the kitchen floor in unit 360-4, and install vinyl in the bathroom and kitchen in unit 362-2.

- 30. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.- Provide fuel report.
- 31. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8688) and must be filed within 10 days of the date of the original orders.


If you have any questions, email me at: lisa.martin@ci.stpaul.mn.us or call me at 651-266-8988 between 6:30 - 8:30 a.m. Please help make Saint Paul a safer place in which to live and work.

Sincerely,

Lisa Martin Fire Inspector

cc: Housing Resource Center

Force Unit



Neighborhood Builders & Contracting Inc.

1001 Valley Oaks Rd Vadnias Heights, MN Bus: 651-231-7336

License #: 20326281

Estimate

DATE

ESTIMATE NO.

8/7/2008

371

### NAME / ADDRESS

360 Fuller Ave St Paul, MN Project: Interior remodel

-N. C. & B. Inc

			PROJECT
PEOPLETION	RATE	QTY	TOTAL
DESCRIPTION			29,500.00
Plumbing: New plumbing install: Labor & material included. 8 units	29,500.00		•
Eltrical: Electrical repair and new wiring where needed. Labor & material included, 8 units.	12,000.00		12,000.00
Cabinets/Sinks: Kitchen & bath cabinets. Labor * material ncluded, 6 units.	12,600.00		12,600.00
Boiler: Repair, labor & material included. Main unit for building.	3,590.00		3,590.00
Drywall: New drywall install, labor & material. Hung, taped, sanded, primed & painted. Includes, but is not limited to: 2 bedrooms, 8 baths, 7 kitchens, 13 individuall walls & 12 ceilings.	8,500.00		8,500.00
Bath: Bath tub & sink install, labor & materials. 2 units.	3,000.00		3,000.00
Concrete: Cosmetic rehab on exterior foundation only. Labor & material, all around property.	1,800.00		1,800.00
Landscape: Rock & pebble application. Labor & material included.	590.00		590.00
Windows: 20 replacement locks w/screens. Labor & material included, 8 units.	1,500.00		1,500.00
Deck: Demo & replacement. Labor & material, main deck.	5,800.00		5,800.00
Basement remodel: Stair install, concrete wall repair and 2 doors installed. Labor & material included.	1,200.00		1,200.00
Any further questions call Jaime Garcia at (651) 338-8521. Have a nic	e day.	TOTAL	\$80,080.00



SI

# PLUMBING/GASFITTING/INSIDE WATER PIPING

PERMIT #:

20 08 088175

Issued Date:

June 5, 2008

## CITY OF SAINT PAL

Department of Safety and Inspect 8 Fourth Street East, Suite Saint Paul, MN 55101-PHONE: (651) 266-FAX: (651) 266-

TR	40	ro	R
	#6~		E.C.

OWNER:

HERRY PLBG DBOX 4261 DPKINS MN 55343 HOANG DAO 1445 SHRYER AVE W ROSEVILLE MN 55113-5831

LMIT ADDRESS: 360 FULLER AVE

ST PAUL MN 55103-2378

TYPE: Plumbing/Inside Water (All) WORK TYPE: Residential Replace

from a	And the second s			mary and all the party of the p
Po In A. V. E. S.	lty Fee I Fee tion to Permit Closet - Plumbing Tub - Plumbing Plumbing	No Yes No 5 3`	# of Dwelling Units Estimated Value of Work Inside Water Piping? Lavatory - Plumbing Shower - Plumbing Gas Range	12000 No 5 2 5
1,i	r Heater		FRES	•

FEES	٥,	· <b>1</b> )
Permit Fee	8:	, ,
Surcharge A		:0
TOTAL	8.	:0_

he responsibility of the person doing the work authorized by this permit to notify the inspector that the work is ready for inspection de access to the work. (MN Rules 1300.0210, Subpart 4)



### MECHANICAL PERMIT

20 08 089222

Issued Date: June 6, 2008

### CITY OF SAINT PAUL

Department of Safety and Impactions
8 Fourth Street Ear Suite 270
Saint Paul. MRI 19101-1024
PHONE: (651 288-8090

FAX: (2F 286-812/

CONTRACTOR:

OWNER:

WELD PLUMBING DONALD WELD 3410 KILMER LANE N PLYMOUTH MN 55441

PERMIT #:

JAMIE GARCIA 360 FULLER AVE ST PAUL MN 55103-2378

PERMIT ADDRESS: 360 FULLER AVE

ST PAUL MN 55103-2378

SUB TYPE: Steam or Hot Water

WORK TYPE: Residential Repair/Alter

		Estimated Value of Work	3500
of Dwelling Units	ì	Estimated value of work	• • • • • • • • • • • • • • • • • • • •
Field Application?	No		tiggers profile gerligtelse for en en en pleastigheit de formatien au en en entre de la commence de la commenc
	A CONTRACTOR OF THE CONTRACTOR	BTU	aller age griftiggegjalrigging i vergandeligiskeringen fra det regenerare overen tidelyggistelyde is ver I de dermen, i di velar vlyring fil i hyddistelyden gir a glainelysgerinasyd artholysgerin i '' '''
Boiler		FEES	
		Permit Fee	58.00
		Surcharge B	1.75
		TOTAL	59.75
	*	•	
		TOWER OFFI ATION FOR	FIRE DEPT Minnesota Rui

REPLACE STEAM TRAPS AS NECESSARY AND VALVE HANDLES, CERTIFY BOILER OPERATION FOR FIRE DEPT. Minnesota Rules, Chapter 1300.0210 Inspections: The person doing the work authorized by a permit shall notify the building official that the work is ready for inspection. The person requesting an inspection required by the code shall provide access to and means for inspection of the work. An Open C of O Exists at this Property.



REMIT TO: CHERRY PLUMBING • PO. BOX 4261 • HOPKINS, MN 55343

	O BOX 4EVI 1			
451-231-7336				
Customer Name Name Northerd Blokes + Contractors	Tenant Hame	Control of the second s		Phone
1001 Velle, Oaks Ral	Job Address 360	<i>ન્ડ</i> િટ	FULL	·er
Wadnies Agts MNS	Cu Ct	faul		Zıp
Cate Expert   Terms   Credit card Type   C	Craditicard No	iredit cerd Exp	Purchase order No	France No
Alimbing &	· x tora	e S	to: [-	5
Levelor 1 Ture	addi	final	)	
morry verded	luc	fer .	heater	
showed valves si	utis_	9 ~ 01	Lac	cefs.
	Development School School and School		6	29500
	Con-Children berkerne - mysterin de die gran. En systemys gester de die gran. En systemys gester de de de de d	QU	OTATION:	
	narry-dimingrousse one was sprantisched strike de landschederscherscherscherscher			The second secon
			The second secon	and the second s
	The state of the s	TOTAL	INVOIGE:	296-
WORK AUTHORIZATION You may do work described for which I will pay amount quoted herein.			The Carles	2420
pay amount quoted herein.  X  WORK ACCEPTED: Work described herein has been completed to my satisfaction.  X	amount arry worl	of time you one Of time you one Owe have done	AR GUARAN  fill expend up to  pinally paid for, to  tor you if it sho  ( ) year	the full o repair
	Marine and the same of the sam	and the second s	\ / y \ a	•

### QUILLCO

3380 232nd STREET EAST HAMPTON, MN. 55031-9727

## **Estimate**

Date	Estimate #
6/24/2008	56

Nemo	e / Address
JAMIE	GARCIA

	Terms	Project
Description	Qty	Total
ELECTRICAL FOR CODE COMPLIANCE 360 FULLER AVE ST PAUL.  GFI REC SINGLE POLE SWITCH LIGHT REC SMOKE DETECTORS CIRCUITS REWIRE BASEMENT BATHROOM REPAIR HALL LIGHTS AND MISSING COVERS AS NEEDED ADD 100 AMP PANEL ELECTRICAL PERMIT TIME AND MATERIAL NOT TO EXCEED ANY ADDITION BY INSPECTOR WILL BE EXTRA CHARGE 7500.00 BEFORE START BALANCE ON COMPLETION BEFORE FINAL INSPECTION IF NOT PAID IN FULL WITHIN 5 DAYS OF COMPLETION ADD 30% ALL PRICES ARE CASH DISCOUNT PRICES 2000.00 DRAW RECEIVED	6 9 10 15 8 9 2 10 1	12,400 00
Thank you for considering Quilleo	Total	\$12,400.00

Signature			
	NAME OF THE OWNER O	 	

# Pro Wire Electrical Services, LLC

# **INVOICE**

1219 8th Ave. S.

South St. Paul, MN 55075 Phone: (651) 757-5740

Fax: (651) 797-2920

E-Mail: zac@prowireelectric.com Web: www.prowireelectric.com MN Contractors License # CA05236

BILL TO:

Date: 07/01/2008 Invoice # 301

FOR:

360 Fuller Ave. St. Paul, MN Bring Up To Code

Salesperson	Job	Payment Terms	Due Date
Satesperson		Due upon receipt	

	Descriptions	Rate	Lin	e Total
Qty/Hours	Materials Needed		\$	1,000.00
	Labor		\$	2,600.00
2.00	Permit & Inspection Fees For 360/362	\$ 53.50	\$	107.00
2.00				
			<del> </del>	
			+	
			4	
			┼	
			-	
			+	
			+	
			+-	
			+	
			+	
			\$	(1,000.00
	1st DOWN PAYMENT		\$	(1,000.00
	2nd DOWN PAYMENT		1.	1000
	PRO WIRE IS NOT LIABLE FOR ANYTHING THE INSPECTOR WANTS		_	
	WANTS ADDED/CHANGED. COAST COULD THEN BE EXTRA		+	
	AT TIME/MATERIAL TO MEET INSPECTION REQUIRMENTS.		+	
		T	tal \$	1.207.0

\$ 707.00

Phone: 651-645-1034

651-644-2492

Fax: 651-644-1880 Alarm License #\_0001102 Weber & Troseth, Inc. Manufacturers Representatives

> 1902 University Avenue St. Paul, MN 55104

## ALARM SYSTEM INSPECTION REPORT

	ALAKM SYSIEM INSTI	- in 250 - 1/a
С	۸	Inspection Location: 360-362 Fuller
U	HOAN NO	Monitoring Co: A/A
S	1445 SPREYER AVE W	Account #: NA Phone: NA
0 0	ity: Boss Ville State: MN Zip 55/13	Type of System: Giler of Kalight Model:
m	Lety. Dosz vijie	Service Technician:
E Pt	none:	(1)
	yes no note qty	yes no note qty
	as so 1 was atotime	15. Trouble indications operated
1.	All fire alarm manual stations operated satisfactorily 3	satisfactorily on simulated open fault for following:
	Heat detectors operated	Initiating circuits / 2
Z.	satisfactorily	Communication circuits
3.	Smoke detectors operated	Armunclator circuits
	satisfactorily	16. Trouble indication operated
4.	Sprinkler flow & tamper switches	satisfactorily on simulated
	functioning	ground fault
5.	All alarm horns operated	17. Trouble indicator operated
	satisfactorily	satisfactorily on loss of normal
6.	Fire alarm annunclator operated satisfactorily	18. Battery operation of system tested
_	All evacuation speakers operated	with AC power turned off
/-	satisfactorily	19. Battery capacity adequate to
Q	All firefighter's phones operated	supervise system & operate bells
0.	satisfactorily	following a period of charging source failure
9.	Damper controls function properly	20. Door holders
	Fans shut down on alarm activation	
	Pressurization fans start up on	COMMENTS:
11.	alarm activation	System-ob
12.	Elevators are recalled on alarm	Į.
	activation	
13.	Monitoring company connections	
	verified	Deficiencies that must be corrected to certify system:
14.	All zone, signal and annuciator circuits tested free of grounds	1/02/2
	and opens	- / NAV
	· · ·	
		- Of MI
	YOUR NEXT INSPECTION IS DUE	Year O Month Myly
	Inspection Date: 5000	
	Technician	
	—(Y )	
	V	



612-824-2411

CALVIN TRAN PO BOX 49099 BLAINE, MN 55499

## ST. PAUL PLUMBING AND Since HEATING CO.

644 Grand Ave. St. Paul, MN 55105-3498 (651) 228-9200 (651) 228-9201 Fax

Site

CALVIN TRAN 360 FULLER AVE ST PAUL, MN 55105

Customer ID

74971

INVOICE

Invoice Number: 177575
Invoice Date: 03/21/08

Order Date: 03/21/08

73280

Order Number:

Page:1

Terms

C.O.D.

PO No. Contact


Customer Report:

Boiler no heat

Service As Follows: NSP RED TAGGED. REMOVED AND CLEANED PILOT. RELITE. UNIT FIRES. TESTED LWC.

Item No.	Description	Unit	Quantity	Unit Price	Total Price
	Shop materials	Each	1	4.60	4.60
	Gas Surcharge	Each	1	3.00	3.00
	Heating Destination Charge	Each	1	68.50	68.50
	FJim W 03/21/08	Hour	0.75	162.00	121.50
	MISSY				





## Invoice

Date	Invoice #
10/25/2008	324

Bill To	
Hoang Dao 1445 Shryer Ave Roseville, MN 55113	

		Due Date	Project	С	laim No.	File	No.
		11/24/2008	400.08.33 Hoang Dao				
Serviced	Item		Description		Qty	Rate	Amount
10/18/2008	Principal PE - CW	I Site visit on	d Meeting 10-18-08 - 56 miles 300.00 not show has been paid)		4	200.00 32.76	800.00
Thank you fo	or the business!				Total		\$832.76

Phone #	Fax#	FTID #20-3136061
763 545 1985	763 545 1287	



REMIT TO: CHERRY PLUMSING . P.O. BOX 4261 . HOPKINS, MN 55343

REMIT TO: OTIELT
Tenani Name Phone
Phone Hoand Dao Job Address Till Acc
illing Address 360 Fuller 712.
sity st Zip City St. Paul MN.
Date Expert Terms Credit card Type Credit card No. Credit card Exp Purchase order No. Invoice No.
10-14-08 1 1 C+ David MN.
The city of St. Paul Pina fixtures
inspection is complete address
ve Supplied to Dlumbing Code.
The balance due for That job is \$ 5,5.
QUOTATION:
Alease forward balance TOTAL INVOICE: \$5.5.
WORK AUTHORIZATION: You may do work described for which I will pay amount quoted herein:  X  I, 2, 3, 4 or 5 YEAR GUARANTEE  At no cost to you, we will expend up to the further amount of time you originally paid for, to repa
WORK ACCEPTED: Work described herein has been completed to my satisfaction.  any work we have done for you if it should fa anytime within() year.
X

FROM: HomeTownPlumbing

**FAX COVER SHEET** 

Hometown Plumbing, Inc. 2440-152<sup>nd</sup> Lane NE

Ham Lake, MN 55304 Office Phone Number: 763-205-2098

Mike Westman: 612-501-7089 Fax number: 763-413-9191

115/08
0

Send to: Trung Tran	From: Sandy Eigenheer HomeTown Plumbing, Inc
Attention:	Date: 09/10/2008
Office:	Office Location: 763-205-2098
Fax Number; 681-605-0059	Fax Number: 763-413-9191

- ☐ Urgent
- ☐ Reply ASAP
- ☐ Please comment
- Please review
- ☐ For your information

Total pages, including cover: 2

PROPERTY MASTERS
PO BOX 49099
BLAINE, MN 55449-0099

PAY TO THE HOME TOWN Plumbing \$ 186.

One hundred eight six dollars in manual and severe Garranteed with usbank.com

MEMORIC Text 360 Fuller 10910000221: 10477565057511 5014

FAX NO. : 7634139191

## HomeTown Plumbing, Inc.

HomeTown Plumbing, Inc 2440 152nd Lanc NE Ham Lake, MN 55304

(612)501-7089 hometownplumbing@comcast.nct

	Invoice
DATE	INVOICE#
09/10/2008	1938
a y at essential enterior measurement and section	DUE DATE
	09/10/2008

BILL TO		
Trung Tran 11835 Daven Minneapolis,		n 144,44 to Allies enthicsonaint-blanchillosiydden

AMOUNT DUE	ENCLOSED.
\$186.00	

Please demen top portion and return with your payment.

			Job Name	dob	Address	Job Phone #
			RPZ Test	i	iler Ave, St. Paul	612-701-5522
Date		Description of Work		Quantity	Rate	Amount
	Annual RPZ Test; Scrial			1:	136.00	136.00
	Conbraco model# 40204 St. Paul Permit Fee	02 Boiler Room at boiler/boiler	feed	1	50.00	50.00
	*permit/test report will b of this invoice.	e sent into the city of St. Paul up	on full payment		displayed and the second secon	
				-	e e e e e e e e e e e e e e e e e e e	
					4	
				To be Combine Amenda	u diversi de la compansión de la compans	
			-	da jarigi - endi programe bis		
hank you f	for your business.	The state of the s			TOTAL	\$186.

MSJ

**Custom Windows** 

INVOICE

2908 Aspen Lakes Drive NE Blaine, MN 55449 (612) 964-7074

To: Hoang Dao 360 Fuller Avenue St. Paul, MN 55103 INVOICE #234792 DATE: OCTOBER 13<sup>TH</sup>, 2008

JOB: 360 Fuller Avenue UNIT #1
\*Window Repair\*

DESCRIPTION	AMOUNT
Inspect chips in stationary window-Resolution: Fill with clear silicone	\$ 120.00
	The second secon
	\$ 120.00

Please make all checks payable to: MSJ Custom Windows



## CONSTRUCTION AND REMODELING

DATE: APRIL 23RD, 2010 INVOICE # 20034

NEIGHBORHOOD-BUILDERS AND REMODISIERS 1001 Valley Oaks Road Vadnais Heigh's, MN 55110 Ph: 612-701-0572 Fax: 612-605-0059

Hoang Dao 360/362 Fuller Avenue St. Paul, MN 55103 Customer ID: 360fuller-dao

SALESPERSON Jaime Garcia		SON JOB PAYMENT		S DU	JE DATE
		Repair Roof-Leak #360-3	Half down upfront	Upon Completion	
QTY		DESCRIPTION		UNIT PRICE	LINE TOTAL
9	Timberline 3	0-Yr Shingles-Gray	August Marin - Greenwal Herring van de Gebeur Austream een de Gebeur van de Gebeur van de Gebeur van de Gebeur	90.00	810.00
6	Plywood 4x8			4.00	24.00
2	Asphalt Felt		•	160.00	320.00
12		& Ceiling) 2x4		2.00	24.00
6		Board (Sheet Rock)		6.00	36.00
1	Joint Compo			15.00	15.00
5		mium Caulk		4.00	20.00
5		pofing Silicone		8.00	40.00
	Galvanized	The Arrange agency of the second		2.00	8.00
4		iling and wall		15.00	30.00
2	Vinyl wrap	and the second s		50.00	50.00
1		tion (1530 sqft.) Ceiling only	3.5"	14.00	70.00
5			and the second s	300.00	300.00
1	Dumpster-3	and the second of the second o		100.00	1000.00
10	Labor Com	plete Roof/Leak Repair		SUBTOTAL	2747.00
	Thank you for your business! Please make checks payable to: Neighborhood Builders and Remodelers		SALES TAX	209.46	
			TOTAL	\$2,956.46	



## CONSTRUCTION AND REMODELING

DATE: MAY 21<sup>ST</sup>, 2010 INVOICE # 20124

NEIGHBORHOOD BUILDERS AND REMODELERS 1001 Valley Oaks Road Vadrais Heights, MN 55110 Ph 612-701 2572 Fact 612-605-0030

FG) Hoang Dao 360/362 Fuller Avenue St. Paul, MN 55103 Customer ID: 360fuller-dao

	SALESP	ERSON	ЈОВ	PAYMENT TER	MS D	UE DATE
1 S	Tommy	Repairs #360-3			Upon Rec	ziept
	QTY		DESCRIPTION		UNIT PRICE	LINE TOTAL
	1	Replace Kitchen	Sink Faucet-Unit #360	.3		150.00
	1	Replace Living R	oom Outlet-Unit #360	.3	1	30.00
		AND THE PROPERTY OF THE PROPER				
						y and reference
		garage and the second of the second				
		and the second s				
		gradient state of the second o		and the second second		
	war side of the second	*				
	· MANARY · ·					
			and the second s		SUBTOTAL	180.00
		Thank you for	your business! Please	nake checks payable to:	SALES TAX	
		Neigl	hborhood Builders and	Kemodelers	TOTAL	180.00







### 360 FULLER AVE -- Property Information --

PIN	Zoning/Use	HPC District
362923420084	RT2	

### Information disclaimer...

Data Disclaimer:-

The City of Saint Paul and its officials, officers, employees or agents does not warrant the accuracy, reliability or timeliness of any information published by this system, and shall not be held liable for any losses caused by reliance on the accuracy, reliability or timeliness of such information. Portions of such information may be incorrect or not current. Any person or entity that relies on any information obtained from this system does so at his or her own risk.

### **List of Activity...**

	Lecelare A	8 8 8			
	Address	Description	Details	Status	
93 048352 VEN 01 XF	LEE'S VENDING SERVICE - 362 FULLER AVE APT 1	ECLIPS License# 0048352	ECLIPS Food Related LEE'S VENDING SERVICE - 362 FULLER AVE APT 1 Type: Food Vending Machine Operator Entered on: 08/25/1993	Canceled	
93 048352 VEN 00 XF	LEE'S VENDING SERVICE - 362 FULLER AVE APT 1	ECLIPS License# 0048352	ECLIPS Food Related LEE'S VENDING SERVICE - 362 FULLER AVE APT 1 Type: Food Vending Machine Entered on: 08/25/1993	Canceled	
10 905299 CSO 00 RF	360 FULLER AVE	Walls need paint.	Referral Type: Citizen Complaint Entered on: 10/04/2010	Finaled	
10 413439 S&C 00 E	360 FULLER AVE		Electrical Permit Type: Service & Circuits Commercial Repair/Alter Issued Date: 05/27/2010 Final Date: 06/24/2010 Contractor: Pro Wire Electrical Services, LLC Estimated Value: \$100.00  Activity (most recent first):	Finaled	Move Top
10 014296 000 00 RF	360 FULLER AVE	Follow up on C of O folder approved with corrections.	MAIN-Electrical Inspection: 06/24/2010: Final Referral	Closed	
10 014295 000 00 CO	360 FULLER AVE		Certificate of Occupancy Type: Residential 3+ Units Occupancy Type: Dwelling Units Residential Units: 8	Pending	
10 008802 S&C 00 E	360 FULLER AVE		Electrical Permit Type: Service & Circuits Residential Repair/Alter Issued Date: 01/20/2010 Final Date: 01/22/2010 Contractor: Pro Wire Electrical Services, LLC Estimated Value: \$110.00	Finaled	

1 of 6 10/8/2010 3:44 PM

Activity (most recent first):

MAIN-Electrical Inspection: 01/22/2010: Final

Closed 09 331662 360 FULLER Remove furniture Parks Summary Abatement Type: Garbage Rubbish and refuse on 000 00 PA AVE ground rear yard. Entered on: 12/01/2009 Closed on: 12/01/2009 Closed 09 294467 360 FULLER Remove household Parks Summary Abatement Type: Garbage Rubbish items, vehicles 000 00 PA AVE parts, and refuse on Entered on: 10/06/2009 Closed on: 10/08/2009 around. Certified 362923420084 Certificate of Occupancy 08 178979 360 FULLER 05/01/2008: Early Type: Residential 3+ Units AVE 000 00 CO Occupancy Type: Dwelling Units C of O in child Residential Units: 8 referral. Class: C Completed on: 01/28/2010 Paid In Full = Yes Inspection Results (most recent first): 01/28/2010: Approved w/Corrections 1. 360 UNIT 1: Inadequate Plumbing Fixtures SPLC 34.11, SPLC 34.17, SBC 2902.1, MPC 4715.0200.C (Abated - 5th reinspection) 2. 360- UNIT 4: Repair Cabinets SPLC 34.10 (7), 34.33 (6) (Abated - 5th reinspection) - Severity 2 3. EXTERIOR: Ext. Window Glass SPLC 34.09 (3), 34.32 (3) (Abated - 5th reinspection) - Severity 2 4. EXTERIOR: Window Screen SPLC 34.09 (3), 34.32 (3) (Deficiency - 5th reinspection) - Severity 2 5. EXTERIOR: Snow/Ice Removal SPLC 113.02, MSFC 1203 (Abated - 5th reinspection) - Severity 2 EXTERIOR: Approved Trash Containers SPLC 34.11 (8), 34.34 (4) (Deficiency - 5th reinspection) - Severity 7. EXTERIOR: Ext. Sanitation SPLC 34.08 (1), 34.31 (1) (Deficiency - 5th reinspection) - Severity 6 8. EXTERIOR: Trash Containers -Frequency SPLC 34.11 (7), 34.34 (4) (Deficiency - 5th reinspection) - Severity 9. EXTERIOR: Res. Entry Security Lighting SPLC 34.14 (2) f (Abated - 3rd reinspection) - Severity 7 10. EXTERIOR: Stair/deck Not Structurally Sound SPLC 34.09 (2) 34.32 (2) (Abated - 3rd reinspection) -Severity 7 11. EXTERIOR: Repair Ext. Guardrail SPLC 34.09 (2) 34.32 (2) (Abated - 3rd reinspection) - Severity 5 12. EXTERIOR: Ext. Walls SPLC 34.09 (1) b,c, 34.32 (1) b,c (Abated - 3rd reinspection) - Severity 7 13. INTERIOR: Heating Equipment Maintenance SPLC 34.11 (6), 34.34 (Abated - 5th reinspection) - Severity 14. INTERIOR: Exterminate Insects & Rodents SPLC 34.10 (6), 34.33(5) (Abated - 5th reinspection) -Severity 4 15. INTERIOR: Light Fixture Globes MSFC 605.1 (Abated - 5th reinspection) 16. INTERIOR: Unsafe Interior Stairway SPLC 34.10 (3), 34.33 (Abated - 5th reinspection) - Severity 7 17. INTERIOR: Res. Interior Allow Access SPLC 34.19 (Deficiency - 5th reinspection) - Severity 2 18. INTERIOR 360 #2: Repair Damaged Elect. Fixtures MSFC 605.1 (Abated - 2nd reinspection) - Severity 5 19. INTERIOR 362 #4: Missing Elect.Cover Plate MSFC 605.6 (Deficiency - 2nd reinspection) - Severity 2 20. INTERIOR 362 #4: Discontinue Use of Multi-Plug Adapters MSFC 605.4 (Deficiency - 2nd reinspection) -Severity 2 21. INTERIOR 362 #4: Discontinue Use of Extension Cords MSFC 605.5 (Deficiency - 2nd reinspection) -22. INTERIOR BASEMENT: Discontinue Use of Extension Cords MSFC 605.5 (Abated - 2nd reinspection) -Severity 2 23. UNIT 360 #1: Comb. Materials - Orderly Storage MSFC 315.2 (Deficiency - 1st inspection) - Severity 2 24. UNIT 362 #4: Unfit For Human Habitation-Condemned SPLC 34.23, MSFC 110.1 (Deficiency - 5th

reinspection)

		3 - 2 3	25. UNIT 362 #4: Overcrowding Sleeping Unit SPLC 34.13, (3), SPLC 34.17 (2) (Deficiency - 1st inspection) Severity 7 26. UNIT 362 #4: Interior Unsanitary SPLC 34.10 (5), 34.33 (4), 34.16 (Deficiency - 1st inspection) - Severity	
		8 2 (	3 27. Required Smoke Detector Affidavit SPLC 39.02(c) Abated - 5th reinspection) - Severity 9	
08 152601 OBS 00 RW	360 FULLER AVE	CURB JUMP F	More History on File. PW Right of Way Permit Type: Obstruction Mork Type: Dumpster Entered on: 09/18/2008	Finaled
08 150540 ELC 00 E	360 FULLER AVE	! - !	Closed on: 10/16/2008 Electrical Permit Type: Electrical Commercial Repair/Alter Issued Date: 09/15/2008 Final Date: 09/25/2008 Contractor: Pro Wire Electrical Services, LLC Estimated Value: \$2,500.00	Finaled
08 089222 STM 00 M	360 FULLER AVE		Activity (most recent first):  MAIN-Electrical Inspection: 09/25/2008: Final 09/19/2008: Corrections Required 09/17/2008: Corrections Required Mechanical Permit Type: Steam or Hot Water Residential Repair/Alter Issued Date: 06/06/2008 Final Date: 07/22/2008 Contractor: Weld & Sons Estimated Value: \$3,500.00	Finaled
08 089055 ADD 00 B	360 FULLER AVE		Activity (most recent first): MAIN-Mechanical Inspection: 07/21/2008: Final Building Permit Type: Residential (Multi-Fam) Addition Issued Date: 06/24/2008 Final Date: 01/06/2009 Contractor: USA Builders And Remodelers Corp State Valuation: \$2,000.00	Finaled
08 088175 PLB 00 PG	360 FULLER AVE		Activity (most recent first): Building Permit Inspection: Final Inspection - Appd Framing/Structural - CorrReqd Architectural (C) Review: 06/24/2008: Approved 06/06/2008: Preliminary Plan Check Plumbing/Gasfitting/Inside Water Piping Type: Plumbing/Inside Water (All) Residential Replace Issued Date: 06/05/2008 Final Date: 09/18/2008 Contractor: Cherry Plbg Estimated Value: \$12,000.00	Finaled
08 044551 000 00 PA	362 FULLER AVE	Remove freezer, mattress, and TV.	Activity (most recent first): MAIN-Plumbing Inspection: 09/17/2008: Final 09/15/2008: Corrections Required 07/28/2008: Approved by Location 06/17/2008: Approved by Location 06/12/2008: Corrections Required Parks Summary Abatement Type: Garbage Rubbish Entered on: 03/19/2008 Closed on: 03/24/2008	Closed
07 220592 000 00 PA	360 FULLER AVE	Pre-Auth WO Remove all garbage/rubbish from over flowing dumpster and on the ground.	Parks Summary Abatement Type: Garbage Rubbish Entered on: 12/18/2007 Closed on: 12/24/2007	Closed
06 094087 000 00 PA	360 FULLER AVE	Remove sofa from	Parks Summary Abatement Type: Garbage Rubbish Entered on: 06/07/2006 Closed on: 06/09/2006	Closed

06 067664 360 FULLER 000 00 CO AVE

C of O in child referral.

362923420084 Certificate of Occupancy 05/01/2008: Early Type: Residential 3+ Units Occupancy Type: Dwelling Units Residential Units: 8

Class: C

Completed on: 03/01/2010

Inspection Results (most recent first): 10/20/2008: Approved 1. EXTERIOR: Ext. Window SPLC 34.09 (3), 34.32 (3) (Abated - 9th reinspection) - Severity 2 2. EXTERIOR: Window Screen SPLC 34.09 (3), 34.32 (3) (Abated - 9th reinspection) - Severity 2 3. EXTERIOR: Private Sidewalks SPLC 34.08 (10) (Abated - 6th reinspection) - Severity 3 4. INTERIOR: Ext. Window Sash SPLC 34.09 (3), 34.32 (3) (Abated - 7th reinspection) - Severity 2 5. INTERIOR: No Interior Guardrail SPLC 34.10 (3) 34.33(2) (Abated - 7th reinspection) - Severity 5 6. INTERIOR: Repair Interior Walls SPLC 34.10 (7), 34.33 (6) (Abated - 7th reinspection) - Severity 4 7. INTERIOR: Repair Ceilings SPLC 34.10 (7), 34.33 (6) (Abated - 7th reinspection) - Severity 4 8. INTERIOR: Repair Plumbing Fixture SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 (Abated - 7th reinspection) - Severity 4 9. INTERIOR: Res. Interior Allow Access SPLC 34.19 (Abated - 7th reinspection) - Severity 2 10. INTERIOR: Residential Basement Dampness SPLC 34.10 (1) (Abated - 6th reinspection) - Severity 3 11. INTERIOR: Blank 1 (Abated - 6th reinspection) 12. INTERIOR: Uncertified Areas Unoccupied SPLC 33.05 (Abated - 4th reinspection) 13. INTERIOR: Unfit For Human Habitation- Condemned SPLC 34.23, MSFC 110.1 (Abated - 3rd reinspection) 14. INTERIOR: Address - Incorrect SPLC 71.01 (Abated - 3rd reinspection) - Severity 5 15. INTERIOR: Misc. Equip.Repair and Maintain SPLC 34.12 (2), 34.35 (1) (Abated - 2nd reinspection) -16. Foundations SPLC 34.09 (1) a, 34.32 (1) a (Abated - 6th reinspection) - Severity 7 10/01/2008: Correction Orders

History

1. EXTERIOR: Ext. Guardrail SPLC 34.09 (2) 34.32 (2) (Abated - 6th reinspection) - Severity 5 2. EXTERIOR: Ext. Handrail SPLC 34.09 (2) 34.32 (2) (Abated - 6th reinspection) - Severity 5 3. EXTERIOR: Stair/deck Not Structurally Sound SPLC 34.09 (2) 34.32 (2) (Abated - 6th reinspection) -Severity 7 4. INTERIOR: Ext. Window Lock SPLC 34.09 (3), 34.32 (3) (Abated - 6th reinspection) - Severity 2 5. INTERIOR: Bathroom Floor Impervious to Water SPLC 34.10(4), 34.33(3) (Abated - 6th reinspection) -Severity 4 INTERIOR: Unsafe Heating Equip.MN Rules 1300.0180 (Abated - 6th reinspection) - Severity 9 7. INTERIOR: Inadequate Plumbing Fixtures SPLC 34.11, SPLC 34.17, SBC 2902.1, MPC 4715.0200.C (Abated -8th reinspection) 8. INTERIOR: Water Heater Maintenance SPLC 34.11 (5), 34.34 (2) (Abated - 5th reinspection) - Severity 6 9. INTERIOR: Hot Water Supply SPLC 34.11(5), 34.34(2), SPC 4715.0200Q (Abated - 5th reinspection) - Severity 7 10. INTERIOR: Repair Plumbing Fixture SPLC 34.11, SBC 2902.1, SPLC 34.17, MPC 415.0220 (Abated - 5th reinspection) - Severity 4 11. INTERIOR: Provide GFCI SPLC 34.14 (2) c (Abated -5th reinspection) - Severity 5

08/28/2008: Condemned/Occupied

07/03/2008: Correction Orders

1. EXTERIOR: Ground Cover SPLC 34.08 (3) (Abated -

4th reinspection) - Severity 3 2. EXTERIOR: Res. Grading and Drainage SPLC 34.08 (2) (Abated - 3rd reinspection) - Severity 3 3. INTERIOR: Fire Doors MSFC 703 (as amended) (Abated - 4th reinspection) - Severity 6 4. INTERIOR: Overcrowding Sleeping Unit SPLC 34.13, (3), SPLC 34.17 (2) (Abated - 3rd reinspection) -Severity 7

03 354313 360 FULLER 362923420084 AVE 000 00 CO

More History on File. Certificate of Occupancy Type: Residential 3+ Units Occupancy Type: Dwelling Units

Residential Units: 8

Class: B

Completed on: 04/17/2006

Paid In Full = Yes

Inspection Results (most recent first): 04/17/2006: Approved 1. BASEMENT: No Interior Handrail SPLC 34.10 (3), 34.33(2) (Abated - 2nd reinspection) - Severity 5 2. ENTRY 362 AND 360 FULLER: Repair Interior Floors SPLC 34.10 (7), 34.33 (6) (Abated - 2nd reinspection) -3. UNIT 1 360: Repair Damaged Elect. Fixtures MSFC 605.1 (Abated - 2nd reinspection) - Severity 5 4. UNIT 2 360: Fire Doors MSFC 703 (as amended) (Abated - 2nd reinspection) - Severity 6 5. UNIT 2 360: Missing Elect.Cover Plate MSFC 605.6 (Abated - 2nd reinspection) - Severity 2 6. UNIT 2 360: Electrical Fixtures Closets NEC 410-8 (b) (1) (Abated - 2nd reinspection) - Severity 2 7. UNIT 2 362: Unit Number Of Locks MSFC 1003.3.1.8 (Abated - 2nd reinspection) - Severity 4

8. UNIT 2 362: Discontinue Use of Extension Cords MSFC 605.5 (Abated - 2nd reinspection) - Severity 2 9. UNIT 3 360: Electrical Fixtures Closets NEC 410-8 (b) (1) (Abated - 2nd reinspection) - Severity 2 10. UNIT 3 360: Discontinue Use of Extension Cords MSFC 605.5 (Abated - 2nd reinspection) - Severity 2 11. UNIT 3 362: Elec Serv. Attachments To Service Conduits. NEC 230-28 (Abated - 2nd reinspection) -

Severity 1 12. UNIT 3 362: Unit llegal Locks MSFC 1003.3.1.8 (Abated - 2nd reinspection) - Severity 4 13. UNIT 4 362: Provide GFCI SPLC 34.14 (2) c

(Abated - 2nd reinspection) - Severity 5 14. UNIT 2 362: Fueled Equipment Storage MSFC 315.2.5 (Abated - 2nd reinspection) - Severity 9

03/13/2006: No Entry (no fee) 1. Required Smoke Detector Affidavit SPLC 39.02(c) (Abated - 3rd reinspection) - Severity 9

02/24/2006: No Entry (fee)

12/13/2005: No Entry (fee)

03 255649 362 FULLER S&C 00 E AVE APT 1

Electrical Permit Type: Service & Circuits Commercial Repair/Alter Issued Date: 02/18/2003

Final Date: 03/03/2003

Contractor: B C & A's Electric Company

Estimated Value: \$400.00

Activity (most recent first):

MAIN-Electrical Inspection: 03/03/2003: Final

Type: Residential (Multi-Fam) Repair

system due to no Issued Date: 02/05/2003 activity in one year . Final Date: 11/16/2005 Closed without final Contractor: Jms Builders State Valuation: \$2,000.00 approval

Activity (most recent first):

Certified

Finaled

Finaled

10/0/0010 0 44 DN4

03 253607 362 FULLER RPR 00 B AVE APT 1

16-Nov-2005: Folder closed by

**Building Permit** 

01 218581 360 FULLER

AVE

000 00 CO

History

Preliminary Inspection: 11/16/2005: Permit Closed

Final Inspection: 11/16/2005: Permit Closed

Preliminary Inspection: 02/21/2003: Verbal Order

Architectural (C) Review: 02/05/2003: Preliminary Plan

Check

362923420084

02/05/2003: Approved

Certificate of Occupancy

Type: Residential

Occupancy Type: Dwelling Units

Residential Units: 8

Class: C

Completed on: 09/18/2003

Paid In Full = Yes

Inspection Results (most recent first): 09/18/2003: Approved
1. UNIT 3 BLDG 360: Discontinue Use of Extension Cords MSFC 605.5 (Abated - 3rd reinspection) - Severity 2

09/18/2003: Correction Orders 1. UNIT 1 BLDG 362: Overcrowding Sleeping Unit SPLC 34.13, (3), SPLC 34.17 (2) (Abated - 2nd reinspection)

- Severity 7

2. UNIT 1 BLDG 362: Unit Dead Bolt Repair SPLC 34.09 (3) i (Abated - 2nd reinspection) - Severity 5

3. UNIT 2 BLDG 360: Discontinue Use of Extension
Cords MSFC 605.5 (Abated - 2nd reinspection) Severity 2

4. UNIT 2 BLDG 360: Overcrowding Sleeping Unit SPLC 34.13, (3), SPLC 34.17 (2) (Abated - 2nd reinspection)

5. UNIT 2 BLDG 360: Unit llegal Locks MSFC 1003.3.1.8 (Abated - 2nd reinspection) - Severity 4

6. UNIT 2 BLDG 362: Discontinue Use of Extension Cords MSFC 605.5 (Abated - 2nd reinspection) - Severity 2

7. UNIT 2 BLDG 362: Excessive Accumulation Of Materials MN Stat 299F.18 (Abated - 2nd reinspection) - Severity 8

8. UNIT 3 BLDG 360: Provide GFCI SPLC 34.14 (2) c

(Abated - 2nd reinspection) - Severity 5

9. UNIT 3 BLDG 362: Discontinue Use of Extension Cords MSFC 605.5 (Abated - 2nd reinspection) -Severity 2

10. UNIT 3 BLDG 362: Zoning - Improper Use SPLC 62.101 (Abated - 2nd reinspection) - Severity 9

11. UNIT 3 BLDG 362: Overcrowding Unit SPLC 34.13 (2), (3), SPLC 34.17 (2) (Abated - 2nd reinspection) - Severity 7

12. UNIT 4 BLDG 362: Provide GFCI SPLC 34.14 (2) c (Abated - 2nd reinspection) - Severity 5

13. UNIT 4 BLDG 362: Discontinue Use of Extension Cords MSFC 605.5 (Abated - 2nd reinspection) - Severity 2

14. UNIT 4 BLDG 360: Discontinue Use of Extension Cords MSFC 605.5 (Abated - 2nd reinspection) - Severity 2

15. UNIT 4 BLDG 360: Bathroom Floor Impervious to Water SPLC 34.10(4), 34.33(3) (Abated - 2nd reinspection) - Severity 4

16. UNIT 4 BLDG 360: Unit llegal Locks MSFC 1003.3.1.8 (Abated - 2nd reinspection) - Severity 4 17. UNIT 4 BLDG 362: Ext. Door Frame SPLC 34.09 (3), 34.32 (3) (Abated - 2nd reinspection) - Severity 3 18. UNIT 4 BLDG 362: Unit llegal Locks MSFC 1003.3.1.8 (Abated - 2nd reinspection) - Severity 4

08/14/2003: Correction Orders
1. Required Smoke Detector Affidavit SPLC 39.02(c)
(Abated - 1st inspection) - Severity 9

#### INVOICE

#### REMODELING IS OUR BUSINESS No Job Too Large or Too Small

REPAIR SHOP ON WHEELS One Hour Emergency Service Office: 651-228-9200

JOB NO. 4984

DATE 644 GR/ Saint Paul				AND AVE. I, MN 55105		JOB NO. 4984		
				JOB LOCATION				
inne Magrid medgrish Venneb In 1997	Connection			360	Paul 55103	Viita kakki nootakkisiitaa kira koraiki siisaa kirkkis kirikkisii kiriinka kiik kirine voo -reooveeeeeeee		
processoring trades sugaring group distribution		APT #		the first and the second secon	2v 5503	APT #	Videoglidesseske om kangilos lijevije kiristopijaka i listorios sistem	
H # W # SERVICE REQUESTED				H#	W #			
				SERVICE PERFORMED				
	Burrow Ration	ngga ging gang apinin kalaban da da Balabanka da Balabanka da Balaban da sa s		* Jy 00	breshot poster a			
amen'n norma algha a glad a parant i men domin di nimeroni a palada.					by temp with		n sighil kaji kajanskyaj ni sa disiminja mila kai gentja mija kajantja kanalis.	
sangkasambinininanan-umanikan-ritele				- Zun Tempony stad to part				
		kalakala da da kalaka kala	make ya a pipanja pipa	425147	<u> LES Liferances en la companyación de la companyac</u>		enida anglesiski sejih ngasi bibisa i ni inga a ta na 144 4444 a m	
		nggang ghang juga na sama untu pi kanila yi sama na nga kura shiking jihinki		- drain	MATERIALS	610p67 1008		
QTY.	MATERIALS	PRICE	AMOUNT	QTY.	MATERIALS	PRICE	AMOUNT	
,	erp Materials	4/40		The state of the s				
						990009 711		
		<b></b>			n kalangan paga paga paga paga paga paga paga	000		
		470000000000000000000000000000000000000						
menson artisen som model did della månya medistriklik								
manangg								
nacionesta en 1999 y Elizabeth (1998)	METHOD OF PAYMENT		And an anti-phonon and an angle (programme and a		TECHNICIAN	HRS.		
Cust.	☐ C.O.D. ☐ Credit Card			Alan				
	Card Exp. Date			Driv	R	1/2		
Card No		ora econoacida a avanta despisa angle 6 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	and the second s	170	4 % Commence			
	Credit on Al	Ž.,	engangan ingga danggap ong ama sa inggalan dalah sambalan		10:45			
COMMENTS / EXTRA WORK DON			NE		MATERIALS	1/11/2		
			makkaridi milikuta kiloma manana ara da 1900 ang		DEL. CHG.			
			ewp /		LABOR			
anna ann an t-anna ann an t-ann an t-a	ALT ED	1201				TRUCK		
		- manuschied germ (Deplementerstehe a.E.Shilli)				TOTAL	1665.	

By signing this invoice the customer understands and agrees to the following:

1. I will pay the labor rates, including overtime rates, explained to me on the telephone.

2. I will pay for all of the labor and materials to the technician at the time the job is completed.

3. If the homeowner does not pay St. Paul Plumbing & Heating for its labor and materials in full, St. Paul Plumbing & Heating may take legal action against the homeowner for payment. In that event, St. Paul Plumbing & Heating is entitled to recover from the homeowner all costs of collection, including reasonable

4. If the work is being performed pursuant to a bid and St. Paul Plumbing has to stop work due to the construction schedule, I will pay St. Paul Plumbing for the work performed to the date of the stop within 30 days of such stop.

5. Our Company is not responsible for deteriorated plumbing or leaks caused by deteriorated plumbing and we are not responsible for any damages caused by leakage during guarantee period.



Ehresmann Wille Engineering, Ltd 6100 GLENWOOD AVENUE GOLDEN VALLEY, MN 55422 (763) 545-1985 FAX (763) 545-1271

October 17, 2008

Mr. Hoang Doa 1445 Shryer Avenue Roseville, Minnesota 55113

Commission #: 400.08.33

Re: The house at 360 Fuller Avenue, St. Paul, Minnesota

Dear Mr. Doa:

This is to confirm my involvement in the above project and render my opinion as to the adequacy of the foundation to support the structure.

I visited the house in your company on this date and inspected the basement masonry foundation walls. I found the walls adequate to support the house for the forseeable future.

Please call me if there are any questions or if you need more complete descriptions or certifications.

Sincerely.

Cecil C. Wille, P.E.

Cerfl. Will

**Principal** 

Certification

THIS IS TO CERTIFY THAT THIS PLAN,
SPECIFICATION OR REPORT WAS PREPARED BY ME
OR UNDER MY DIRECT SUPERVISION AND THAT I AM
A DULY REGISTERED ENGINEER IN THE STATE OF
MINNESOTA

Cecil C. Wille, P.E.

Cert C. Wills

Reg. No.: 8771

ACORD	ı

ACORD 25 (2009/01)

## CERTIFICATE OF LIABILITY INSURANCE


DATE (MM/DD/YYYY)


06/29/10

Mi]		Hartwig Insurance		ONLY AND O	CONFERS NO RIC HIS CERTIFICATE	D AS A MATTER OF INFO SHTS UPON THE CERTIF DOES NOT AMEND, EXT ORDED BY THE POLICIE	ICATE TEND OR	
Lal	evi	Holyoke Ave S .11e MN 55044	22 460 1001				NAIC#	
Phone: 952-469-5502 Fax: 952-469-1881					INSURERS AFFORDING COVERAGE			
#430	NED.			INSURER A: W	Western National In	nsurance Co.	15377	
				INSURER C:				
		Hoang Dao 1445 Shryer Ave W Roseville MN 55113		INSURER D:				
		Roseville MN 55113		INSURER E:				
CO	/ERA	GES				gerzat zubei dat zeste zelogen i genergione genere u en en en en de arche el de addition de administrativa de a		
AN M	Y REQ Y PER	ICIES OF INSURANCE LISTED BELOW HAV LUIREMENT, TERM OR CONDITION OF ANY TAIN, THE INSURANCE AFFORDED BY THE B. AGGREGATE LIMITS SHOWN MAY HAVE	CONTRACT OR OTHER DOCUMENT WITE POLICIES DESCRIBED HEREIN IS SUBJ	TH RESPECT TO WHICH SECT TO ALL THE TERM	THIS CERTIFICATE M. S, EXCLUSIONS AND C	AY BE ISSUED OR		
NSR LTR	ADO'U	TYPE OF INSURANCE	POLICY NUMBER	POLICY EFFECTIVE DATE (MM/DD/YYYY)	POLICY EXPIRATION DATE (MM/DD/YYYY)	LIMITS		
A		GENERAL LIABILITY  X COMMERCIAL GENERAL LIABILITY	PENDING	07/01/10	07/01/11	DAMAGE TO RENTED PREMISES (Ea occurence)	s 1000000 s 100000	
		CLAIMS MADE OCCUR					\$ 1000	
							s 1000000	
							s 2000000 s 2000000	
		POLICY PRO- JECT LOC				PRODUCTS - COMP/OP AGG	\$ 200000	
- Personal		AUTOMOBILE LIABILITY ANY AUTO				COMBINED SINGLE LIMIT (Ea accident)	\$	
		ALL OWNED AUTOS SCHEDULED AUTOS				BODILY INJURY (Per person)	\$	
		HIRED AUTOS NON-OWNED AUTOS				BODILY INJURY (Per accident)	\$	
						PROPERTY DAMAGE (Per accident)	s	
CII CIANCO CONTRA		GARAGE LIABILITY				AUTO ONLY - EA ACCIDENT	\$	
		ANY AUTO				OTHER THAN	\$	
es communica						AGG	\$	
		EXCESS / UMBRELLA LIABILITY					\$ \$	
		OCCUR CLAIMS MADE				AGGREGATE	\$	
		DEDUCTING F					\$	
		DEDUCTIBLE RETENTION \$					\$	
	WOR	KERS COMPENSATION			***************************************	WC STATU- OTH- TORY LIMITS ER	***************************************	
		PROPRIETOR/PARTNER/EXECUTIVE Y / N				E.L. EACH ACCIDENT	\$	
	OFFI	CER/MEMBER EXCLUDED? datory in NH)				E.L. DISEASE - EA EMPLOYEE	\$	
	If yes	describe under CIAL PROVISIONS below				E.L. DISEASE - POLICY LIMIT	\$	
A	Pr	er operty Section	PENDING	07/01/10	07/01/11	Building Deductibl	950000 2500	
DES	L CRIPTI	ON OF OPERATIONS / LOCATIONS / VEHIC	L LES / EXCLUSIONS ADDED BY ENDORS	I SEMENT / SPECIAL PRO	VISIONS	Ber men men den bester bester den bester bes		
CE	RTIFI	CATE HOLDER		CANCELLAT	ION		eresenen er erestaturen (op - universitet er et en	
				SHOULD ANY O	F THE ABOVE DESCRI	BED POLICIES BE CANCELLED	BEFORE THE EXPIRATION	
				DATE THEREOF	, THE ISSUING INSURI	ER WILL ENDEAVOR TO MAIL	10 DAYS WRITTEN	
Klein Bank LOAN: 290757 PO Box 119				NOTICE TO THE	NOTICE TO THE CERTIFICATE HOLDER NAMED TO THE LEFT, BUT FAILURE TO DO SO SHALL IMPOSE NO OBLIGATION OR LIABILITY OF ANY KIND UPON THE INSURER, ITS AGENTS OR REPRESENTATIVES.			
				IMPOSE NO OB				
		Chaska MN 55318		AUTHORIZED RE				
AC	APA	25 (2009/01)	taa koken ykkoningon kenakrisid senakrisid senakrisid eksterrisid senakrisid senakrisid kan dalah da	- CVE		ORPORATION, All rights	s reserved.	

### ELECTRIC, FIRE AND SECURITY INC. • 4921 BABCOCK TRAIL • I.G.H., MN 55077 • (651) 450-0352

SERVICE REPORT CUSTOMER AUTH. JOB NUMBER SERVICED BY 102 700 **CUSTOMER NAME AND ADDRESS** PHONE NUMBER FULLEY AC | | | - | | | - | | | | EXT. PHONE IN ADVANCE **DATE PROMISED** O YES O NO 1AU NAME OF CONTACT AND UNIT NUMBER BILL TO: ☐ CONTRACT ☐ SERVICE ☐ WARRANTY ☐ OTHER ☐ FIRE ALARM ☐ DOOR ENTRY ☐ INSPECT. ☐ PHONE ☐ NURSE CALL ☐ MATY ☐ ELECT. ☐ EM. LIGHTING PROBLEM: DISPATCHED DATE: Mary mary and TIME: PM WORK PERFORMED: ARRIVED AT SITE DATE: KMIAIEN O=PAIDEM DATEN AM TIME: LOXUAL WIRING PM TRAVEL TO JOB SPECIAL TRAVEL **BENCH TIME** WAIT TIME TIME AT JOB SUPPLY TIME RETURN TRAVEL HOURS COMMENTS: **OVERTIME TOTAL HOURS DESCRIPTION PRICE** DESCRIPTION **PRICE** P.O. STK. P.O. STK. # TOTAL. ☑ JOB COMPLETED ☐ ADDITIONAL WORK NEEDED CONTINUED ON INVOICE NO. WORK COMPLETED BY DATE **CUSTOMER SIGNATURE** DATE
















CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-8951

 Web:
 www.stpaul.gov/dsi

November 9, 2010

Hoang Dao 1445 Shryer Ave W Roseville MN 55113-5831

### NOTICE OF CONDEMNATION UNFIT FOR HUMAN HABITATION ORDER TO VACATE

RE: 360 FULLER AVE

Dear Property Representative:

Your building was inspected on November 9, 2010.

The building was found to be unsafe, unfit for human habitation, a public nuisance, a hazard to the public welfare or otherwise dangerous to human life. A Condemnation Placard has been posted on the building.

The following deficiency list must be completed or the building vacated by the re-inspection date.

A reinspection will be made on November 24, 2010 at 1 pm.

CONDEMNATION OF THE BUILDING REVOKES THE CERTIFICATE OF OCCUPANCY.

Failure to complete the corrections may result in a criminal citation. The Saint Paul Legislative Code requires that no building be occupied without a Fire Certificate of Occupancy.

### **DEFICIENCY LIST**

- 1. 362-1 and throughout MSFC 703 Provide, repair or replace the fire rated door and assembly. The minimum rating must be:-Repair and maintain the door closer.
- 2. 362-1, 2 and 360-3 MSFC 1003.3.1.8 Remove unapproved locks from the unit doors. The door must be openable from the inside without the use of keys or special knowledge or effort.

- 3. 362-1-4, 360-3 SPLC 34.13 (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the sleeping rooms to: 2 occupants.-Building 362-1, 2, 3, and 4 Building 360-3

  No access to unit 1
- 4. 362-1-4, 360-3 SPLC 34.13 (2), (3), SPLC 34.17 (2) Reduce and maintain the number of occupants in the unit.
- 5. 362-2, 4 MSFC 1011.2 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exitway.
- 6. Basement SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.-Remove all mattresses, couches, furniture, tires, personal items from the basement.
- 7. Basement MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area.
- 8. Exterior SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screen. Replace all torn or missing screens.
- 9. Exterior-Throughout SPLC 34.09 (3). 34.32 (3) Repair and maintain the window glass.
- 10. Exterior-Throughout SPLC 34.09 (3), 34.32 (3) Provide or repair and maintain the window screen.-Replace all missing and torn screens.
- 11. Interior SPLC 34.23, MSFC 110.1 This occupancy is condemned as unfit for human habitation. This occupancy must not be used until re-inspected and approved by this office.-This building is condemned based on multiple deficiencies and the majority of all units over-occupied. This property is not maintained or managed and should have an administrator appointed.
- 12. Interior SPLC 34.19 Provide access to the inspector to all areas of the building. Provide access to all units including unit 1, and the basement.
- 13. Interior-Basement MN Stat 299F.18 Immediately remove and discontinue excessive accumulation of combustible materials.-Remove all furniture and mattresses from the basement.
- 14. Interior-Basement and Hallways MSFC 315.2.5 Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operator or repaired within a building.
- 15. Interior-Hallways MSFC 308.2.1 No person shall throw or place, or cause to be thrown or placed, a lighted match, cigar, cigarette, matches, or other flaming or glowing substance or object on any surface or article where it can cause an unwanted fire.

- 16. Interior-Throughout SPLC 34.12 (2), 34.35 (1) Repair and maintain all required and supplied equipment in an operative and safe condition.-Repair or replace all broken and missing door handles throughout.
- 17. Interior-Throughout SPLC 34.11 (6) Provide and maintain a minimum of 68 degrees F in all habitable rooms at all times.-Building 360 radiators are cold and unit 360-2 using space heater.
- Interior-Throughout MSFC 907.20 as amended Provide required annual maintenance of the fire alarm system by a qualified person and provide written documentation to this office as proof of compliance.-Immediately have the annual maintenance of the fire alarm system and provide written verification.
  - 19. Throughout All Units SPLC 34.09 (3), 34.32 (3) Repair and maintain the window sash.-All openable windows must be able to remain in the open position when opened.
  - 20. Throughout All Units and Hallways SPLC 34.10 (7), 34.33 (6) Repair and maintain the walls in an approved manner.-Paint and patch the walls throughout as necessary.
- Unit 3 SPLC 34.10 (6), 34.33 (5) Exterminate and control insects, rodents or other pests. Provide documentation of extermination.-Report of mice. Hire a licensed exterminator to treat the unit for mice and roaches.
  - 22. Unit 360-2 MSFC 605.5 Discontinue use of extension cords used in lieu of permanent wiring.
  - 23. Unit 360-2 MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-9090.-Immediatly discontinue use of lamps hung upside down hanging on extension cords-Fire hazard.
  - 24. Unit 362-2 MSFC 901.6 Provide required annual maintenance of the fire extinguishers by a qualified person and tag the fire extinguishers with the date of service.-Fire extinguisher expired in 2008. Immediately service all expired fire extinguishers.
  - Unit 362-2 SPLC 34.10 (7), 34.33 (6) Repair or replace and maintain the woodwork in an approved manner.-Replace the entry door to unit.
    - SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.

      Provide fuel report.
  - 27. SPLC 39.02(c) Complete and sign the provided smoke detector affidavit and return it to this office.

For an explanation or information on some of the violations contained in this report, please visit our web page at: http://www.ci.stpaul.mn.us/index.aspx?NID=211

## INSPECTION REQUEST

Address: 360 FULLER AVE
x Residential: Multi Family Residential/Commercial Commercial
Type Construction: 2 story wood frame
Category: II Accessory Structures: None
Referred by: Martin Of: Fire Insp
Condemned: Yes No x Date: Condemnation was lifted but CofO still revoked.
Opening category II vacant building per C of O revocation by Fire Inspector Martin. Fire Inspection Supervisor Owens has confirmed category II vacant building status. At time of inspection found building to be vacant and secure, yard area acceptable. Posted placards and took photos. I spoke with PO, Mr. Hoang Dao, p# 651 353 8971, I told him we were discussing cat I or cat II status and I would call him on the morning of Dec 1, 2010 to notify him of the decision. I called Mr. Dao this morning and left voice message that building has been determined to be a cat II VB due multiple outstanding code violation and he will now need to go through CCI process. ~MD
Category: II  Photos: Yes Placards: Yes
Signed: Matt Dornfeld Date: December 1 2010

December 1, 2010

Date:

Signed: