402 Munnehaha the W

Basement steps Dryer Kitchen floor Wallboard	Smoke detector affadavit Windows	Smoke, CO alarms	Electrical	Furnaces & Water Heaters Plumbing	Category
32, 33, 34 1 52 46, 51, 53	58 10, 11, 12, 13, 14, 25	26,35	44, 38, 39, 40, 41, 42	28, 29, 31, 37, 56, 57	Items
Carpenter and inspector contacted - spce presents code compliance challenge Dryer not connected - no gas line. To avoid onfusion, \ Flooring replacement n - old linoleum removed in downstairs kitchen, new flooring installed in all kitchens, bathrooms & stairway landings Drywall removed to track plumbing leak - replace	CO/gas digital monitor installed in basement- no detection Sent to DCI - not requested at time of inspection Estimates obtained for installation of all upper level windows, new bedroom egress window downstairs, and repairs of window frames on lower levels - Site visit tomorrow.	Defective circuit breaker replaced - electrical corn in kitchen removed Upstairs light fixtures that were dropped for painting and all receptacle, switch plates removed for painting were restored to position, Smoke and CO alarms already present in lower unit at time of inspection Smoke and CO alarms installed in upper unit day of inspection	Pumber confirmed on sink installation Electrician confirmed on panel inspection, GFI circuit in bathroom, unapproved line in basement Orphan circuits in basement removed Cover plates for receptacles, switches & junction boxes	Site visit by contractor & bid accepted 7/25/11 Clothes hamper within 30" moved Down tubes on water heater installed CO/gas digital monitor installed - no detection Leak stopped - new wax ring installed on toilet	Status
Underway at time of inspection Contractor contacted	<			Underway	Start
Completed	Completed Completed	Completed Completed Completed	Underway Underway Completed Completed	Aug. 15, 2011 Completed	Projected Completion

Cabinets, upstairs flooring, woodowrk	Bathroom ventilation	Exterior lighting Appearance		Root Exterior doors Porch deck walkways	Pets	Cleanliness
50, 52, 54	30	3, 5, 47 6, 15, 16		, 8,9,24 2 17 18 19	27	45, 48, 49, 52, 23
Molding around new and some existing doors will be installed - seeking clarification on flooring comments and cabinets	House painted 2X in 14 years - waiting site visit by contractor on vinyl siding estimate Holes repaired - waiting arrival of salvaged siding appropriate for 1917 construction Both bathrooms have exhaust fan ventilation	Light fixtures near front and rear doors, stairwell replaced. Missing globe replaced Grass and weeds in fenceline cut, weeds along west side of house pulled, weeds pulled where boat was parked	Conversation with DSI indicates no handrails required on rear deck - seeking clarification on what handrails were damaged or need repair Rear deck installed under permit - seeking clarification on inspector's comments Weeds (creeping charlie overgrowing edge of sidewalk cut)	No leakage present from root, no inspection of roof actually conducted. Did mention that I had obtained estimated to reroof house. Exterior doors primed and where missing molding replacesd. Deadbolt installed. Front porch purchased - waiting delivery and installation	Volunteers have helped clean out lower level and basement - Dumpster provided nearly full Clear, unostructed pathway present to all exits Dog feces removed and floor disinfected Pets licensed and neutered	Ramsey Co. Public Health - house calls program contacted - Social worker has visited tenant several times
comment Completed	r Seeking clarification of	Completed	Completed	Completed	Completed Completed Completed	

	Vehicles and Boat				Garage and rear fence
	20				15
operational, Don't think inspector actually looked and certainly didn't ask.	All vehicles including boat and trailer licensed. All vehicles	under permit, will be replaced.	When trash dumpster removed, rear fence, previously installed	completed	Repairs and repainting will take place after housing priorities
licensed	Already				