



CITY OF SAINT PAUL  
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220  
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989  
Facsimile: 651-266-9124  
Web: [www.stpaul.gov/dsi](http://www.stpaul.gov/dsi)

## Code Compliance Report

March 10, 2011

PRODIGY REAL ESTATE  
2035 COUNTY ROAD D EAST STE E  
MAPLEWOOD MN 55109

Re: 936 Earl St  
File#: 10 128265 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on February 22, 2011.

Please be advised that this report is accurate and correct as of the date March 10, 2011. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from March 10, 2011. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

**BUILDING**                      **Inspector: Jim Seeger**                      **Phone: 651-266-9046**

- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Remove or encapsulate asbestos in an approved manner.
- Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Strap or support top of stair stringers for structural stability.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts.
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Install floor covering in bathroom and kitchen that is impervious to water.
- Repair walls, ceiling and floors throughout, as necessary.

Re: 936 Earl St  
March 10, 2011  
Page 2

---

<b>BUILDING</b>	<b>Inspector: Jim Seeger</b>	<b>Phone: 651-266-9046</b>
-----------------	------------------------------	----------------------------

---

- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Provide major clean-up of premises.
- Verify proper venting of bath exhaust fan to exterior.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Install downspouts and a complete gutter system on north side of house and garage.
- Install rain leaders to direct drainage away from foundation.
- Provide general rehabilitation of garage.
- Install address numbers visible from street and on the alley side of garage.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Openings in stair risers must be less than 4 inches.
- Replace or remove fence.
- Install tempered glass in front stair window.
- Install 1 hour fire rated wall at north wall of garage.
- Install pop open hardware on 3rd floor door.
- Call for insulation inspection for second floor rear room that is gutted.
- Third floor window at top of stairs needs to be tempered.
- Remove or cement shut fireplace.
- Replace all decayed siding, trim and flashing.
- Replace basement stairs.
- A building permit is required to correct the above deficiencies.

---

<b>ELECTRICAL</b>	<b>Inspector: Dan Jambor</b>	<b>Phone: 651-266-9032</b>
-------------------	------------------------------	----------------------------

---

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Provide a complete circuit directory at service panel indicating location and use of all circuits
- Verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Verify that fuse/circuit breaker amperage matches wire size
- Close openings in service panel/junction box with knock out seals, breaker blanks and/or junction boxes

Re: 936 Earl St  
March 10, 2011  
Page 3

**ELECTRICAL**      **Inspector: Dan Jambor**      **Phone: 651-266-9032**

- Properly strap cables and conduits in basement/ service conduit on the exterior of the house.
- Install/replace GFCI receptacle in basement/first/second bathroom adjacent to the sink
- Ground bathroom light in basement/first bathroom/second bathroom and disconnect receptacle on fixture
- Remove all cord wiring
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code
- Install hard-wired, battery backup smoke detector per bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Remove and or/ re-wire all illegal, improper or hazardous wiring in basement/garage
- Replace all painted-over receptacles.
- **Note:** Both Units - Provide ground rod.
- Throughout building, install outlets and light fixtures as specified in Bulletin 80-1.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

**PLUMBING**      **Inspector: Denny Watters**      **Phone: 651-266-9051**

- Basement - Both Water Heaters - T and P relief discharge piping incorrect (MPC 2210 Subp. 4)
- Basement - Water Heater - No gas shut off or gas piping incorrect (IFGC 402.1)
- Basement - Water Heater - Vent must be in chimney liner (IFGC 501.12)
- Basement - Water Heater - Water piping incorrect (MPC 1730 Subp. 1)
- Basement - Water Heater - gas venting incorrect (IFGC 503)
- Basement - Water Heater - not fired or in service (MPC 2180)
- Basement - Water Meter - meter is removed or not in service (MPC 4715.1700)
- Basement - Gas Piping - pipe sizing incorrect (IFGC 402.1)
- Basement - Laundry Tub - faucet is missing, broken or parts missing (MPC 0200. P.)
- Basement - Laundry Tub - unvented (MPC 0200 E)
- Basement - Laundry Tub - waste incorrect (MPC 2300)
- Basement - Laundry Tub - water piping incorrect (MPC 0200 P.)

Re: 936 Earl St  
March 10, 2011  
Page 4

**PLUMBING**                      **Inspector: Denny Watters**                      **Phone: 651-266-9051**

- Basement - Soil and Waste Piping - improper connections, transitions, fittings or pipe usage (MPC 2420) Ferncos on stack.
- Basement - Soil and Waste Piping - no front sewer clean out (MPC 1000)
- Basement - Soil and Waste Piping - no soil stack base clean out
- First Floor - Laundry Stand Pipe - unvented (MPC 0200 E)
- First Floor - Laundry Tub - Stand pipe - waste incorrect (MPC 2300)
- First Floor - Sink - waste incorrect (MPC 2300)
- First Floor - Toilet Facilities - fixture is missing (MPC 0200 0.)
- First Floor - Toilet Facilities - unvented (MPC 0200. E)
- First Floor - Tub and Shower - faucet is missing (MPC 0200. P.)
- First Floor - Tub and Shower - fixture is missing (MPC 0200 0.)
- First Floor - Tub and Shower - unvented (MPC 0200. E)
- Second Floor - Lavatory - unvented (MPC 0200. E)
- Second Floor - Lavatory - waste incorrect (MPC 2300)
- Second Floor - Sink - unvented (MPC 0200. E)
- Second Floor - Sink - waste incorrect (MPC 2300)
- Second Floor - Toilet Facilities - unvented (MPC 0200. E)
- Second Floor - Tub and Shower - unvented (MPC 0200. E)
- Second Floor - Tub and Shower - waste incorrect (MPC 2300)
- Obtain plumbing permits prior to commencement of work.

**HEATING**                      **Inspector: Maureen Hanson**                      **Phone: 651-266-9043**

- Clean and Orsat test boiler burner. Check all controls for proper operation. Provide documentation from a licensed contractor that the heating unit is safe.
- Install approved metal chimney liner.
- Connect boiler and water heater venting into chimney liner.
- Vent clothes dryer to code.
- Provide adequate combustion air and support duct to code.
- Provide support for gas lines to code.
- Plug, cap and/or remove all disconnected gas lines and any unapproved valves.
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- Provide heat in every habitable room and bathrooms.
- Support supply and return piping for heating system according to code.
- Conduct witnessed pressure test on hot water heating and gas piping systems and check for leaks.
- Install back flow preventer on city water fill line to hot water heating system and pipe vent as required.
- Repair or replace radiator valves as needed.
- Mechanical permits are required for the above work.

Re: 936 Earl St  
March 10, 2011  
Page 5

## **ZONING**

1. This property is in a (n) RT1 zoning district.
2. This property was inspected as a Duplex.

### **Notes:**

- See attachment for permit requirements and appeals procedure.
- Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.
- Interior of garage not available for inspection. Repair per applicable codes.

**This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).**

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger  
Code Compliance Officer  
Department of Safety and Inspections  
City of Saint Paul  
375 Jackson Street, Suite 220  
Saint Paul MN 55101  
Phone: 651-266-9046  
Email: james.seeger@ci.stpaul.mn.us

JLS:ml  
Attachments