

CITY OF SAINT PAUL Christopher B. Coleman, Mayor 375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 *Telephone:* 651-266-8989 *Facsimile:* 651-266-9124 *Web:* <u>www.stpaul.gov/dsi</u>

October 15, 2010

VAN ANH THI NGUYEN 10938 WACONIA COURT NE BLAINE MN 55449

Re: 1187 Edgerton St File#: 07 171207 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on September 22, 2010.

Please be advised that this report is accurate and correct as of the date October 15, 2010. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from October 15, 2010. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING	Inspector: Jim Seeger	Phone: 651-266-9046
	inspectore on seeger	

- Insure basement cellar floor is even, is cleanable, and all holes are filled.
- Install plinth blocks as needed under posts in basement & ensure adequate footing for load imposed.
- Tuck Point interior/exterior of foundation as necessary.
- Remove mold, mildew and moldy or water damaged materials.
- Permanently secure top and bottom of support posts in an approved manner.
- Cover water meter pit with concrete or decay resistant, screwed-down cover. Cleanouts to be flush with floor slab.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Strap or support top of stair stringers for structural stability.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts.
- Repair or replace damaged doors and frames as necessary, including storm doors.

BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Weather seal exterior doors, threshold and weather-stripping.
- Install floor covering in bathroom and kitchen that is impervious to water.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Any framing members that required repair or do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner.
- Re-level structure as much as is practical.
- Provide fire block construction as necessary and seal chases in basement ceiling.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Co Conservation Code and the MN Dept. of Labor and Industry.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Provide general rehabilitation of garage.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Openings in stair risers must be less than 4 inches.
- Replace rear porch entry stairs and deck to code, also se conc floor deck or remove.
- Replace roof hover hang on front porch.
- Replace bathtub.
- Install support for floor joist in basement for north side bay area.
- Remove all decayed floor joist, post and beams and replace per code. Many support problems with beams and post.
- Install new stairs to basement from rear grade level entry.
- Install insulated doors at entry points per code requirements.
- Install tapered glass at rear entry windows to code.
- Install new tub surround in first floor bathroom
- Install tempered glass at window in front stair landing and rear stair landing to code.
- Remove second floor kitchen.
- Install one hour fire rated wall at south side of garage to meet fir rating between property lines.
- A building permit is required to correct the above deficiencies.

ELECTRICAL Inspector: Dan Moynihan

Phone: 651-266-9036

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Verify that circuit breaker amperage matches wire size
- Close openings in service panel/junction box with knock out seals, breaker blanks and/or junction boxes
- Replace GFCI receptacle in second bathroom adjacent to the sink
- Ground bathroom light in second bathroom
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Install hard-wired, battery backup smoke detector per bulletin 80-1 and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Properly wire exterior lights at back door
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the 2008 NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBINGInspector: Tom SchweitzerPhone: 651-266-9055• Basement - Gas Piping - dryer gas shutoff; connector or piping incorrect (IFGC 402.1)

- Basement Gas Piping run dryer vent to code (IFGC 613.1 IMC 604.1)
- Basement Laundry Tub unvented (MPC 0200 E)
- Basement Laundry Tub water piping incorrect (MPC 0200 P.)
- Basement Soil and Waste Piping no soil stack base clean out
- Basement Water Heater No gas shut off or gas piping incorrect (IFGC 402.1)
- Basement Water Heater T and P relief discharge piping incorrect (MPC 2210 Subp. 4)
- Basement Water Heater Water piping incorrect (MPC 1730 Subp. 1)
- Basement Water Heater gas venting incorrect (IFGC 503)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Meter raise meter to a minimum 12 inches above floor (MPC 2280)
- Basement Water Meter support meter properly (MPC 2280)
- Basement Water Piping add appropriate hangers (MPC 1430 Subp. 4)
- Basement Water Piping provide water piping to all fixtures and appliances (MPC 1700)

PLUMBING Inspector: Tom Schweitzer Phone: 651-266-9055

- Basement Water Piping run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Exterior Lawn Hydrants Requires backflow assembly or device (MPC 2000)
- First Floor Gas Piping range gas shut off; connector or piping incorrect (IFGC 411 1.3.3)
- First Floor Sink Provide clean out on kitchen stack
- First Floor Sink waste incorrect (MPC 2300)
- First Floor Toilet Facilities incorrectly vented (MPC 2500)
- First Floor Tub and Shower incorrectly vented (MPC 2500)
- First Floor Tub and Shower provide stopper (MPC 1240)
- Second Floor Gas Piping range gas shut off; connector or piping incorrect (IFGC 411 1.3.3)
- Second Floor Lavatory faucet is missing, broken, or parts missing (MPC 0200.P.)
- Second Floor Sink waste incorrect (MPC 2300)
- Second Floor Tub and Shower Provide access (MPC 0900)
- Second Floor Tub and Shower faucet is missing, broken or parts missing (MPC 0200. P.)
- Obtain plumbing permits prior to commencement of work.

HEATING Inspector: Jerry Hanson Phone: 651-266-9044

- Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leaks; provide documentation from a licensed contractor that the heating unit is safe.
- Vent clothes dryer to code.
- Provide support for gas lines to code.
- Plug, cap and/or remove all disconnected gas lines.
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide access for inspection of inside of ducts or provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
- Repair and/or replace heating registers as necessary.
- Provide heat in every habitable room and bathrooms.
- Conduct a witnessed pressure test on the entire gas piping system.
- A gas mechanical permit is required for the above work.

ZONING

- 1. This property is in a(n) R4 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

Notes:

- See attachment for permit requirements and appeals procedure.
- Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.
- Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Joe Ehrlich between 7:30 - 9:00 AM at 651-266-8989 or leave a voice mail message.

Sincerely,

James L. Seeger Code Compliance Officer

JLS:dj

Attachments