

**Date:** September 15, 2011  
**File #:** 11 - 276186  
**Folder Name:** 23 ISABEL ST W  
**PIN:** 072822110042

**HP District:**  
**Property Name:** O.A. Beal House  
**Survey Info:** RA-SPC-1952



Unapproved exterior electrical wiring



Bulge in wall, deteriorated masonry



West side and garage



South side



Unfinished rehab




Front posting



**Date:** September 15, 2011  
**File #:** 11 - 276186  
**Folder Name:** 23 ISABEL ST W  
**PIN:** 072822110042

**HP District:**  
**Property Name:** O.A. Beal House  
**Survey Info:** RA-SPC-1952



**Posting for owner's agent**



**Open wall**



**Water damaged masonry**



**Unfinished rehab**



**Missing caulk, open wall**



**Missing caulk, open wall**



**Date:** September 15, 2011  
**File #:** 11 - 276186  
**Folder Name:** 23 ISABEL ST W  
**PIN:** 072822110042

**HP District:**  
**Property Name:** O.A. Beal House  
**Survey Info:** RA-SPC-1952



**Shed**



**Electrical conductors coming out of the ground**



**East side**