Date: February 01, 2011
File #: 11 - 011345
Folder Name: 437 BANFIL ST
PIN: 012823340016



South and east sides




Garage



North and west sides

March 31, 2011 11 - 011345 Date: File #: **Folder Name: 437 BANFIL ST** PIN: 012823340016









Posting

Date: February 10, 2012 File #: 11 - 011345 Folder Name: 437 BANFIL ST PIN: 012823340016



Open plumbing vent



Water damaged walls and ceiling



Water damaged walls and ceiling, mold



Water damaged, open wall, mold



Water damaged walls and ceiling, mold




Water damaged, buckled, sloping floor

Date: February 10, 2012 File #: 11 - 011345 Folder Name: 437 BANFIL ST PIN: 012823340016



Water damaged walls and ceiling, mold





'S'trap unvented plumbing



Water damaged floor covering and wall



Bathroom shower/tub



Open plumbing in basement




Posts in contact with the floor, water damaged

Date: February 10, 2012 File #: 11 - 011345 Folder Name: 437 BANFIL ST PIN: 012823340016



02/10/2012

Water damaged walls, peeling paint





Damaged, open kitchen floor covering



'S' trap unvented plumbing



Water damaged walls and ceiling, peeling paint



North most west side deck



2nd floor south side flat roof

Date: February 10, 2012 File #: 11 - 011345 Folder Name: 437 BANFIL ST

PIN: 437 BANFIL S 012823340016



Chimney



South side 2nd floor flat roof



Garage



North and west sides



Foundation

Date: «Indate» HP District: «overlay»
File #: «filenum» Property Name: «hpname»
Folder Name: «foldername» Survey Info: «hpinvent»

PIN: «PIN»

Date: March 06, 2012 File #: 11 - 011345 Folder Name: 437 BANFIL ST PIN: 012823340016



South most west side posting

Date: March 06, 2012 File #: 11 - 011345 Folder Name: 437 BANFIL ST PIN: 012823340016 HP District: Property Name: Survey Info:



North most west side posting