

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 Telephone: 651-266-8989 Facsimile: 651-266-9124 Web: www.stpaul.gov/dsi

# **Code Compliance Report**

July 11, 2012

AXIS REALTY C/O TERRY DANIELS 121 MCKNIGHT ROAD N # A ST PAUL MN 55119 \* \* This Report must be Posted on the Job Site \* \*

Re: 1673 Cottage Ave E File#: 11 127342 VB3

Dear Property Owner:

The following is the Code Compliance report you requested on January 05, 2012.

Please be advised that this report is accurate and correct as of the date July 11, 2012. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from July 11, 2012. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

#### BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Repair walls, ceiling and floors throughout, as necessary.
- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible.
- Provide major clean-up of premises.

Re: 1673 Cottage Ave E

July 11, 2012

Page 2

## BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Provide general rehabilitation of garage.
- Review all applicable codes & policies when replacing windows including egress windows for sleeping rooms.
- Remove all floor covering from first floor and basement including stairs.
- Remove all and ceiling covering from basement.
- Install egress windows in all third floor bedrooms.
- Have all of house mitigated by a licensed mitigating contractor and retested when done for the mold issues in house.
- A building permit is required to correct the above deficiencies.

### ELECTRICAL Inspector: Dan Moynihan Phone: 651-266-9036

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Bond around water meter with a copper wire sized for the electrical service per Article 250 of the NEC
- Close openings in service panel/junction boxes with knockout seals, breaker blanks, and/or junction box covers
- Install/replace GFCI receptacle in first floor bathroom adjacent to the sink
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Replace all electrical with excessive water damage.
- Based on repair list purchase permit for 9 circuits.
- Install garage wiring on exterior of house in an approved conduit system.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All buildings on the property must meet the St. Paul Property Maintenance Code (Bulletin 80-1).
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

#### PLUMBING Inspector: Rick Jacobs Phone: 651-266-9054

- Basement Water Heater missing install the water heater to code.
- Basement Water Meter corroded piping; incorrect piping (MPC 0200 0.)
- Basement Water Meter meter is removed or not in service (MPC 4715.1700)
- Basement Water Meter service valves not functional or correct (MPC 1800 Subp 3,4)
- Basement Water Piping provide water piping to all fixtures and appliances (MPC 1700)

Re: 1673 Cottage Ave E

July 11, 2012

Page 3

## PLUMBING Inspector: Rick Jacobs Phone: 651-266-9054

- Basement Water Piping some water piping is missing install to code.
- Basement Water Piping repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement Water Piping run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement Gas Piping dryer gas shutoff; connector or piping incorrect (IFGC 402.1)
- Basement Gas Piping replace improper piping or fittings (IFGC 406.1.2)
- Basement Gas Piping run dryer vent to code (IFGC 613.1 IMC 604.1)
- Basement Soil and Waste Piping unplugged or open piping; back pitched piping (MPC 1000)
- Basement Lavatory, toilet and shower are missing.
- Basement Lavatory faucet is missing, broken, or parts missing (MPC 0200.P.)
- Basement Lavatory fixture is broken or parts missing (MPC 0200 0.)
- Basement Lavatory waste incorrect (MPC 2300)
- Basement Lavatory water piping incorrect (MPC 0200 P.)
- Basement Toilet Facilities faucet is missing, broken or parts missing (MPC 0200. P.)
- Basement Toilet Facilities fixture is broken or parts missing (MPC 0200 0.)
- Basement Toilet Facilities waste incorrect (MPC 2300)
- Basement Toilet Facilities water piping incorrect (MPC 0200 P.)
- Basement Shower faucet is missing, broken or parts missing (MPC 0200. P.)
- Basement Shower fixture is broken or parts missing (MPC 0200 0.)
- Basement Shower provide anti-scald valve (MPC 1380. Subp. 5)
- Basement Shower waste incorrect (MPC 2300)
- Basement Shower water piping incorrect (MPC 0200 P.)
- First Floor Lavatory is missing install to code.
- First Floor Lavatory faucet is missing, broken, or parts missing (MPC 0200.P.)
- First Floor Lavatory fixture is broken or parts missing (MPC 0200 0.)
- First Floor Tub and Shower incorrectly vented (MPC 2500)
- First Floor Tub and Shower provide anti-scald valve (MPC 1380. Subp. 5)
- First Floor Tub and Shower waste incorrect (MPC 2300)
- Obtain plumbing permits prior to commencement of work.

# HEATING Inspector: Maureen Hanson Phone: 651-266-9043

- Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe
- Replace furnace flue venting to code
- Connect furnace and water heater venting into chimney liner
- Vent clothes dryer to code
- Provide adequate combustion air and support duct to code
- Provide support for gas lines to code
- Plug, cap and/or remove all disconnected gas lines.

1673 Cottage Ave E Re:

July 11, 2012

Page 4

HEATING **Inspector: Maureen Hanson** Phone: 651-266-9043

- Install furnace air filter access cover
- Clean all supply and return ducts for warm air heating system
- Repair and/or replace heating registers as necessary
- Provide heat in every habitable room and bathrooms
- Mechanical gas permit is required for the above work.

#### **ZONING**

- 1. This property is in a(n) R3 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

#### **Notes:**

- See attachment for permit requirements and appeals procedure.
- Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger, Code Compliance Officer Department of Safety and Inspections City of Saint Paul 375 Jackson Street, Suite 220 Saint Paul MN 55101

Phone: 651-266-9046

Email: james.seeger@ci.stpaul.mn.us

JLS:ml Attachments