

Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Deteriorated front steps, exposed rebar

Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Plumbing improperly installed and incorrect materials installed without permit

Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Floors throughout main floor

Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



¼ Newly installed since last inspection OSB used to enclose unapproved basement bathroom.

Date: September 08, 2014
File #: 14 - 320006
Folder Name: 318 FRONT AVE
PIN: 252923420224



Basement bathroom

