

RLH VO 15-11

APPLICATION FOR APPEAU

6	C'ID 1011		
TA TERMENT HAVE PA	Saint Paul City Council – Legislative Hearings		
The state of the s	RECEI	VED 310 City Hall, 15 W. K Saint Paul, Min	00
AO TVAS INTERNAL INTE	MAR 04	2015 Telephone: (6	551) 266-8585
We need the following to process your ap	ppeal: CITY CI	ERK	
\$25 filing fee (non-refundable) (payable to (if cash: receipt number	being appealed	HEARING DATE & TIME (provided by Legislative Heart Tuesday, March 2) Time 11:30 a.m. Location of Hearing: Room 330 City Hall/Courthous	, 2015
Address Being Appealed:			
Number & Street: 315 BLAIR AVE City: ST. PAUL State: MU Zip: 55104			
Appellant/Applicant: Eugene Ko	Em	ail eugene. Kotz @	Xce lenerg
Phone Numbers: Business 612-598-57	804 Residence	Cell	
Signature: Lugar n- 16th		Date: 3/4/15	
Name of Owner (if other than Appellant): _	"1		
Mailing Address if Not Appellant's:			
Phone Numbers: Business	Residence	Cell	
What Is Being Appealed	d and Why?	Attachments Are Accept	able
Vacate Order/Condemnation/ Revocation of Fire C of O	See A Ha		
Summary/Vehicle Abatement			-
Fire C of O Deficiency List/Correction			
Code Enforcement Correction Notice			
Vacant Building Registration			
Other (Fence Variance, Code Compliance, etc.)			

To Whom It May Concern, The subject property had a terrible toward that I was proactive in persuit the eviction process. Even though I was going through the process and waiting for my court date, a wisome order was initiated and my building cited for damages caused by this terant. I am renedying the property as no spech, however, the existion! process did not allow for expedient removal of this NVISANCE. I am an upstanding citizen, and have Never had profilens until Now. France planning on selling this property in MAY 2015. Regards Gene Kotz



CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989 Facsimile: 651-266-8951 Web: www.stpaul.gov/dsi

February 20, 2015

EUGENE R KOTZ 2021 BLUE JAY ST SHAKOPEE MN 55379-4384

REVOCATION OF FIRE CERTIFICATE OF OCCUPANCY AND ORDER TO VACATE

RE:

315 BLAIR AVE Ref. # 114498

Dear Property Representative:

Your building was inspected on February 20, 2015, in response to a complaint. Since you have failed to comply with the applicable requirements, it has become necessary to revoke the Certificate of Occupancy in accordance with Section 40.06 of the Saint Paul Legislative Code.

A reinspection will be made on March 2, 2015 at 11:00am. All work must be completed or the property vacated.

The Saint Paul Legislative Code further provides that no building shall be occupied without a Certificate of Occupancy. Failure to immediately complete the following deficiency list or the building vacated may result in a criminal citation.

DEFICIENCY LIST

- 1. INTERIOR FRONT PORCH SPLC 34.23, MSFC 110.1 This occupancy is condemned as unsafe or dangerous. This occupancy must not be used until re-inspected and approved by this office. -Front Porch is condemned due to extensive structural issues. Porch is pulling away from the building and is not properly supported. Immediately repair, replace, or remove under permit. Contact DSI at 651-266-8989.
- 2. EXTERIOR FRONT STEPS SPLC 34.09 (2) 34.32 (2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.

- 3. EXTERIOR GARAGE MSFC 605.1 Remove unapproved exposed wiring and install in accordance with the electrical code. This work may require a permit(s). Call DSI at (651) 266-8989. -Fixtures in the garage.
- 4. GARAGE NFPA 211 8-2.4 Immediately discontinue use and remove the wood burning stove from the residential garage. -Remove the improperly installed woodstove.
- 5. INTERIOR BASEMENT SPLC 34.10 (3), 34.33(2) Provide an approved handrail. The top of the handrail must be between 34 and 38 inches above the treads and run the entire length of the stair.
- 6. INTERIOR BASEMENT SPLC 34.10 (3), 34.33(2) Repair or replace the unsafe stairway in an approved manner. -Basement stair treads were loose and not matching in size.
- 7. INTERIOR BASEMENT MSMC 504.6 Provide, repair or replace the dryer exhaust duct. Exhaust ducts for domestic clothes dryers shall be constructed of metal and shall have a smooth interior finish. The exhaust duct shall be a minimum nominal size of four inches (102 mm) in diameter and installed in accordance with the mechanical code. This work may require a permit(s). Call DSI at (651) 266-8989. -Dryer vent was not properly installed and was not connected to the gas dryer.
- 8. INTERIOR BASEMENT UMC 1346.703 Provide 30 inches clearance around all mechanical equipment. -Items stored too close to the water heater.
- 9. INTERIOR BASEMENT SPLC 34.10 (1) Abate and maintain the basement reasonably free from dampness and free of mold and mildew. -Visible mold on the basement walls.
- 10. INTERIOR BEDROOMS MSFC 1028.3 Remove the materials that cause an exit obstruction. Maintain a clear and unobstructed exit way. -Remove the items blocking the bedroom egress windows.
- 11. INTERIOR DRYER MN Rules 1300.0180 Immediately discontinue use of unsafe heating appliance until repaired or replaced by a licensed contractor. This work may require a permit(s). Call DSI at (651) 266-9090. Red tags may not be removed except by fire inspector. -Dryer was red tagged. Inspector unplugged and shut the gas off to the unit.
- 12. INTERIOR FOUNDATION SPLC 34.09 (1) a, 34.32 (1) a Provide and maintain foundation elements to adequately support this building at all points.
- 13. INTERIOR FOUNDATION SPLC 34.10 (2), 34.33 Repair and maintain the damaged structural member. This repair may require a building permit; call DSI at (651) 266-8989. -Foundation support for the basement was not sitting on its footing.
- 14. INTERIOR KITCHEN MSFC 603.7 Immediately cease using the stove or oven for heating.

- 15. INTERIOR REAR DOOR SPLC 34.09 (3) i Provide and maintain an approved one-inch throw single cylinder deadbolt lock.
- 16. INTERIOR REAR ENTRY DOOR Ext. Door SPLC 34.09 (3), 34.33 (3) Repair and maintain the door in good condition.
- 17. INTERIOR THROUGHOUT MSFC 605.6 Provide electrical cover plates to all outlets, switches and junction boxes were missing.
- 18. INTERIOR THROUGHOUT MSFC 605.1 Repair or replace damaged electrical fixtures. This work may require a permit(s). Call DSI at (651) 266-8989. -There were several broken outlets.
- 19. INTERIOR THROUGHOUT MSFC 1003.3.1.8 Remove unapproved locks from the exit doors. The door must be openable from the inside without the use of keys or special knowledge or effort. -Remove the locks on the basement door and the door leading to the second floor.
- 20. INTERIOR THROUGHOUT MSFC 315.2 Provide and maintain orderly storage of materials.-
- 21. INTERIOR THROUGHOUT MSFC 308.2.1 No person shall throw or place, or cause to be thrown or placed, a lighted match, cigar, cigarette, matches, or other flaming or glowing substance or object on any surface or article where it can cause an unwanted fire. There were several cigarette butts, disposed of on combustible surfaces throughout the home.
- 22. INTERIOR THROUGHOUT MSFC 605.1- All light fixtures shall be maintained with protective globes if originally equipped.
- 23. INTERIOR THROUGHOUT SPLC 34.10 (5), 34.33 (4), 34.16 Provide and maintain interior in a clean and sanitary condition.
- -Basement had a large amount of dirty clothes that were moldy on the floor on a dust covered surface.
- -Thoroughly clean the unit.
- 24. INTERIOR THROUGHOUT SPLC 34.11, MSBC 2902.1, SPLC 34.17, MSPC 415.0220 Repair or replace and maintain all parts of the plumbing system to an operational condition. -There has been recent plumbing work (new fixtures, lines) without any permits obtained.
- 25. INTERIOR SPLC 34.09 (3), 34.33 (3) -Provide or repair and maintain the window screens, where broken or missing.
- 26. INTERIOR SPLC 34.16 (2) Properly dispose all of your garbage in the owner-provided containers.

- 27. INTERIOR MN Stat. 299F.362 Immediately provide and maintain a smoke detector located outside each sleeping area. -Low battery indicator on smoke detector.
- 28. INTERIOR BASEMENT SPLC 34.11 (4), 34.34 (1), MPC 4515, MPC 326 Connect or cap the sewer piping in accordance with the plumbing code. -Main stack was leaking. Contact a licensed plumber to repair under permit. Contact DSI at 651-266-8989.
- 29. INTERIOR THROUHOUT SPLC 34.10 (7), 34.34 (6) Repair and maintain the walls in an approved manner. -There were several holes in the walls.
- 30. SPLC 34.11 (6), 34.34 (3) Provide service of heating facility by a licensed contractor which must include a carbon monoxide test. Submit a completed copy of the Saint Paul Fire Marshal's Existing Fuel Burning Equipment Safety Test Report to this office.
- 31. SPLC 39.02(c) Complete and sign the smoke detector affidavit and return it to this office.

Saint Paul Legislative Code authorizes this inspection and collection of inspection fees. For forms, fee schedule, inspection handouts, or information on some of the violations contained in this report, please visit our web page at: http://www.stpaul.gov/cofo

You have the right to appeal these orders to the Legislative Hearing Officer. Applications for appeals may be obtained at the Office of the City Clerk, 310 City Hall, City/County Courthouse, 15 W Kellogg Blvd, Saint Paul MN 55102 Phone: (651-266-8585) and must be filed within 10 days of the date of this order.

If you have any questions, email me at: adrian.neis@ci.stpaul.mn.us or call me at 651-266-8992 between 7:30 - 9:00 a.m. Please help to make Saint Paul a safer place in which to live and work.

Sincerely,

A.J. Neis Fire Inspector

Ref. # 114498