



CITY OF SAINT PAUL
Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, Minnesota 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-9124
Web: www.stpaul.gov/dsi

Code Compliance Report

March 08, 2013

Patrick D Keeler
1248 12th Ave N
New Brighton MN 55112-6402

**** This Report must be Posted
on the Job Site ****

Re: 1059 Van Slyke Ave
File#: 06 267582 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on February 27, 2013.

Please be advised that this report is accurate and correct as of the date March 08, 2013. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from March 08, 2013. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

BUILDING **Inspector: Jim Seeger** **Phone: 651-266-9046**

- Tuck Point interior/exterior of foundation as necessary.
- Install 20 minute fire rated doors, with self closing device, between common areas and individual units. All penetrations required to have property intumescent device or caulk (per current building codes).
- Maintain one hour fire separation between dwelling units and between units and common areas.
- Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Repair or replace damaged doors and frames as necessary, including storm doors.
- Weather seal exterior doors, threshold and weather-stripping.
- Install floor covering in bathroom and kitchen that is impervious to water.
- Repair walls, ceiling and floors throughout, as necessary.

Re: 1059 Van Slyke Ave
March 8, 2013
Page2

BUILDING **Inspector: Jim Seeger** **Phone: 651-266-9046**

- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Install rain leaders to direct drainage away from foundation.
- Remove trees which are against foundation of home and garage.
- Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil.
- Install safety glass in window on basement stair landing.
- Install handrails to code on basement stairs.
- Install safety glass in window on rear stair landing to 2nd floor.
- Replace rear header over 2nd floor porch windows and have inspected before covering.
- Install safety glass in window over 2nd floor bathtub.
- Repair front porch, needs new decay resistant framing for post to foundation and re-leveling for 1st. and 2nd floor.
- Insure 3rd. floor is insulated to code over front porch.
- Install handrails and guardrails to code in attic or 3rd. floor.
- Install handrail at front steps (at house and at street)
- Provide major repair to garage on north side , foundation requires repairs and plans for reconstruction.
- A building permit is required to correct the above deficiencies.

ELECTRICAL **Inspector: Dave Blank** **Phone: 651-266-9035**

- Ground the electrical service to the water service with a copper conductor within 5 feet of the entrance point of the water service
- Verify/install a separate 20 ampere laundry circuit and a separate 20 ampere kitchen appliance circuit
- Properly strap cables and conduits in basement/ service conduit on the exterior of the house.
- Ground bathroom light in basement/first bathroom/second bathroom and disconnect receptacle on fixture
- Remove all cord wiring
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code

Re: 1059 Van Slyke Ave
March 8, 2013
Page3

ELECTRICAL **Inspector: Dave Blank** **Phone: 651-266-9035**

- Install hard-wired, battery backup smoke detector and other smoke detectors as required by the IRC. Also, Install carbon monoxide detector(s) within 10 feet of all bedrooms
- Install exterior lights at front/side/back entry doors
- Check building write-up for fire resistance requirements if both panels are in the common area in a basement or move 2nd unit electrical panel board to the second unit
- Install box extensions on paneled walls.
- Verify for correct electrical installations above ACT ceilings and correct if necessary.
- Properly wire boiler circulation pump.
- Install main bonding jumpers.
- Correctly install wiring on rear porch.
- Provide disconnect for water heater.
- Attach service knob.
- Ensure installation of common area circuits from each service panel
- Based on repair list, purchase permit for a minimum of 12 circuits
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.
- All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING **Inspector: Jim Kaufer** **Phone: 651-266-9054**

- Basement - Water Heater - No gas shut off or gas piping incorrect (MFGC 402.1)
- Basement - Water Heater - Vent must be in chimney liner (MFGC 501.12)
- Basement - Water Heater - gas venting incorrect (MFGC 503)
- Basement - Water Heater - not fired or in service (MPC 2180)
- Basement - Water Meter - raise meter to a minimum 12 inches above floor (MPC 2280)
- Basement - Water Meter - service valves not functional or correct (MPC 1800 Subp 3,4)
- Basement - Water Meter - support meter properly (MPC 2280)
- Basement - Water Piping - add appropriate hangers (MPC 1430 Subp. 4)
- Basement - Water Piping - boiler fill water line requires backflow assembly or device (MPC 2100)
- Basement - Water Piping - provide water piping to all fixtures and appliances (MPC 1700)
- Basement - Water Piping - run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement - Gas Piping - dryer gas shutoff; connector or piping incorrect (MFGC 411)
- Basement - Gas Piping - run dryer vent to code (MFGC 614.1 - 614.7)
- Basement - Soil and Waste Piping - no front sewer clean out (MPC 1000)
- Basement - Soil and Waste Piping - no soil stack base clean out
- Basement - Laundry Tub - incorrectly vented (MPC 2500)
- Basement - Laundry Tub - provide a vacuum breaker for the spout (MPC 2000 B)
- Basement - Laundry Tub - waste incorrect (MPC 2300)

Re: 1059 Van Slyke Ave
March 8, 2013
Page4

PLUMBING **Inspector: Jim Kaufer** **Phone: 651-266-9054**

- First Floor - Gas Piping - range gas shut off; connector or piping incorrect (MFGC 411)
- First Floor - Lavatory - waste incorrect (MPC 2300)
- First Floor - Sink - waste incorrect (MPC 2300)
- First Floor - Toilet Facilities - reset the toilet on a firm base (MPC 0870)
- First Floor - Tub and Shower - Provide a vacuum breaker for the handheld shower (MPC 2000 B)
- First Floor - Tub and Shower - provide anti-scald valve (MPC 1380. Subp. 5)
- First Floor - Tub and Shower - replace waste and overflow (MPC 1240)
- Second Floor - Gas Piping - range gas shut off; connector or piping incorrect (MFGC 411)
- Second Floor - Sink - incorrectly vented (MPC 2500)
- Second Floor - Sink - waste incorrect (MPC 2300)
- Second Floor - Toilet Facilities - reset the toilet on a firm base (MPC 0870)
- Second Floor - Tub and Shower - provide anti-scald valve (MPC 1380. Subp. 5)
- Second Floor - Tub and Shower - replace waste and overflow (MPC 1240)
- Second Floor - Tub and Shower - waste incorrect (MPC 2300)
- Exterior - Lawn Hydrants - Requires backflow assembly or device (MPC 2000)
- All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4715 & Chapter 326, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and the Saint Paul Regional Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul under an approved permit.

HEATING **Inspector: Jerry Hanson** **Phone: 651-266-9044**

- Install approved level handle manual gas shutoff valve on furnace/boiler and remove unapproved valve
- Clean and Orsat test both boiler burners. Check all controls for proper operation. Provide documentation from a licensed contractor that the heating units are safe.
- Install approved metal chimney liner
- Connect boiler and water heaters venting into chimney liner.
- Vent clothes dryer to code
- Provide adequate combustion air and support duct to code
- Provide support for gas lines to code
- Plug, cap and/or remove all disconnected gas lines and unapproved valves.
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- Provide heat in every habitable room and bathrooms
- Support supply and return piping from heating system according to code
- Conduct witnessed pressure test on gas piping systems and check for leaks
- Pipe boiler pressure relief valve discharge full outlet size to within 18 inches of the floor.
- Install back flow preventer on city water fill line to hot water heating system and pipe vent as required.

Re: 1059 Van Slyke Ave
March 8, 2013
Page5

HEATING **Inspector: Jerry Hanson** **Phone: 651-266-9044**

- Repair or replace fin tube radiation and covers as needed
- Repair or replace radiator valves as needed
- Place cast iron and copper fin tube radiation on separate heating zones.
- Mark each boiler to which dwelling unit it serves.
- Install isolation valves on boiler supply and return pipes.
- Mechanical gas and hydronic permits are required for the above work.

ZONING

1. This property is in a(n) R4 zoning district.
2. This property was inspected as a Single Family Dwelling

This property was inspected as a Duplex which is not permitted in this zoning district; this property may be a non-conforming use and will require zoning approval before a sale can be approved, any permits may be issued or any work on the property is started.

Notes:

- See attachment for permit requirements and appeals procedure.
- Provide plans and specifications for any portion of the building that is to be rebuilt.
- Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.
- Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger, Code Compliance Officer

Phone: 651-266-9046

JLS:ml

Email: james.seeger@ci.stpaul.mn.us

Attachments