

CITY OF SAINT PAUL Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220 Saint Paul, Minnesota 55101-1806 

 Telephone:
 651-266-8989

 Facsimile:
 651-266-9124

 Web:
 www.stpaul.gov/dsi

# **Code Compliance Report**

August 01, 2013

Leroy Hayes Jr. 9443 Misty Bridge St Houston TX 77075-5023 \* \* This Report must be Posted on the Job Site \* \*

Re: 910 Cottage Ave E File#: 11 307538 VB2

Dear Property Owner:

The following is the Code Compliance report you requested on July 12, 2013.

Please be advised that this report is accurate and correct as of the date August 01, 2013. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from August 01, 2013. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected:

### **ZONING**

- 1. This property is in a(n) R4 zoning district.
- 2. This property was inspected as a Single Family Dwelling.

# BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Tuck Point interior/exterior of foundation as necessary.
- Dry out basement and eliminate source of moisture.
- Remove mold, mildew and moldy or water damaged materials.
- Install handrails (34 inches 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment.
- Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary.
- Provide complete storms and screens, in good repair for all door and window openings.
- Provide functional hardware at all doors and windows
- Weather seal exterior doors, threshold and weather-stripping.
- Repair walls, ceiling and floors throughout, as necessary.

Re: 910 Cottage Ave E

August 1, 2013

Page 2

# BUILDING Inspector: Jim Seeger Phone: 651-266-9046

- Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present.
- Air-seal and insulate attic/access door.
- Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible.
- Provide major clean-up of premises.
- Repair siding, soffit, fascia, trim, etc. as necessary.
- Provide proper drainage around house to direct water away from foundation of house.
- Provide proper drainage around house to direct water away from foundation of garage.
- Install downspouts and a complete gutter system.
- Install rain leaders to direct drainage away from foundation.
- Provide general rehabilitation of garage.
- Remove trees which are against foundation of home and garage.
- Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil.
- Replace sidewalk at top of front stairs from street.
- Replace front steps at house.
- Replace 1st floor bathroom wall covering around bathtub. Have walls inspected before covering.
- Basement had water on floor at time of inspection.
- Replace water damaged siding on garage.
- Raise grade and sidewalk around house and slope soil away from structure.
- A building permit is required to correct the above deficiencies.

#### ELECTRICAL Inspector: Dave Blank Phone: 651-266-9035

- Properly strap cables and conduits in basement.
- Repair or Replace all broken, missing or loose light fixtures, switches and outlets, covers and plates
- Check all outlets for proper polarity and verify ground on 3-prong outlets (no power at time of inspection).
- Remove any 3-wire ungrounded outlets and replace with 2-wire or ground 3-wire to code
- Remove and or/ re-wire all illegal, improper or hazardous wiring in garage (no access).
- Properly wire dishwasher circuit.
- Ensure use of box extensions on paneled walls.
- Install proper outlet box for smoke detector.
- Based on repair list, purchase permit for a minimum of 6 circuits.
- All added receptacles must be grounded, tamper-resistant and be on an Arc-Fault Circuit Interrupter-protected circuit.
- Any open walls or walls that are opened as part of this project must be wired to the standards of the current NEC.

Re: 910 Cottage Ave E

August 1, 2013

Page 3

#### ELECTRICAL Inspector: Dave Blank Phone: 651-266-9035

• All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

## PLUMBING Inspector: Troy McManus Phone: 651-266-9053

- Basement Water Heater gas venting incorrect (MFGC 503)
- Basement Water Heater not fired or in service (MPC 2180)
- Basement Water Meter service valves not functional or correct (MPC 1800 Subp 3,4)
- Basement Water Piping provide water piping to all fixtures and appliances (MPC 1700)
- Basement Water Piping repair or replace all corroded, broken or leaking piping (MPC 4715.1720)
- Basement Water Piping run 1 inch water line from meter to first major take off (SPRWS Water Code)
- Basement Soil and Waste Piping no front sewer clean out (MPC 1000)
- Basement Soil and Waste Piping replace corroded cast iron or steel waste piping (MPC 0200)
- Basement Gas Piping dryer gas shutoff; connector or piping incorrect (MFGC 411)
- Basement Gas Piping run dryer vent to code (MFGC 614.1 614.7)
- Basement Laundry Tub provide a vacuum breaker for the spout (MPC 2000 B)
- Basement Laundry Tub unvented (MPC 0200 E)
- Basement Laundry Tub waste incorrect (MPC 2300)
- Basement Laundry Tub water piping incorrect (MPC 0200 P.)
- Basement Toilet Facilities reset the toilet on a firm base (MPC 0870)
- Basement Toilet Facilities unvented (MPC 0200. E)
- Basement Toilet Facilities waste incorrect (MPC 2300)
- Basement Tub and Shower provide anti-scald valve (MPC 1380. Subp. 5)
- Basement Tub and Shower unvented (MPC 0200. E)
- Basement Tub and Shower waste incorrect (MPC 2300)
- First Floor Lavatory waste incorrect (MPC 2300)
- First Floor Sink incorrectly vented (MPC 2500)
- First Floor Sink waste incorrect (MPC 2300)
- First Floor Sink water piping incorrect (MPC 0200 P.)
- First Floor Toilet Facilities reset the toilet on a firm base (MPC 0870)
- First Floor Toilet Facilities waste incorrect (MPC 2300)
- First Floor Tub and Shower Provide access (MPC 0900)
- First Floor Tub and Shower provide anti-scald valve (MPC 1380, Subp. 5)
- First Floor Tub and Shower replace waste and overflow (MPC 1240)
- First Floor Tub and Shower unvented (MPC 0200. E)
- First Floor Tub and Shower waste incorrect (MPC 2300)
- First Floor Tub and Shower water piping incorrect (MPC 0200 P.)
- Exterior Lawn Hydrants Requires backflow assembly or device (MPC 2000)

Re: 910 Cottage Ave E

August 1, 2013

Page 4

# PLUMBING Inspector: Troy McManus Phone: 651-266-9053

• All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4715 & Chapter 326, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and the Saint Paul Regional Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul under an approved permit.

# HEATING Inspector: Maureen Hanson Phone: 651-266-9043

- Clean and Orsat test furnace burner. Check all controls for proper operation. Check furnace heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe.
- Replace furnace flue venting.
- Connect furnace and water heater venting into chimney liner.
- Vent clothes dryer to code
- Provide support for gas lines to code
- Plug, cap and/or remove all disconnected gas lines
- Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.
- All supply and return ducts for warm air heating system must be clean before final approval for occupancy. Provide documentation from a licensed duct-cleaning contractor that the duct system has been cleaned.
- Repair and/or replace heating registers as necessary
- Provide heat in every habitable room and bathrooms
- Run condensate drain from A/C unit coil three-quarter inch nominal size to an approved location and secure as needed.
- Verify that A/C system is operable, if not, repair, replace or remove and seal all openings.
- Mechanical gas permit is required for the above work.

#### **Notes:**

- See attachment for permit requirements and appeals procedure.
- Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.
- Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

910 Cottage Ave E Re:

August 1, 2013

Page 5

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger Code Compliance Officer Department of Safety and Inspections City of Saint Paul 375 Jackson Street, Suite 220 Saint Paul MN 55101

Phone: 651-266-9046

Email: jim.seeger@ci.stpaul.mn.us

JLS:ml Attachments