


St. Paul Heritage Preservation Commission

August 27, 2015 Public Hearing/Design Review

(%

Central Presbyterian Church

500 Cedar Street Individual Heritage Preservation Site










Figure 1 - Top View, Cedar Street is on the left 2/12/15




Figure 4 View of East side showing hipped roof of rear of church and apartment buildings parking garage immediately behind church 2/12/15




Figure 6 View from South side showing bell tower at left and hipped roof at right 7/27/15




Figure 7 Detail of current portion of south side eastern end of main roof showing missing shingles 7/27/15




Figure 8 Detail view of south side main roof by bell tower showing missing shingles 7/27/15




Figure 9 View taken from southwest side 7/27/15





Figure 10 View taken from northwest side 7/27/15






Figure 12 Detail view of gable of northeast corner showing missing shingles 7/27/15





Figure 137 DECRA stone coated steel shingle XD in natural slate on a different church 6/20/15

Architectural Shingle at a Fraction of the Weight



Shingle XD[®] Installation Components:



Shingle XD[®] Specifications:

Minimum Pitch 🕨	4:12		
Panel Size 🕨	14-1/8" x 52-3/8"		
Installed Exposure ►	12-1/4" x 49-1/2"		
Panels per Square >	23.8		
Installed Weight >	150 lbs./sq.		

Shingle XD[®] Color Blends



Old Hickory



Jaeger Associates, inc 1906- 310th Street Titonka, Iowa 50480 www.jaegerassociatesinc.com 515-320-1635

50 - Year Limited Warranty: 120 mph Wind Warranty: Highest Impact Resistance to Hall, FreezerThem Resistant; Fire Safe; U., File #F(14710; Florida Building Code, Miami-Dade County NOA, COMC and ICC-ES reports available at www.decra.com.






96880258 - 01/18

C BBCRA Rooling Systems, Inc. The USGBC logo is a registered tradematiowned by the USGBC and is used to occordance with USGBC Coaldelines.

DECRA Shingle XD



- Won't Crack, Break, Burn, Curl, Split or Rot
- Walkable, Low Maintenance, Long Life
- Non-Porous, Freeze / Thaw Resistant
- Interlocking Panels Provide Protection Against the Elements

Jaeger Associates, Inc 1906 310th Street. Titonka, Iowa 50480 www.jaegerassociatesinc.com 515-320-1635



Figure 1 St. John Cantius Church Wilno, MN




Figure 2 Detail of St. John Cantius Church



Figure 3 Our Lady of the Prairie Belle Plaine, MN



Figure 4 Detail of Our Lady of the Prairie

500 Cedar Street, Central Presbyterian Church File #15-036 HPC Public Hearing 8-27-15, Item IV.A.

ROOFING MATERIAL COMPARISON TABLE

Product	Thickness	Widths	Exposure	Shape
GAF Timberline*	1/8 to 3/8"	4 1/2 to 5 5/8"	5 5/8"	Trapezoidal
CertainTeed Independence*	1/8 to 1/4"	3 to 8 1/8"	5″	Rectangular
GAF Slateline*	1/8"	7 5/8"	7 1/2"	Trapezoidal
Wood Shingles [‡]	1/4 to 3/8"	3 to 6"	5″	Rectangular
Slate	3/16"	10 to 14"	8"-14"	Rectangular
DECRA Shingle XD ⁺	0.0138" (profile**: 3/8"-1/2")	5 to 7 1/2"	6 1/8"	Rectangular

* tar and gravel surface

** profile of bend in metal panel

[†] stone-coated steel. Measurements based on profile and division of pattern stamped into panels.

[‡]examples are sawn and rough-sawn (not split).

