



737 Plum Street south elevation (above) and southwest elevations (below)







Exposed 4" clapboard beneath cement asbestos shingle (above left), west elevation with projecting bay (above right), and blocked-in windows on south elevation (below)







C. 1970 rear addition (above) and garage (below)







Dining Room west projecting bay window (above left), door trim (above right), and view towards front room (below)







Rear addition kitchen (above) and den (below)







Upstairs hallway (above left), west upstairs bedroom (above right) with dropped ceiling detail, and basement (below)

