## Saint Paul Fire Department FIRE INCIDENT DISPOSITION



INCIDENT NUMBER:	16-41948	DATE OF INCIDENT: 12/06/2016	
TIME OF INCIDENT:	2306 hours	POLICE CASE #: N/A	
INVESTIGATOR(s):	Aspnes		
INCIDENT ADDRESS:	418 Sherburne Avenue, Saint Paul, MN 55103		
OCCUPANT NAME:	John L. Gherity	<b>PHONE</b> : 651-224-4019	
OWNER NAME:	Dorothy E. Gherity	PHONE: Unknown	
ADDRESS OF OWNER:	Unknown		
PROPERTY DAMAGED:	Single family dwelling	<b>AREA OF ORIGIN:</b> 1 <sup>st</sup> floor dining area on floor next to east wall.	
DAMAGE ESTIMATE:	Building \$1,000	Vehicle \$N/A	Other(Describe) \$N/A
VALUE:	Building \$73,700	Vehicle \$N/A	<b>Other(Describe)</b> \$N/A
Damage Estimate CONTENTS ONLY:	<b>\$</b> 500		
INJURY/DEATH (if yes, explain)	🛛 No 🗌 Yes		
SMOKE DETECTOR, SPRINKLER, and CARBON MONOXIDE INFORMATION:	Smoke Detector Present: Detector Functioning: Sprinkler System Present Sprinkler Heads activated C.O Detector Present:		No Unknown   No Unknown   No Unknown   No Unknown   No Unknown   No Unknown   No Unknown
FIRE CAUSE CLASSIFICATION:	Accidental Juvenile/Incendiary   Incendiary Child (under 10 years old)   Natural Undetermined   Under Investigation Indetermined		
SYNOPSIS:	The fire department was dispatched for a reported structure fire. Firefighters arrived to find a small fire in the dining room. Firefighters extinguished the fire and performed overhaul. The occupant was home at the time of the fire, noticed smoke while in the basement, turned off all breakers at the fuse panel, and evacuated. He denies performing any hot work, using any appliances, or smoking today in the area of origin. There were no appliances plugged in near the area of origin. Carelessly discarded smoking materials were found all over the home but not in the immediate area of origin. The home was extremely dirty and disorganized with a significant amount of dirt from the basement having been deposited on the first floor. The ignition source was probably discarded smoking materials or an open flamed device. The first material ignited was probably ordinary combustibles present in the house. The act that brought them together was probably careless disposal of smoking materials or careless use of an open flamed device. The classification of fire cause is undetermined.		

DISPOSITION:	E-mail only Hold Scene until approved
	🗌 DO NOT DEMOLISH until approved 🔀 Scene Released
	Analysis of Evidence Pending 🛛 Report to Follow

DFSS Form #141 (12/19/2013)