



CITY OF SAINT PAUL

Christopher B. Coleman, Mayor

375 Jackson Street, Suite 220
Saint Paul, MN 55101-1806

Telephone: 651-266-8989
Facsimile: 651-266-9124
www.stpaul.gov/dsi

Code Compliance Report

June 06, 2017

*** * This Report must be Posted
on the Job Site * ***

Walker Properties LLC
3230 Gorham Ave
Minneapolis MN 55426-4294

Re: 670 Western Ave N
File#: 15 189531 VB3

Dear Property Owner:

The following is the Code Compliance report you requested on May 08, 2017.

Please be advised that this report is accurate and correct as of the date June 06, 2017. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from June 06, 2017. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected. A Legislative Code exemption (Chapter 33.03(f)) allows a Category 2 Vacant Building to be sold "as is" providing the buyer, prior to closing, completes an approval process. For further information, call Reid Soley at 651-266-9120.

ZONING

1. This property is in a(n) RT1 zoning district.
2. This property was inspected as a Single Family Dwelling.

BUILDING Inspector: Jim Seeger

Phone: 651-266-9046

1. Dry out basement and eliminate source of moisture. SPLC 34.10 (10)
2. Install floor covering in bathroom and kitchen that is impervious to water. SPLC 34.10 (4)
3. Repair walls, ceiling and floors throughout, as necessary. SPLC 34.34 (6)
4. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34

- for additional information) if lead base paint is present. SPLC 34.33 (1)
5. Any framing members that required repair or do not meet code (where wall and ceiling covering is removed, members that are over-spanned, over-spaced, not being carried properly, door and window openings that are not adequately supported, etc.) are to be reconstructed in an approved manner. SPLC 34.34 (1)
 6. Charred building components shall be scraped or sandblasted completely clean and water-damaged components replaced. A determination of necessary fire damage corrective measures shall be made by this department or by a registered structural engineer as to replacement, repairs, etc. All smoke damaged and charred members shall be cleaned, sealed and deodorized. SPLC 34.09
 7. Provide fire block construction as necessary and seal chases in basement ceiling. MNRC Ch 1309 Sect. 602.8
 8. Where wall and ceiling covering is removed install full thickness or code-specified insulation. MN Energy Code Ch. 1322.1101 (except. 4)
 9. Air-seal and insulate attic/access door. MN Energy Code Ch 1322.1102.4
 10. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1
 11. Provide major clean-up of premises. SPLC 34.34 (4)
 12. Remove mold, mildew and moldy or water damaged materials. SPLC 34.10 (1)
 13. Provide proper drainage around house to direct water away from foundation of house. SPLC 34.08 (2)
 14. Provide proper drainage around house to direct water away from foundation of garage. SPLC 34.08 (2)
 15. Install downspouts and a complete gutter system. SPLC 34.33 (1d)
 16. Install rain leaders to direct drainage away from foundation. SPLC 34.33 (1d)
 17. Install address numbers visible from street and on the alley side of garage. SPLC 70.01
 18. Grade must drain away from foundation of dwelling. Maintain 6 inch clearance between wood and soil. MNRC Ch 1309-Sect. 404.1.6
 19. Install flashing on north side of house at bottom of siding.
 20. Remove all wall , ceiling and floor covering from house on all 3 floors.
 21. Replace fire damaged framing and missing 1st. floor south header.
 22. Replace all damaged siding , trim and house wrap with inspections before covering.
 23. Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment. MNRC Ch 1309 Sect. 311 & 312
 24. Install safety glass in window at top of 2nd. floor stairs.
 25. Insulate ceiling and walls to code.
 26. Replace all fire damaged sheathing and weather barrier.
 27. Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary. SPLC 34.09 (3)
 28. Provide complete storms and screens, in good repair for all door and window

- openings. SPLC 34.09 (3e)
29. Provide functional hardware at all doors and windows. SPLC 34.09 (3f)
 30. Exit doors shall be capable of being opened from the inside, easily and without the use of a key. Remove all surface bolts. SPLC 34.09 (3h)
 31. Repair or replace damaged doors and frames as necessary, including storm doors. SPLC 34.09 (3f)
 32. Weather seal exterior doors, threshold and weather-stripping. SPLC 34.09 (3f)
 33. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

Notes:

1. See attachment for permit requirements and appeals procedure.
2. This property is designated by the Vacant Buildings Department as a Category #3 which requires a \$5,000.00 Performance Bond or Deposit at the time the permit is issued.
3. Provide plans and specifications for any portion of the building that is to be rebuilt.
4. Most of the roof covering could not be inspected from grade. Recommend this be done before rehabilitation is attempted.
5. Interior of garage not available for inspection. Repair per applicable codes.

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

Re: 670 Western Ave N
June 06, 2017
Page 4

If you have any questions regarding this inspection report, please contact Jim Seeger between 7:30 - 9:00 AM at 651-266-9046 or leave a voice mail message.

Sincerely,

James L. Seeger
Code Compliance Officer
Department of Safety and Inspections
City of Saint Paul
375 Jackson Street, Suite 220
Saint Paul MN 55101
Phone: 651-266-9046
Email: jim.seeger@ci.stpaul.mn.us

Attachments