

CITY OF SAINT PAUL, MN

Christopher B. Coleman, Mayor

DEPARTMENT OF SAFETY AND INSPECTIONS

Steve Magner, Manager of Code Enforcement Katie Larson, Truth-in-Sale of Housing Manager

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806

Phone: 651-266-8989 Fax: 651-266-1919 Web: <u>www.stpaul.gov/dsi</u>

Truth-in-Sale of Housing Report

This is a visual disclosure report based on the current City of Saint Paul Truth-in-Sale of Housing Evaluator Guidelines and is valid for one year from the date of issuance and for the owner named.

Property Address: 581 HALL AVE Date of Evaluation: Jul 12, 2017 Date of Expiration: Jul 12, 2018

This report is intended to provide basic information to the home buyer and seller prior to the time of sale.

This report WILL NOT be used to enforce the requirements of the Legislative Code; however, it will be used to determine if there is compliance with the requirements for sale within the City of Saint Paul, MN.



MAJOR NOTIFICATIONS AND WARNINGS

For questions on these items, call the City's Information and Complaint Line at 651-266-8989

- Residential Type: Single Family Dwelling
- Smoke Detectors:
 - Smoke Detector Present: Y
 - Smoke Detector Properly Located: Y
 - Smoke Detector Hard Wired (required in Single Family Homes): Y
 - Smoke Detector Comments:
- Open Permits:

This property has No Open Permits.

HAZARDOUS

Attic Space

• Electrical wiring/outlets/fixtures

Basement Only

Electrical wiring, outlets and fixtures

Bathroom(s)

• Electrical outlets and fixtures

Plumbing System

• Gas piping (all floors)

Sleeping Room(s)

· Electrical outlets and fixtures

BELOW MINIMUM

Basement/Cellar

- · Basement/Cellar Floor
- First Floor, Floor System
- Foundation
- · Stairs and Handrails

Enclosed Porches and Other Roc

· Walls, ceiling and floor condition

Exterior Space

- Drainage (grade)
- · Exterior walls
- Foundation
- Open porches, stairways and deck(s)
- · Roof structure and covering

Hallways, Stairs and Entries

Stairs and handrails to upper floors

Heating System(s)

• Installation and visible condition

Plumbing System

• Water piping (all floors)

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)

H: Hazardous Condition

B: Below Minimum

C: See Comments

M: Meets Minimum

Y: Yes

N: No

NV: Not Visible

NA: Not Applicable

CITY OF SAINT PAUL TRUTH-IN-SALE OF HOUSING REPORT

Address: 581 HALL AVE File Number: File#: 17-058815

Date of Evaluation: Jul 12, 2017 Owner: Mariana Lazo

Zoning District: RT1 Client Name: Pedro Serrano
Present Occupancy: Client Contact: 612-207-7829

Number of Units Evaluated Single Family: Figure 1. Single Family: Client Name: Luis Alegara.

Number of Units Evaluated: Single Family Evaluator Name: Luis Alcaraz

Υ

Dwelling Evaluator Contact: Work: 612-743-8228

inspectucasa@yahoo.com

Basement/Cellar

1. Stairs and HandrailsB - Head room less than 6 feet 8 inches

B -Missing guardrail

B - Tread less than 9", riser more than 8"uneven

risers

2. Basement/Cellar Floor B

B - Floor: holes or cracked/damaged areas

B - Uneven or buckled floor areasB - Crawl space vapor barrier is

missing/incomplete

3. Foundation B

B - Missing, cracked or deteriorated blocks, bricks

stones or mortar

4. Evidence of Dampness or Staining

C - Stains evident

5. First Floor, Floor System B

C - Evidence of water seepage

B - Rot, decay, insect damage in areas

B - Wood in contact with dirt/Lacks 18" clearance

over dirt in crawl space(s) B - Damaged components

6. Beams and Columns M

Electrical Services

7a. Number of Electrical Services 1

7b. Amps 100

7c. Volts 120-240

Basement Only

8. Electrical service M

installation/grounding

Electrical wiring, outlets and H H - Missing knockouts on panel

fixtures

Plumbing System

10. Floor drain(s) (basement)11. Water and vent piping (all M

floors)

12. Water piping (all floors) B

B - Missing backflow preventer

13. Gas piping (all floors) H

H - Uncapped dryer supply

14. Water heater(s), installation M

15. Water heater(s), venting M

581 HALL AVE

Sul 12, 2017
Evaluator: Luis Alcaraz

Page # 3

Report Rating Key (Where there are	e multiple rooms to a cate	gory, the Evaluator must specify t	the room to which a Comment is related)
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable
16. Plumbing fixture (basement)	es M		
Heating System(s)			
heating plant(s) ex	ot required to opera cept during the hea ctober 15 and April	ting	
17a. Number of Hea Systems	ting 1		
17b. Type	Hot		

B - Rusted areas

Water

Gas

В

Ν

M

NA

NA

NA

NA

NA

Μ

M

Ν

M

Μ

M

Μ

M

M

Μ

Ν

M

M

17c. Fuel

condition

Type

Kitchen

height

staining

fixtures

exhaust

height

condition

18. Installation and visible

(required in heating season) 20. Combustion venting

21a. Additional heating unit(s):

21b. Additional heating unit(s):

21c. Installation and visible

21d. Viewed in operation

21e. Combustion venting

23. Floor condition and ceiling

24. Evidence of dampness or

25. Electrical outlets and

28. Window size/openable

doors/windows/mechanical

31. Floor condition and ceiling

32. Evidence of dampness or

34. Window size and openable

35. Window and door condition

Hallways, Stairs and Entries

area/mechanical exhaust

Living and Dining Room(s) 30. Walls and ceiling

26. Plumbing fixtures

27. Water flow

29. Condition of

22. Walls and ceiling

19. Viewed in operation

staining
33. Electrical outlets and M
fixtures

36. Walls, ceilings, floors M

C - Floor is out-of-level

581 HALL AVE

Sulvator: Luis Alcaraz

Jul 12, 2017

Page # 4

C - Floors are out-of-level

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related) B: Below Minimum C: See Comments M: Meets Minimum Y: Yes N: No NV: Not Visible NA: Not Applicable 37. Evidence of dampness or Ν staining 38. Stairs and handrails to В upper floors B - Head room less than 6 feet 8 inches B - Tread less than 9" 39. Electrical outlets and Μ fixtures 40. Window and door conditions **Smoke Detectors** Υ 41a. Present 41b. Properly Located Υ 41c. Hard-Wire Bathroom(s) 42. Walls and ceiling M 43. Floor condition and ceiling M height C - Floor is out-of-level 44. Evidence of dampness or Ν staining 45. Electrical outlets and Н H - Missing cover plates fixtures 46. Plumbing fixtures M 47. Water flow Μ 48. Windows size/openable M area/mechnical exhaust 49. Condition of Μ windows/doors/mechanical exhaust Sleeping Room(s) 50. Walls and ceilings M 51. Floor condition, area and Μ ceiling height C - Floors are out-of-level 52. Evidence of dampness or Ν staining 53. Flectrical outlets and Η H - Ungrounded 3-prong outlets fixtures H - Broken/missing outlet/switch plate(s) 54. Window size and openable Μ area 55. Window and door condition M

Enclosed Porches and Other Rooms

56. Walls, ceiling and floor B condition C - Floors are out-of-level 57. Evidence of dampness or Ν staining 58. Electrical outlets and NA fixtures 59. Window and door condition NA

Attic Space

60. Roof boards and rafters M 61. Evidence of dampness or Υ staining C - Stains evident 62. Electrical

Н H - Exposed /improperly terminated wiring wiring/outlets/fixtures

: Hazardous Condition	B: Below Minimu		C: See Comments	he room to which a Comment is related M: Meets Minimum
: Yes	N: No	3111	NV: Not Visible	NA: Not Applicable
63. Ventilation	14. 140	Υ	144.1401.41010	TW. Net Applicable
os. ventuation		Y	B - Exhaust fan(s) do	not vent to exterior
Exterior Space			Extradst rangs do	not vent to exterior
64. Foundation		В		
_		D	B - Damaged / weather	ered areas
			B - Foundation bowed	
			B - Missing / damage	d mortar -block
65. Basement/cellar windows		M		
66. Drainage (grade)		В	D. Crada dasan't alla	w overfood water to drain
			away from building	w surface water to drain
			B - Damaged/Settled	walk(s)/driveway
67. Exterior walls		В	3	, ,
			B - Damaged areas	
		. .	C - Walls out of pluml	D
68. Doors(frames/storms/screens)69. Windows(frames/storms/screens)		M		
		М		
70. Open porches, stairways and deck(s)		В		_
			B - Improper rise/run	on steps
71. Cornice and trim(s)		M	B - Loose railing	
72. Roof structure and covering		В		
				3/4" overhang at rake edges
			B - Missing/damaged	
		N //	B - Trees / vegetation	in contact with roof
73. Gutters and downspouts		M M		
74. Chimney(s)75. Outlets, fixtures and service		M		
entrance		IVI		
Garage(s)/Accesso	orv Structure(:	s)		
76. Roof structure and covering		NA		
77. Wall structure and covering		NA		
78. Slab condition		NA		
79. Garage door(s)		NA		
80. Garage opener(s)		NA		
81. Electrical wiring, outlets and		NA		
fixtures				
Fireplace/Woodsto	ove			
82. Number of Units		NA		
83. Dampers installed		NA		
84. Installation		NA		
85. Condition		NA		
Insulation				
86a. Attic Insulation: Present		Υ		
86b. Attic Insulation: Type		Cellulose		
86c. Attic Insulation: Depth		3-6		
070 Form -1-1:	lnoulotion:	inches		
87a. Foundation Insulation:		N		

Jul 12, 2017 581 HALL AVE Evaluator: Luis Alcaraz Page # 6

Present

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)

H: Hazardous Condition

B: Below Minimum

C: See Comments

M: Meets Minimum

Y: Yes

N: No

NV: Not Visible

NA: Not Applicable

87b. Foundation Insulation: NA

Type

87c. Foundation Insulation: NA

Depth

88a. Knee Wall Insulation: NA

Present

88b. Knee Wall Insulation: Type NA 88c. Knee Wall Insulation: Depth NA 89a. Rim Joist Insulation: N

Present

89b. Rim Joist Insulation: Type NA 89c. Rim Joist Insulation: Depth NA

General

90. Carbon Monoxide Alarm M

General Comments

Smoke Detectors

41a. Present Y
41b. Properly Located Y
41c. Hard-Wire Y

581 HALL AVE

Sulvator: Luis Alcaraz

Page # 7

LEGAL NOTICES:

Chapter 189 of the Saint Paul Legislative Code requires all single family, duplex, condo, townhouse and co-op homes for sale in the city to have a Truth-in-Sale of Housing disclosure report prepared and available to prospective buyers. A Truth-in-Sale of Housing disclosure report must be done for Contract-For-Deed sales.

A Truth-in-Sale of Housing (TISH) Disclosure Report in the City of Saint Paul is intended to provide basic information to the home buyer and seller prior to the time of sale. Failure to obtain a Truth-in-Sale of Housing disclosure report or failure to make that disclosure report available to prospective buyers, is a violation of law and is punishable as a misdemeanor carrying up to 90 days in jail and/or a \$1,000.00 fine.

A valid Truth-in-Sale of Housing disclosure report must be conspicuously displayed at the premises for all prospective buyers. TISH disclosure reports are also available online: https://online.stpaul. gov/web/portal/public-search

- This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this evaluation form will be used to determine if there is compliance with the requirements for a hardwired smoke detectors.
- This TISH report is based on the current Truth-in-Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- This TISH is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- This TISH report covers only the items listed on the form and only those items visible at the time of the evaluation.
- The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- This TISH report is valid for one year from the date of issue and only for the owner named on this
- If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- Automatic garage doors should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.
- All single family residences in Saint Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, (651)228-6230. (Saint Paul Legislative Code, Chapter 58.)
- Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, and (651)266-6234.
- A house built before 1950 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, (651)292-6525.
- Neither the City of Saint Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.

Questions regarding this report should be directed to the evaluator. If you desire a reinspection and amended report, please contact your evaluator. They will perform a reinspection and file an amended report with the City of Saint Paul. The TISH evaluator may charge for this reinspection. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth-in-Sale of Housing Program, Phone 651-266-8989.

581 HALL AVE Jul 12, 2017

Evaluator Statement:

I hereby certify I prepared this report in compliance with the Saint Paul Evaluator Guidelines, City of Saint Paul City Ordinance 189 and all other applicable policies and procedures of the Truth-in_Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrent future useful life of any house component or fixture. I have included all required information pages with this report. Evaluator Name: Luis Alcaraz

Phone: Work: 612-743-8228 Evaluation Date: Jul 12, 2017

581 HALL AVE Jul 12, 2017 Evaluator: Luis Alcaraz Page # 9