


**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

This is the interior, east side wall during the second visit.



Date: January 17, 2019  
File #: 16 - 032685  
Folder Name: 455 GRAND AVE  
PIN: 012823310114



Interior East side wall, different angle.  
Note the piping. Second inspection.


**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Interior carriage house east side wall on second inspection.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Interior carriage house east side wall on second inspection.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Furnace inside the main house that was not working during second inspection.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Kitchen remodel in the main house not done under permit.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Kerosene heater in main house bedroom.



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114

Kerosene heater in main house bedroom.





**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114


Propane heater inside main house  
bedroom.



Date: January 17, 2019  
File #: 16 - 032685  
Folder Name: 455 GRAND AVE  
PIN: 012823310114



Date: January 17, 2019  
File #: 16 - 032685  
Folder Name: 455 GRAND AVE  
PIN: 012823310114



**Date:** January 17, 2019  
**File #:** 16 - 032685  
**Folder Name:** 455 GRAND AVE  
**PIN:** 012823310114