


Cracking and separation on the East side exterior of the Carriage House.



Cracking and separation of the West exterior wall of the Carriage House.





Exterior west wall damage above window.



Date:	January 17, 2019
File #:	16 - 032685
Folder Name:	455 GRAND AVE
PIN:	012823310114


More damage exterior west wall. Window pulling away from the brick



"garage door" of carriage house. Header cracked and separating.




Zoomed out view of the "garage door".




Date:	January 17, 2019
File #:	16 - 032685
Folder Name:	455 GRAND AVE
PIN:	012823310114


West wall exterior of carriage house.



Interior west wall of the carriage house. You can see daylight through the various cracking and separation.



Cracking and separation on the west wall of the Carriage House.



North wall. Hard to tell in pictures, but this wall is bulging inward.



West side of carriage house doorway. Phone camera is straight, doorway is slanted.



Date:	January 17, 2019
File #:	16 - 032685
Folder Name:	455 GRAND AVE
PIN:	012823310114

Interior East wall damage with carious cracking. Note the piping.









Date:	January 17, 2019
File #:	16 - 032685
Folder Name:	455 GRAND AVE
PIN:	012823310114

